Access Audit Site Report



Prepared By Group

Engineering with Precision, Pace & Passion. (224) 293 - 6451 www.wtengineering.com Choke Canyon State Park 700 TX-72 Three Rivers, TX 78071 Accessibility Evaluation Inspection Date: 06/13/2022 Inspectors: Tanya Scheibe

Cover Letter
CHOKE CANYON STATE PARK PROGRAM REPORT 202301
Findings
Headquarters (HQ)
Calliham Unit (CU)
CU - Dining Hall
CU - Gymnasium
CU - Group Hall
CU - Restrooms
CU - Nature Center
CU - Screened Shelters
CU - Old Park Store By Ramp
Trails
South Shore (SS), Day Use Unit





July 28, 2023

Jessica Burke, ADA Coordinator Support Resources Texas Parks and Wildlife Department 4200 Smith School Road Austin, TX 78744

Dear Jessica,

Thank you for the opportunity to be of service to you by performing an accessibility evaluation for the Choke Canyon State Park located at 700 TX-72, Three Rivers, TX 78071. The facility was inspected on 06/13/2022.

We recommended that all barriers that are identified in this evaluation recommended in one of the phases below, be removed as soon as possible. A transition plan should be developed to assist in planning the removal of all barriers. To help with this, we have identified all barriers on a finding by finding basis with a phase identifier as follows:

1 (Phase 1): Should be completed immediately. This category includes findings that have little or no cost, were in violation of the codes at the time of construction, or pose an imminent safety threat.

2 (Phase 2): Should be completed as soon as possible. Includes findings that would remove barriers to the greatest number of people to your goods and services and findings new to the technical standards such as recreation elements

3 (Phase 3): Should be completed as soon as possible, but there may be other items that will provide greater access to persons with disabilities. This category includes findings that have a high financial impact on the entity, are subject to standards not yet final, or involve a partner entity.

4 (Option): Not necessary to complete, because other sites exist that meet Title II requirements for program access, or retrofit is technically infeasible, or variance is a construction tolerance.

5 (Smart Practice): Should be completed but not necessarily required. This category includes findings and or elements that were in compliance with previous editions of the codes and standards but have since changed. This category also includes techniques or elements that are not a part of the federal or state requirements, but are suggested in advisory language, or have been successfully implemented by other entities. Generally, these items are easily modified to provide the greatest degree of access as well as compliance with the most current codes and standards.

Periodic maintenance to ensure continued accessibility is essential in providing a safe and usable environment. Parking lot markings, signage, door opening pressures, and maintaining clear floor space at doors and other elements and fixtures, available to the public, must be part of an ongoing maintenance schedule.

224.293.6333 wtengineering.com





If you have any questions regarding this report or would like to schedule a meeting with myself and your architect, attorney, or contractor, please feel free to contact me.

Legend of Abbreviations:

AFF... Above the finished floor AGL... Above Ground Level AR... Accessible Route CIL... Change in Level CFS... Clear Floor Space EPC... Elevated Play Component GLPC...Ground Level Play Component

Sincerely,

Tanya Schule

Tanya Scheibe, RAS #1369





TEXAS PARKS AND WILDLIFE DEPARTMENT CHOKE CANYON STATE PARK

AMERICANS WITH DISABILITIES ACT COMPLIANCE INITIATIVE PROGRAM AND POLICY REPORT JULY 28, 2023

INTRODUCTION

The Texas Parks and Wildlife Department (TPWD) is subject to the many requirements of the Americans with Disabilities Act (ADA). To assist it in meeting those requirements, TPWD retained The WT Group, LLC (WTG) Accessibility Practice in 2021.

Title II of the ADA applies to TPWD sites, along with 89,000 other units of state and local government. WTG has a broad scope of work that matches the ADA requirements found in title II. It includes:

- Schedule and conduct project management meetings;
- Conduct access audits of 89 sites, including Choke Canyon State Park;
- Prepare a site report that describes deficits at Choke Canyon State Park, and suggests solutions to those deficits;
- Provide guidance regarding the programs or opportunities Texans can enjoy at Choke Canyon State Park;
- Conduct community engagement events to determine the access preferences and priorities of Texans who visit Choke Canyon State Park;
- Provide a Choke Canyon State Park Transition Plan that identifies deficits, notes solutions, identifies the officer responsible for barrier removal, and notes the phase or timing of barrier removal;
- Provide a GIS shapefile regarding the accessibility of Choke Canyon State Park;
- Provide a method of tracking barrier removal at Choke Canyon State Park; and
- Report to TPWD leadership and stakeholders.

THIS REPORT

This report addresses program and policy advice, and then the WTG observations of deficits at Choke Canyon State Park. Other deliverables are provided under separate cover.

What is a Program?



A unit of state or local government is required to make the "programs" it offers accessible to people with and without disabilities. The term "program" is broadly defined as an opportunity made available by the state to the public, and the term public includes both people with and without disabilities. As an example, if a state park offers camping it must make certain that some campsites are of an accessible design.

The number to be made accessible is called scoping and it is usually a percentage or ratio of the similar sites. For example, if a state park has outdoor constructed features such as grills, fire pits, and benches, it must make 20% of an accessible design. Those 20% accessible must be dispersed throughout the park.

In an ADA context, "programs" at a state park or state natural area include but are not limited to:

Hiking	Fishing
Camping	Bird Watching
Swimming	Playgrounds
Lodging	Beaches
Boating	Interpretive activities
Parking	Visitor Centers
Trams	Picnicking
Sports fields	Viewing areas
Restrooms	Grilling

The Federal and Texas Accessibility Standards

The current Texas Accessibility Standards (TAS 2012) became effective in 2012 after an amendment process. Those Standards are almost identical to the federal 2010 Standards for Accessible Design, and both effectively address parking, entries, restrooms, and other typical building elements. They also address playgrounds, boating and fishing areas, and sports fields and courts. They do not however address some of the assets at Choke Canyon State Park. Trails, campsites, and picnic areas are not yet a final and enforceable state or federal standard.

That will change at the end of 2023 or early 2024. The Texas Department of Licensing and Regulation (TDLR) has signaled its intent to adopt the pending federal guidance for key outdoor assets integral to TPWD sites like Choke Canyon State Park. This includes trails, beaches, campsites, picnic areas, viewing areas, and constructed park assets like grills, fire pits, and benches.

In discussing the Standards, it is important to use the correct definition of park assets. Most definitions are found in TAS 2012 at section 106. As noted above, TDLR plans to add the pending federal guidance regarding some outdoor areas to TAS. It is important to remember that the Standards set the floor, not the ceiling. Making a slope more gentle, or a route wider, is always a smart practice with universal design benefits.

Some selected definitions of park assets common to TPWD are noted below.

- **Trail**: A pedestrian route developed primarily for outdoor recreational purposes. A pedestrian route developed primarily to connect elements, spaces, or facilities within a site is not a trail.
- **Trailhead**: An outdoor space that is designed by an entity responsible for administering or maintaining a trail to serve as an access point to the trail. The junction of two or more trails or the undeveloped junction of a trail and a road is not a trailhead.
- **Picnic Facility**: A site or portion of a site developed for outdoor recreational purposes that contains picnic units.
- **Picnic Unit**: An outdoor space in a picnic facility used for picnicking that contains outdoor constructed features.
- **Outdoor Constructed Features**: Picnic tables, fire rings, grills, fireplaces, wood stoves, trash and recycling receptacles, water hydrants, utility and sewage hookups, outdoor rinsing showers, benches, and viewing scopes provided at outdoor recreation facilities.
- **Camp Shelter**: A partially enclosed structure that provides campers and hikers cover from weather and that does not contain plumbing fixtures or kitchen appliances. Camp shelters are not transient lodging facilities or residential dwelling units.
- **Camping Facility**: A site or portion of a site developed for outdoor recreational purposes that contains camping units.
- **Camping Unit**: An outdoor space in a camping facility used for camping that contains outdoor constructed features, parking spaces for recreational vehicles, tent pads or tent platforms, or camp shelters.
- Viewing Area: An outdoor space developed for viewing landscapes, wildlife, or other points of interest.
- **Boarding Pier**: A portion of a pier where a boat is temporarily secured for the purpose of embarking or disembarking.
- **Boat Launch Ramp**: A sloped surface designed for launching and retrieving trailered boats and other watercraft to and from a body of water.
- **Gangway**: A variable-sloped pedestrian walkway that links a fixed structure or land with a floating structure. Gangways that connect to vessels are not addressed by these Standards.
- **Transition Plate**: A sloping pedestrian walking surface located at the end(s) of a gangway.
- **Play Area**: A portion of a site containing play components designed and constructed for children.
- **Play Component**: An element intended to generate specific opportunities for play, socialization, or learning. Play components are manufactured or natural; and are standalone or part of a composite play structure.



Two other key outdoor assets are not included in the definitions. Both are defined below.

- **Beach access routes**: A beach access route (BAR) connects an entry point to the beach to the water, as defined below:
 - At a tidal beach, to the high tide level
 - At a river beach, to the mean high water level
 - At a lake, pond, or reservoir beach, to the normal recreation water level

A BAR can be temporarily placed at a beach for all hours the beach is open, and need not be a permanent fixture.

• Outdoor Recreation Access Routes (ORAR): A route that connects outdoor recreation assets at an outdoor recreation site. An ORAR is not a trail.

Conditions for Exceptions at Certain Outdoor Recreation Assets

In developing the scoping and technical requirements for accessibility at beaches, trails, and other outdoor developed areas, a wide net was cast to assure a variety of perspectives. The process involved:

- Officials from states with beaches and trails
- Officials from local entities with beaches and trails
- People with disabilities
- Landscape architects and civil engineers
- Parks and recreation officials

Throughout the process, all agreed that there are times that an existing beach, a new beach, an existing trail, or a new trail cannot meet the technical requirements for accessibility. The belief of regulatory bodies however is that these conditions should arise infrequently. The four conditions for exception are defined and discussed below.

• Section 1019.1.1: Compliance is not practicable due to terrain.

This is best clarified as naturally occurring terrain. It is applicable to both existing trails, and new trails. When locating and designing new trails, making the trail accessible should be a very high priority. *This is especially important at Choke Canyon State Park where one of the five existing trails are accessible.*

• Section 1019.1.2: Compliance cannot be accomplished with the prevailing construction practices.

This is best clarified as a reference to prohibitions on the use of foreign soil or motorized equipment. As an example, if a trail bed is being carved by TPWD staff and volunteers on their hands and knees, with pick axes, shovels, and hoes, all because of a prohibition on motorized equipment in the park, this exception may apply

• Section 1019.1.3: Compliance would fundamentally alter the function or purpose of the facility or the setting.



This is best clarified as having a clear understanding of the purpose of the asset. A sharply ascending trail in a mountainous West Texas state park may have the intended use of endurance training. To "flatten" the trail is possible from a design perspective, but the trail then loses its function or purpose.

• Section 1019.1.4: Compliance is limited or precluded by any of the following laws, or by decisions or opinions issued or agreements executed pursuant to any of the following laws:

Endangered Species Act (16 USC 1531 et seq.);

National Environmental Policy Act (42 USC 4321 et seq.);

National Historic Preservation Act (16 USC 470 et seq.);

Wilderness Act (16 USC 1131 et seq.); or

Other federal, State of Texas, or local laws the purpose of which is to preserve threatened or endangered species; the environment; or archeological, cultural, historical, or other significant natural features.

There are other mitigating factors regarding accessibility. Four are discussed below.

- Construction Tolerance (see 104.1.1 Construction and Manufacturing Tolerances): All dimensions are subject to conventional industry tolerances except where the requirement is stated as a range with specific minimum and maximum end points. This is likely most applicable in new construction, but may also apply to making transition plan retrofits.
- Equivalent Facilitation (see 103 Equivalent Facilitation): Nothing in these requirements prevents the use of designs, products, or technologies as alternatives to those prescribed, provided they result in substantially equivalent or greater accessibility and usability. This is likely most applicable in new construction, but may also apply to making transition plan retrofits.
- Technical Infeasibility (see 106 Definitions): With respect to an alteration of a building or a facility, a condition wherein compliance with a requirement of this Standard has little likelihood of accomplishment because existing structural conditions would require removing or altering a load-bearing member that is an essential part of the structural frame; or because other existing physical or site constraints prohibit modification or addition of elements, spaces, or features that are in full and strict compliance with the minimum requirements. This is likely most applicable to making transition plan retrofits.
- Safe Harbor (see US DOJ title II section 35.151(c)): If a public entity has constructed or altered required elements of a path of travel in accordance with the specifications in either the 1991 Standards or the Uniform Federal Accessibility Standards, or TAS 1994, before March 15, 2012, the public entity is not required to retrofit such elements to reflect incremental changes in the 2010 Standards solely because of an alteration to a primary function area served by that path of travel. It is important to note that the 1991 Standards and TAS 1994 did not address technical requirements for recreation assets, such as boating areas, fishing areas, beaches, campsites, trails, picnic



areas, playgrounds, sports fields, sports courts, and more. The Safe Harbor approach cannot be applied to such assets.

Campsites

We have sorted campsites into several categories. These include tent only campsites, recreational vehicle campsites, shelter sites, and sites that combine features in a hybrid approach, such as an RV site with utilities.

In evaluating Choke Canyon State Park, WTG used TAS 2012, the pending outdoor developed areas guidance, and smart practices that make public spaces and outdoor recreation assets more accessible to people with disabilities. We also applied the concepts of construction tolerance, technical infeasibility, safe harbor, equivalent facilitation, and other limitations on when a site must be made accessible.

What is Inclusion?

The title II regulation requires Choke Canyon State Park programs to be available in the most integrated setting. This is defined as the setting in which people with and without disabilities interact together. Using the camping example above, inclusive camping would locate accessible campsites amidst inaccessible campsites to facilitate interaction between campers with and without disabilities.

While all programs must be inclusive, that does not mean that everyone with every type of disability or health condition must be allowed to participate in every program. The concept of essential eligibility allows Choke Canyon State Park to apply neutral conditions to determine who uses programs. Again, using camping, if there are 20 campsites and a person with a disability is the 21st person to register, the neutral concept of "capacity" applies and that camper has no place to camp. If that camper is the 20th person to seek camping but does not pay the campsite fee, the neutral concept of paying the same fees can apply and that camper will not camp at Choke Canyon State Park.

How Can Programs in General Be Made Accessible?

The title II regulation at section 35.150(b) lists a number of ways to make Choke Canyon State Park programs accessible. These include but are not limited to:

- Removing architectural barriers;
- Removing communication barriers;
- Changing rules and policies;
- Providing additional staff training;
- Providing different staff ratios;
- Providing adaptive equipment;
- Providing auxiliary aids and services such as a sign language interpreter;

Choke Canyon State Park Program and Policy Report July 28, 2023 page 7

- Providing accessible transportation when transportation is part of the opportunity;
- Reassignment of services to accessible locations;
- Conducting duplicate opportunities, one in accessible location and the other in an inaccessible location;
- Designing and constructing new facilities that are therefore fully compliant;
- Home visits; and
- Other methods that make programs accessible.

Choke Canyon State Park staff should be aware of, and ready to, provide such modifications.

Are the Choke Canyon State Park Programs Accessible and Inclusive?

In our review of the opportunities available at Choke Canyon State Park, we saw:

- two fishing areas at Calliham;
- two boating areas at Calliham and three boating areas at South Shore;
- two swimming areas at Calliham;
- 51 camping areas at Calliham;
- 20 cabins at Calliham
- Five trails at Calliham;
- 53 picnic areas at Calliham and four picnic areas at South Shore; and
- Several sports fields or courts at Calliham.

Of these, the accessibility status and our recommendation is:

- Make two Calliham fishing areas accessible;
- Make two of the five boating areas at Calliham and South Shore accessible;
- Make one swimming area at Calliham accessible;
- Make two of the ten tent-only campsites at Calliham accessible;
- Of the 40 hybrid campsites at Calliham, maintain the four accessible campsites and make the corrections in the site report
- Make the one youth group camp site accessible
- There are 20 cabins and four are accessible, leave as is and make corrections in site report to maintain accessibility
- Make one more trail accessible at Calliham;
- Of the 57 picnic areas eight are accessible, make 11 more accessible



- At Calliham, leave soccer, tennis, and basketball as is and maintain for accessibility; and
- At Calliham, leave baseball field as is and inaccessible until later replaced or renovated.

Camping Clarification

A number of campsites of each type provided within the park (see the Outdoor Developed Area Guidelines at 244.2, which will eventually be a part of the revisions to TAS 2012) must be retrofit to make the program of camping accessible, and to meet the soon-to-be-adopted State of Texas standard.

We have sorted campsites into three types: tent only, hybrid (usable by tent or RV), and group. TPWD or Choke Canyon State Park staff can also distinguish these sites by amenities provided (covered tables, water only, electric, scenic views, etc.).

If concessionaires are to provide camping experiences at the Park, those sites too must include accessible campsites.

Conclusion

The staff at Choke Canyon State Park offer experiences and assets desired by park visitors. Those same experiences and assets must be accessible to and usable by people with disabilities. See the following site report to identify barriers and recommendations for barrier removal.

JNM/TRS/CHOKE CANYON STATE PARK PROGRAM REPORT 202301

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
1	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	Element meets all standards and requirements	Calliham Unit - 16 standard and 2 accessible; parking meets scoping requirements	None	2010 ADAS Section: N/A		
2	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	Calliham Unit - enter side - 4'7", exit side - 4'2"	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces
3	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 16 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	Calliham HQ - no van stall or sizing	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2, 208.2.4		Main of characterized of particular

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
4	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	The cross slopes (long dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	Calliham HQ - enter side, access aisle 7.7% slope, 5.3%; exit side, stall - 4.9%, access aisle - 6.1%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		+ + &

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
5	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	Calliham HQ - both stalls and access aisles have loose gravel	Maintain stalls to reduce loose gravel or slip hazards.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₂ ¹ / ₂ ¹ / ₂
6	Headquarters (HQ) : HQ - Parking	[28.46601, -98.35448]	The accessible parking stall signage is incorrect and/or missing from each accessible parking space. Parking space identification signs shall include the International Symbol of Accessibility. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	Calliham HQ - signage missing on exit side	Acquire and mount at appropriate heights and locations accessible parking signs where missing	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6		RESERVED PARKING
7	Headquarters (HQ) : Calliham HQ - Public Spaces	[28.4658131 -98.354186 3]	The floor mat or carpet pile height is too high. Carpet or carpet tile shall be securely attached and shall have a firm cushion, pad, or backing or no cushion or pad. Carpet or carpet tile shall have a level loop, textured loop, level cut pile, or level cut/uncut pile texture. Pile height shall be 1/2 inch maximum. Exposed edges of carpet shall be fastened to floor surfaces and shall have trim on the entire length of the exposed edge.	2 of 2 rugs are not secure	Secure rug to prevent trip hazard.	2015 ABAAS Section: 302.2 2012 TAS Section: 302.2 2010 ADAS Section: 302.2		<u>1/2 max</u>

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
8	Headquarters (HQ) : Calliham HQ - Public Spaces	[28.46601, -98.35448]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	top shelf 61.25" above finished floor	Remount operable parts to be in reach range of 15" min to 48" max.	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1	UBBINES STATE	to max
9	Headquarters (HQ) : Calliham HQ - Public Spaces	[28.46601, -98.35448]	The transaction counter provides for a parallel approach but does not provide a minimum clear width of 36 inches. Transaction counters shall be 36 inches high and a minimum of 36 inches wide and should extend the same depth as the sales or service counter top.	low portion of the counter is in good range but is blocked by computer	Relocate computer to provide accessible transaction counter space.	2015 ABAAS Section: 904.4.1 2012 TAS Section: 904.4.1 2010 ADAS Section: 904.4.1		38° Min.
10	Headquarters (HQ) : Calliham HQ - Public Spaces	[28.46601, -98.35448]	The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	fish tank side - 15lbf; other side- 15lbf	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
11	Headquarters (HQ) : Calliham HQ - Public Spaces	[28.46601, -98.35448]	There is no accessible route to the picnic table. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no accessible route to picnic table, not of accessible design	Create an accessible route with crushed stone or other outdoor material from parking or walkway to picnic table. Replace picnic table with one that provides required knee and toe clearance as a smart practice.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSEL ENTENCES

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
	Headquarters (HQ) : Calliham HQ - Employee Spaces	[28.46601, -98.35448]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	entry from public space is 31" wide, .75" CIL; offices - 4 knobs; closet - 8" maneuvering clearance on pull due to shelf; office to side - storage in clearance on push and pull; office door beside sliding door - clearance on push reduced by water	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Replace doors with doors having 80" overhead clearance and 32" clear width. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
13	Headquarters (HQ) : Calliham HQ - Employee Spaces	[28.46601, -98.35448]	Changes in level greater than ½ inch (13 mm) high shall be ramped, and shall comply with 405 or 406.	not in use, no route to booth due to lack of curb ramp	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% along the AR where curbs are present.	2015 ABAAS Section: 303.4 2012 TAS Section: 303.4 2010 ADAS Section: 303.4		
14	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign on door, lacks Braille, International Symbol of Accessibility, and raised characters	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
15	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 67" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
16	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	31" clearance in front of the toilet due to trash	Relocate trash can to provide required 60" clearance around toilet.	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
17	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 6" from rear wall, extends 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
18	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	29" grab bar, 10" at toilet centerline	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2		Top of bar 33"-36"
19	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
20	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted too far from the front of the toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		yer and the second seco
21	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The second secon
22	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.7% by drain	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
23	Headquarters (HQ) : Calliham HQ - Women's Restroom	[28.46601, -98.35448]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	7" clearance on push side, lock 60" AFF, 19lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and mount between 34" and 48" aff.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
24	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign on door, lacks Braille, lacks International Symbol of Accessibility, lacks raised characters	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
25	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 64" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		view SP 10 max
26	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	trash 36" in clearance	Relocate trash can to provide required 60" clearance around toilet.	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
27	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 6" from rear wall, extends 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
28	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	30" grab bar, 10" at toilet centerline	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to the wall side of center and 24" to the open side and 33" to 36" AFF.	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2	Image: Sector secto	p of ar 333-36"
29	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	side grab bar mounted 37" AFF, rear grab bar mounted 36.5" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
30	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	mounted too far from front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		yeuros 1 2.9
31	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
32	Headquarters (HQ) : Calliham HQ - Men's Restroom	[28.46601, -98.35448]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	lock 60" AFF, 7" clearance on push, door sticks/ exceeds 30lbf, fast close	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp and mount between 34" and 48" aff.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
33	Headquarters (HQ) : South Shore HQ - Employee Spaces	[28.4673399 -98.246462 1]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	employee spaces only in this site, 3 knobs within, 12" clearance on pull side in sink room	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
34	Headquarters (HQ) : South Shore HQ - Employee Spaces	[28.4673186 -98.246496 9]	Employee Work Areas. Common use circulation paths within employee work areas shall comply with 402. EXCEPTIONS: 1. Common use circulation paths located within employee work areas that are less than 1000 square feet (93 m2) and defined by permanently installed partitions, counters, casework, or furnishings shall not be required to comply with 402. 2. Common use circulation paths located within employee work areas that are an integral component of work area equipment shall not be required to comply with 402. 3. Common use circulation paths located within exterior employee work areas that are fully exposed to the weather shall not be required to comply with 402.	25.5" width to back offices from entry	Make corrections for compliant circulation path.	2015 ABAAS Section: F206.2.8, F206.2.8.1, F206.2.8.2 2012 TAS Section: 206.2.8, 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 3, 206.2.8 Advisory 1, 206.2.8 Advisory 2 2010 ADAS Section: 206.2.8, 206.2.8 Exception 1, 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 2, 206.2.8 Exception 3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
35	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673446 -98.246494 3]	Knee clearance at 27 inches off the floor is not 8 inches minimum deep. The knee clearance, measured from the bottom of the apron or the outside bottom edge of the lavatory, must be 27 inches at a point located 8 inches back from the front edge and continuing to 11 inches minimum in depth at 9 inches above the floor. The top of the lavatory rim may be no higher than 34 inches.	trash in clear floor space	Remove trash bin to provide 8" deep knee clearance.	2015 ABAAS Section: 306.3.1, 306.3.2, 306.3.3, 306.3.4, 306.3.5 2012 TAS Section: 306.3.2, 306.3.3, 306.3.4, 306.3.5, 306.3.1 2010 ADAS Section: 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.1		Tee clearance 6° deep toe space
36	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673116 -98.246440 6]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes not insulated	Insulate exposed pipes under one sink.	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
37	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673304 -98.246464 8]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth is 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	dryer 53" AFF	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
38	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673257 -98.246475 5]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	bench in clear floor space	Relocate bench to provide required 60" clearance around toilet.	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
39	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.467321, -98.246462 1]	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than 44 inches above the floor.	closed side	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	2015 ABAAS Section: 604.6 2012 TAS Section: 604.6 2010 ADAS Section: 604.6		Transfer side
40	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673069 -98.246446]	The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	door doesn't open 90, push hardware 61" above finished floor, requires pinch, .5" lipped threshold	For all doors along the public circulation route, inspect, adjust, and maintain doors so they can open 90 degrees. For all doors along the public circulation route, repair, provide beveled threshold. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" minimum, 48" maximum aff.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
41	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4673399 -98.246462 1]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 4" from rear, extends 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	<image/>	
42	Headquarters (HQ) : South Shore HQ - Employee Restroom	[28.4671984 -98.246419 2]	The restroom is not compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lavatory. The entry door does not contain the required minimum maneuvering spaces on the pull/push sides. The entry door encroach into the required clear floor space for fixtures. Grab bars are missing and/or incorrectly installed. Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both.	unable to audit second restroom due to damaged plumbing, hasn't been used since 2008, assumed identical	Make corrections needed to make this restroom accessible or mount signage directing users to the accessible restroom in this building.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		SO" MIN CLEAR SO" MIN.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
43	Calliham Unit (CU): CU - Maintenance	[28.4763514 -98.349759 3]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	main entry - knob, 5.5" change in level, window 48" above finished floor	Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Replace doors with ones having sidelight viewing windows max 43" aff.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
44	Calliham Unit (CU): CU - Maintenance	[28.4763089 98.349716 4]	50% of the single accommodation restrooms provided in this grouping are not nearly compliant. The restrooms do not have the required minimum clear floor space or maneuvering clearances for the toilet, The restrooms do not have the required minimum clear floor space or maneuvering clearances for the lavatory, The entry doors do not contain the required minimum maneuvering spaces on the pull/push sides, The entry doors encroach into the required clear floor space for fixtures, Grab bars are missing and/or incorrectly installed, Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both, The restrooms contain floor level changes greater than a 1/2 inch, the showers are too small and missing numerous accessible elements.	non compliant restroom - no signage, 59" by 46"	Create compliant wheelchair accessible restrooms and correct all features to be accessible if feasible to meet 50% compliant restrooms in this location.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		OUT

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
45	Calliham Unit (CU): CU - Maintenance	[28.4763113 -98.349753 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	restroom - knob, clearance on push reduced by shelf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
46	Calliham Unit (CU): CU - Maintenance	[28.4763278 -98.349652]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	door from main room to garage - knob, window 48" above finished floor, 3" CIL, 7" clearance on push; door across garage - knob, window 47.5" above finished floor, 3" CIL, 5" clearance on push due to fire extinguisher	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Replace doors with ones having sidelight viewing windows max 43" aff.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
47	Calliham Unit (CU): CU - Maintenance	[28.4763089 -98.349673 5]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	flammable shed - knob, surface fails; sign shed - pinch hardware on push and pull, 5.5" CIL	Provide required maneuvering clearance on push and pull side of doors. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
48	Calliham Unit (CU): CU - Maintenance	[28.4763231 98.349689 6]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	no route to carport due to surface	For employee spaces, create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the building.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	
49	Calliham Unit (CU): CU - Residence	[28.4777424 -98.350108]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	residence by gym has gravel lot, residence by maintenance seems unused - gravel lot, lacks route	Provide firm and stable parking surface at each residence. Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the building.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	
50	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4792136 -98.349587 7]	There is no accessible route to the baseball fields and amenities. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to baseball field, no route to dugouts, spigot, 2 of 2 trash, 2" CIL to dugout close to lot, 4" on dugout farther	Create an accessible route with crushed stone or other outdoor material from parking or walkway to fields and amenities.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2	ACCESSIBLE ENTENCES
The M/T					I		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation 2010 ADAS Section: 206.2.2		Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
51	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4788081 , -98.349901 5]	The wheelchair seating space is not the correct size. Where a wheelchair space can be entered from the front or rear, the wheelchair space shall be 36 inches wide x 48 inches deep minimum. Wheelchair seating spaces shall adjoin accessible routes and shall not overlap circulation paths. Accessible routes shall not overlap wheelchair spaces.	dugout close to lot lacks wheelchair space due to trash can	Relocate garbage can to provide required 36" by 48" CFS in dugout	2015 ABAAS Section: 802.1.2 , 802.1.3 2012 TAS Section: 802.1.2, 802.1.3		SINCE UNDER SPACE - ROAT OF
52	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4794387 -98.348584 5]	The 30 inches minimum by 48 inches minimum clear floor space required at the operable part is not flat (2% or 1:48 maximum slope) in all directions. Changes in level are not permitted at required clear floor or ground space except that slopes not steeper than 1:48 shall be permitted.	3.3% slope in tennis gate entry	Correct or repair slope in CFS to max 2.08%.	2015 ABAAS Section: 305.2 2012 TAS Section: 305.2 2010 ADAS Section: 305.2		48 min uiu OC
53	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4795437 -98.349002 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.5" gap at tennis entry, 1.25" gap at entry to basketball	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And the second s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
54	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4794918 , -98.348812 5]	Element meets all standards and requirements	soccer field complies, has route and CFS for viewing	None	2010 ADAS Section: N/A		
55	Calliham Unit (CU): CU - Sports Fields/ Courts	[28.4796061 -98.349000 2]	There is no accessible route to the balls. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to sports balls	Create an accessible route with crushed stone or other outdoor material from parking or walkway to sports balls.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIL ENTENCES
56	Calliham Unit (CU): CU - Dump Station	[28.4794776 , -98.344303 7]	Element meets all standards and requirements	dump station complies	None	2010 ADAS Section: N/A		
	•							
57	Calliham Unit (CU): CU - Parking	[28.4721876 -98.339693]	Element meets all standards and requirements	parking by fish cleaning and 200 sites - 13 standard, 4 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
58	Calliham Unit (CU): CU - Parking	[28.4719813 -98.339738 6]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	stalls by fish cleaning and 200 sites - no access aisles, stalls by picnic - no access aisles	Add access aisles to all accessible stalls, with proper signage and striping.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		
59	Calliham Unit (CU): CU - Parking	[28.4720108 -98.339733 2]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 13 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	by fish cleaning and 200 sites - lacks van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
60	Calliham Unit (CU): CU - Parking	[28.4719813 -98.339723 8]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	by fish cleaning and 200 sites - left stall - 2.8% slope, 2.5%, right - 3.6%; stalls on picnic side of loop - left - 5.5%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
61	Calliham Unit (CU): CU - Parking	[28.4719801 , -98.339733 2]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	by fish clean and 200 sites - loose gravel both stalls, left stall has major overgrowth; picnic side of loop - loose gravel	Maintain parking stalls to be free of debris and overgrowth	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		12 12 12 12 12 12 12 12 12 12 12 12 12 1
62	Calliham Unit (CU): CU - Parking	[28.4719801 -98.339725 2]	The accessible route is constructed such that a park vehicle can obstruct the minimum 36 inch width. Parking spaces and access aisles shall be designed so that cars and vans, when parked, cannot obstruct the required clear width of adjacent accessible routes.	by fish cleaning and 200 sites - stall in front of fish clean blocks entry walkway	Relocate parking and stripe a no parking zone at entry to AR to prevent cars from blocking AR	2015 ABAAS Section: 502.7 2012 TAS Section: 502.7 2010 ADAS Section: 502.7		
63	Calliham Unit (CU): CU - Parking	[28.4720626 -98.339697]	Element meets all standards and requirements	in front of restroom building, by 200 sites - 19 standard, 2 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		
64	Calliham Unit (CU): CU - Parking	[28.4720638 -98.338106 5]	The accessible parking stall is not wide enough. Each parking space must be at least 8' feet wide and shall be marked to define the width. The measurements of parking spaces and access aisles shall be made from the centerline of the markings. Where the parking space is not adjacent to another parking space or access aisle, the measurement shall be permitted to include the full width of the line defining the parking space.	in front of restroom building, by 200 sites, left stall - 7'	Repaint stalls to be 8' wide each.	2015 ABAAS Section: 502.2 2012 TAS Section: 502.2 2010 ADAS Section: 502.2		Free to Var

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
65	Calliham Unit (CU): CU - Parking	[28.4720744 , -98.338101 1]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	in front of restroom building, by 200 sites - no access aisle	Paint 5' access aisle, with proper signage and striping	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		
66	Calliham Unit (CU): CU - Parking	[28.4720556 -98.338106 5]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	in front of restroom building, by 200 sites, left - 2.7% slope	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		-44-
67	Calliham Unit (CU): CU - Parking	[28.4720556 -98.338113 2]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	in front of restroom building, by 200 sites - both have overgrowth and loose gravel	Maintain stalls and access aisles to eliminate gaps, overgrowth, and cracks.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₂

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
68	Calliham Unit (CU): CU - Parking	[28.4825614 -98.351306 9]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign. Parking signs shall be centrally located at the head of each stall.(NM)	in front of shelter with route by main boat ramp - sign mounted at the access aisle	Relocate existing accessible parking sign to be centrally located at the head of the stall, mounted at a minimum of 60" above ground level.	2015 ABAAS Section: 502.6 2010 ADAS Section: 502.6		Van Accessible 60 inches min.
69	Calliham Unit (CU): CU - Parking	[28.4794776 , -98.350016 8]	Element meets all standards and requirements	baseball parking - 25 standard, 2 accessible; meets scoping	None	2010 ADAS Section: N/A		
70	Calliham Unit (CU): CU - Parking	[28.4793833 -98.350081 2]	The accessible parking stall is not wide enough. Each parking space must be at least 8' feet wide and shall be marked to define the width. The measurements of parking spaces and access aisles shall be made from the centerline of the markings. Where the parking space is not adjacent to another parking space or access aisle, the measurement shall be permitted to include the full width of the line defining the parking space.	baseball parking - facing field 6' 5"	Repaint stalls to be 8' wide each.	2015 ABAAS Section: 502.2 2012 TAS Section: 502.2 2010 ADAS Section: 502.2		Tert for Yun Tert for Yun Tert for Yun Tert for Yun Tert for Carl
71	Calliham Unit (CU): CU - Parking	[28.4793433 -98.350156 3]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	baseball parking, away from field - 4'9"	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
72	Calliham Unit (CU): CU - Parking	[28.479315, -98.350083 9]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 25 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 2 accessible stalls with a minimum of 1 being designed as van accessible.	baseball parking - no van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
73	Calliham Unit (CU): CU - Parking	[28.4793126 -98.350000 7]	The cross slopes (long dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	baseball - facing field, access aisle - 4.3% slope, 44%, stall - 2.7%. facing away - access aisle - 4.7%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
74	Calliham Unit (CU): CU - Parking	[28.4793079 -98.350081 2]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	baseball parking - overgrowth and gravel in lot	Maintain parking stall surface to be free of debris and overgrowth	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		<u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4</u> <u>¹/4 <u>¹/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4</u> <u>¹/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> <u>²/4 <u>²/4 <u>²/4 <u>²/4 <u>²/4</u> (²/4) (²/4</u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u>
75	Calliham Unit (CU): CU - Parking	[28.4806895 -98.350370 9]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of accessible stalls based on the total: 1-25: 1 accessible/1 van 26-35: 2 accessible/1 van 36-50: 3 accessible/1 van 51-100: 4 accessible/1 van 101-300: 8 accessible/2 van 301-500: 12 accessible/2 van 501-800: 16 accessible/3 van 801-1000: 20 accessible/4 van 1001-over: 20 accessible plus 1 for every 100 spaces/1 of every 6 should be a van stall	lot between dining hall and gym - 2 accessible, 57 standard; 15 standard pull through, none accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls. Create one or more accessible pull through stalls min 8' wide with 5' aisle	2015 ABAAS Section: F208.2 2010 ADAS Section: 208.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
76	Calliham Unit (CU): CU - Parking	[28.4803853 -98.350357 4]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	lot between dining hall and gym - access aisle is angled and only 4'3"; facing rec hall - 4'7"	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aide serving car parking spaces
77	Calliham Unit (CU): CU - Parking	[28.4803853 -98.350391]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 57 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 3 accessible stalls with a minimum of 1 being designed as van accessible.	lot between dining hall and gym - stall marked "van" is only 14'2" at end of access aisle; facing rec - van sign but sizing is 13'1"	Repaint one van stall and access aisle to 11' and 5' or 8' and 8'. Remove sign from other stall.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		Team Team Team 100 1 1

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
78	Calliham Unit (CU): CU - Parking	[28.4803971 -98.350378 9]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	lot between dining hall and gym - access aisle 5.7%, 3%. facing rec - access aisle - 2.8%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		
79	Calliham Unit (CU): CU - Parking	[28.4803983 , -98.350384 3]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	lot between dining hall and gym - all full of loose gravel	Maintain stalls and access aisles to eliminate gaps, loose gravel, and cracks.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		<u><u>Y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u><u>y</u></u>

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
80	Calliham Unit (CU): CU - Parking	[28.4803476 -98.350366 8]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	between gym and dining hall - sign located in wrong stall	Relocate signage to accessible stall.	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6 2010 ADAS Section: 502.6		Van Accessible 60 nches mn.
81	Calliham Unit (CU): CU - Parking	[28.4803028 , -98.34907]	There are no or not enough accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of (XX) parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of (XX) accessible stalls with a minimum of (XX) being designed as van accessible.	gym/nature center - 104 standard, 2 ADA, 7 standard pull through stalls	Create three or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls. Create one or more accessible pull through stalls min 8' wide with min 5' aisle	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		Specialized of Management Extension Marca of Parameters 1 1 1
82	Calliham Unit (CU): CU - Parking	[28.4800765 -98.348536 2]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	gym/nature center, facing group hall - 3'7"	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving ar parking spaces

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
83	Calliham Unit (CU): CU - Parking	, -98.349087 4]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 104 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 5 accessible stalls with a minimum of 1 being designed as van accessible.	gym/nature center, "van stall" is 8' stall, 3'7" access aisle	Repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2, 208.2.4		Director of length and more of length and the second and of length and the second and the director of length and the second and the second and the director of length and the second and the second and the director of length and the second and the second and the director of length and the second and the second and the director of length and the second and the second and the director of length and the director of length and the second and the director of length and
84	Calliham Unit (CU): CU - Parking	, -98.348549	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	gym/nature center - facing dining - 3.1% slope in access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
85	Calliham Unit (CU): CU - Parking	[28.4800812 -98.348504]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	gym/nature center, excessive gravel in all stalls and access aisles	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂
86	Calliham Unit (CU): CU - Parking	[28.4888594 , -98.341429 7]	Element meets all standards and requirements	campsite restroom parking/ bird sanctuary - 7 standard, 3 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		
87	Calliham Unit (CU): CU - Parking	[28.4888559 -98.341406 9]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 7 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 3 accessible stalls with a minimum of 1 being designed as van accessible.	campsite restroom parking/ bird sanctuary - van marked stall in front of bathroom does not comply due 15'2" stall sizing	Repaint van stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2, 208.2.4		Name of States plane Name of States plane 100 1

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
88	Calliham Unit (CU): CU - Parking	[28.4888417 , -98.341406 9]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	campsite restroom parking/ bird sanctuary - full of gravel, bird side/van has overgrowth	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		2 max 2 max 2 y/2 2
89	Calliham Unit (CU): CU - Parking	[28.4898413 , -98.339406]	Element meets all standards and requirements	group pavilion at end of electric sites - 5 standard, 1 accessible; meet scoping requirements	None	2010 ADAS Section: N/A		
90	Calliham Unit (CU): CU - Parking	[28.4899226 , -98.339428 8]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	group pavilion at end of electric sites - 4'9" width	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces
91	Calliham Unit (CU): CU - Parking	[28.4899049 .98.339443 5]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	group pavilion at end of electric sites - no van stall	Add van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2, 208.2.4		Home of characterized Home begins of characterized 1000 million 1000 million 1000 million 1 1000

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
92	Calliham Unit (CU): CU - Parking	[28.4899096 , -98.339448 9]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	group pavilion at end of electric sites - debris, loose gravel	Maintain accessible stalls to be free of debris and overgrowth	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		1/2 1/2 1/2 1/2 1/2
93	Calliham Unit (CU): CU - Parking	[28.4893132 , -98.346867 9]	Element meets all standards and requirements	parking at pavilion at end of screened shelters - 4 standard, 1 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		
94	Calliham Unit (CU): CU - Parking	[28.4893226 ,-98.346937 6]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	parking at pavilion at end of screened shelters - 4'3" width	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access alse serving cer parking spaces
95	Calliham Unit (CU): CU - Parking	[28.4893014 , -98.346854 5]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 4 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	parking at pavilion at end of screened shelters - no van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2, 208.2.4		Name of States,

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
96	Calliham Unit (CU): CU - Parking	[28.4893038 , -98.346878 6]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	parking at pavilion at end of screened shelters - loose gravel on stalls	Maintain stalls to be free of debris and overgrowth	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		12 12 12 12 12 12 12 12 12 12 12 12 12 1
97	Calliham Unit (CU): CU - Parking	[28.4892991 ,-98.346857 2]	The access aisle is not located on an accessible route of travel to the accessible building entrance. Accessible parking spaces serving a particular building shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. In buildings with multiple accessible entrances with adjacent parking, accessible parking spaces shall be dispersed and located closest to the accessible entrances.	parking at pavilion at end of screened shelters - 3'8" entry	Relocate parking stop to widen route to min 36"	2015 ABAAS Section: F208.3.1 2012 TAS Section: 208.3.1 2010 ADAS Section: 208.3.1		
98	Calliham Unit (CU): CU - Parking	[28.4898366 , -98.343681 4]	Element meets all standards and requirements	parking at RV shelter near site 133 - 8 standard, 3 accessible; meets scoping requirement	None	2010 ADAS Section: N/A		
99	Calliham Unit (CU): CU - Parking	[28.4898271 -98.343670 7]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	parking at RV shelter near site 133 - gravel in all stalls and access aisles	Maintain stalls and access aisles to be free of debris	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		12 12 12 12 12 12 12 12 12 12 12 12 12 1
100	Calliham Unit (CU): CU - Parking	[28.4881439 -98.347449 9]	Element meets all standards and requirements	screened shelter Restroom and pavilion - 7 standard, 4 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
101	Calliham Unit (CU): CU - Parking	[28.4881439 -98.347452 6]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	screened shelter, restroom, and pavilion - no access aisles painted at either	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		
102	Calliham Unit (CU): CU - Parking	[28.46601, -98.35448]	There are no van accessible parking stalls. 1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 7 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	screened shelter, restroom, and pavilion - stalls with van signs lack aisles	Repaint stall and access aisle to 11' and 5' or 8' and 8'.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		Number of the second

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
103	Calliham Unit (CU): CU - Parking	[28.4881416 -98.347452 6]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	screened shelter, restroom, and pavilion, restroom, right stall - 4.4% slope, left - 3.6%. shelter, left - 2.4%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		+ + +
104	Calliham Unit (CU): CU - Parking	[28.4881427 -98.347456 6]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	screened shelter, restroom and pavilion - both sets full of gravel	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
105	Calliham Unit (CU): CU - Parking	[28.4821229 , -98.352924 3]	Element meets all standards and requirements	parking lots surrounding boat ramp/ day use area - 5 accessible, 104 standard, 5 pull through accessible, 108 pull through standard; meets scoping requirements	None	2010 ADAS Section: N/A		
106	Calliham Unit (CU): CU - Parking	[28.4824576 -98.352420 1]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	parking lots surrounding boat ramp/ day use area -RV pull thru, left to right - 1st stall 4.3%, 3.7%, 1st access aisle - 3.7%, 2.2%, 3rd access aisle - 2.9%, 4th stall 2.3%; in front of restroom, left access aisle - 5.2%, in front of shelter - access aisle - 2.3%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
107	Calliham Unit (CU): CU - Parking	[28.4820993 ,-98.352935]	The accessible parking space and/or access aisle contains loose gravel and/or surface materials that do not provide for a stable, firm slip resistant surface. Parking spaces and access aisles serving them shall comply with floor or ground surface requirements. The ground surface shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level, slopes exceeding 1:48, and detectable warnings shall not be permitted.	parking lots surrounding boat ramp/ day use area - all stalls have gravel in them	Maintain stalls frequently to eliminate loose gravel and/or surface materials that do not provide for a stable, firm slip resistant surface.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		
108	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4826132 , -98.35284 92], [28.4829268 , -98.354973 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	look out by boats - 1" gap at entry, gap count along path - 31 total	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Amena di colicio di Vari Anti di colicio di

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
109	Calliham Unit (CU): CU - Exterior Accessible Route	[28.46601, -98.35448]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	fish clean by 200 sites - 6" gap at entry, 1.25" gap in middle of path, 1.25" at entry	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demark diode of them
110	Calliham Unit (CU): CU - Exterior Accessible Route	- ,	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	9" gap at pier by 200 sites	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demant dixide of train http://www.international.org

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
	Calliham Unit (CU): CU - Exterior Accessible Route	[28.471874, -98.339465] [28.4711266 -98.339821 7]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	lookout walkway by fish cleaning near 200 - excessive cross slope at last bit for 100 feet, 9.8%, 9.5%, 9%, 5.4%, 4.4%, 3.5%	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
112	Calliham Unit (CU): CU - Exterior Accessible Route	, -98.338708 6]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	picnic side - 1"	Repair or reset pavers to eliminate CIL.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		1/2 1/2 1/2 1/2 1/2

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
113	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4717821 , -98.33822 58], [28.4720037 , -98.339132 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	200 sites area - loop with fish cleaning, picnic side to restroom 1" gap, 1",1", 2", 2", 1.5", 1.5", 1", 1.5", 2", 1". to side lot from restroom - 1.5", 1.5", 1", 1", 1" 1" 1"	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
114	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4719141 -98.338730 1]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	overhead to restroom by 200 sites reduced by tree to 64" above finished floor	Maintain overhead clearance of min. 80"	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection
115	Calliham Unit (CU): CU - Exterior Accessible Route	[28.471966, -98.338923 2]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	near 200 sites, picnic area mud on path to accessible picnic spot	Maintain path to be free of mud	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Organ is the Use all Crown and

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
116	Calliham Unit (CU): CU - Exterior Accessible Route	[28.472164, -98.338494]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	from RV stalls to picnic area, beginning of path by sites 200 - 6" gap, 4" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Advanced databalan ut based and an and an
117	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4799421 -98.348694 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap at entry to gym	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demant divide ut hard

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
118	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4798266 -98.348766 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	between nature Center back patio to restrooms - two 1.5" gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And a second database of
119	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4798549 -98.348809 8]	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.3% (1:12).	left ramp by main ramp restroom - 9.8% slope	Correct curb ramp running slope to max 8.33%	2015 ABAAS Section: 406.1 2012 TAS Section: 406.1 2010 ADAS Section: 406.1		Ladig Silevak

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
120	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4824812 -98.352594 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	ramps by restroom by main boat ramp, right ramp - 3" gap at bottom, 1.5" gap at top	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Annual disting of the second s
121	Calliham Unit (CU): CU - Exterior Accessible Route	,	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	outlook by main boat ramp - bush towards end reduces route	Trim plants to maintain min 36" clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
122	Calliham Unit (CU): CU - Exterior Accessible Route	[28.483014, -98.354587 3]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	outlook by main boat ramp/ restroom - 16 gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		denorm for line of order of or

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
123	Calliham Unit (CU): CU - Exterior	[28.4812199 -98.352460	inch. Openings in floor or ground surfaces	in front of shelter by main ramp - 1.25" gap, 1" gap in front of	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3		demant dische si tussi
	Accessible Route	3]	than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	gap, i gap in front of sign		302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		2 Million and a second se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
124	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4812671 -98.352476 4]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	from shelter by main boat ramp to restrooms, along parking lot, sidewalk - deterioration at turn	Resurface AR where deterioration occurs.	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Corpus is the landres of the landres
125	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4804242 -98.351858 1]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1" change in level at metal grate before restroom on picnic side by main boat ramp	Repair or reset pavers to eliminate CIL.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		¹ / ₄ ² / ₄ ¹ / ₄
126	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4806612 -98.351733 4]	The running slope of walking surfaces shall not be steeper than 1:20.	6% slope at top of path to restroom by picnic area by main boat ramp, 5.7% 1/3rd down	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
127	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4812105 , -98.35244 96], [28.4804254 , -98.351840 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	from shelter by main boat ramp to restrooms, along parking lot, sidewalk - 1", 1.5", 1", 1", 2", 1", 1", 1", 1", 75" - 20 total. after turn to restroom - 1" gap 1/3rd down path, 2" halfway down, at start of curve - 9" gap, at entry to restroom building - 1.75" gap, turn to path at restroom 1.25" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And dealers of the second seco

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
128	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4802132 -98.351140 6]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	pathway to restroom behind picnic by main ramp - overhead reduced by tree at turn	Maintain overhead clearance of min. 80"	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
129	Calliham Unit (CU): CU - Exterior Accessible Route	[28.480937, -98.351559 1]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	path from dining hall patio to restroom - 5.6% slope	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
130	Calliham Unit (CU): CU - Exterior Accessible Route	, [28.4808627	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	path from dining hall patio to restroom - 1.5" gap, 1" gap, .75", 1.25"	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		A construct disclored transfer of the second

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
131	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4811657 -98.351226 5]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1.25" change in level from parking to group hall, on walkway closest - 2", 2"	Repair, bevel or ramp change in level along accessible route.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		^{1/4} max ^{1/4} ² ^{1/2} ^{1/4} ^{1/2}
132	Calliham Unit (CU): CU - Exterior Accessible Route	,	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	at rec/ group hall - (17) 1"-3" gaps on walkways	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And and a darker of share.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
133	(CU): CU - Exterior Accessible Boute	[28.4802674 -98.351999] [28.4803382 -98.350403]	perpendicular to the dominant direction of	path to restroom by main ramp, through picnic tables, starting at restroom building - 103 instances of gaps total	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
134	Calliham Unit (CU): CU - Exterior Accessible Route	, -98.349567	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	path along archery on exterior, from baseball parking lot - 3.5% slope after metal grate	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
135	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4798195 , -98.34989 88], [28.4794564 , -98.348584 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	gap count from baseball lot to end of tennis - 20 gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
136	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4800824 -98.348618]	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.3% (1:12).	curb ramp at gym - 9.3% slope	Correct curb ramp running slope to max 8.33%	2015 ABAAS Section: 406.1 2012 TAS Section: 406.1 2010 ADAS Section: 406.1		The
137	Calliham Unit (CU): CU - Exterior Accessible Route	[28.479968, -98.348707 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	around front of gym/ dining hall, gap count - 32 total. gap total going down center of gym, between gym and Nature Center - 11 total	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		An experiment of a second of a

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
138	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4795048 -98.348663 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	restrooms by basketball - entry near women's 3 gaps on path, entry by men's at corner - 2 gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demonification of the state of

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
139	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4796132 , -98.349122 3]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	35.7% slope on path to men's restroom from basketball	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
140	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4802922 -98.349133]	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.3% (1:12).	10.2% slope at curb ramp by archery range	Correct curb ramp running slope to max 8.33%	2015 ABAAS Section: 406.1 2012 TAS Section: 406.1 2010 ADAS Section: 406.1		The
141	Calliham Unit (CU): CU - Exterior Accessible Route	[28.480291, -98.349129]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	deterioration/ overgrowth at curb ramp infront of archery range, reduces width and access	Maintain overgrowth to provide 36" width surface.	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Provide a real barrier of the second
142	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4870972 , -98.348414 2]	Element meets all standards and requirements	from site 20 to restroom - path complies	None	2010 ADAS Section: N/A		

Finding Ar Number	rea Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4825048 -98.352787 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	entry to old park store building (now storage) - 1.25" gap, rear access to building from walkway - 3 instances of 1.25" gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
144	Calliham Unit (CU): CU - Exterior Accessible Route	, -98.354079]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	HQ - 14 gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	Area Description	Lat/Long	Finding					Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
145	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4660218 -98.354158 1]	The curb ramp slope exceeds the maximum running slope (Parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.3% (1:12).	14.9% slope on exit side	Correct curb ramp running slope to max 8.33%	2015 ABAAS Section: 406.1 2012 TAS Section: 406.1 2010 ADAS Section: 406.1		Indig Sdryk
146	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4660076 -98.354144 7]	The curb ramp does not have a compliant top landing and the side flares are too steep. In alterations, where there is no landing at the top of Curb Ramps, Curb Ramp flares shall be provided and shall not be steeper than 1:12.	HQ enter side - no level landing, right flare - 17.6% slope, left 13.8% slope	Correct slope of side flares to max 8.33%	2015 ABAAS Section: 406.4 EXCEPTION 2012 TAS Section: 406.4 Exception 2010 ADAS Section: 406.4 Exception		- status ma The data title mage
147	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4900193 -98.339427 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	pavilion by RV sites - 8 instances of gaps from .5"-1.5"	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	Kanada Kanad Kanada Kanada	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
148	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4888783 -98.341488 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	RV restroom - 11 instances of gaps total	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demonstrational of the second se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
149	Calliham Unit (CU): CU - Exterior Accessible Route	, -98.343728 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	7 gaps on route to pavilion by 133	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demant disclor of basel Angel demants of program in the second s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
150	Calliham Unit (CU): CU - Exterior Accessible Route	[28.4881062 -98.347409 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	screened shelter restrooms - 17 instances of gaps ranging from .75"-1.5"	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And a second distribution of frame with a second distribution of the secon

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number Area Description Lat/Long Finding	As Built	Recommendation	Citation	Photos	Figure
151 Calliham Unit (CU): CU - Exterior [28.4810525 , -98.351288 An item or items project more than 4 incher into the circulation path. Wall-mounted objects that have leading edges between inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of th floor are cane detectable and are therefor not hazardous. Where it is necessary or desirable to have objects protrude from th wall, a manner of cane detection must be provided.	projects 7" at screened shelter house and restroom by group hall, shelf projects at restroom by group hall 8"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
152	Calliham Unit (CU): CU - Park Elements	[28.4826486 , -98.351306 9]	Where picnic facilities contain more than two picnic units, at least 20 percent, but not less than two, of the picnic units shall provide mobility features complying with F245.2	2 of 47 covered picnic tables comply	Create access to 20% of the shelters or picnic areas at the site as a smart practice.	2015 ABAAS Section: F245.2.2		
153	Calliham Unit (CU): CU - Park Elements	[28.4716948 ,98.339274 6]	There is no accessible route to the beach or floating device. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to beach or floatation device by 200 sites	Create an accessible route with crushed stone or other outdoor material from parking or walkway to beach or floating device.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIL ENTRACES
154	Calliham Unit (CU): CU - Park Elements	[28.4826604 -98.351357 9]	Water spouts at water hydrants and water utility hook-ups shall be 28 inches (710 mm) minimum and 36 inches (915 mm) maximum above the ground.	2 of 2 accessible covered picnic tables by emperor run - spigot height 16" above finished floor (AFF), 16.5" AFF	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	2005.2.2 2015 ABAAS Section: 1011.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
155	Calliham Unit (CU): CU - Park Elements	-98.349019]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	fountain at basketball projects 12"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		A CONTRACT OF THE OWNER
156	Calliham Unit (CU): CU - Park Elements	[28.479935, -98.348726 7]	There is no drinking fountain for standing persons. Spout outlets of drinking fountains for standing persons shall be 38 inches minimum and 43 inches maximum above the finish floor or ground.	fountain by basketball - low bowl only	Add second high bowl fountain for standing persons.	2015 ABAAS Section: 602.7 2012 TAS Section: 602.7 2010 ADAS Section: 602.7, 211.2		5 max
157	Calliham Unit (CU): CU - Park Elements	-98.349011]	The spout is not positioned correctly from the vertical support. The spout shall be located 15 inches minimum from the vertical support and 5 inches maximum from the front edge of the unit, including bumpers.	fountain by basketball - 8" from support	Remount or replace fountain to provide 15" from vertical support to the spout	2015 ABAAS Section: 602.5 2012 TAS Section: 602.5 2010 ADAS Section: 602.5		5 max 15 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
158	Calliham Unit (CU): CU - Park Elements	[28.4798537 ,98.349017 7]	The angle of the water flow is to great from a spout located between 3 an 5 inches from the front of the drinking fountain. The angle of the water stream shall be measured horizontally relative to the front face of the unit. Where spouts are located less than 3 inches of the front of the unit, the angle of the water stream shall be 30 degrees maximum. Where spouts are located between 3 inches and 5 inches maximum from the front of the unit, the angle of the water stream shall be 15 degrees maximum.	fountain by basketball - greater than 15 degrees	Adjust spout flow to max 15 degrees measured from the front of the unit.	2015 ABAAS Section: 602.6 2012 TAS Section: 602.6 2010 ADAS Section: 602.6		
159	Calliham Unit (CU): CU - Park Elements	[28.4798042 -98.349040 5]	There is not enough toe space clearance under the drinking fountain. Space under an element between the finish floor or ground and 9 inches above the finish floor or ground shall be considered toe clearance Space extending greater than 6 inches beyond the available knee clearance at 9 inches above the finish floor or ground shall not be considered toe clearance. Where toe clearance is required at an element as part of a clear floor space, the toe clearance shall extend 17 inches minimum under the element.	fountain by basketball - 10.75" depth	Remount or replace fountain with one provided 17" min and 25" max deep toe clearance	2015 ABAAS Section: 306.2.3 2012 TAS Section: 306.2.3 2010 ADAS Section: 306.2.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
160	Calliham Unit (CU): CU - Park Elements	[28.4886924 -98.344128 5]	There is no accessible route to the bird sanctuary. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to bird sanctuary, within is not accessible surface	Create an accessible route with crushed stone or other outdoor material from parking or walkway to bird sanctuary	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESUL CATABOAC
161	Calliham Unit (CU): CU - Campsites	[28.4726096 , -98.33711]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	no route to primitive campsites by sites 200	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
162	Calliham Unit (CU): CU - Campsites	[28.4888535 -98.341801 2]	Parking spaces and pull-up spaces for recreational vehicles shall be 20 feet (6100 mm) wide minimum. EXCEPTION: Where two adjacent parking spaces are provided for recreational vehicles, one parking space shall be permitted to be 16 feet (4880 mm) wide minimum.	site 120 - gravel surface, left stall has 2.5%, 3.9% on right side	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.2, 1012.2 EXCEPTION		
163	Calliham Unit (CU): CU - Campsites	[28.4885683 -98.341712 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	2" gap at entry to campsite 108	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		deman databa di sala di sa

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
164	Calliham Unit (CU): CU - Campsites	[28.4884999 , -98.341585 3]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	path to bird sanctuary from 108 has overhang	Maintain overhead clearance of min. 80"	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection
165	Calliham Unit (CU): CU - Campsites	[28.4888087 -98.340913 4]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	109 has overhanging trees on route	Maintain overhead clearance of min. 80"	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection
166	Calliham Unit (CU): CU - Campsites	[28.4885824 -98.341712 7]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	site 108, left side - 3% slope, lot full of gravel	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
167	Calliham Unit (CU): CU - Campsites	[28.4885636 -98.341702]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	109 - gravel in lot, overgrowth on left side, 4.3% slope on left side	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		
168	Calliham Unit (CU): CU - Campsites	[28.4889926 -98.340940 2]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	119 - gravel in lot	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		
169	Calliham Unit (CU): CU - Campsites	[28.4890869 , -98.340993 9]	Element meets all standards and requirements	all RV/ Electric site amenities comply for all accessible sites	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
170	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4717632 -98.339741 3]	Not enough of the railings, guards, or handrails are at the allowable height. At least 25 percent of the railings, guards, or handrails shall be 34 inches maximum above the ground or deck surface.	small pier by 200 sites - 43" above finished floor all around	Lower 25% of the railing; dispersed through pier, to max 34".	2015 ABAAS Section: 1005.2.1 2010 ADAS Section: 1005.2.1		
171	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4717821 -98.339730 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	fish pier by 200 sites - 2" gap towards entry	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		destruct datafore of based segis travelar an expension of based of based of based of the offer of based
172	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4719011 -98.339526 7]	There is no accessible route to the boats or kayak launch. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to rentable boats, no route to kayak launch	Create an accessible route with crushed stone or other outdoor material from parking or walkway to kayak launch or boat rental.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIGLE DATIRANCES

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
173	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4817032 , -98.353879 2]	There is no accessible route to the beach. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to beach	Create an accessible route with crushed stone or other outdoor material from parking or walkway to beach.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSILE ENTRACES
174	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4821394 -98.353906]	The required edge protection is not provided. Where compliant railings, guards, or handrails are provided, edge protection shall also be provided. Curbs or barriers shall extend 2 inches minimum above the surface of the fishing pier or platform or The ground or deck surface shall extend 12 inches minimum beyond the inside face of the railing. Toe clearance shall be provided and shall be 30 inches wide minimum and 9 inches minimum above the ground or deck surface beyond the railing.	left side at boat ramp - small dock only offers 1" edge protection	Provide 2" high curb or 12" extended surface beyond railing for edge protection.	2015 ABAAS Section: 1005.3.1, 1005.3.2 2010 ADAS Section: 1005.3.1, 1005.3.2		
175	Calliham Unit (CU): CU - Fishing/ Boating/ Swimming	[28.4823398 -98.353999 9]	The minimum number of boarding piers are not accessible. Where boarding piers are provided at boat launch ramps, at least 5 percent, but no fewer than one, of the boarding piers be accessible.	right side pier at boat ramp - CIL to access (stairs), high slopes to access boarding piers	Provide 5%, but not less than one accessible boarding pier at boat launches.	2015 ABAAS Section: F235.3 2010 ADAS Section: 235.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
176	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4719047 , -98.339733 2]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	fish cleaning by 200 sites - table 38" AFF	Replace picnic table with one of an accessible design as a smart practice.	2015 ABAAS Section: 1011.4.2		
177	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4718988 -98.339734 6]	Table The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	25" width around fish cleaning near 200 sites	Widen EAR to min 36" clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		
178	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4719589 -98.338798 5]	Element meets all standards and requirements	both accessible picnic areas by sites 200 comply	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
179	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4826132 -98.352078 1]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	1 of 2 fish clean stations in area has deteriorated surface at entry and excessive slope	Resurface AR where deterioration occurs	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		How have the second sec
180	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.482618, -98.352049 9]	There is no accessible route to the fish cleaning station. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to 1 of 2 fish cleaning due to surface	Leave as is and make corrections to route to the other fish cleaning station in this area.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIC DYNAMCS
181	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4718551 -98.338657 6]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	unmarked picnic area by 200 sites - loose gravel	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
182	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4810902 -98.352666 8]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	shelter by main boat ramp - 0 of 6 picnic tables accessible	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
183	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.481095, -98.352693 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	shelter by main boat ramp - 1" at turn to entry, 1" 2 squares in, 1.5" at entry, 1.5" at grill	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
184	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4811138 -98.352672 2]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	shelter by main boat ramp - 0 of 2	Replace picnic table with one of an accessible design as a smart practice.	2015 ABAAS Section: 1011.4.2		
185	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4895254 -98.346782 1]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	pavilion at end of screen shelter - 0 of 4	Replace picnic table with one of an accessible design as a smart practice.	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
186	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4895112 -98.346776 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	pavilion at end of screen shelter - 3 gaps on path	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And and disclose of transmit
187	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4898884 -98.343912 1]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	RV shelter by 133 - 0 of 3 tables accessible	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		
188	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4898837 -98.343917 5]	Table Where picnic facilities contain two or fewer picnic units, each picnic unit shall provide mobility features complying with F245.2.	RV shelter by site 133 - clear floor space for fire extinguisher reduced by table	Relocate tables to provide clear floor space for operable parts.	2015 ABAAS Section: F245.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
189	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4899049 , -98.343914 8]	Objects project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	RV shelter by site 133 - fire extinguisher projects 7"	Relocate object to not protrude into the circulation path	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		4 max 4" is the max. an object may project if the bottom is greater than 27" off the floor
190	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4879223 -98.347857 6]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	screened shelter area across from restroom - 0 of 4 accessible	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
191	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4879259 -98.347859]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	screened shelter area across from restroom - 8 gaps on route	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		denormal dation of share.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
192	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4879318 , -98.347962 2]	Where picnic facilities contain two or fewer picnic units, each picnic unit shall provide mobility features complying with F245.2.	screened shelter area across from restroom - table placement reduces route at entry to 35.5"	Relocate table to provide 36" accessible route.	2015 ABAAS Section: F245.2.1		
193	Calliham Unit (CU): CU - Fish Cleaning/ Shelters	[28.4879388 -98.347973]	Objects project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	screened shelter area across from restroom - extinguisher projects 7"	Relocate object to not protrude into the circulation path	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		4 max 4" is the max. an object may project if the bottom is greater than 27" off the floor

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
194	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796804 -98.348434 3]	The U-shaped kitchen is not wide enough. In U-shaped kitchens enclosed on three contiguous sides, clearance between all opposing base cabinets, counter tops, appliances, or walls within kitchen work areas shall be 60 inches.	45.25" between counter and island, 51" between sink and island	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	2015 ABAAS Section: 804.2.2 2012 TAS Section: 804.2.2 2010 ADAS Section: 804.2.2		
195	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796615 -98.348434 3]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	metal sink 36" AFF	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		e' dery ter jace

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
196	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796592 , -98.348450 4]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY
197	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796521 , -98.348461 1]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe clearance.	both sinks lack clearance	Remove base cabinet and lower sink height to max 34" aff.	2015 ABAAS Section: 606.2, 804.4 2012 TAS Section: 606.2, 804.4 2010 ADAS Section: 606.2, 804.4		A man
198	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796521 -98.348445]	The controls are located such that operation require reaching across burners. Where knee and toe space is provided, the underside of the range or cooktop shall be insulated or otherwise configured to prevent burns, abrasions, or electrical shock. The location of controls shall not require reaching across burners	ovens require reach over	Replace oven with one having controls on the front panel	2015 ABAAS Section: 804.6.4 2012 TAS Section: 804.6.4 2010 ADAS Section: 804.6.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
199	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796615 -98.348445]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	counter 41.75" AF	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1		36 [°] max
200	CU - Dining Hall: Dining Hall - Public Spaces	[28.479678, -98.348463 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	door to kitchen - 10" clearance on push side due to shelf, knob, 10" clearance on pull due to counter	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
201	CU - Dining Hall: Dining Hall - Public Spaces	[28.4796662 -98.348493 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	from kitchen to exterior, fridge side - 2.25" clearance on pull, requires excessive force (beyond 30lbf), lock 59" AFF	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" to 48" aff.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
202	CU - Dining Hall: Dining Hall - Public Spaces	[28.479612, -98.348510 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a gap greater than 1/2 inch wide. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	from kitchen to exterior, sink side - 3" clearance on pull, requires excessive force (beyond 30lbf), lock 59" AFF, 2" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp, mounted 34" to 48" aff.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
203	CU - Dining Hall: Dining Hall - Public Spaces	[28.4794694 -98.348564 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	tennis side of double door to dining - cart in back clearance on push side	Provide required maneuvering clearance on push side of door.	2015 ABAAS Section: 404.2.4.4, 404.2.4.1 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1		
204	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795637 -98.348528 2]	The accessible route contains running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	dining hall connects to gym	Correct or repair running slope of AR to max 5%	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3		
205	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795908 -98.348611 3]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	patio - 9 instances of gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demant direction of transf

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
206	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795319 -98.348701 2]	There is no accessible route to the grill. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to grill	Relocate grill to accessible surface.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSILL ENTERACES
207	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795908 -98.348643 5]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	0 of 6 patio picnic tables of accessible design, all lack toe clearance	Replace 20% of picnic tables with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		
208	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795778 -98.348624 7]	The running slope of walking surfaces shall not be steeper than 1:20.	there are 4.5%-5% running slopes throughout back patio	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
209	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795578 -98.348665]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	9.5" toe clearance at 1 of 1 picnic tables outside of the gym	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
210	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795566 -98.348647 5]	Picnic facilities shall provide outdoor recreation access routes complying with 1016 in accordance with F245.4 and 245.4 of IAC	only connects from building side, no route to basketball, tennis court, and walking path	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area	2015 ABAAS Section: F245.4		
211	CU - Dining Hall: Dining Hall - Public Spaces	[28.4798867 -98.348408 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	4 instances of gaps along front entry	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		A grant de relation of trainer Facilitation de relation of trainer y

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
212	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795908 -98.348622 1]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	patio - 2" change in level, 1" change in level	Repair or reset pavers to eliminate CIL.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		VA max VA VA VA VA VA VA
213	CU - Dining Hall: Dining Hall - Public Spaces	[28.4795837 -98.348522 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	exterior of dining hall, on rear side - 5 instances of gaps, front entry - 11 instances of gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demart drafter of training of the second sec

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation		Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
214	CU - Dining Hall: Dining Hall - Employee Spaces	[28.4796898 -98.348453 1]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	3 employee closets in kitchen have knobs	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
215	CU - Dining Hall: Dining Hall - Men's Restroom	[28.479678, -98.348455 8]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign on door, lacks International Symbol of Accessibility (ISA), Braille, raised lettering	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
216	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4796922 -98.348437]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook in stall 65" above finished floor	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
217	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4796898 -98.348461 1]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 6" from rear wall, extends 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
218	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4797134 -98.348538 9]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
219	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4797087 -98.348487 9]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	lacks hardware on pull, pinch on the push	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
220	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4797134 -98.348520 1]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		6 15 min
221	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4796851 -98.348514 8]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		1
222	CU - Dining Hall: Dining Hall - Men's Restroom	[28.4796898 -98.348520 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	men's restroom- knob, 9" clearance on push, 18lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
223	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4796662 -98.348428 9]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign on door, lacks International Symbol of Accessibility, raised lettering, Braille	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
						2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
224	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4796662 -98.348445]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook in stall 65" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
225	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4796757 -98.348479 9]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 6" from rear wall, extends to 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
226	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4796945 -98.348498 7]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
227	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4797063 -98.348560 4]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	not self closing, requires pinch, no hardware on exterior	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
228	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4797323 -98.348627 4]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
229	CU - Dining Hall: Dining Hall - Women's Restroom	[28.4797181 ,-98.348611 3]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
230	CU - Dining Hall: Dining Hall - Women's Restroom	[28.479711, -98.348614]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	women's restroom- 20 lbf, knob, 10" clearance on push, 9" clearance on pull	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
231	CU - Gymnasium: Gym - Public Spaces	[28.4798419 , -98.348777 6]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	beveled edge around gym .75" AFF	Repair, bevel or ramp CIL along accessible route (AR) to max .25".	2015 ABAAS Section: 303.3 2012 TAS Section: 303.3 2010 ADAS Section: 303.3		¹ / ₂ <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u>
232	CU - Gymnasium: Gym - Public Spaces	[28.4797794 -98.348718 6]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	volleyball net holder makes two 3" holes	Fill and maintain gaps to max .5" when volleyball net not in use.	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		B m.
233	CU - Gymnasium: Gym - Public Spaces	[28.4797794 , -98.348729 3]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	0 of 10 tables provide knee clearance	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		King Ser Man, So Ser Man, Ser Man

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
234	CU - Gymnasium: Gym - Public Spaces	[28.4797888 , -98.348750 8]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	no route to stage	Provide a ramp for access to the stage.	2015 ABAAS Section: 303.3 2012 TAS Section: 303.3 2010 ADAS Section: 303.3		1/2 1/2 1/2 1/2 1/2
235	CU - Gymnasium: Gym - Public Spaces	[28.4797417 , -98.348729 3]	Treads shall be 11 inches (280 mm) deep minimum and uniform	steps to stage - 9" depth (6)	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	2015 ABAAS Section: 504.2 2012 TAS Section: 504.2 2010 ADAS Section: 504.2		
236	CU - Gymnasium: Gym - Public Spaces	[28.4797841 -98.348740 1]	Open risers are not permitted.	steps to stage - open risers (6)	Install kick plates on all stairs or replace with ones having closed risers	2015 ABAAS Section: 504.3 2012 TAS Section: 504.3 2010 ADAS Section: 504.3		Constant for function

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
237	CU - Gymnasium: Gym - Public Spaces	[28.4798926 -98.348729 3]	Handrails fail: The inside handrail is not continuous. Handrails shall be continuous within the full length of each stair flight. Inside handrails on switchback or dogleg stairs shall be continuous between flights. At the bottom of a stair flight, handrails shall extend at the slope of the stair flight for a horizontal distance at least equal to one tread depth beyond the last riser nosing. Extension shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent stair flight. At the top of a stair flight, handrails shall extend horizontally above the landing for 12 inches (305 mm) minimum beginning directly above the first riser nosing. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent stair flight.	steps to stage - handrails lack extensions	Install handrails on both sides of stairway mounted 34" to 38" aff, with top and bottom extensions. Handrails must be 1.25"-2" in diameter, or a non-circular grip that has a perimeter dimension of 4"-6.25" maximum, with a minimum gap of 1.5" between handrail and wall. Handrails shall be continuous for the full flight of the stairs and continue around any switchbacks.	2015 ABAAS Section: 505.3, 505.10.2, 505.10.3 2012 TAS Section: 505.3, 505.10.2, 505.10.3 2010 ADAS Section: 505.3, 505.10.2, 505.10.2, 505.10.3		12 min 10 10 10 10 10 10 10 10 10 10
238	CU - Gymnasium: Gym - Public Spaces	[28.4797606 , -98.348729 3]	The handrails as well as the handrail extensions are not at the correct height. The tops of handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground.	to stage- handrails both 27" AFF	Replace or remount handrails to 34" to 38" aff	2015 ABAAS Section: 505.4 2012 TAS Section: 505.4 2010 ADAS Section: 505.4		(a) stairs

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
239	CU - Gymnasium: Gym - Public Spaces	[28.4798266 -98.348766 9]	The handrail is not secure. Handrails shall not rotate within their fittings.	to stage- handrails wobble, not sturdy	Tighten or repair handrail to be secure in its fittings	2015 ABAAS Section: 505.9 2012 TAS Section: 505.9 2010 ADAS Section: 505.9		
240	CU - Gymnasium: Gym - Public Spaces	[28.4797653 -98.348707 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a gap greater than 1/2 inch wide. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	table closet - knob, clearance on pull reduced by table, 2" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
241	CU - Gymnasium: Gym - Public Spaces	[28.4798077 -98.348799 1]	The door exceeds the maximum pressure to open the door. Interior doors shall have a maximum opening force of 5 pounds. These forces do not apply to the force required to retract latch bolts or disengage other devices that hold the door or gate in a closed position. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum. Door and gate spring hinges shall be adjusted so that from the open position of 70 degrees, the door or gate shall move to the closed position in 1.5 seconds minimum.	doors to dining hall area - bleacher side 18lbf, table closet side 20lbf	Inspect, adjust, and maintain 5 lbf to open doors	2015 ABAAS Section: 404.2.9 2012 TAS Section: 404.2.9 2010 ADAS Section: 404.2.9		
242	CU - Gymnasium: Gym - Public Spaces	[28.4798631 -98.348768 2]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	21" clear floor space for lights	Provide required 30" by 48" CFS at operable parts.	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
243	CU - Gymnasium: Gym - Public Spaces	[28.4797841 -98.348734 7]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	thermostat and lights 59" above finished floor	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		TO max
244	CU - Gymnasium: Gym - Public Spaces	[28.4798525 -98.348710 6]	Treads shall be 11 inches (280 mm) deep minimum and uniform	side of stage steps lack uniform depth and compliant hand rails	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible. Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions.	2015 ABAAS Section: 504.2 2012 TAS Section: 504.2 2010 ADAS Section: 504.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
245	CU - Gymnasium: Gym - Public Spaces	[28.4797417 -98.348729 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	door off stage to side steps, chair closet - knob, back clearance reduced to 35" by wall, door can't open 90, door with tables on other side is identical with same issues	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
246	CU - Gymnasium: Gym - Public Spaces	[28.4797936 -98.348766 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	chair closet - knob, clearance on pull reduced by chairs, 11" clearance on push	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
247	CU - Gymnasium: Gym - Public Spaces	[28.4797888 -98.348772 3]	The threshold has a gap greater than 1/2 inch wide. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	push double doors by chair closet - left 15lbf, right 17lbf, 1" gap; exterior double doors following, left- 15lbf, right 17lbf	For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
248	CU - Gymnasium: Gym - Public Spaces	[28.4797947 -98.348878 2]	All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	push double doors, nature center side, left - 15lbf, fast close, right - 15lbf; exterior doors following, left- 15lbf, right - over 30lbf	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
249	CU - Gymnasium: Gym - Public Spaces	[28.4796462 -98.348882 2]	The threshold has a gap greater than 1/2 inch wide. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	exit doors on back side if gym, closer to fire hydrant - right 23lbf, 2.5" gap, left - compliant; other side - right when inside - stuck on something, requires excessive force. left - 5" gap	For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
250	CU - Gymnasium: Gym - Employee Spaces	[28.4798171 -98.348729 3]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	no route to employee shed behind gym	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
251 CU - Gymnasium Gym - Employee Spaces	[28.4797888 -98.348774 9]	The stairway handrails are not nearly compliant. The handrails have the following issues: - Installed at the incorrect height - The bottom handrail extensions are missing or extend incorrectly - The top handrail extensions are missing or extend incorrectly - The handrail gripping surface is not the correct size - The handrail is not located with the correct spacing from the wall or adjacent surface - The handrails are obstructed. Handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground. The top handrails shall extend a minimum of 12 inches beyond the top nosing and shall be parallel with the floor or ground surface. At the bottom of a stair flight, handrails shall extend at the slope of the stair flight for a horizontal distance at least equal to one tread depth beyond the last riser nosing. Extension shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent stair flight. The orientation of at least one handrail, including the extension, shall be in the direction of the run of the stair and perpendicular to the direction of the stair nosing. Handrail gripping surfaces with a circular cross section shall have an outside diameter of 1-1/4 inches minimum and 2 inches maximum. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2-1/4 inches maximum. The hand grip portion of handrails shall have a smooth surface with no sharp corners. Gripping surfaces (top or sides) shall be uninterrupted by newel posts, other construction elements or obstructions. Any wall or other surface adjacent to the handrail shall be free of sharp or abrasive elements. Handrails projecting from a wall shall have a space of 1-1/2 inches minimum between the wall and the handrail.	stage egress steps for employees only - lack compliant handrails on both sides	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions. Install detectable warning strip on top tread of each stairway as a smart practice.	2015 ABAAS Section: 505.1 2012 TAS Section: 505.1 2010 ADAS Section: 505.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
					•			
252	CU - Gymnasium: Gym - Women's Restroom	[28.4797299 -98.348670 3]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	signage lacks Braille, raised characters, or International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	WOMEN	
253	CU - Gymnasium: Gym - Women's Restroom	[28.479737, -98.348671 7]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth is 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	hook in stall 66" above finished floor	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
254	CU - Gymnasium: Gym - Women's Restroom	[28.4797252 , -98.348660 9]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 6" from rear wall, extend 48" from rear wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
255	CU - Gymnasium: Gym - Women's Restroom	[28.4797158 -98.348662 3]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37" above finished floor	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
256	CU - Gymnasium: Gym - Women's Restroom	[28.4797228 -98.348681 1]	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than 44 inches above the floor.	flush on wall side	Remount flush mechanism on the open side, in the alternative, install an auto flush unit.	2015 ABAAS Section: 604.6 2012 TAS Section: 604.6 2010 ADAS Section: 604.6		Transfer side

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Fi	gure
257	CU - Gymnasium: Gym - Women's Restroom	[28.4797382 -98.348663 6]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	hardware requires pinch, missing on pull	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
258	CU - Gymnasium: Gym - Women's Restroom	[28.4797323 , -98.348654 2]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		48 max
259	CU - Gymnasium: Gym - Women's Restroom	[28.4797323 , -98.348675 7]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		Market

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
260	CU - Gymnasium: Gym - Women's Restroom	[28.4797323 -98.348632 8]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	11 of 11 hooks 64" AFF	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
261	CU - Gymnasium: Gym - Women's Restroom	[28.4797287 -98.348683 7]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground. Clear floor or ground space complying with 305 shall be provided and shall be positioned at the end of the bench seat and parallel to the short axis of the bench	bench 16" depth, no side clear floor space	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff and provide required clear floor space on the short axis of the bench.	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
262	CU - Gymnasium: Gym - Women's Restroom	[28.4797275 , -98.348663 6]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	no accessible shower	Create an accessible shower in locker/bathing room.	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDARD ROLLIN TYPE SHOWED COMMANDARY IN A SHOWED SH
263	CU - Gymnasium: Gym - Women's Restroom	[28.4797134 -98.348665]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	women's restroom- sign in clear floor space on push, 10" clearance on push, 16lbf, fast close	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
264	CU - Gymnasium: Gym - Men's Restroom	[28.479737, -98.348675 7]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	MEN	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
265	CU - Gymnasium: Gym - Men's Restroom	[28.4797181 -98.348673]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar mounted 8" from wall, extends 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
266	CU - Gymnasium: Gym - Men's Restroom	[28.479737, -98.348673]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37"AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
267	CU - Gymnasium: Gym - Men's Restroom	[28.4798596 , -98.348734 7]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self closing, pinch hardware, missing on exterior side	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
268	CU - Gymnasium: Gym - Men's Restroom	[28.4798171 -98.348729 3]	The compartment door is located too far from the partition or wall. The door shall be located in front of the clear space and diagonal to the water closet. Where located in the front partition, the door opening shall be 4 inches maximum from the side wall or partition farthest from the water closet. Where located in the side wall or partition, the door opening shall be 4 inches maximum from the front partition. Toilet compartment doors shall not swing into the minimum required compartment area.	door 10" from partition	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	2015 ABAAS Section: 604.8.1.2 2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2		Alternate door location
269	CU - Gymnasium: Gym - Men's Restroom	[28.4797983 -98.348753 5]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		yam 6
270	CU - Gymnasium: Gym - Men's Restroom	[28.4798643 -98.348746 8]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer protrudes 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
271	CU - Gymnasium: Gym - Men's Restroom	[28.4798313 -98.348777 6]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	10 of 10 hooks 64" AFF	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
272	CU - Gymnasium: Gym - Men's Restroom	[28.4798442 -98.348754 8]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground. Clear floor or ground space complying with 305 shall be provided and shall be positioned at the end of the bench seat and parallel to the short axis of the bench	bench 16" depth no clear floor space	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff and provide required clear floor space on the short axis of the bench.	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min +

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
273	CU - Gymnasium: Gym - Men's Restroom	[28.4797747 -98.348807 1]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	non accessible shower	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STADDARD DOLLIN TYPE SHOWER Under the state of the state
274	CU - Gymnasium: Gym - Men's Restroom	[28.4797971 -98.348761 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	men's restroom- 8" clearance on push, floor sign in clearance in push, fast close, 13lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
275	CU - Group Hall: Group Hall - Public Spaces	[28.4810054 -98.351256]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	operable parts to screen lack clear floor space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min ie ie R
276	CU - Group Hall: Group Hall - Public Spaces	[28.4810007 -98.351223 8]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	screen string exceeds 48," unable to measure	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		veiu gy 10 max
277	CU - Group Hall: Group Hall - Public Spaces	[28.4810148 -98.351229 2]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink 36" AFF	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		Ter clearance

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
278	CU - Group Hall: Group Hall - Public Spaces	[28.4810077 -98.351221 1]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe clearance.	lacks knee clearance	Remove base cabinet and lower sink height to max 34" aff.	2015 ABAAS Section: 606.2, 804.4 2012 TAS Section: 606.2, 804.4 2010 ADAS Section: 606.2, 804.4		Lenn
279	CU - Group Hall: Group Hall - Public Spaces	[28.4810007 -98.351301 6]	The controls are located such that operation require reaching across burners. Where knee and toe space is provided, the underside of the range or cooktop shall be insulated or otherwise configured to prevent burns, abrasions, or electrical shock. The location of controls shall not require reaching across burners	controls on back side of oven	Replace oven with one having controls on the front panel	2015 ABAAS Section: 804.6.4 2012 TAS Section: 804.6.4 2010 ADAS Section: 804.6.4		20 mar -20 mar (a)
280	CU - Group Hall: Group Hall - Public Spaces	[28.4810242 -98.351229 2]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	fire extinguisher projects 5.5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
281	CU - Group Hall: Group Hall - Public Spaces	[28.4810242 -98.351304 3]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	thermostat 59" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
282	CU - Group Hall: Group Hall - Public Spaces	[28.4810101 -98.351298 9]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	counter 42" AFF	Lower 36" wide segment of service counter to max 36" aff.	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.2, 904.4.1		36'min 36'max
283	CU - Group Hall: Group Hall - Public Spaces	[28.4809983 , -98.351247 9]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	patio door - 18lbf	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
284	CU - Group Hall: Group Hall - Public Spaces	[28.4810054 -98.351269 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a gap greater than 1/2 inch wide.	back hallway exit - lacks clearance on pull, 1" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, fill gaps at door entries to max .5".	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
285	CU - Group Hall: Group Hall - Public Spaces	[28.4809959 , -98.351218 4]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	entry door - 13lbf	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
286	CU - Group Hall: Group Hall - Employee Spaces	[28.4809771 -98.351261 3]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	3 employee room doors have knobs	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
287	CU - Group Hall: Group Hall - Unisex Restroom	[28.4810054 -98.351234 5]	50% of the single accommodation restrooms provided in this grouping are not nearly compliant. The restrooms do not have the required minimum clear floor space or maneuvering clearances for the toilet, The restrooms do not have the required minimum clear floor space or maneuvering clearances for the lavatory, The entry doors do not contain the required minimum maneuvering spaces on the pull/push sides, The entry doors encroach into the required clear floor space for fixtures, Grab bars are missing and/or incorrectly installed, Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both, The restrooms contain floor level changes greater than a 1/2 inch, the showers are too small and missing numerous accessible elements.	non compliant, unisex restroom lacks signage	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom. Create compliant wheelchair accessible restrooms and correct all features to be accessible if feasible to meet 50% compliant restrooms in this location.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		TO MIN. CLEAR TO MIN. CLEAR TO MIN. TO MIN.
288	CU - Group Hall: Group Hall - Unisex Restroom	[28.4810007 -98.351223 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a gap greater than 1/2 inch wide. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	restroom- knob, 9.5" clearance on pull, 2.5" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
289	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890398 -98.341455 2]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hand dryer 49" AFF, hook 64" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
290	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890091 , -98.341444 5]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	2 standard 1 ambulatory stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
291	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890433 -98.341436 4]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 41.5" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
292	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890445 -98.341441 8]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	21.5" from metal side, 20" from other side	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		uie 09 35-37
293	CU - Restrooms: CU - Women's Campsite Shower House	[28.489035, -98.341457 9]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self closing, no hardware on pull, pinch on push	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
294	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890492 -98.341449 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both grab bars extend 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
295	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890209 -98.341455 2]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hook 64" AFF	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
296	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890327 -98.341449 8]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground. Clear floor or ground space complying with 305 shall be provided and shall be positioned at the end of the bench seat and parallel to the short axis of the bench	bench lacks CFS, 16" depth	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff and provide required clear floor space on the short axis of the bench.	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min 4
297	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890421 , -98.341457 9]	Alternate roll-in type shower compartments shall be 36 inches (915 mm) wide and 60 inches (1525 mm) deep minimum clear inside dimensions measured at center points of opposing sides. A 36 inch (915 mm) wide minimum entry shall be provided at one end of the long side of the compartment.	shower 44" width	Correct shower stall, if feasible, to compliant dimensions for an alternate roll in shower of 36" deep by 60" wide with a 36" opening on the long dimension	2015 ABAAS Section: 608.2.3 2012 TAS Section: 608.2.3 2010 ADAS Section: 608.2.3		back wall wall from 35 mn 100 min 100 min 10
298	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890633 , -98.341455 2]	The grab bar is located above the seat In alternate roll-in type shower compartments, grab bars shall be provided on the back wall and the side wall farthest from the compartment entry. Grab bars shall not be provided above the seat. Grab bars shall be installed 6 inches maximum from adjacent walls.	seat on wrong wall, missing grab bar	Provide grab bars in the shower mounted in the correct locations for the shower type	2015 ABAAS Section: 608.3.3 2012 TAS Section: 608.3.3 2010 ADAS Section: 608.3.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
299	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890492 -98.341417 6]	The operable parts of controls are incorrectly installed. In alternate roll-in type shower compartments, the controls, faucets, and shower spray unit shall be located above the grab bar, but no higher than 48 inches (1220 mm) above the shower floor. Where a seat is provided, the controls, faucets, and shower spray unit shall be located on the side wall adjacent to the seat 27 inches (685 mm) maximum from the side wall behind the seat or shall be located on the back wall opposite the seat 15 inches (380 mm) maximum, left or right, of the centerline of the seat. Where a seat is not provided, the controls, faucets, and shower spray unit shall be installed on the side wall farthest from the compartment entry.	controls more than 15" from the corner	Remount shower controls to the correct location in the alternate shower	2015 ABAAS Section: 608.5.3 2012 TAS Section: 608.5.3 2010 ADAS Section: 608.5.3		
300	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890527 -98.341449 8]	There is no hand held sprayer unit. The sprayer unit must have a 59 inches hose and be mounted 48 inches maximum to the top of mounting bracket off the floor. The shower spray unit shall have an on/off control with a non-positive shutoff. If an adjustable-height shower head on a vertical bar is used, the bar shall be installed so as not to obstruct the use of grab bars.	fixed shower head only, mounted 72" AFF	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held; in the alternative, remount fixed shower head to max 48" aff	2015 ABAAS Section: 608.6 2012 TAS Section: 608.6 2010 ADAS Section: 608.6		SHOWER SPRAY UNIT

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
301	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890515 -98.341439 1]	Where a seat is provided in a standard roll- in shower compartment, it shall be a folding type, shall be installed on the side wall adjacent to the controls, and shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. Where a seat is provided in an alternate roll-in type shower compartment, it shall be a folding type, shall be installed on the front wall opposite the back wall, and shall extend from the adjacent side wall to a point within 3 inches (75 mm) of the compartment entry. In transfer-type showers, the seat shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. The top of the seat shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the bathroom finish floor. Seats shall comply with 610.3.1 or 610.3.2.	seat mounted on wrong wall	Remount seat to correct wall for alternate roll-in shower.	2015 ABAAS Section: 610.3 2012 TAS Section: 610.3 2010 ADAS Section: 610.3		
302	CU - Restrooms: CU - Women's Campsite Shower House	[28.4890445 , -98.341428 4]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	women's- 12 lbf	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
303	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890586 -98.341447 1]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 65" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
304	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890398 ,-98.341444 5]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	1 standard, 1 ambulatory, 1 urinal	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS		
305	CU - Restrooms: CU - Men's	[28.4890586	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 41.5" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	Section: 213.3.1 2015 ABAAS Section:		
	Campsite Shower House	-98.341412 3]				604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		
306	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890409 -98.341424 3]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	tile side 20" centerline, metal side 22" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1	<image/>	uiu 09 35-37

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
307	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890327 -98.341431 1]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door has pinch hardware on push, missing on pull	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
308	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890492 -98.341449 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both extend 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
309	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890421 -98.341428 4]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	unable to audit due to heavy use at time of audit, likely identical to men's	Make corrections to shower in men's to be fully compliant	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDAGO ROLLIN TYPE SHOWEN
310	CU - Restrooms: CU - Men's Campsite Shower House	[28.4890303 -98.341441 8]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	men's- 10lbf	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
311	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880072 -98.347208 5]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks 66" AFF	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
312	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4879789 -98.347221 9]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground. Clear floor or ground space complying with 305 shall be provided and shall be positioned at the end of the bench seat and parallel to the short axis of the bench	bench lacks CFS, 16" depth	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff and provide required clear floor space on the short axis of the bench.	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min /
313	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4879883 , -98.347205 8]	Alternate roll-in type shower compartments shall be 36 inches (915 mm) wide and 60 inches (1525 mm) deep minimum clear inside dimensions measured at center points of opposing sides. A 36 inch (915 mm) wide minimum entry shall be provided at one end of the long side of the compartment.	shower 44" width	Correct shower stall, if feasible, to compliant dimensions for an alternate roll in shower of 36" deep by 60" wide with a 36" opening on the long dimension	2015 ABAAS Section: 608.2.3 2012 TAS Section: 608.2.3 2010 ADAS Section: 608.2.3		back wall is add in the set of th
314	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880355 -98.347219 3]	The grab bar is located above the seat In alternate roll-in type shower compartments, grab bars shall be provided on the back wall and the side wall farthest from the compartment entry. Grab bars shall not be provided above the seat. Grab bars shall be installed 6 inches maximum from adjacent walls.	grab bar not provided on side wall	Provide grab bars in the shower mounted in the correct locations for the shower type	2015 ABAAS Section: 608.3.3 2012 TAS Section: 608.3.3 2010 ADAS Section: 608.3.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
315	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880072 -98.347216 6]	There is no hand held sprayer unit. The sprayer unit must have a 59 inches hose and be mounted 48 inches maximum to the top of mounting bracket off the floor. The shower spray unit shall have an on/off control with a non-positive shutoff. If an adjustable-height shower head on a vertical bar is used, the bar shall be installed so as not to obstruct the use of grab bars.	fixed shower head 70" AFF	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held; in the alternative, remount fixed shower head to max 48" aff	2015 ABAAS Section: 608.6 2012 TAS Section: 608.6 2010 ADAS Section: 608.6		SHOWER SPRAY UNIT
316	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880096 -98.347216 6]	Where a seat is provided in a standard roll- in shower compartment, it shall be a folding type, shall be installed on the side wall adjacent to the controls, and shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. Where a seat is provided in an alternate roll-in type shower compartment, it shall be a folding type, shall be installed on the front wall opposite the back wall, and shall extend from the adjacent side wall to a point within 3 inches (75 mm) of the compartment entry. In transfer-type showers, the seat shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. The top of the seat shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the bathroom finish floor. Seats shall comply with 610.3.1 or 610.3.2.	seat located on side wall	Remount seat to correct location for alternate roll-in shower	2015 ABAAS Section: 610.3 2012 TAS Section: 610.3 2010 ADAS Section: 610.3		
317	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880261 -98.347216 6]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirror 40.5" AFF	Lower mirror so bottom reflective surface is max 40" AFF and 74" at the top.	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
318	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880166 -98.347200 5]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook in stall 65" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
319	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880308 ,-98.347211 2]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	2 standard, 1 ambulatory stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
320	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880213 -98.347216 6]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
321	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4879931 -98.347248 8]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	metal side - 22" centerline, tile side - 20" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		UIII 09
322	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880496 -98.347211 2]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self closing, no hardware on pull, pinch on push side	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
323	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880355 -98.347219 3]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both extend 48" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
324	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880402 -98.347224 6]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 36.75" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
325	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880072 , -98.34723]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper too close	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		uiuus gr
326	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880025 -98.347216 6]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.6% at sink	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
327	CU - Restrooms: CU - Women's Screened Shelter Shower House	[28.4880119 , -98.347246 1]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	women's- 17lbf	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
328	CU - Restrooms: CU - Men's Screened Shelter Shower House	[28.46601, -98.35448]	Restrooms and shower rooms must be compliant including accessible sinks, urinals when two or more are provided, a wheelchair stall, an ambulatory stall if 6 or more of a combination of stalls and toilets are provided, and an accessible shower. Operable parts must also comply.	Men's restroom could not be assessed at time of audit due to high occupancy, assumed to be very similar to women's	Make corrections to men's restroom to provide compliant restroom and shower facilities.	Capture Section: 1		
	_	_		_	-			
329	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717443 -98.338258]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	men's- fast close, 24lbf	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
330	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717667 -98.338258]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
331	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717726 -98.338252 6]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 66" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
332	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717632 -98.338260 7]	The dimensions of the toilet stall do not comply. Wheelchair accessible compartments shall be 60 inches wide and 59 inches deep minimum for floor mounted water closets measured perpendicular to the rear wall. Door shall not swing into the minimum clear floor space required for the toilet.	stall 59" width	Widen accessible stalls to min. 60" clear width, 59" depth	2015 ABAAS Section: 604.8.1.1 2012 TAS Section: 604.3.2 2010 ADAS Section: 604.3.2		Wall hung Foor Mount

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
333	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717726 -98.338244 6]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar extends 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
334	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717679 ,-98.338247 3]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 36.5" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
335	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.471775, -98.338255 3]	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than 44 inches above the floor.	flush on wall side	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	2015 ABAAS Section: 604.6 2012 TAS Section: 604.6 2010 ADAS Section: 604.6		Transfer side

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
336	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717714 -98.338255 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door hardware pinch on push, missing on pull, not self closing	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2		
						2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
337	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717644 -98.338258]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted in the front	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		Curried and the second
338	CU - Restrooms: CU, By Campsite 201 - Men's Restroom	[28.4717597 -98.338266]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The second secon

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
339	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717726 -98.338252 6]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
						2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
340	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.471762, -98.338241 9]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook in stall 66" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
341	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717443 -98.338258]	The dimensions of the toilet stall do not comply. Wheelchair accessible compartments shall be 60 inches wide and 59 inches deep minimum for floor mounted water closets measured perpendicular to the rear wall. Door shall not swing into the minimum clear floor space required for the toilet.	58" x 58"	Widen accessible stalls to min. 60" clear width, 59" depth	2015 ABAAS Section: 604.8.1.1 2012 TAS Section: 604.3.2 2010 ADAS Section: 604.3.2		Wall hung Floor Mount
342	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717679 -98.338266]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar extends 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
343	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	,	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 37" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
344	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.471775, -98.338252 6]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door hardware pinch on pull, no handle on push, not closing	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
345	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717703 -98.338241 9]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		10 mm k
346	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717691 -98.338274 1]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		
347	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717915 -98.338268 7]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap by drain	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
348	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717679 -98.338252 6]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.6% cross slope by hand dryer	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
349	CU - Restrooms: CU, By Campsite 201 - Women's Restroom	[28.4717679 -98.338243 2]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	women's- fast close, 20lbf	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
350	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.480456, -98.352012 4]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	WOMEN	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
351	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804478 -98.352033 8]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 64.5" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
352	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804537 -98.352044 6]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	3 standard 1 ambulatory stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
353	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804631 -98.352052 6]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
354	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804726 -98.352044 6]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	tile side - 22" centerline, metal side - 20" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		uiu 09 35-37
355	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.480449, -98.352049 9]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self closing, lack hardware on both sides	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
356	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804207 -98.351990 9]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both grab bars extend 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
357	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804678 -98.352033 8]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper directly above on metal side	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
358	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804207 -98.352012 4]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	both toilet paper dispensers mounted too close	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		veu 89

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
359	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804537 , -98.352047 2]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		Not the second s
360	CU - Restrooms: CU, By Group Hall - Women's Restroom	[28.4804749 -98.352059 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	women's- 2.5" clearance on push, 15lbf, floor sign in clearance on push	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
361	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804584 -98.352041 9]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	MEN	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
362	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804726 -98.352055 3]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth is 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	urinal flush 50" AFF, hook 67" AFF	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
363	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804678 -98.352044 6]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	2 standard, 1 ambulatory, 1 urinal	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
364	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804584 , -98.352033 8]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 41" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		
365	CU - Restrooms: CU, By Group Hall - Men's Restroom	,	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	toilet centerline 23" on tile side	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		UIEU00
366	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804537 -98.352082 1]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door lacks hardware on both sides	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
367	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804537 -98.352049 9]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both grab bars extend 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
368	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804254 -98.352079 4]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper above grab bar 3.5"	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
369	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804395 , -98.352033 8]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted too close	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		Year St.
370	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804384 -98.352037 8]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The second secon
371	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804773 -98.352039 2]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	3.5% slope at sink	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
372	CU - Restrooms: CU, By Group Hall - Men's Restroom	[28.4804773 -98.352049 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	men's- floor sign in door clearance, 3.5" clearance on push, fast close, 20 lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
373	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825602 -98.352649 4]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
374	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825755 -98.352632]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar extends 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
375	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825578 -98.352654 8]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 36.75" AFF	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
376	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825708 -98.352656 1]	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for the flush valves shall be mounted on the wide side of toilet areas, no more than 44 inches above the floor.	flush on wall side	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit.	2015 ABAAS Section: 604.6 2012 TAS Section: 604.6 2010 ADAS Section: 604.6		Transfer side

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
377	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825614 -98.352656 1]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door has pinch hardware, missing on other side, not self closing	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
378	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825743 , -98.352645 4]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper 27" on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		7.9

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
379	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825661 -98.352634 6]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The second secon
380	CU - Restrooms: CU, By Main Boat Ramp - Men's Restroom	[28.4825779 -98.352656 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	men's- sign in clearance on push, 24 lbf, fast close	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
381	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825802 -98.352653 4]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
382	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825661 ,-98.352641 3]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 64" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		umax
383	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825732 -98.352648 1]	The dimensions of the toilet stall do not comply. Wheelchair accessible compartments shall be 60 inches wide and 59 inches deep minimum for floor mounted water closets measured perpendicular to the rear wall. Door shall not swing into the minimum clear floor space required for the toilet.	stall 59" width	Widen accessible stalls to min. 60" clear width, 59" depth	2015 ABAAS Section: 604.8.1.1 2012 TAS Section: 604.3.2 2010 ADAS Section: 604.3.2		Wall hung

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
384	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825626 -98.352642 7]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side bar extends 48"	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	<image/>	
385	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825637 -98.352656 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	both 36.75" above finished floor	Remount grab bars in accessible stall to 33" to 36" above the finished floor (AFF).	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
386	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825637 -98.352650 7]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self closing, pinch on push, no hardware on pull	Adjust stall door to be self-closing. Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2		
						2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
387	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825519 -98.352634 6]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper on front partition	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		C unit of the second se
388	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825779 -98.352645 4]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
389	CU - Restrooms: CU, By Main Boat Ramp - Women's Restroom	[28.4825814 -98.352629 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
390	CU - Nature Center: Nature Center Public	[28.4799221 -98.349092 8]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	28" width between table and sign	Widen AR to compliant 36" clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 40 min 9 9 9 9 9 9 9
391	CU - Nature Center: Nature Center Public	[28.4799209 -98.349080 7]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hat projects 6"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The second secon
392	CU - Nature Center: Nature Center Public	[28.4798973 -98.349067 3]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	0 of 2 tables offer knee clearance	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		King Bage Structure Ban Bantas Bantas
393	CU - Nature Center: Nature Center Public	[28.4798525 -98.349090 1]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	0 of 3 tables at Nature Center patio of accessible design	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
394	CU - Nature Center: Nature Center Public	[28.4799444 , -98.349099 5]	Element meets all standards and requirements	Nature Center door complies	None	2010 ADAS Section: N/A		
395	CU - Nature Center: Nature Center Public	[28.46601, -98.35448]	50% of the single accommodation restrooms provided in this grouping are not nearly compliant. The restrooms do not have the required minimum clear floor space or maneuvering clearances for the toilet, The restrooms do not have the required minimum clear floor space or maneuvering clearances for the lavatory, The entry doors do not contain the required minimum maneuvering spaces on the pull/push sides, The entry doors encroach into the required clear floor space for fixtures, Grab bars are missing and/or incorrectly installed, Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both, The restrooms contain floor level changes greater than a 1/2 inch, the showers are too small and missing numerous accessible elements.	restrooms currently used only for storage	Ensure compliant wheelchair accessible restrooms and correct all features to be accessible if feasible to meet 50% compliant restrooms in this location.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		
	<u></u>							

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
396	CU - Nature Center: Nature Center Employee	[28.4799303 -98.349166 5]	50% of the single accommodation restrooms provided in this grouping are not nearly compliant. The restrooms do not have the required minimum clear floor space or maneuvering clearances for the toilet, The restrooms do not have the required minimum clear floor space or maneuvering clearances for the lavatory, The entry doors do not contain the required minimum maneuvering spaces on the pull/push sides, The entry doors encroach into the required clear floor space for fixtures, Grab bars are missing and/or incorrectly installed, Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both, The restrooms contain floor level changes greater than a 1/2 inch, the showers are too small and missing numerous accessible elements.	assumed employee restroom - not compliant, lacks signage, lacks directional signage	Create compliant wheelchair accessible restrooms and correct all features to be accessible if feasible to meet 50% compliant restrooms in this location.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		BY MIN CLEAN TO MIN CLEAN TO MIN CLEAN TO MIN CLEAN TO MIN CLEAN TO MIN CLEAN TO MIN CLEAN
397	CU - Nature Center: Nature Center Employee	[28.4799751 -98.349202 8]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	archery storage door - knob, no clearance on pull, storage in back clearance on push and offers 34" back clearance	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
398	CU - Nature Center: Nature Center Employee	[28.479968, -98.349190 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	restroom door - knob, 8" clearance on push	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
399	CU - Nature Center: Nature Center Employee	[28.4799586 -98.349163 9]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	closet - knob, flag in clearance on push, fire extinguisher on push, clearance on pull reduced by shelf, backside of closet - knob, no clearance on pull due to storage, hallway closet - 2 knobs	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
400	CU - Nature Center: Nature Center Employee	[28.4799244 -98.349202 8]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	side door to archery - requires pinch on push and pull, handle on push 59" AFF, 4" clearance on push	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted maximum 48" above finished floor.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
	1	1	1	1		1		
401	CU - Nature Center: Archery Course	[28.4799114 -98.349534]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1" change in level at archery walkway	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		
402	CU - Nature Center: Archery Course	[28.4798336 -98.349330 2]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	15 instances of gaps ranging from 1"-3"	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	de la constante de la constante de la constant	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
403	CU - Nature Center: Archery Course	, -98.349300	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3% slope on entire first run of course	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
404	CU - Screened Shelters: Shelter 16	[28.4885164 -98.347589 4]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	air conditioner unit buttons 63" AFF, lights 51" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		in max
405	CU - Screened Shelters: Shelter 16	[28.4885164 -98.347581 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a vertical change greater than 1/4 inch high. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	knob, 9" clearance on push due to bed, 9" change in level	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
406	CU - Screened Shelters: Shelter 16	[28.4885565 , -98.347463 3]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	gravel in both stalls	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		
407	CU - Screened Shelters: Shelter 16	[28.4885895 , -98.347541 1]	Element meets all standards and requirements	beds comply, provides clear floor space	None	2010 ADAS Section: N/A		
408	CU - Screened Shelters: Shelter 17	[28.488138, -98.347801 3]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	lights 50" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		

Finding Area I Number	Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
	ters: Shelter	28.4881463 -98.347804]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold has a gap greater than 1/2 inch wide. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. Hand- activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate.	entry- knob, 8" clearance on push due to bed	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
			Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor. EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.					
410	CU - Screened Shelters: Shelter 17	[28.4881699 -98.347838 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap at entry to patio	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		destruet disclose of land and disclose of land 24 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
411	CU - Screened Shelters: Shelter 17	[28.4881651 , -98.347779 8]	Operable parts shall comply with 309.3 and 309.4. EXCEPTIONS: 1. Fire rings, grills, fireplaces, wood stoves, water hydrants, and water utility hookups shall comply with 309.4 to the extent practicable. 2. Trash and recycling receptacles with hinged lids and controls to keep out large animals shall comply with 309.4 to the extent practicable. 3. Dumpster type trash and recycling receptacles shall not be required to comply with 309.3 and 309.4. 4. Sewage hatches shall not be required to comply with 309.3 and 309.4.	spigot 18" AFF	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	2015 ABAAS Section: 1011.3, 1011.3 EXCE PTIONS: 1, 1011.3 EXCE PTIONS: 2, 1011.3 EXCE PTIONS: 3, 1011.3 EXCE PTIONS: 4		
412	CU - Screened Shelters: Shelter 17	[28.4881746 -98.347779 8]	The accessible path of travel contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	3.3% slope in floor	Correct or repair cross slope of AR to max 2.08%	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3		
413	CU - Screened Shelters: Shelter 17	[28.4881746 , -98.347648 4]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	gravel in both stalls	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		
414	CU - Screened Shelters: Shelter 17	[28.4881604 , -98.347777 2]	Element meets all standards and requirements	beds comply, provides clear floor space	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
415	CU - Screened Shelters: Shelter 18	[28.4876442 -98.348101 7]	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	picnic table blocking route	Relocate table to provide min 36" clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max, 48 mm, 48 mm, 90 00 00 00 00 00 00 00 00 00 00 00 00 0
416	CU - Screened Shelters: Shelter 18	[28.4876442 -98.348074 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap in clear floor space for fire pit. 1.25" on other side, 1.25" gap on path to patio, 1.25" gap approaching door from parking, 12.5" gap between parking and site	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		An and a data of the second se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
417	CU - Screened Shelters: Shelter 18	,	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	air conditioner unit buttons 71" AFF, lights 53" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		U max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
418	CU - Screened Shelters: Shelter 18	[28.4876559 , -98.348074 9]	Element meets all standards and requirements	beds comply, provides clear floor space	None	2010 ADAS Section: N/A		
419	CU - Screened Shelters: Shelter 18	[28.4876406 -98.348085 6]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	entry- 7" clearance on push due to bed on push	Provide required maneuvering clearance on push side of door.	2015 ABAAS Section: 404.2.4.4, 404.2.4.1 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.4,		
420	CU - Screened Shelters: Shelter 18	[28.4877066 -98.348042 7]	Operable parts shall comply with 309.3 and 309.4. EXCEPTIONS: 1. Fire rings, grills, fireplaces, wood stoves, water hydrants, and water utility hookups shall comply with 309.4 to the extent practicable. 2. Trash and recycling receptacles with hinged lids and controls to keep out large animals shall comply with 309.4 to the extent practicable. 3. Dumpster type trash and recycling receptacles shall not be required to comply with 309.3 and 309.4. 4. Sewage hatches shall not be required to comply with 309.3 and 309.4.	spigot 17" AFF	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	2015 ABAAS Section: 1011.3, 1011.3 EXCE PTIONS: 1, 1011.3 EXCE PTIONS: 2, 1011.3 EXCE PTIONS: 3, 1011.3 EXCE PTIONS: 4		
421	CU - Screened Shelters: Shelter 18	[28.4877455 -98.348073 5]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	tree overhangs in head clearance	Maintain overhead clearance of min. 80".	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
422	CU - Screened Shelters: Shelter 18	[28.48763, -98.347935 4]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	gravel in both stalls, right stall - 3.1% slope, left 2.9%	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		
423	CU - Screened Shelters: Shelter 20	[28.4871727 -98.348316 3]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	gravel in both stalls, left stall - 2.4% slope	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
424	CU - Screened Shelters: Shelter 20	[28.4870595 , -98.348428 9]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	.75" change in level at entry from parking	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		12 12 12 12 12 12 12 12 12 12 12 12 12 1
425	CU - Screened Shelters: Shelter 20	[28.4870784 -98.348439 7]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.5" gap at entry, 13" gap in clear floor space for fire pit	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		An open of a balance of a balan

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
426	CU - Screened Shelters: Shelter 20	[28.4870689 -98.348407 5]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	air conditioner unit buttons 71" AFF, lights 53" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max
427	CU - Screened Shelters: Shelter 20	[28.4870701 -98.348420 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	entry- 7" clearance on push due to bed on push, knob	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
428	CU - Screened Shelters: Shelter 20	[28.4871632 -98.348400 8]	Operable parts shall comply with 309.3 and 309.4. EXCEPTIONS: 1. Fire rings, grills, fireplaces, wood stoves, water hydrants, and water utility hookups shall comply with 309.4 to the extent practicable. 2. Trash and recycling receptacles with hinged lids and controls to keep out large animals shall comply with 309.4 to the extent practicable. 3. Dumpster type trash and recycling receptacles shall not be required to comply with 309.3 and 309.4. 4. Sewage hatches shall not be required to comply with 309.3 and 309.4.	spigot 16.5" AFF	Replace operable parts with ones usable without a tight pinch or grasp, mounted within reach range of 15" to 48" above the ground as a smart practice.	2015 ABAAS Section: 1011.3, 1011.3 EXCE PTIONS: 1, 1011.3 EXCE PTIONS: 2, 1011.3 EXCE PTIONS: 3, 1011.3 EXCE PTIONS: 4		
429	CU - Screened Shelters: Shelter 20	[28.4871538 , -98.348466 5]	The tree extends down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	tree overhangs in head clearance	Maintain overhead clearance of min. 80"	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection
430	CU - Screened Shelters: Shelter 20	[28.4871137 -98.348431 6]	Element meets all standards and requirements	beds comply, provides clear floor space	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
431	CU - Old Park Store By Ramp: Park Store - Employee	[28.482526, -98.352854 6]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	23" width, knob on close, rear door - pinch lock, no clearance on push. entry door - lock 61" AFF	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace doors with doors having 80" overhead clearance and 32" clear width. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
432	Trails: Trail Surface	[28.4795342 , -98.344480 7]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	bird trail not compliant surface	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		
433	Trails: Trail Surface	[28.4824954 , -98.35100 92], [28.4866399 -98.348155 4]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	emperor run - paved, but has heavy amounts of loose gravel on top for entirety of path	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice. Frequently maintain trail surface in identified washout areas to assure CIL's remain 2" or less and gaps are filled as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
434	Trails: Trail Surface	[28.4837826 , -98.34909 41], [28.4865974 -98.348166 1]	The tree branches extend down too close to the route of travel. Any obstruction that overhangs a route of travel must be a minimum of 80 inches above the walking surface as measured from the bottom of the obstruction.	emperor run - five instances of tree in overhead	Maintain overhead clearance of min. 80" along trail as a smart practice	2015 ABAAS Section: 307.3 2012 TAS Section: 307.3 2010 ADAS Section: 307.3		Any Projection

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
435	Trails: Trail Surface	[28.4826132 , -98.35102]	The cross slope shall not be steeper than 1:48. EXCEPTION: Where the surface is other than concrete, asphalt, or boards, cross slopes not steeper than 1:20 shall be permitted when necessary for drainage.	emperor run - 3.6% before first curve, 3.2% after (2) placard	Correct or repair pathway cross slope to max 2.08% as a smart practice.	2015 ABAAS Section: 1017.2		
436	Trails: Trail Surface	[28.46601, -98.35448]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	owl hollow not accessible surface	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		
437	Trails: Trail Surface	[28.478676, -98.347117 3]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	hawk alley non compliant surface	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
438		[28.488725, -98.344069]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	green jay pass - not accessible surface	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
439	South Shore (SS), Day Use Unit: SS - Parking	[28.4710582 , -98.254675]	Element meets all standards and requirements	parking along picnic area 1-2 in no wake zone - 69 standard; 5 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		
440	South Shore (SS), Day Use Unit: SS - Parking	[28.4710606 .98.254671]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	parking along 1-2 picnic area in no wake zone - access aisle in front of picnic 58 - 3% slope	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		
441	South Shore (SS), Day Use Unit: SS - Parking	[28.4718622 -98.253630 3]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	no wake zone in front of restroom - stall and access aisle have loose gravel, faded paint, in front of shelter by 63 - loose gravel, major overgrowth in both stall and access aisle, in front of picnic 58 - loose gravel in 3 stalls and 2 access aisles	Maintain stalls and access aisles to reduce loose gravel and overgrowth.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		Max M M M M M M M M M M M M M M M M M M

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
442	South Shore (SS), Day Use Unit: SS - Parking	[28.4718469 -98.253626 3]	The accessible parking stall signage is incorrect and/or missing from each accessible parking space. Parking space identification signs shall include the International Symbol of Accessibility. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	no wake zone restroom stall - missing sign, missing van sign	Acquire and mount at appropriate heights and locations accessible parking signs where missing	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6		RESERVED PARKING
443	South Shore (SS), Day Use Unit: SS - Parking	[28.493085, -98.247180 9]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	by dam - both stalls and access aisles have loose gravel, right stall has grass	Maintain accessible stalls and aisles to be free of debris and overgrowth	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₁ / ₁ / ₂
444	South Shore (SS), Day Use Unit: SS - Parking	[28.4724057 -98.251433 6]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	day use area - in front of restroom, left to right - 3.2% slope; in front of picnic spot 52 - right stall 2.3%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
445	South Shore (SS), Day Use Unit: SS - Parking	[28.4723857 -98.251426 8]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	day use area, in front of restroom - full of loose gravel, in front of picnic table 47 - loose gravel, right spot overgrowth	Resurface stalls and access aisles to eliminate excessive debris and overgrowth.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂ ¹ / ₂
446	South Shore (SS), Day Use Unit: SS - Parking	[28.4930756 , -98.247191 6]	Element meets all standards and requirements	parking by restricted dam gate - 19 standard, 2 accessible; meets scoping requirements	None	2010 ADAS Section: N/A		
447	South Shore (SS), Day Use Unit: SS - Parking	[28.4726214 , -98.250807 3]	Element meets all standards and requirements	day use/ boat ramp area - 21 standard, 6 ADA, 39 RV/ Pull through, 7 ADA RV pull through; meet scoping requirements	None	2010 ADAS Section: N/A		
448	South Shore (SS), Day Use Unit: SS - Parking	[28.472711, -98.251023 2]	The parking sign/s are missing. Parking space identification signs shall include the International Symbol of Accessibility (ISA). Signs identifying van parking spaces shall contain the designation "van accessible." All signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	boat ramp parking lot - 7 ADA pull through stalls - 6 of 7 lack signage	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6 2010 ADAS Section: 502.6		Van Accessible 60 nches min.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
449	South Shore (SS), Day Use Unit: SS - Parking	[28.46601, -98.35448]	Element meets all standards and requirements	lot behind main restroom by shelter - 14 standard, 2 accessible; meets scoping	None	2010 ADAS Section: N/A		
450	South Shore (SS), Day Use Unit: SS - Parking	[28.4930096 , -98.247207 7]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	lot behind main restroom, by shelter - loose gravel in both stalls and access aisle	Resurface stalls and access aisles to eliminate excessive debris	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
451	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4930638 -98.247234 6]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	curb ramp by dam has overgrowth at entry	Repair, bevel or ramp change in level along accessible route.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		¹ / ₄ ¹ / ₂ ¹ / ₂

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
452	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.493105, -98.247238 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	at dam/ restricted area - 1.25" gap, 1" gap in front of accessible stalls closest to shelter	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And the first of the second se
453	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4728383 -98.249762 5]	The running slope of walking surfaces shall not be steeper than 1:20.	to fish cleaning by shelter 46 - 6.8% slope at top of path	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
454	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4728725 -98.249745 1]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	to fish cleaning by shelter 46 - 3.5% slope at fork	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
455	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4728702 -98.249745 1]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	to fish cleaning by shelter 46 - 6" gap at entry to path, in front of 47, going towards accessible parking by 49 - 1" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Manuard daudior of band
456	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725448 -98.251463 1]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	at parking for restroom by boat ramp - 1" gap along lot, 2.25" gap in front of right accessible stall	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demonst densitier of transf

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
457	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4727075 -98.251421 5]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	from parking in front of restroom to main boat ramp - 1.5" change in level in front of wood covered picnic area	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		1/2 max 1/2 1/2 1/2 1/2 1/2
458	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.47288, -98.25138]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	8" gap where path meets road from restroom to main boat ramp	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demart database of based based of studies of the second studies of the 95 max
459	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725766 -98.251646 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.5" gap going towards outlook shelter by men's restroom by main boat ramp	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demuet decide of hard
460	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725813 -98.251654 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	from men's restroom (main boat ramp) to overlook - five 1" gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demont database of hard

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
461	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725766 -98.251558 3]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	debris/ mud on path by covered picnic 48 accessible parking	Maintain sidewalk to be free of mud and debris	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Ourput is the function of the set of the set
462	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725707 -98.251637 4]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	sand surface going towards metal covered accessible picnic table beside men's restroom by main boat ramp, loose sand along entire front spaces by restroom	Maintain AR to be free of sand and debris	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Part & Bernsteiner Bernsteiner Bernsteiner Weiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heiter Bernsteiner Heit
463	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4724104 , -98.25151]	The running slope of walking surfaces shall not be steeper than 1:20.	9.2% slope on beginning of path to restroom by main boat ramp	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
464	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.472447, -98.251464 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	two 1" gaps from accessible parking to restroom by main boat ramp, on path - 5 instances of gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		structure of and of other structure of and o

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
465	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4724328 -98.251456 4]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	parking lot behind main restroom by shelter - 1.5" change in level	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		¹ / ₄ max ¹ / ₄ ¹ / ₂ ¹ / ₄

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
466	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4719412 , -98.253643 7]	The running slope of walking surfaces shall not be steeper than 1:20.	15.2% slope to men's restroom in no wake zone	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
467	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4719365 -98.253658 4]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	deteriorated/ mud at turn to corner by women's restroom in no wake zone	Maintain AR to be free of mud	2015 ABAAS Section: 302.1 2012 TAS Section: 302.1 2010 ADAS Section: 302.1		Unit of a state of a

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
468	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.47176, -98.25375]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	restrooms between no wake zone, sidewalk along restroom - 4 instances of gaps	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demand facilita of training of the second se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
469	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4719247 .98.253667 8]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1" change in level at slope by men's restroom in no wake zone	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		1/4 max 1/4 1/4 1/2 1/2 1/2
470	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4725884 , -98.251660 2]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.25" gap at entry to shelter by picnic 63	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demonst doction of transf The filter of transfer of t
471	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4719648 -98.253763 1]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	fire box projects 6.75" at restroom in no wake zone	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
472	South Shore (SS), Day Use Unit: SS - Exterior Accessible Route	[28.4719554 -98.253771 1]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.8% slope in rear of no wake zone restroom	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
		I				1		
473	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723857 -98.251676 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	men's- 3.75" clearance on push, sign in clearance on pull, 10lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding A Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
474	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.472388, -98.251662 9]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
475	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723951 -98.251644 1]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	urinal 49" AFF, hook 66" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		to max
476	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4724045 -98.251665 6]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	2 standard, 1 ambulatory, 1 urinal	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
477	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4724234 , -98.251660 2]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		
478	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4724045 -98.251654 8]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	metal side - 22" centerline, tile side 20" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		UIEU 09
479	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723857 -98.251681 7]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door has no hardware on either side	Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
480	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723998 -98.251649 5]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	extends 47" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
481	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723998 -98.251660 2]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	.75" below is toilet paper	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" above the finished floor (AFF) and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
482	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4723951 , -98.251649 5]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	too close to front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		ymu gy umu gy 7-9
483	South Shore (SS), Day Use Unit: SS - Men's Restroom	,	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		
484	South Shore (SS), Day Use Unit: SS - Men's Restroom	[28.4724045 -98.251660 2]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	3% slope at sink	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
485	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723951 -98.251660 2]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	WOMEN	
486	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723998 , -98.251649 5]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook in stall 65" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		do max
487	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723998 -98.251665 6]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	3 standard, 1 ambulatory stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
488	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4724092 -98.251654 8]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		
489	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723762 -98.251665 6]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	tile side - 22.5" centerline , metal side - 19.5" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		uite 09

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
490	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.472408, -98.251648 1]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door hardware pinch on interior side, missing on pull, not self closing	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
491	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723974 -98.251649 5]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	both extend 46" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
492	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723951 -98.251644 1]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper too close to front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		y un straight of the straighto
493	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4724069 -98.251646 8]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		
494	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4724045 -98.251652 2]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	5" gap at drain	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
495	South Shore (SS), Day Use Unit: SS - Women's Restroom	[28.4723951 -98.251676 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a vertical change greater than 1/4 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	women's- 3.5" clearance on push, 13lbf, 2.7% slope, lipped threshold, 1" change in level	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, repair, provide beveled threshold. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		
					I			
496	South Shore (SS), Day Use Unit: SS - Boating/ Fishing/ Swimming	[28.4723149 , -98.249407 1]	The minimum number of boarding piers are not accessible. Where boarding piers are provided at boat launch ramps, at least 5 percent, but no fewer than one, of the boarding piers be accessible.	pier at ramp by 46 doesn't seem to be in working order, lots of overgrowth issues, seemed a bit unstable	If boat ramp is used, provide accessible boarding pier at boat launches free of CILs and correct the slope of the accessible route to the pier.	2015 ABAAS Section: F235.3 2010 ADAS Section: 235.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
497	South Shore (SS), Day Use Unit: SS - Boating/ Fishing/ Swimming	[28.4733948 -98.251375 9]	The minimum number of boarding piers are not accessible. Where boarding piers are provided at boat launch ramps, at least 5 percent, but no fewer than one, of the boarding piers be accessible.	no route to piers at main boat ramp due to excessive slopes, no clear ground space	Provide 5%, but not less than one accessible boarding pier at boat launches.	2015 ABAAS Section: F235.3 2010 ADAS Section: 235.3		
498	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4932783 , -98.247215 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.25" gap at entry to outlook shelter by dam	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Hermanet disciplice of transf
499	South Shore (SS), Day Use Unit: SS - Park Elements	[28.472823, -98.249641 8]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	fish cleaning by shelter 46 - 38.5" AFF	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		Kine Sala Sala Sala Sala Sala Sala Sala Sal

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
500	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4729444 , -98.249688 8]	Element meets all standards and requirements	picnic shelter 46 complies	None	2010 ADAS Section: N/A		
501	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4730246 -98.249793 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	covered picnic table 47 - 1" gap at entry, 2" gap at corner	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Administration of bandless of the second sec
502	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4732604 -98.250989 6]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	fish cleaning by main boat ramp - table 39" AFF	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		King Sharp and King S

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
503	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4733099 -98.250978 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	fish cleaning by main boat ramp - 8" gap at entry	Correct or fill gaps to be max .5".	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Amart dada dha dha dha
504	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4732545 -98.250923 9]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	fish cleaning by main boat ramp - no route to trash	Relocate garbage can to be along accessible route.	2010 ADAS Section: 206.2.2, 206.2		
505	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4732486 -98.250984 3]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	fish cleaning by main boat ramp - 4" gap, 8" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		A mark data of start

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
506	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4726768 , -98.251079 5]	There is no accessible route to the 7 spigots in the main parking lot. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to 7 of 7 spigots in main parking lot	Create an accessible route with crushed stone or other outdoor material from parking or walkway to 2 spigots.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSULE DATABACES
507	South Shore (SS), Day Use Unit: SS - Park Elements	[28.472665, -98.251534 1]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	not numbered, metal roof, picnic area by men's restroom at main boat ramp - 1" gap at entry	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Auronaut daudiou shtuari Auronaut daudiou shtuari Auronaut daudiou shtuari Munimetari daudiou shtuari daudiou shtuari Munimetari daudiou shtuari daudiou shtuari Munimetari daudiou shtuari daudiou shtuari daudiou shtuari daudiou shtuari daudiou shtuari Munimetari daudiou shtuari dau
508	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4726167 -98.251691]	Element meets all standards and requirements	overlook by men's at main boat ramp complies, wheel chair space offered on sides	None	2010 ADAS Section: N/A		
509	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4723951 -98.251740 7]	Outdoor rinsing showers shall provide at least one hand-held shower spray unit with a hose 59 inches (1500 mm) long minimum. The hand-held shower spray unit shall have at least one fixed position located 15 inches minimum (380 mm) and 48 inches (1220 mm) maximum above the ground. EXCEPTION: Where vandalism is a consideration, a fixed shower head located at 48 in (1220 mm) above the ground shall be permitted in place of a hand-held shower spray unit.	outdoor rinsing shower, fixed head only - 79" AFF	Remount or replace shower head with one that is hand held and mounted with one fixed position 15" to 48" above the ground; in the alternative, mount a fixed shower head at 48" above the ground as a smart practice.	2015 ABAAS Section: 1011.7, 1011.7 EXCEPTION		

Finding Are Number	rea Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
(S Ur	(SS), Day Use	[28.4723951 -98.251735 3]	There is no accessible route to the outdoor rinsing shower. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to outdoor rinsing shower due to - 6" change in level, 1" gap	Repair, bevel, or ramp CIL along AR. Correct or fill 1" gap along AR.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
511	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4723633 , -98.25175 54], [28.4721841 , -98.252251 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	from restroom by main boat ramp to rear lot/ shelter - 1.25" gap at beginning, .75" 2 squares in, 1.25" five squares in, 1" eight squares in, 1" 11 squares in, 1.5" gap 21 squares in, 1" gap 24 squares in 24 squares in	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		demonstrational relief.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Are Number	ea Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
512 S (S U	South Shore SS), Day Use Jnit: SS - Park Elements	(28.4723291 -98.252191 3]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	shelter behind main restroom building - 0 of 5 picnic tables comply	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
513	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4723574 -98.252207 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	shelter behind main restroom building - .75" gap at entry, 1" gap in middle of path, 1" gap at entry,	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		And the second s
514	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4723291 -98.252239 6]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	shelter behind main restroom building - 0 of 3 tables comply	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
515	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4714355 ,-98.254310 2]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	shelter by picnic 63 - 2" gap at entry	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Annual disclore of load
516	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4711148 , -98.25473]	The running slope of walking surfaces shall not be steeper than 1:20.	5.8% slope on top of path to 58 and 59	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
517	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4710853 ,-98.254756 8]	The accessible route of travel contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.4% on turn to path at 58	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
518	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4711926 -98.254789]	Element meets all standards and requirements	shelters 58 and 59 comply	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
519	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4710806 -98.254857 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.25" gap at entry to 58, 1" gap at entry to 59	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		Annual Studies of Fand
520	South Shore (SS), Day Use Unit: SS - Park Elements	[28.4480599 ,-98.305527]	There are no or not enough accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of (XX) parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of (XX) being designed as van accessible.	wildlife management reservation - site had multiple put outs along highway, 0 of 5 ADA stalls, need hunting permit to use	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		Description Benchmarking register 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
521	South Shore (SS), Day Use Unit: SS - Maintenance	[28.4675898 -98.251169 4]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	20" width, non compliant surface at gate, no route to 2 sheds, both have knobs and changes in level, knob on caution door, 3" change in level, door gets stuck, screen door to break room - requires pinch, 3" change in level	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace doors with doors having 80" overhead clearance and 32" clear width. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
522	South Shore (SS), Day Use Unit: SS - Maintenance	[28.4675379 -98.251139 9]	Element meets all standards and requirements	break room complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
523	South Shore (SS), Day Use Unit: SS - Maintenance	[28.4675356 -98.251138 5]	The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor. EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11.	3" change in level, 49.5" window, lacks hardware on push	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp. For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" AFF.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
524	South Shore (SS), Day Use Unit: SS - Maintenance	[28.4675261 -98.251155 9]	There is no accessible route to the picnic table. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	no route to picnic at maintenance, non compliant table	Create an accessible route with crushed stone or other outdoor material from parking or walkway to picnic table. Replace picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESULC ENTRACES

Finding Area I Number	Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
(SS) Ui	S), Day Use	.98.251161 3]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	restroom - knob, clearance reduced by toilet on push, exterior door - 48.5" window, knob, clearance on back pull lacks due to surface	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Provide required maneuvering clearance on push and pull side of doors. Replace hardware with lever hardware Replace doors with ones having sidelight viewing windows max 43" aff.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
(SS) Ui	S), Day Use	6]	The restroom is not compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lavatory. The entry door does not contain the required minimum maneuvering spaces on the pull/push sides. The entry door encroach into the required clear floor space for fixtures. Grab bars are missing and/or incorrectly installed. Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both.	non compliant restroom, not in use	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	2015 ABAAS Section: 603.1 2012 TAS Section: 603.1 2010 ADAS Section: 603.1		GO" MIN. CLEAR GOT MIN. GOT MIN. GOT MIN. GOT MIN.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
527	South Shore (SS), Day Use Unit: SS - Residence	[28.4672078 -98.253779 1]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	gravel lot at residence	Create AR with crushed and compacted stone or similar outdoor material to residence entry.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
						-		
528	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719188 -98.253693 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	men's- exceeds 30 lbf, 4.1% slope	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
529	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719047 -98.253724 2]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	MEN	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
530	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719388 -98.253696]	Knee clearance at 27 inches off the floor is not 8 inches minimum deep. The knee clearance, measured from the bottom of the apron or the outside bottom edge of the lavatory, must be 27 inches at a point located 8 inches back from the front edge and continuing to 11 inches minimum in depth at 9 inches above the floor. The top of the lavatory rim may be no higher than 34 inches.	knee clearance 24.25" AFF	Replace sink with one providing 27" knee clearance that is a min 8" deep	2015 ABAAS Section: 306.3.1, 306.3.2, 306.3.3, 306.3.4, 306.3.5 2012 TAS Section: 306.3.2, 306.3.3, 306.3.4, 306.3.5, 306.3.1 2010 ADAS Section: 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.4, 306.3.5, 306.3.1		Tor clearance 6° deep tor soace
531	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719188 -98.253728 2]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	2 standard, 1 ambulatory, and 1 urinal	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
532	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719259 -98.253708 1]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42.25" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
533	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719235 -98.253712 1]	The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	tile side - 24" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		uiu 09 35-37
534	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719094 -98.253696]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door lacks hardware, not self closing	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
535	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719141 -98.253726 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	tile side - extends 46" to grab bar end, metal side - extends 47" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	<image/>	
536	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719141 -98.253704]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper roll on side of grab bar	Relocate toilet paper roll to provide minimum 12" above the grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
537	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4719188 -98.253716 1]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted too close to the front of the toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		r.g.
538	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.47192, -98.253742 9]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		North State
539	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.471933, -98.253738 9]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap, debris	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
540	South Shore (SS), Day Use Unit: SS - Mens Restroom Between No Wake Zone	[28.4718988 -98.253726 8]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	3% slope at urinal	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
541	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719094 -98.253720 1]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign lacks Braille, raised characters, and International Symbol of Accessibility	Replace sign with one of contrasting colors that includes Braille, raised characters, and the symbol of accessibility and mount on the wall, latch side of the door, 48" to the baseline of the lowest character and 60" to the baseline of the highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
542	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719188 -98.253714 8]	Knee clearance at 27 inches off the floor is not 8 inches minimum deep. The knee clearance, measured from the bottom of the apron or the outside bottom edge of the lavatory, must be 27 inches at a point located 8 inches back from the front edge and continuing to 11 inches minimum in depth at 9 inches above the floor. The top of the lavatory rim may be no higher than 34 inches.	knee clearance 24" AFF	Replace sink with one providing 27" knee clearance that is a min 8" deep	2015 ABAAS Section: 306.3.1, 306.3.2, 306.3.3, 306.3.4, 306.3.5 2012 TAS Section: 306.3.2, 306.3.3, 306.3.4, 306.3.5, 306.3.1 2010 ADAS Section: 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.3, 306.3.2, 306.3.1		The clearance the clearance 6' deep lae space
543	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719047 -98.253709 4]	The operable part is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hook 65" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		the second secon

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
544	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	,	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	3 standard, 1 ambulatory	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
545	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719153 , -98.253710 7]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 42" width	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		
546	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone		The toilet is not located within the range to the side wall or partition. The centerline of the toilet shall be 17 inches minimum and 19 inches maximum side wall or partition in the ambulatory accessible toilet compartment.	tile - 22" centerline, metal - 20" centerline	Remount toilet to 17" to 19" from the side wall to center line in ambulatory stalls	2015 ABAAS Section: 604.9.1 2012 TAS Section: 604.9.1 2010 ADAS Section: 604.9.1		UIII 00 35-37

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
547	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719082 -98.253717 5]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door hardware missing on pull, pinch on push, not self closing	Adjust stall door to be self-closing Replace stall hardware with hardware operable without a tight pinch or grasp on both sides of the stall door	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
548	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719188 -98.253714 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	metal side extends 46" to grab bar end, tile extends 45.5" to grab bar end	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	<image/>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
549	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4718976 -98.253698 7]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper mounted behind front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		y un the second
550	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4719117 ,98.253737 6]	An item or items project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		A CONTRACT OF A
551	South Shore (SS), Day Use Unit: SS - Women's Restroom Between No Wake Zone	[28.4718999 -98.253728 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	women's- 3.7% slope, 15lbf	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		