# **Access Audit Site Report**





Engineering with Precision, Pace & Passion. (224) 293 - 6451 www.wtengineering.com

Garner State Park
234 RR 1050
Concan, TX 78838
Accessibility Evaluation
Inspection Date: 10/06/2021
Inspectors: Tanya Scheibe

# Table of Contents

er Letterer Letter
RNER STATE PARK PROGRAM REPORT 202301
lings
ypress Springs Group Camping Area
eadquarters Area
ersimmon Hill Camping Area
ve Oak Camping Area
io Frio Camping Area
iver Crossing Camping Area
hady Meadows Camping Area
mployee Spaces
akmont Camping Area
ecan Grove Camping Area
ample Cabins
ample Shelter Campsites
isitors Center
rails



July 28, 2023

Jessica Burke, ADA Coordinator Support Resources Texas Parks and Wildlife Department 4200 Smith School Road Austin, TX 78744

Dear Jessica,

Thank you for the opportunity to be of service to you by performing an accessibility evaluation for the Garner State Park located at 234 RR 1050, Concan, TX 78838. The facility was inspected on 10/06/2021.

We recommended that all barriers that are identified in this evaluation recommended in one of the phases below, be removed as soon as possible. A transition plan should be developed to assist in planning the removal of all barriers. To help with this, we have identified all barriers on a finding by finding basis with a phase identifier as follows:

- 1 (Phase 1): Should be completed immediately. This category includes findings that have little or no cost, were in violation of the codes at the time of construction, or pose an imminent safety threat.
- 2 (Phase 2): Should be completed as soon as possible. Includes findings that would remove barriers to the greatest number of people to your goods and services and findings new to the technical standards such as recreation elements
- 3 (Phase 3): Should be completed as soon as possible, but there may be other items that will provide greater access to persons with disabilities. This category includes findings that have a high financial impact on the entity, are subject to standards not yet final, or involve a partner entity.
- 4 (Option): Not necessary to complete, because other sites exist that meet Title II requirements for program access, or retrofit is technically infeasible, or variance is a construction tolerance.
- 5 (Smart Practice): Should be completed but not necessarily required. This category includes findings and or elements that were in compliance with previous editions of the codes and standards but have since changed. This category also includes techniques or elements that are not a part of the federal or state requirements, but are suggested in advisory language, or have been successfully implemented by other entities. Generally, these items are easily modified to provide the greatest degree of access as well as compliance with the most current codes and standards.

Periodic maintenance to ensure continued accessibility is essential in providing a safe and usable environment. Parking lot markings, signage, door opening pressures, and maintaining clear floor space at doors and other elements and fixtures, available to the public, must be part of an ongoing maintenance schedule.





If you have any questions regarding this report or would like to schedule a meeting with myself and your architect, attorney, or contractor, please feel free to contact me.

## Legend of Abbreviations:

AFF... Above the finished floor

AGL... Above Ground Level

AR... Accessible Route

CIL... Change in Level

CFS... Clear Floor Space

EPC... Elevated Play Component

GLPC...Ground Level Play Component

Sincerely,

Zanya Schule

Tanya Scheibe, RAS #1369



# TEXAS PARKS AND WILDLIFE DEPARTMENT GARNER STATE PARK

# AMERICANS WITH DISABILITIES ACT COMPLIANCE INITIATIVE PROGRAM AND POLICY REPORT JULY 28, 2023

#### **INTRODUCTION**

The Texas Parks and Wildlife Department (TPWD) is subject to the many requirements of the Americans with Disabilities Act (ADA). To assist it in meeting those requirements, TPWD retained The WT Group, LLC (WTG) Accessibility Practice in 2021.

Title II of the ADA applies to TPWD sites, along with 89,000 other units of state and local government. WTG has a broad scope of work that matches the ADA requirements found in title II. It includes:

- Schedule and conduct project management meetings;
- Conduct access audits of 89 sites, including Garner State Park;
- Prepare a site report that describes deficits at Garner State Park, and suggests solutions to those deficits:
- Provide guidance regarding the programs or opportunities Texans can enjoy at Garner State Park;
- Conduct community engagement events to determine the access preferences and priorities of Texans who visit Garner State Park;
- Provide an Garner State Park Transition Plan that identifies deficits, notes solutions, identifies the officer responsible for barrier removal, and notes the phase or timing of barrier removal;
- Provide a GIS shapefile regarding the accessibility of Garner State Park;
- Provide a method of tracking barrier removal at Garner; and
- Report to TPWD leadership and stakeholders.

#### THIS REPORT

This report addresses program and policy advice, and then the WTG observations of deficits at Garner State Park. Other deliverables are provided under separate cover.

#### What is a Program?

A unit of state or local government is required to make the "programs" it offers accessible to people with and without disabilities. The term "program" is broadly defined as an opportunity made available by the state to the public, and the term public includes both people with and without disabilities. As an example, if a state park offers camping it must make certain that some campsites are of an accessible design.

The number to be made accessible is called scoping and it is usually a percentage or ratio of the similar sites. For example, if a state park has outdoor constructed features such as grills, fire pits, and benches, it must make 20% of an accessible design. Those 20% accessible must be dispersed throughout the park.

In an ADA context, "programs" at a state park or state natural area include but are not limited to:

Hiking	Fishing
Camping	Bird Watching
Swimming	Playgrounds
Lodging	Beaches
Boating	Interpretive activities
Parking	Visitor Centers
Trams	Picnicking
Sports fields	Viewing areas
Restrooms	Grilling

#### The Federal and Texas Accessibility Standards

The current Texas Accessibility Standards (TAS 2012) became effective in 2012 after an amendment process. Those Standards are almost identical to the federal 2010 Standards for Accessible Design, and both effectively address parking, entries, restrooms, and other typical building elements. They also address playgrounds, boating and fishing areas, and sports fields and courts.

They do not however address some of the assets at Garner State Park. Trails, campsites, and picnic areas are not yet a final and enforceable state or federal standard.

That will change at the end of 2023 or early 2024. The Texas Department of Licensing and Regulation (TDLR) has signaled its intent to adopt the pending federal guidance for key outdoor assets integral to TPWD sites like Garner State Park. This includes trails, beaches, campsites, picnic areas, viewing areas, and constructed park assets like grills, fire pits, and benches.

In discussing the Standards, it is important to use the correct definition of park assets. Most definitions are found in TAS 2012 at section 106. As noted above, TDLR plans to add the pending federal guidance regarding some outdoor areas to TAS. It is important to remember that the Standards set the floor, not the ceiling. Making a slope more gentle, or a route wider, is always a smart practice with universal design benefits.

Some selected definitions of park assets common to TPWD are noted below.

- Trail: A pedestrian route developed primarily for outdoor recreational purposes. A
  pedestrian route developed primarily to connect elements, spaces, or facilities within a
  site is not a trail.
- Trailhead: An outdoor space that is designed by an entity responsible for administering
  or maintaining a trail to serve as an access point to the trail. The junction of two or more
  trails or the undeveloped junction of a trail and a road is not a trailhead.
- **Picnic Facility**: A site or portion of a site developed for outdoor recreational purposes that contains picnic units.
- Picnic Unit: An outdoor space in a picnic facility used for picnicking that contains outdoor constructed features.
- Outdoor Constructed Features: Picnic tables, fire rings, grills, fireplaces, wood stoves, trash and recycling receptacles, water hydrants, utility and sewage hookups, outdoor rinsing showers, benches, and viewing scopes provided at outdoor recreation facilities.
- Camp Shelter: A partially enclosed structure that provides campers and hikers cover from weather and that does not contain plumbing fixtures or kitchen appliances. Camp shelters are not transient lodging facilities or residential dwelling units.
- Camping Facility: A site or portion of a site developed for outdoor recreational purposes that contains camping units.
- Camping Unit: An outdoor space in a camping facility used for camping that contains outdoor constructed features, parking spaces for recreational vehicles, tent pads or tent platforms, or camp shelters.
- Viewing Area: An outdoor space developed for viewing landscapes, wildlife, or other points of interest.
- **Boarding Pier**: A portion of a pier where a boat is temporarily secured for the purpose of embarking or disembarking.
- **Boat Launch Ramp**: A sloped surface designed for launching and retrieving trailered boats and other watercraft to and from a body of water.
- Gangway: A variable-sloped pedestrian walkway that links a fixed structure or land with a
  floating structure. Gangways that connect to vessels are not addressed by these
  Standards.
- **Transition Plate**: A sloping pedestrian walking surface located at the end(s) of a gangway.
- Play Area: A portion of a site containing play components designed and constructed for children.
- Play Component: An element intended to generate specific opportunities for play, socialization, or learning. Play components are manufactured or natural; and are standalone or part of a composite play structure.

Two other key outdoor assets are not included in the definitions. Both are defined below.

- Beach access routes: A beach access route (BAR) connects an entry point to the beach to the water, as defined below:
  - At a tidal beach, to the high tide level
  - At a river beach, to the mean high water level
  - At a lake, pond, or reservoir beach, to the normal recreation water level

A BAR can be temporarily placed at a beach for all hours the beach is open, and need not be a permanent fixture.

 Outdoor Recreation Access Routes (ORAR): A route that connects outdoor recreation assets at an outdoor recreation site. An ORAR is not a trail.

### **Conditions for Exceptions at Certain Outdoor Recreation Assets**

In developing the scoping and technical requirements for accessibility at beaches, trails, and other outdoor developed areas, a wide net was cast to assure a variety of perspectives. The process involved:

- Officials from states with beaches and trails
- Officials from local entities with beaches and trails
- People with disabilities
- Landscape architects and civil engineers
- Parks and recreation officials

Throughout the process, all agreed that there are times that an existing beach, a new beach, an existing trail, or a new trail cannot meet the technical requirements for accessibility. The belief of regulatory bodies however is that these conditions should arise infrequently. The four conditions for exception are defined and discussed below.

• Section 1019.1.1: Compliance is not practicable due to terrain.

This is best clarified as naturally occurring terrain. It is applicable to both existing trails, and new trails. When locating and designing new trails, making the trail accessible should be a very high priority. This is especially important at Garner State Park, as only two of the 21 trail and trail segments throughout the Park are accessible.

 Section 1019.1.2: Compliance cannot be accomplished with the prevailing construction practices.

This is best clarified as a reference to prohibitions on the use of foreign soil or motorized equipment. As an example, if a trail bed is being carved by TPWD staff and volunteers on their hands and knees, with pick axes, shovels, and hoes, all because of a prohibition on motorized equipment in the park, this exception may apply

 Section 1019.1.3: Compliance would fundamentally alter the function or purpose of the facility or the setting.

This is best clarified as having a clear understanding of the purpose of the asset. A sharply ascending trail in a mountainous West Texas state park may have the intended use of endurance training. To "flatten" the trail is possible from a design perspective, but the trail then loses its function or purpose.

 Section 1019.1.4: Compliance is limited or precluded by any of the following laws, or by decisions or opinions issued or agreements executed pursuant to any of the following laws:

Endangered Species Act (16 USC 1531 et seq.);

National Environmental Policy Act (42 USC 4321 et seq.);

National Historic Preservation Act (16 USC 470 et seq.);

Wilderness Act (16 USC 1131 et seq.); or

Other federal, State of Texas, or local laws the purpose of which is to preserve threatened or endangered species; the environment; or archeological, cultural, historical, or other significant natural features.

There are other mitigating factors regarding accessibility. Four are discussed below.

- Construction Tolerance (see 104.1.1 Construction and Manufacturing Tolerances): All
  dimensions are subject to conventional industry tolerances except where the requirement
  is stated as a range with specific minimum and maximum end points. This is likely most
  applicable in new construction, but may also apply to making transition plan retrofits.
- Equivalent Facilitation (see 103 Equivalent Facilitation): Nothing in these requirements
  prevents the use of designs, products, or technologies as alternatives to those
  prescribed, if they result in substantially equivalent or greater accessibility and usability.
  This is likely most applicable in new construction, but may also apply to making transition
  plan retrofits.
- Technical Infeasibility (see 106 Definitions): With respect to an alteration of a building or a facility, a condition wherein compliance with a requirement of this Standard has little likelihood of accomplishment because existing structural conditions would require removing or altering a load-bearing member that is an essential part of the structural frame; or because other existing physical or site constraints prohibit modification or addition of elements, spaces, or features that are in full and strict compliance with the minimum requirements. This is likely most applicable to making transition plan retrofits.
- Safe Harbor (see US DOJ title II section 35.151(c)): If a public entity has constructed or altered required elements of a path of travel in accordance with the specifications in either the 1991 Standards or the Uniform Federal Accessibility Standards, or TAS 1994, before March 15, 2012, the public entity is not required to retrofit such elements to reflect incremental changes in the 2010 Standards solely because of an alteration to a primary function area served by that path of travel.

It is important to note that the 1991 Standards and TAS 1994 did not address technical requirements for recreation assets, such as boating areas, fishing areas,

beaches, campsites, trails, picnic areas, playgrounds, sports fields, sports courts, and more. The Safe Harbor approach cannot be applied to such assets.

#### **Campsites**

We have sorted campsites into several categories. These include tent only campsites, recreational vehicle campsites, shelter sites, and sites that combine features in a hybrid approach, such as an RV site with utilities.

In evaluating Garner State Park, WTG used TAS 2012, the pending outdoor developed areas guidance, and smart practices that make public spaces and outdoor recreation assets more accessible to people with disabilities. We also applied the concepts of construction tolerance, technical infeasibility, safe harbor, equivalent facilitation, and other imitations on when a site must be made accessible.

#### What is Inclusion?

The title II regulation requires Garner State Park programs to be available in the most integrated setting. This is defined as the setting in which people with and without disabilities interact together. Using the camping example above, inclusive camping would locate accessible campsites amidst inaccessible campsites to facilitate interaction between campers with and without disabilities.

While all programs must be inclusive, that does not mean that everyone with every type of disability or health condition must be allowed to participate in every program. The concept of essential eligibility allows Garner State Park to apply neutral conditions to determine who uses programs.

Again, using camping, if there are 20 campsites and a person with a disability is the 21<sup>st</sup> person to register, the neutral concept of "capacity" applies and that camper has no place to camp. If that camper is the 20<sup>th</sup> person to seek camping but does not pay the campsite fee, the neutral concept of paying the same fees can apply and that camper will not camp at Garner.

#### **How Can Programs in General Be Made Accessible?**

The title II regulation at section 35.150(b) lists a number of ways to make Garner State Park programs accessible. These include but are not limited to:

- Removing architectural barriers;
- Removing communication barriers;
- Changing rules and policies;
- Providing additional staff training;
- Providing different staff ratios;
- Providing adaptive equipment;

- Providing auxiliary aids and services such as a sign language interpreter;
- Providing accessible transportation when transportation is part of the opportunity;
- Reassignment of services to accessible locations;
- Conducting duplicate opportunities, one in accessible location and the other in an inaccessible location;
- Designing and constructing new facilities that are therefore fully compliant;
- Home visits; and
- Other methods that make programs accessible.

Garner staff should be aware of, and ready to, provide such modifications.

#### Are the Garner State Park Programs Accessible and Inclusive?

In our review of the opportunities available at Garner, we saw:

- One playground at Shady Meadows;
- One boating area at Oakmont;
- One swimming area at Pecan Grove;
- 12 RV only sites at Shady Meadows;
- 342 hybrid tent/RV campsites at Pecan Grove, Oakmont, Shady Meadows, River Crossing, Rio Frio, Live Oak, and Persimmon Hill;
- 37 shelter campsites at Pecan Grove, Oakmont, and River Crossing;
- 17 cabins at Oakmont;
- Five bunkhouses at Cypress Springs;
- 21 trails throughout the Park;
- 15 picnic areas at Oakmont and Cypress Springs;
- Two volleyball courts at Oakmont and Rio Frio;
- One basketball court at Oakmont; and
- One miniature golf course at Oakmont.



#### Of these, the accessibility status and our recommendation is:

- Make the Shady Meadows playground accessible;
- Make the Oakmont boating area accessible;
- Make the Pecan Grove swimming area accessible;
- Make two of the 12 RV only sites at Shady meadows accessible, leaving the remaining ten as is and inaccessible until later altered for another purpose;
- Make 11 of the 342 hybrid tent/RV campsites throughout the Park accessible and disperse among the different camping areas, leaving the remaining 331 as is and inaccessible until later altered for another purpose;
- Make three of the 37 shelter campsites at Pecan Grove, Oakmont, and River Crossing accessible and disperse the accessible sites among these areas, leaving the remaining 34 as is and inaccessible until later altered for another purpose;
- Maintain the designated accessible cabin and implement the site report retrofits;
- Make one more of the 17 cabins accessible, leaving the remaining 15 as is and inaccessible until later altered for another purpose;
- Maintain the five accessible bunkhouses and implement the site report retrofits;
- Make seven of the 21 trails or trail segments accessible, and focus on retrofits needed for the two trails marked as accessible;
- Make three of the 15 picnic areas at Oakmont and Cypress Springs accessible and disperse throughout the Park, leaving ten picnic areas as is and inaccessible until later altered;
- Make either one of the two volleyball courts at Oakmont or Rio Frio accessible, leaving one as is and inaccessible until later altered for another purpose;
- Make the basketball court at Oakmont accessible; and
- Make the miniature golf course at Oakmont accessible.

#### **Camping Clarification**

A number of campsites of each type provided within the park (see the Outdoor Developed Area Guidelines at 244.2, which will eventually be a part of the revisions to TAS 2012) must be retrofit to make the program of camping accessible, and to meet the soon-to-be-adopted State of Texas standard.

We have sorted campsites into three types: RV only, hybrid (usable by tent or RV), and shelters. TPWD or Garner staff can also distinguish these sites by amenities provided (covered tables, water only, electric, scenic views, etc.).



TPWD is prohibited from using contractors or concessionaires that discriminate on the basis of disability. If concessionaires are to provide outdoor recreation experiences at the Park, those must be accessible to and inclusive of people with disabilities.

#### Conclusion

The staff at Garner State Park offer experiences and assets desired by park visitors. Those same experiences and assets must be accessible to and usable by people with disabilities. See the following site report to identify barriers and recommendations for barrier removal.

JNM/TRS/GARNER STATE PARK PROGRAM REPORT 202301



Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
1	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.60264, -99.73267]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap to women's restroom	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	More and designed of train and train
2	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026695 -99.732666 5]	The accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.5% to women's restroom	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
3	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026435 -99.732620 8]	maneuvering clearances shall comply with 302. Changes in level are not permitted.	Men's restroom door - maneuvering clearance ramped on pull side. garbage can in push side maneuvering clearance	Correct or repair slope at doorway landing to max 2.08% in any direction for level Relocate storage or other objects to provide required maneuvering clearance	2015 ABAAS Section: 404.2.4.4, 404.2.4.4 EX CEPTIONS: 1, 404.2.4.4 E XCEPTIONS: 2  2012 TAS Section: 404.2.4.4, 404.2.4.4 Exception 1, 404.2.4.4 Exception 2  2010 ADAS Section: 404.2.4.4, Exception: 404.2.4.4 Exception: 404.2.4.4 Exception: 404.2.4.4 Exception: 404.2.4.4 Exception: 404.2.4.4 Exception:		
4	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026378 , -99.732665 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	Men's shower door - wall and curtains pull side	Provide required maneuvering clearance around pull side of door Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	2015 ABAAS Section: 404.2.4.1, 404.2.4.4 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1		The state of the s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
5	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026489 -99.732674 1]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	Sink rim is 35" above finished floor	Lower sinks to max 34" above the finished floor (AFF) to front of rim.	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS	Exec cheatence  Too cheatence  6' deep toe space
6	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732676 8]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipes lack insulation	Insulate exposed pipes under one sink.	Section: 606.3  2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5	ACCESSIBLE LAVATORY  Fig. 400 to Polycology
7	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026326 -99.732676 8]	There are not enough accessible toilet compartments. The room contains 1 toilet compartments. A minimum of 1 must be wheelchair accessible.	Ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1	
8	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732668 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	Grab bars installed 13" from rear wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	The same of the sa

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
9	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026477 -99.732670 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	Toilet paper dispenser installed 9" above side bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	
10	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026466 -99.732671 5]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Hand dryer projects 5" into the circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	2 3 4 5 0 N
11	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026477 -99.732678 2]	The accessible path of travel contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	2.6% slope at drain, 3.2% slope at shower drain	Correct or repair cross slope of AR to max 2.08%.	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3	ALACK TOTAL

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
12	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732676 8]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Coat hook installed at 72.5" AFF	Remount at least one hook to max 48" AFF.	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
13	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026407 -99.732683 5]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	Shower dimensions are 40" x 40"	Correct transfer shower to compliant 36" by 36" clear inside dimension	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		See at Control Williams of the control of the contr
14	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732674 1]	Shower controls are in the incorrect location In transfer type shower compartments, the controls, faucets, and shower spray unit shall be installed on the side wall opposite the seat 38 inches (965 mm) minimum and 48 inches (1220 mm) maximum above the shower floor and shall be located on the control wall 15 inches (380 mm) maximum from the centerline of the seat toward the shower opening.	Shower controls are closer to back wall from the seat centerline	Remount shower controls to the correct location in the transfer shower.	2015 ABAAS Section: 608.5.1 2012 TAS Section: 608.5.1 2010 ADAS Section: 608.5.1	<b>B</b>	side wall  16 max  330  Xillian and a side wall  16 max  330  Xillian and a side wall  16 max  330  Xillian and a side wall  80  80  80  80  80  80  80  80  80

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
15	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732679 5]	The shower seat does not have a compliant space between it and the wall. The folding seat must be mounted 17-19 inches above the floor, and have a maximum space of 1-1/2 inches between the edge of the seat and the side wall and 2-1/2 inches maximum to the seat wall.	2.5" space and 16" from back wall	Remount shower seat to the correct location and height in the shower.	2015 ABAAS Section: 610.3.2 2012 TAS Section: 610.3.2 2010 ADAS Section: 610.3.2		Seed 13 to 15 to 1
16	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.60262, -99.73267]	The fan control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	Fan control require pinch or grasp	Replace fan control with an operable part usable without a tight pinch or grasp.	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
17	Cypress Springs Group Camping Area: Cypress Springs Men's Restroom	[29.6026419 -99.732683 5]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 34 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.		Lower operating mechanisms to max 48" AFF to highest operable part; leave as is if employee only operated.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		20 mm
	Π	I	T	Ī	T	I		Sacrate 1
18	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026396 , -99.732678 2]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	Sink rim 34.25" above finished floor	Lower sinks to max 34" AFF to front of rim.	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		Fore clearance  See clearance

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
19	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026372 , -99.732671 5]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipes are not insulated	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAWYORY
20	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026396 -99.732684 8]	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of 1 must be wheelchair accessible.	ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
21	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026337 -99.732671 5]	The stall door fails to comply with all of the door requirements. The stall door must be self-closing.	Stall door is not self- closing	Adjust stall door to be self-closing.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
22	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026337 -99.732672 8]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	Bar installed 13.75" from rear wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1	# P # # 11 10 10 6
						2010 ADAS Section: 604.5.1	
23	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026454 -99.732676 8]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	Toilet paper dispenser installed 11.5" above grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	
24	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026477 -99.732679 5]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Hand dryer projects 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
25	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026384 -99.732680 8]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Hook installed at 72.75"	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5	
26	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026407 ,-99.732670 1]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	Shower dimensions: 40" x 40"	Correct transfer shower to compliant 36" by 36" clear inside dimension	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1	See at
27	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026489 -99.732676 8]	The shower seat does not have a compliant space between it and the wall. The folding seat must be mounted 17-19 inches above the floor, and have a maximum space of 1-1/2 inches between the edge of the seat and the side wall and 2-1/2 inches maximum to the seat wall.	2.5" from back wall	Remount shower seat to the correct location and height in the shower.	2015 ABAAS Section: 610.3.2 2012 TAS Section: 610.3.2 2010 ADAS Section: 610.3.2	22.23 sould see the see that th

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
28	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026447 -99.732682 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%.	Women's door - ramped pull side, garbage can push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
29	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026454 , -99.732678 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. All interior doors must be maintained so that the operating pressure does not exceed 5 lbf to open.	Women's shower door - wall and curtains in maneuvering clearance on pull side, 7 lbf	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
30	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.60262, -99.73267]	The fan control is not accessible because it requires tight grasping, pinching or twisting of the wrist.	Fan control knob requires pinch, grasp or twist	Replace fan control with an operable part usable without a tight pinch or grasp.	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
31	Cypress Springs Group Camping Area: Cypress Springs Women's Restroom	[29.6026394 -99.732675 1]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	Hand dryer installed at 57"	Lower operating mechanisms to max 48" AFF to highest operable part; leave as is if employee only operated.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		Desc. Solvers and

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
32	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027909 -99.732232 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The threshold has a gap greater than 1/2 inch wide. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	Bunk 3 (typical)- knob, bench back pull side, beds pull side, 2" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		
33	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027793 , -99.732219 4]	Element meets all standards and requirements	Bunk 3 - access to 2 beds at front of room of 8 total	None	2010 ADAS Section: N/A		
34	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.602783, -99.732214 1]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	Bunk 3 - light switches behind bench and door, lacks clear floor space	Remove, or relocate storage in CFS at fixtures and operable parts along the AR Provide required 30" by 48" CFS at operable parts For deficit, leave as is, employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
35	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.60279, -99.732226 2]	The air conditioner is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	Bunk 3 - Air conditioner controls at 72" AFF	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max 48 max 48 max
36	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027918 -99.732326]	The accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.6% from parking to bunk 3	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3	BANANT : III BANAN	The same of the sa

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
37	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027334 , -99.73223 98], [29.6028721 , -99.732364 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap at bunk 3, 1" gap to bunk 2, 1" gap at bunk 2	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3		destinant direction of honors.  Interplacements of honors of honors of honors.  St. max.
38	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027369 ,-99.73223 98], [29.6028943 ,-99.732357 8]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1.5" CIL at bunk 3, 1.25" CIL at bunk 2	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
39	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028343 , -99.732413]	The running slope of walking surfaces shall not be steeper than 1:20.	6.9% running slope	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	
40	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028786 , -99.732552 1]	Element meets all standards and requirements	parking scoping complies- 19 standard, 1 accessible	None	2010 ADAS Section: N/A	
41	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028728 ,-99.732529 3]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	Lacks access aisle	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1	Assume a plan and the sear that a plan a pla
42	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028821 -99.732526 6]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 4 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 4 accessible stalls with a minimum of 1 being designed as van accessible.	Lacks aisle, stall less than 16'	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4	To A house of shoots have   To A house the state of the shoot of the

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
43	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028844 , -99.732510 5]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	Parking stall surface very loose	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		½ max ½ ½ ½ ½ ½ ½
44	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6028798 , -99.732526 6]	The access aisle is not located on an accessible route of travel to the accessible building entrance. Accessible parking spaces serving a particular building shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. In buildings with multiple accessible entrances with adjacent parking, accessible parking spaces shall be dispersed and located closest to the accessible entrances.	route of travel is through driveway	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk.	2015 ABAAS Section: F208.3.1 2012 TAS Section: 208.3.1 2010 ADAS Section: 208.3.1		
45	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027571 , -99.732199 8]	Water spouts at water hydrants and water utility hook-ups shall be 28 inches (710 mm) minimum and 36 inches (915 mm) maximum above the ground.	Water spout provided at each bunk, lacks accessible route, below reach range	Remount water spouts to 28" min or 36" max above the ground as a smart practice.  Create an AR to water spouts at each bunkhouse.	2015 ABAAS Section: 1011.6		
46	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6025243 , -99.732516 8]	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	Route leading from dining hall to river - narrow, rough stones, steps	Create an accessible route with surface that is firm and stable and connect from dining hall to river	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 44 mm A 45 mm 45 mm A 4

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
47	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6027437 ,-99.732189 6]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	1 table provided outside each of 5 bunks, lacks accessible route, lacks wheelchair space	Replace picnic table with one of an accessible design as a smart practice.	2015 ABAAS Section: 1011.4.2		
48	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6024277 -99.732286 2]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	0 of 6 picnic tables accessible behind dining hall	Replace 20% of picnic tables with one of an accessible design as a smart practice.	2015 ABAAS Section: 1011.4.2		
49	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6023828 , -99.732348 9]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	Grill and fire pit lack AR	Provide an accessible route (AR) to each element within the site.	2010 ADAS Section: 206.2.2, 206.2		
50	Cypress Springs Group Camping Area: Cypress Springs Bunks (5)	[29.6023819 , -99.732346 9]	Where provided, cooking surfaces shall be 15 inches (380 mm) minimum and 34 inches (865 mm) maximum above the ground.	Grill surface 38" above ground surface	Raise or lower cooking surface to be 15" min to 34" max above the ground; in the alternative, replace with a compliant surface as a smart practice.	2015 ABAAS Section: 1011.5.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
51	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025323 -99.732408 6]	The sink is not accessible. A clear floor space at least 30 inches by 48 shall be provided in front of a sink to allow forward approachThe clear floor space shall be on an accessible route and shall extend a maximum of 19 inches underneath the sinkSinks shall be mounted with the counter or rim no higher than 34 inches above the finish floorKnee clearance at least 27 inches high, 30 inches wide and 19 inches deep shall be providedHot water and drain pipes exposed under sinks shall be insulated or otherwise configured so as to protect against contact. There shall be no sharp or abrasive surfaces under sinksFaucet controls not require tight grasping, pinching or twisting of the wristThe force required to activate controls shall be not greater than 5 lb. Lever-operated, push-type and electronically controlled mechanisms are examples of acceptable designsSelf-closing valves are allowed if the faucet remains open for at least 10 seconds.		Replace sink with model that allows CFS and knee clearance 30" wide and 27" high while rim height is max 34" aff	2015 ABAAS Section: 606.2, 606.2 EXCEPTIONS: 1, 606.2 EXCEPTIONS: 4, 606.2 EXCEPTIONS: 5, 606.2 EXCEPTIONS: 7, 606.3, 606.4, 606.5  2012 TAS Section: 606.2, 606.2 Exception 1, 606.2 Exception 4, 606.2 Exception 5, 606.2 Exception 6, 606.2 Exception 7, 606.3, 606.4, 606.5  2010 ADAS Section: 606.2 Exception 1, 606.2 Exception 7, 606.3 Exception 7, 606.3 Exception 1, 606.2 Exception 1, 606.2 Exception 7, 606.3		No. of the control of

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
52	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025439 , -99.732403 2]	Controls for faucets shall comply with 309. Hand-operated metering faucets shall remain open for 10 seconds minimum. Operable parts shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. The force required to activate operable parts shall be 5 pounds (22.2 N) maximum.	kitchen- sink hardware requires tight grasp	Replace sink/shower hardware with one operable without a tight pinch or grasp.	2015 ABAAS Section: 309.4, 606.4 2012 TAS Section: 309.4, 606.4 2010 ADAS Section: 309.4, 606.4	
53	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025346 -99.732424 7]	The U-shaped kitchen is not wide enough. In U-shaped kitchens enclosed on three contiguous sides, clearance between all opposing base cabinets, counter tops, appliances, or walls within kitchen work areas shall be 60 inches.	kitchen- 44" from refrigerator to counter	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and appliances.	2015 ABAAS Section: 804.2.2  2012 TAS Section: 804.2.2  2010 ADAS Section: 804.2.2	60 min
54	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025544 , -99.732400 6]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	kitchen- garbage at 32" from sink edge	Relocate garbage to provide compliant 36" clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	24 max. 48 mm 24 max. 48 max.
55	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025533 -99.732395 2]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	kitchen75" CIL near drain	Repair, bevel or ramp CIL along AR to max .25"	2015 ABAAS Section: 303.3  2012 TAS Section: 303.3  2010 ADAS Section: 303.3	Умах Умах Умах Умах Умах Умах

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
56	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025486 -99.732389 8]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	kitchen- significant gaps, 3"+, around floor drain	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		The control of the co
57	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025533 -99.732389 8]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	dining room- 2.5" gap	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3		the control of the co

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
58	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025486 -99.732424 7]	The switches/controls are positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	dining room- light switch 53", heater 52", fan 60", lights 53.5", heater 52"	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1		10 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
59	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025451 -99.732404 6]	and gates shall comply with 404.2.4.	kitchen to dining room door- maneuvering clearance reduced by built in counter/storage	Provide required maneuvering clearance on push side of door	2015 ABAAS Section: 404.2.4.4, 404.2.4.1 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1	FIRE	The state of the s
60	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025486 -99.732392 5]	The door operating hardware is not accessible. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.		Replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		Lever Panic Bar Loop Handle Operating hardware must be contered between 34" and 48" above the floor or ground

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
61	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025556 -99.732400 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	kitchen exterior- 1.25" and 2.25" on approach	Correct or fill gaps to be max .5".	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		destinant described of Stand  Long, described in the animal of Stand  35 mass.
62	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025439 ,-99.732414]	The door operating hardware is not accessible. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	kitchen exterior door- knob hardware	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		Lever Panic Bar Loop Handle Operating hardware must be centered between 34" and 48" above the floor or ground

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
63	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025486 -99.732389 8]	The door must have a smooth surface within 10 inches of the floor on the push side. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. All gates, including ticket gates, shall meet all applicable specifications for doors.	kitchen exterior door - both doors have rot and damage on exterior push side	Provide kick plate on push side of door from floor to 10" AFF.	2015 ABAAS Section: 404.2.10 2012 TAS Section: 404.2.10 2010 ADAS Section: 404.2.10	
64	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025649 -99.732412 6]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	dining from parking door - 2.6% at right door and 4.8% left door	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
65	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025556 -99.732403 2]	Thresholds, if provided at doorways, shall be 1/2 inch (13 mm) high maximum. Raised thresholds and changes in level at doorways shall comply with 302 and 303. Changes in level of ½ inch (6.4 mm) high maximum shall be permitted to be vertical Changes in level between ¼ inch (6.4 mm) high minimum and ½ inch (13 mm) high maximum shall be beveled with a slope not steeper than 1:2. Changes in level greater than ½ inch (13 mm) high shall be ramped, and shall comply with 405 or 406.	dining from parking door75"+ CIL at left and right door	Repair, bevel or ramp CIL at doorway.	2015 ABAAS Section: 303.3, 404.2.5, 303.2, 303.4 2012 TAS Section: 303.3, 404.2.5, 303.2, 303.4 2010 ADAS Section: 303.3, 404.2.5, 303.2, 303.4		½ max 64
66	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025463 -99.732400 6]	The door operating hardware is not located within the compliant range. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be centered between 34 inches and 48 inches above the floor.	dining from parking door - both sets of doors are mounted at 48" AFF to very bottom of gripping area	For all doors along the public circulation route, remount hardware 34" to 48" AFF.	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		Lever Panic Bar Loop Handle Operating hardware must be centered between 34" and 44" above the floor or ground
67	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025439 -99.732408 6]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	dining from parking door - both doors 20 lbf, fast closing	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
68	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025603 -99.732395 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	patio doors: left door - 4.6%, 25 lbf; right door - 7.3%, 16 lbf and 25 lbf; all close fast	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	MARKY TOTAL STATE OF THE STATE	
69	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.60267, -99.73256]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.2% slope on approach to dining hall	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		STATE OF STA
70	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6025852 -99.732509 8]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.25" and similar gaps at expansion joints	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3		destinant discission of transi-

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								
71	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	[29.6024985 -99.732353 6]	Stairways must have handrails on both sides. Handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground. The top handrails shall extend a minimum of 12 inches beyond the top nosing and shall be parallel with the floor or ground surface. At the bottom of a stair flight, handrails shall extend at the slope of the stair flight for a horizontal distance at least equal to one tread depth beyond the last riser nosing. Extension shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent stair flight. The orientation of at least one handrail, including the extension, shall be in the direction of the run of the stair and perpendicular to the direction of the stair nosing. Handrail gripping surfaces with a circular cross section shall have an outside diameter of 1-1/4 inches minimum and 2 inches maximum. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2-1/4 inches maximum. The hand grip portion of handrails shall have a smooth surface with no sharp corners. Gripping surfaces (top or sides) shall be uninterrupted by newel posts, other construction elements or obstructions. Any wall or other surface adjacent to the handrail shall be free of sharp or abrasive elements. Handrails projecting from a wall shall have a space of 1-1/2 inches minimum between the wall and the handrail.		Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	2015 ABAAS Section: 505.2  2012 TAS Section: 505.2  2010 ADAS Section: 505.2		(a) Stairs Rear X - head days

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
72	Cypress Springs Group Camping Area: Cypress Springs Dining Hall	-99.732352	The handrails as well as the handrail extensions are not at the correct height. The tops of handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground.	rear patio (2 sets of stairs)- handrails 30", 33"	Replace or remount handrails to 34" to 38" aff	2015 ABAAS Section: 505.4 2012 TAS Section: 505.4 2010 ADAS Section: 505.4		34-38 (a) stairs

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
73	Headquarters Area: Headquarters Building	[29.5989058 -99.743985]	The water flow from the spout is too low. The spout shall provide a flow of water 4 inches high minimum.	no water flow from either spout	Adjust spout flow height to min 4".	2015 ABAAS Section: 602.6 2012 TAS Section: 602.6 2010 ADAS Section: 602.6		4 inches de
74	Headquarters Area: Headquarters Building	[29.5990504 ,-99.74387 77], [29.5990481 ,-99.744070 8]	The curb ramp side flares are too steep. The sides of curb ramps (curb ramp flares) where provided, shall not be steeper than 1:10.	NE lot- right side 11%, West lot - 12.2% right side, 11.3% left side	Correct slope of curb ramp side flares to max 10%	2015 ABAAS Section: 406.3 2012 TAS Section: 406.1, 406.3 2010 ADAS Section: 406.1, 406.3		SJSh No.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
75	Headquarters Area: Headquarters Building	[29.5990446 , -99.74407 49], [29.5990492 , -99.743880 4]	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%. Ramps should have the least possible slope but in no case more than 8.3% (1:12).	NE lot - 13.8%, West lot 9.8%	Correct slope of ramp to max 8.33%	2015 ABAAS Section: 405.2 2012 TAS Section: 405.2 2010 ADAS Section: 405.2	THE STATE OF THE S	MANUEL STATE OF THE PARTY OF TH
76	Headquarters Area: Headquarters Building	[29.5990061 , -99.74407 89], [29.5990504 , -99.743877 7]	The curb ramp on the accessible route contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	NE lot - 3.2%, West lot 2.7%	Correct curb ramp cross slope to max 2.08%	2015 ABAAS Section: 405.3  2012 TAS Section: 405.3  2010 ADAS Section: 405.3		100

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
77	Headquarters Area: Headquarters Building	[29.5990061 , -99.74407 49], [29.5990492 , -99.743880 4]	Detectable warning surfaces complying with R305 shall be provided at the following locations on pedestrian access routes and at transit stops: Curb ramps and blended transitions at pedestrian street crossings; Pedestrian refuge islands; Pedestrian atgrade rail crossings not located within a street or highway; Boarding platforms at transit stops for buses and rail vehicles where the edges of the boarding platform are not protected by screens or guards; and Boarding and alighting areas at sidewalk or street level transit stops for rail vehicles where the side of the boarding and alighting areas facing the rail vehicles is not protected by screens or guards. Detectable warning surfaces are not required at pedestrian refuge islands that are cutthrough at street level and are less than 1.8 meters (6.0 ft) in length in the direction of pedestrian travel.	lacks detectable warning surface at both curb ramps	Install required detectable warnings at curb ramps along the public right of way or at curb ramps within a site as a smart practice.	2012 TAS Section: 705.1 2010 ADAS Section: 705		The season for the season of t
78	Headquarters Area: Headquarters Building	[29.5991752 -99.743955 5]	Objects project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	plants project into accessible route reducing route width	Relocate object to not protrude into the circulation path	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		4 max  4" is the max. an object may project if the bottom is greater than 27" off the floor

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
79	Headquarters Area: Headquarters Building	[29.5991273 ,-99.74395 28], [29.5992265 ,-99.743935 4]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	multiple .75" changes in level on accessible route to building	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½
80	Headquarters Area: Headquarters Building	[29.5990002 -99.743931 4]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1.5" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	The Residence of the Section of the	descripted described of head

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
81	Headquarters Area: Headquarters Building	[29.5988988 , -99.743982 3]	Element meets all standards and requirements	Employee entry complies	None	2010 ADAS Section: N/A		
82	Headquarters Area: Headquarters Building	[29.5988941 ,-99.743966 2]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	End office has furniture in maneuvering clearance, one office has sliding door without hardware	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
83	Headquarters Area: Headquarters Building	[29.5989041 , -99.744001 7]	Element meets all standards and requirements	break room door complies	None	2010 ADAS Section: N/A		
84	Headquarters Area: Headquarters Building	[29.5988895 -99.744006 5]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	pipe chase- refrigerator in maneuvering clearance on pull side, change in level at doorway, door 28.5" wide	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
85	Headquarters Area: Headquarters Building	[29.5989046 , -99.744004 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	Break room exterior- vending machine pull side, storage push side, closes fast	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	
86	Headquarters Area: Headquarters Building	[29.5989395 -99.743983 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	break room exit- fridge pull side, storage push side	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	2015 ABAAS Section: 404.2.4.1, 404.2.4.4 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1	
87	Headquarters Area: Headquarters Building	[29.5989151 -99.743987 7]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	break room- 26.5" width route of travel to exit	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	24 max 48 min 24

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
88	Headquarters Area: Headquarters Building	[29.5989128 -99.743998 4]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	break room- lacks clear floor space at refrigerator	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS	48	3 min
		100 500000	T			Section: 305.3		12 min. 1
89	Headquarters Area: Headquarters Building	[29.5989023 , -99.743990 4]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim	break room- sink rim 34.25" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3	Ener. clearance	1)* min 8° min 8° min 100 of country or 100 of country
		,	or counter edge no higher than 34 inches above the finished floor.			2012 TAS Section: 606.3	The state of the s	6" deep toe space
						2010 ADAS Section: 606.3		
90	Headquarters Area: Headquarters Building	[29.5988807 -99.744005]	All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	of force to open. Glass edge at bottom	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
91	Headquarters Area: Headquarters Building	[29.5989013 -99.744005 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	hall exit exterior- 10 lb of force to open, closes fast, glass at bottom of door 8" above finished floor, 3.5% slope	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
92	Headquarters Area: Headquarters Building	[29.5989051 -99.744000 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	office exit interior- cabinet pull side, storage push side in maneuvering clearance	Relocate obstacles to provide 48" maneuvering clearance around door.	2015 ABAAS Section: 404.2.4.4, 404.2.4.1 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1		The state of the s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
93	Headquarters Area: Headquarters Building	[29.5989053 -99.743990 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	office exit - 2.5% slope at doorway, storage push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	ATTOMBS.	
94	Headquarters Area: Headquarters Building	[29.5989297 , -99.743977]	Element meets all standards and requirements	lowered service counter complies	None	2010 ADAS Section: N/A		
95	Headquarters Area: Headquarters Building	[29.5988978 -99.743991 4]	All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	exit, interior door - 7 lb force to open, glass starts at 8" above finished floor	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
96	Headquarters Area: Headquarters Building	[29.598892, -99.743989 3]	All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	entry door to counters- 6 lb of force to open, glass starts at 8" above finished floor	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
97	Headquarters Area: Headquarters Building	[29.5989048 , -99.743995 1]	The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	exit- 12 lb of force to open, closes fast, glass starts at 8" above finished floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
98	Headquarters Area: Headquarters Building	[29.59892, -99.74403]	Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	entry- 12 lb force to open, glass starts at 8" above finished floor	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
99	Headquarters Area: Headquarters Building	[29.59892, -99.74403]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.	entry interior- 8 lb of force to open, glass starts at 8" above finished floor, desk in maneuvering clearance prevents opening to 90 degrees	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
100	Headquarters Area: Headquarters Building	[29.5989114 -99.743983 9]	The brochure rack is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	lobby- brochures 58" above finished floor	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1	arques F. rques	10 max 48 max 48 max
101	Headquarters Area: Headquarters Building	[29.59916, -99.74399]	Element meets all standards and requirements	10 of 10 benches have CFS and comply	None	2010 ADAS Section: N/A		
102	Headquarters Area: Headquarters Building	[29.5990615 , -99.743993 9]	Element meets all standards and requirements	3 of 3 garbage cans comply	None	2010 ADAS Section: N/A		
103	Headquarters Area: Headquarters Building	[29.5988552 -99.744143 4]	Changes in level greater than ½ inch (13 mm) high shall be ramped, and shall comply with 405 or 406.	Curb at self pay kiosk	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% along the AR where curbs are present.	2015 ABAAS Section: 303.4  2012 TAS Section: 303.4  2010 ADAS Section: 303.4		
104	Headquarters Area: Headquarters Parking	[29.5989606 , -99.744296 1]	Element meets all standards and requirements	parking scoping complies, 2 of 30. 6 standard stalls, lacks accessible stalls, 24 trailer/RV stalls, 2 are accessible	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
105	Headquarters Area: Headquarters Parking	[29.5989408 , -99.744323]	The access aisle is on the driver's side of the stall. Access aisles must be located on the passenger side of the stall for angled van accessible stalls.	west lot- right stall, aisle on drivers side	Relocate access aisle to the passenger side of the stall.	2015 ABAAS Section: 502.3.4 2012 TAS Section: 502.3.4 2010 ADAS Section: 502.3.4	
106	Headquarters Area: Headquarters Parking	[29.5989338 , -99.74428 27], [29.5989419 , -99.744314 9]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	west lot- left 3.3%, aisle 3.1%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4	
107	Headquarters Area: Headquarters Parking	[29.5985851 ,-99.743728 9]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of 7 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	Staff parking lot - 0-7 parking stalls are accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	2015 ABAAS Section: F208.2  2012 TAS Section: 208.2  2010 ADAS Section: 208.2	See Among Maring Manage

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
108	Headquarters Area: Headquarters Parking	[29.5990551 , -99.743842 9]	Element meets all standards and requirements	parking scoping complies, 17 total, 2 accessible	None	2010 ADAS Section: N/A		
109	Headquarters Area: Headquarters Parking	[29.5990434 , -99.743844 2]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	NE lot- access aisle 54"	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1	33 55 34 55 35 35	access aisle serving car parking spaces
110	Headquarters Area: Headquarters Parking	[29.5990212 , -99.74384 82], [29.5990667 -99.743844 2]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	NE lot- left stall 2.9%, right stall 4.4%	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4	To the second se	-4-8

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
111	Headquarters Area: Headquarters Parking	[29.5990504 -99.743885 8]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	NE lot- left 35", right 47" above ground surface	Raise existing accessible parking signs so lowest end of bottom sign is min 60" AFF.	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6 2010 ADAS Section: 502.6	ESS BLECC SSIL	Accessible 60 inches min.
		ı	1		T			
112	Headquarters Area: Headquarters Staff Restroom	[29.5989105 , -99.744011 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	Staff restroom - 2.7% slope push side of door	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	SAMANET THE SAME AND A	
113	Headquarters Area: Headquarters Staff Restroom	[29.5988895 -99.743977]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Lacks signage	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		The state of the s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
114	Headquarters Area: Headquarters Staff Restroom	[29.5988848 -99.743998 4]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	40.25" to bottom of reflective surface	Lower mirror so reflective surface is max 40" AFF.	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		
115	Headquarters Area: Headquarters Staff Restroom	[29.5989011 -99.743993 1]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipe lacks insulation	Insulate exposed pipes under one sink.	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY
116	Headquarters Area: Headquarters Staff Restroom	[29.5989105 -99.743995 7]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	51.75" to sink (likely safe harbor), supplies and garbage can in clearance	Relocate sink to provide required 60" clearance around toilet; leave as is if restroom constructed or last altered before March 15, 2012 citing safe harbor	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
117	Headquarters Area: Headquarters Staff Restroom	[29.5989175 , -99.743977]	The toilet is not located within the range allowed from the side wall or partition. The centerline of the toilet must be 16 to 18 inches from the side wall.	18.5" from wall to centerline of toilet	Remount toilets to 16" to 18" from the side wall to centerline.	2015 ABAAS Section: 604.2 2012 TAS Section: 604.2 2010 ADAS Section: 604.2		16"-18"

	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								
118	Headquarters Area: Headquarters Staff Restroom	[29.5989175 -99.743993 1]	The toilet seat is not located within the range allowed off the floor. The height of accessible water closets shall be a minimum of 17 inches and a maximum of 19 inches measured to the top of a maximum 2-inch high toilet seat.	seat 15.5" AFF	Replace toilet seat, or re-set or replace toilet to 17" to 19" AFF.	Section: 604.4  2012 TAS Section: 604.4  2010 ADAS Section:		17" to 19"
119	Headquarters Area: Headquarters Staff Restroom	[29.5989128 ,-99.743990 4]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	Soap dispenser installed 7.75" above grab bar	Remount soap dispenser , 15" to 48" aff and min 12" above or 1.5" below grab bar.	604.4  2015 ABAAS Section: 609.3, 609.4  2012 TAS Section: 609.4, 609.3  2010 ADAS Section: 609.3, 609.4	SOFTERINY	
120	Headquarters Area: Headquarters Staff Restroom	[29.5988895 -99.743966 2]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	Toilet paper dispenser not installed withing compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" AFF and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		Juliu gy 7-9

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
121	Headquarters Area: Headquarters Men's Restroom	[29.5989244 -99.743993 1]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	men's restroom door- 12 lbf	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
122	Headquarters Area: Headquarters Men's Restroom	[29.5988871 ,-99.743998 4]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	Men's- bottom off reflective surface is 42" AFF	Lower mirror so reflective surface is max 40" AFF.	2015 ABAAS Section: 603.3  2012 TAS Section: 603.3  2010 ADAS Section: 603.3		
123	Headquarters Area: Headquarters Men's Restroom	[29.5988895 , -99.743985]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Men's- pipe lacks insulation	Insulate exposed pipes under one sink.	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAWTORY  ACCESSIBLE LAWTORY  For any or equipment

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
124	Headquarters Area: Headquarters Men's Restroom	[29.5989268 ,-99.743970 3]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	Men's- sanitizer installed at 50.5", soap 49" AFF	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part. Lower soap dispenser to max 44" above the finished floor (AFF) for a forward reach over counter.	2015 ABAAS Section: 308.2.1, 308.3.2  2012 TAS Section: 308.2.1, 308.3.2  2010 ADAS Section: 308.2.1, 308.3.2	SSPECIAL PROPERTY OF THE PROPE	DPM STATE ST
125	Headquarters Area: Headquarters Men's Restroom	[29.5988988 , -99.743966 2]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Men's- hand dryer projects 7" into the circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
126	Headquarters Area: Headquarters Women's Restroom	[29.598881, -99.743967 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	Women's door - closes fast, sign in pull clearance, sink push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
127	Headquarters Area: Headquarters Women's Restroom	[29.5989256 -99.744001 1]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Sign mounted on pull side of door, high	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6,	FUC.
128	Headquarters Area: Headquarters Women's Restroom	[29.5988941 -99.744014 5]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	Reflective surface 40.5" AFF	Lower mirror so reflective surface is max 40" AFF.	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
129	Headquarters Area: Headquarters Women's Restroom	[29.5989011 -99.743979 6]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipe lacks insulation	Insulate exposed pipes under one sink.	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAWTORY  The stage or reposted.
130	Headquarters Area: Headquarters Women's Restroom	[29.5989105 , -99.743982 3]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	52" to sink, may meet safe harbor	Relocate sink to provide required 60" clearance around toilet; leave as is if constructed or last altered before March 15, 2012 citing safe harbor	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
131	Headquarters Area: Headquarters Women's Restroom	[29.5989011 -99.743998 4]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	Toilet paper dispenser mounted 6" above side grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar.	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
132	Headquarters Area: Headquarters Women's Restroom	[29.5989163 -99.743979 6]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.5% cross slope at drain	Correct or repair slope to max 5% running and 2.08% cross.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		Section 1.
133	Headquarters Area: Nature Trail	[29.5991122 , -99.744615 4]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	nature trail, loose surface, narrows	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		
134	Headquarters Area: Nature Trail	[29.5991203 -99.744628]	The surface of the clear ground space shall be firm and stable The slope of the clear ground space surface shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage	Trail sign lacks CFS due to surface	Correct surface at trailhead signage to be firm, stable and have max slope of 2.08% or 5% if other than concrete asphalt or boards as a smart practice.	2015 ABAAS Section: 1011.2.2, 1011.2.3, 1011.2 EXCEPTION		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
135	Persimmon Hill Camping Area: Persimmon Hill Campsites	[29.6023196 -99.738066 1]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 35 Persimmon Hill sites accessible; elements include - picnic area, camp site, water spout, grill and garbage hook; 123 total water sites	Create the required number of accessible camp sites of this type within the site per table F244.2 as a smart practice, seven required	2015 ABAAS Section: F244.2		
136	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023469 , -99.738053 3]	The landing at the door does not have a compliant landing. Doors with an approach from the hinge side must have a landing on the pull side that is a minimum of 60 inches in depth perpendicular to the door in a close position by a minimum width dimension of 36 inches plus the door width. The additional 36 inches must extend past the door on the latch side. The entire landing must be free of obstructions and must be flat (2% max. slope is considered flat in any direction).	Men's restroom door - 5.4% slope at door landing area	The entire landing must be free of obstructions and must be flat (2% max. slope is considered flat in any direction).	2015 ABAAS Section: 404.2.4.1 2012 TAS Section: 404.2.4.1 2010 ADAS Section: 404.2.4.1		St rain from any motion of the state of the
137	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023364 -99.738066 7]	The door operating hardware exceeds maximum height requirements. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, pinching or twisting of the wrist to operate.	Men's restroom door - Door handle 51.5" AFF	Hardware shall be installed 34 inches minimum and 48 inches maximum above the finish floor or ground.	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
138	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023376 -99.738068 1]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Lacks correct signage	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5,	MEN	FUC.
139	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023364 -99.738068 1]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirror 44.5" AFF	Lower mirror so reflective surface is max 40" AFF.	703.6 2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
140	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023329 -99.738058 7]	either a side or front approach. Where a clear floor or ground space allows a parallel	Operable parts above reach range - sanitizer 55", hand dryer 57", light switch 53.5"	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1		48 max 48 max
141	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023317 -99.738057 3]	There are not enough accessible toilet compartments. The room contains toilet compartments. A minimum of 1 must be wheelchair accessible .	Ambulatory stall only; lacks accessible stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
142	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023282 -99.738056]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	Toilet compartment 36" wide	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS Section: 604.8.2.1 2010 ADAS Section: 604.8.2.1		35-37 35
143	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023329 -99.738057 3]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	grab bar on one side only	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" aff	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4 2012 TAS Section: 609.4, 609.3, 604.8.2.3 2010 ADAS Section: 609.3, 609.4, 604.8.2.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
144	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023329 -99.738057 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide.	Stall door width 27.5"	Widen stall doors to 32" when opened to 90 degrees.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2	
						2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2	
145	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023329 -99.738061 4]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Hand dryer projects 5" into the circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
146	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023434 -99.738076 1]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Hook installed at 70.5" AFF	Remount at least one hook to max 48" aff and shelves to 40" - 48" AFF.	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
147	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023387, -99.73806]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	41.5" d × 39" w	Correct size of transfer shower to compliant 36" by 36" clear inside dimension.	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		Seed control was seed of the control parts of appears seed

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
148	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023364 -99.738057 3]	Where a seat is provided in a standard rollin shower compartment, it shall be a folding type, shall be installed on the side wall adjacent to the controls, and shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. Where a seat is provided in an alternate roll-in type shower compartment, it shall be a folding type, shall be installed on the front wall opposite the back wall, and shall extend from the adjacent side wall to a point within 3 inches (75 mm) of the compartment entry. In transfer-type showers, the seat shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. The top of the seat shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the bathroom finish floor. Seats shall comply with 610.3.1 or 610.3.2.	Lacks proper seat	Provide the correct seat based on shower type.	2015 ABAAS Section: 610.3  2012 TAS Section: 610.3  2010 ADAS Section: 610.3	
149	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.60215, -99.73795]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Multiple 1" gaps along path to road	Correct or fill gaps to be max .5".	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	demonstration of vanil
150	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.60196, -99.73809], [29.6022608 -99.738039]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	CIL at roadway, 1.5" close to men's	Repair, bevel or ramp CIL along AR.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	Yamax Yamax

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	Area Description	Latt Long	i mamg	AS Built	Tiesenmenauten	Citation	i notos	riguio
151	Persimmon Hill Camping Area: Persimmon Hill Men's Restroom	[29.6023218 -99.738002 5]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3.5% slope at turn to men's, 3.1% slope along front of building	Correct or repair cross slope along AR to max 2.08%.	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	SEARCH SALES	
152	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.60233, -99.73804]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	Women's- 14.4% slope at door, garbage can push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
153	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023434 , -99.73806]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Sign lacks Braille, symbol of access and raised characters, not located at door	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6  2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6  2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
154	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023317 ,-99.738046 6]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	Reflective surface 40.75" AFF	Lower mirror so reflective surface is max 40" AFF.	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section:		
155	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023387 -99.738058 7]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	Sink rim 35" AFF	Lower sinks to max 34" AFF to front of rim.	603.3  2015 ABAAS Section: 606.3  2012 TAS Section: 606.3  2010 ADAS Section: 606.3		Fore clearance  Tor clearance  6° deep toe space
156	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023376 -99.738054 6]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipes lack insulation	Insulate exposed pipes under one sink.	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESIBLE LAWTORY

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
157	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023352 -99.738056]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.		Lower operating mechanisms to max 48" AFF to highest operable part Lower to max 44" AFF for a forward reach over counter.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		SOLUTION STATE OF THE STATE OF
158	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023504 -99.738061 4]	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of 1 must be wheelchair accessible .	Ambulatory stall only; lacks accessible stall	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
159	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023376 , -99.738061 4]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	ambulatory stall 59" deep	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep.	2015 ABAAS Section: 604.8.2.1 2012 TAS	52 52 10 07 68 10 47 52 07 52 10 07 68 10 07 68 10 07 52 07	S 35-37 35-3
	Hestroom					Section: 604.8.2.1		25 July 25 Jul
						2010 ADAS Section: 604.8.2.1		
160	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023352 , -99.738053 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	Stall door 27.5" wide	Widen stall doors to 32" when opened to 90 degrees.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2	24 23 26 27 23 20 20 20 20 20 20 20 20 20 20 20 20 20	
						2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2		
						2010 ADAS Section: 404.2.3, 404.2.7,		
						604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
161	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023364 -99.738050 6]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	Grab bar one side only	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4 2012 TAS Section: 609.4, 609.3, 604.8.2.3 2010 ADAS Section: 609.3, 609.4, 604.8.2.3	
162	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023411 -99.738065 4]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	Grab bar mounted 13" from rear wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" AFF.	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	
163	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023387 -99.738065 4]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Hand dryer protrudes 5"	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
164	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023271 , -99.73806]	The accessible path of travel contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	2.5% slope at drain, 3.1% slope at shower	Correct or repair cross slope of AR to max 2.08%.	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3	AMARITY CONTROL OF THE PROPERTY OF THE PROPERT	
165	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023411 -99.738064]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Hooks 69" AFF	Remount at least one hook to max 48" AFF.	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
166	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023411 -99.738054 6]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	39.5" wide, 40" deep	Correct size of transfer shower to compliant 36" by 36" clear inside dimension.	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		Seed Control Wall Seed Seed Control Wall Seed Seed Seed Control Wall Seed Seed Seed Seed Seed Seed Seed Se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
167	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023387 ,-99.738054 6]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	Chair in CFS	Provide appropriate CFS on the exterior of the transfer shower.	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1	Seed to back wall back wall wall wall wall a seed of the control o
168	Persimmon Hill Camping Area: Persimmon Hill Women's Restroom	[29.6023317 -99.738068 1]	A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610.A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610. EXCEPTION: In residential dwelling units, seats shall not be required in transfer type shower compartments provided that reinforcement has been installed in walls so as to permit the installation of seats complying with 608.4.	Lacks seat	Provide the required folding or non-folding seat in the transfer shower.	2015 ABAAS Section: 608.4, 608.4 EXCEPTION  2012 TAS Section: 608.4, 608.4 Exception  2010 ADAS Section: 608.4, 608.4 Exception	
169	Persimmon Hill Camping Area: Parking Lot	[29.6025195 ,-99.737988 9]	Element meets all standards and requirements	restroom- parking scoping complies, 4 standard, 1 accessible	None	2010 ADAS Section: N/A	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
170	Persimmon Hill Camping Area: Parking Lot	[29.6025265 , -99.737991 6]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	restroom- lacks access aisle next to accessible stall	Create one or more 5' adjacent access aisle, with proper signage and striping.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		Agramação sidas el e san sua dia santa de sensador de escuellos estal esta esta esta esta esta esta esta esta
171	Persimmon Hill Camping Area: Parking Lot	[29.602523, -99.737988 9]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 1 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	restroom- lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		Machine Conting Market   Machine Conting Mar
172	Persimmon Hill Camping Area: Parking Lot	[29.6004683 , -99.73557 36], [29.6012519 , -99.736292 4]	There are no or not enough accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance.	Persimmon Hill Camping parking - lacks accessible parking spaces - 21 standard, 0 accessible; overflow lot - 27 standard, 0 accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	2015 ABAAS Section: F208.2  2012 TAS Section: 208.2  2010 ADAS Section: 208.2		Volume of bring home

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
173	Live Oak Camping Area: Live Oak RV Dump Station	[29.6009208 -99.735752]	Water spouts at water hydrants and water utility hook-ups shall be 28 inches (710 mm) minimum and 36 inches (915 mm) maximum above the ground.	RV dump station water spout low	Remount water spouts to 28" min or 36" max above the ground as a smart practice.	2015 ABAAS Section: 1011.6		
174	Live Oak Camping Area: Live Oak Campsites	[29.6006567 -99.732875 8]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 65 designated accessible campsites in Live Oak loop - table, parking, fire ring, utility and water; 215 total electric sites provided in park	Create the required number of accessible camp sites of each type provided per table F244.2 as a smart practice; nine electric campsites required	2015 ABAAS Section: F244.2		
175	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006782 ,-99.732867 3]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Signage lacks Braille and symbol of access	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
176	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006584 -99.732871 3]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	All 3 mirrors are minimum of 40.75" AFF	Lower mirror so reflective surface is max 40" AFF.	2015 ABAAS Section: 603.3  2012 TAS Section: 603.3  2010 ADAS Section: 603.3		
177	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006701 ,-99.732863 2]	The rim of the urinal Is too high. Wall-hung urinals must be provided with an elongated rim projecting a minimum of 13 1/2 inches from the wall and a maximum of 17 inches above the floor.	24" and 25" AFF	Lower urinal so that rim height is max 17" AFF.	2015 ABAAS Section: 605.2  2012 TAS Section: 605.2  2010 ADAS Section: 605.2		13½ min 17 max
178	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006829 -99.732872 6]	The urinal is located in an area that does not provide the required clear floor space for a front approach. The surrounding elements of a urinal must provide a minimum of 30 by 48 inches of clear floor space for a front approach.	Lacks 30" width	Relocate privacy wall at urinal to provide 30" CFS.	2015 ABAAS Section: 605.2  2012 TAS Section: 605.2  2010 ADAS Section: 605.2	23 20 30 31	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
179	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006771 -99.732879 3]	The urinals flush handle is mounted too high. Flush controls shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist and shall be mounted no more than 48 inches above the floor. The force required to activate controls shall be no greater than 5 lb. Electronic automatic flushing controls are acceptable and preferable.	Flush handle 51" AFF	Lower flush handle at urinal to max 48" AFF.	2015 ABAAS Section: 605.4 2012 TAS Section: 605.4 2010 ADAS Section: 605.4		
180	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006771 -99.732861 9]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	Sanitizer 55", dryer 57.5", light switch 53.5" AFF	Lower operating mechanisms to max 48" AFF to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2  2012 TAS Section: 308.2.1, 308.3.2  2010 ADAS Section: 308.2.1, 308.3.2		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
181	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006712 -99.732867 3]	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of 1 must be wheelchair accessible.	Lacks accessible toilet compartment	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
182	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006712 -99.732867 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32".	Stall door 27" width	Widen stall doors to 32" when opened to 90 degrees.	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
183	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006619 -99.732875 3]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	Grab bars on one side only	Add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4 2012 TAS Section: 609.4, 609.3, 604.8.2.3 2010 ADAS Section: 609.3, 609.4, 604.8.2.3	
184	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006712 -99.732872 6]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Hook mounted 73" AFF	Remount at least one hook to max 48" AFF.	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5  2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5  2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
185	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006666 -99.732863 2]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	shower 37.5" x 40"	Correct shower to compliant 36" by 36" clear inside dimension.	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1	22 22 33 30	Seed well back well well well well well well well wel
186	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006712 -99.732864 6]	Where a seat is provided in a standard rollin shower compartment, it shall be a folding type, shall be installed on the side wall adjacent to the controls, and shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. Where a seat is provided in an alternate roll-in type shower compartment, it shall be a folding type, shall be installed on the front wall opposite the back wall, and shall extend from the adjacent side wall to a point within 3 inches (75 mm) of the compartment entry. In transfer-type showers, the seat shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. The top of the seat shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the bathroom finish floor. Seats shall comply with 610.3.1 or 610.3.2.	Lacks seat in shower	Provide the correct seat based on shower type.	2015 ABAAS Section: 610.3 2012 TAS Section: 610.3 2010 ADAS Section: 610.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
187	Live Oak Camping Area: Live Oak Men's Restroom	[29.6006619 -99.732864 6]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	5.2% slope at door landing	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
188	Live Oak Camping Area: Live Oak Women's Restroom	[29.6005481 , -99.73291 29], [29.6006833 -99.732784 1]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap on route to women's, 1" gap on route to men's	Correct or fill gaps to be max .5".	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	No of the latest and	destinant designed of hosel    Common projections of the common projec
189	Live Oak Camping Area: Live Oak Women's Restroom	[29.6004573 -99.732946 9]	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	Reduces on men's side at parking due to parking stop in path	Relocate parking stop to provide 36" minimum clear width.	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		At max.  At
190	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006364 -99.732826 4]	Element meets all standards and requirements	Vending machine complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
191	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006603 ,-99.732862 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	7.3% slope in doorway	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
192	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006573 -99.732868 6]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	Signage lacks Braille, symbol of access and raised characters, sign at door high	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	WOMEN	FUC.
193	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006677 -99.732874]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY  To a risp or regulatoric

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
194	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006666 -99.732886]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	Hand dryer 58", power outlets and soap dispenser high and over sink, hand sanitizer 55"	Lower operating mechanisms to max 48" AFF to highest operable part; leave as is if employee only operated. Lower to max 44" AFF for a forward reach over counter.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		DOMESTIC STATE OF THE STATE OF
195	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006666 -99.732879 3]	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of 1 must be wheelchair accessible .	Ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights.	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
196	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006829 , -99.732880 7]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	59" depth of stall	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1 2012 TAS	\$5° 19 00 65 05 65 05 55 For 101 egs 600 050, 650 050 55	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
						Section: 604.8.2.1 2010 ADAS Section:		¥ \$ 1
197	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006712 -99.732861 9]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and must be self-closing.	Door 28" width, not self-closing	Widen stall doors to 32" when opened to 90 degrees. Adjust stall door to be self-closing.	604.8.2.1  2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2  2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2  2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
198	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006747 -99.732861 9]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	Grab bar on one side only	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" AFF.	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4 2012 TAS Section: 609.4, 609.3, 604.8.2.3 2010 ADAS Section: 609.3, 609.4, 604.8.2.3	
199	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006642 -99.732864 6]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	Hand dryer protrudes 7" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item.	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
200	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006736 -99.732878]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	Hook mounted at 70.5" AFF	Remount at least one hook to max 48" AFF.	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
201	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006666 -99.732867 3]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	40" wide, 39" deep	Correct transfer shower to compliant 36" by 36" clear inside dimension	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		See and Control of the control of th
202	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006526 -99.732843 1]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	Chair in CFS	Provide appropriate CFS on the exterior of the transfer shower.	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		Seed Control Seed Wall Seed Seed Wall Seed Seed Seed Seed Seed Seed Seed Se

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
203	Live Oak Camping Area: Live Oak Women's Restroom	[29.6006736 -99.732865 9]	A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610.A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610. EXCEPTION: In residential dwelling units, seats shall not be required in transfer type shower compartments provided that reinforcement has been installed in walls so as to permit the installation of seats complying with 608.4.	Seat missing	Provide the required folding or non-folding seat in the transfer shower.	2015 ABAAS Section: 608.4, 608.4 EXCEPTION  2012 TAS Section: 608.4, 608.4 Exception  2010 ADAS Section: 608.4, 608.4 Exception	
204	Live Oak Camping Area: Live Oak Parking Lot	[29.6008322 , -99.732738 5]	Element meets all standards and requirements	north lot- parking scoping complies, 4 standard, 1 accessible	None	2010 ADAS Section: N/A	
205	Live Oak Camping Area: Live Oak Parking Lot	[29.6008275 -99.732717 1]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	north lot - 2.6% slope in access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
206	Live Oak Camping Area: Live Oak Parking Lot	[29.6007879 -99.732753 3]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 3 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	north lot - lacks van parking signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		September of Managham French of Managham September of Managham Sep
207	Live Oak Camping Area: Live Oak Parking Lot	[29.6008263 , -99.732714 4]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	north lot - access aisle is 54" wide	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1  2012 TAS Section: 502.3.1  2010 ADAS Section: 502.3.1	35 35 56 35	access aisle serving car parking spaces
208	Live Oak Camping Area: Live Oak Parking Lot	[29.6004299 , -99.732997 3]	Element meets all standards and requirements	south lot- parking scoping complies, 3 standard, 1 accessible	None	2010 ADAS Section: N/A		
209	Live Oak Camping Area: Live Oak Parking Lot	[29.6004404 -99.732989 3]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	south lot - access aisle 54" wide	Repaint access aisles to be 5' each.	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces  area to be be marked marked 60 min 1525

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
210	Live Oak Camping Area: Live Oak Parking Lot	[29.6004835 , -99.732981 3]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	south lot - lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table.	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		A Distriction of District Private Priv
211	Live Oak Camping Area: Live Oak Parking Lot	[29.600445, -99.733010 8]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	south lot - loose surface in parking stall	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material.	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4	Xma 3 3	4 12 1/2

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
212	Rio Frio Camping Area: Rio Frio Campsites	[29.5960514 -99.731401 5]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	campsites in Rio Frio include table, fire ring, utility, water, parking, none designated accessible; 114 total sites in this area, 74 include electric, 40 are water only Park includes 123 water only and 215 electric sites total.	Create the required number of accessible camp sites for each type of site provided per table F244.2 as a smart practice; seven total water sites and nine electric sites required within the park; cost for water sites included in Persimmon Hill finding, cost for electric sites included in Live Oak finding.	2015 ABAAS Section: F244.2		
213	Rio Frio Camping Area: Rio Frio Volleyball	[29.598454, -99.732978 2]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of 10 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	0 of 10 parking stalls are accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		Street of Period
214	Rio Frio Camping Area: Rio Frio Volleyball	[29.5986626 -99.732985 6]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	lacks route to volleyball 45' map measurement	Provide an accessible route to each element within the site.	2010 ADAS Section: 206.2.2, 206.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
215	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974785 , -99.732182]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirrors 41.5"	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3  2012 TAS Section: 603.3  2010 ADAS Section: 603.3		TO THE PARTY OF TH
216	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974668 -99.732202 1]	The rim of the urinal Is too high. Wall-hung urinals must be provided with an elongated rim projecting a minimum of 13 1/2 inches from the wall and a maximum of 17 inches above the floor.	both urinals 24"	Lower urinal so that rim height is max 17" aff	2015 ABAAS Section: 605.2 2012 TAS Section: 605.2 2010 ADAS Section: 605.2		13½ min 17 max
217	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974738 -99.732180 6]	The urinals flush handle is mounted too high. Flush controls shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist and shall be mounted no more than 48 inches above the floor. The force required to activate controls shall be no greater than 5 lb. Electronic automatic flushing controls are acceptable and preferable.	both urinal flush controls - 50"+	Lower flush handle at urinal to max 48" aff	2015 ABAAS Section: 605.4  2012 TAS Section: 605.4  2010 ADAS Section: 605.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
218	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974808 -99.732177 9]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	sanitizer 49.5", light switch 53", hand dryer 57"	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		22) Feet (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
219	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974808 -99.732191 3]	There are not enough accessible toilet compartments. The room contains 1 toilet compartments. A minimum of 1 must be wheelchair accessible .	lacks accessible toilet compartment	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
220	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.597475, -99.732180 6]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door width 30"	Widen stall doors to 32" when opened to 90 degrees	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.3, 404.2.7, 604.8.2.2	
221	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974808 -99.732183 3]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	grab bar extends 48" from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	43 46 47 \$ 40 50 51
222	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.597482, -99.732194]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 5" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
223	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974808 -99.732199 4]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	3% cross slope at stall	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
224	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974738 -99.732207 4]	The door is equipped with a door closer and returns to a closed position too quickly. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum.	men's- door closes fast	Inspect, adjust, and maintain closing speed on door closers	2015 ABAAS Section: 404.2.8.1 2012 TAS Section: 404.2.8.1 2010 ADAS Section: 404.2.8.1		90" 5 seconds min. 12"
225	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974761 -99.732191 3]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hook installed at 62.5" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.2.1, 308.1, 222.2, 803.5		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
226	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974831 -99.732188 7]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground.	bench - 40" x 9"	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min
227	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974855 -99.732186]	There is no hand held sprayer unit. The sprayer unit must have a 59 inches hose and be mounted 48 inches maximum to the top of mounting bracket off the floor. The shower spray unit shall have an on/off control with a non-positive shutoff. If an adjustable-height shower head on a vertical bar is used, the bar shall be installed so as not to obstruct the use of grab bars.	lacks hand held shower spray, fixed spray mounted at 65"	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held	2015 ABAAS Section: 608.6 2012 TAS Section: 608.6 2010 ADAS Section: 608.6		SHOWER SPRAY UNIT  59° Long Flexible Hose Water Temperature: 120° F Max. above the shower floor.  Geurder's Book, Inc.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
228	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Men's	[29.5974761 -99.732183 3]	Where a seat is provided in a standard rollin shower compartment, it shall be a folding type, shall be installed on the side wall adjacent to the controls, and shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. Where a seat is provided in an alternate roll-in type shower compartment, it shall be a folding type, shall be installed on the front wall opposite the back wall, and shall extend from the adjacent side wall to a point within 3 inches (75 mm) of the compartment entry. In transfer-type showers, the seat shall extend from the back wall to a point within 3 inches (75 mm) of the compartment entry. The top of the seat shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the bathroom finish floor. Seats shall comply with 610.3.1 or 610.3.2.	shower seat is not compliant	Provide the correct seat based on shower type.	2015 ABAAS Section: 610.3 2012 TAS Section: 610.3 2010 ADAS Section: 610.3		
229	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5975157 , -99.732414]	Element meets all standards and requirements	parking scoping complies- 1 of 5 stalls accessible	None	2010 ADAS Section: N/A		
230	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5975275 -99.732408 6]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	access aisle 56" width	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces  area to lead

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
231	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974995 -99.732391 2]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		Metabolish Palama Sanah
232	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5975216 -99.732409 9]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	5.9% slope access aisle, 2.7% slope stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		-4

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
233	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974787 ,-99.732194 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	women's - 3% slope, door propped open with garbage can, closes fast	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
234	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974995 -99.732188 7]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	41.5" above finished floor to reflective surface	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		
235	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974761 , -99.732194]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
236	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974761 -99.732187 3]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	hand dryer 58", outlets and soap high and over sink	Lower operating mechanisms to max 48" aff to highest operable part Lower to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
237	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974761 -99.732183 3]	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of 1 must be wheelchair accessible .	ambulatory only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
238	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974831 -99.732187 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door 31" wide, not self closing	Widen stall doors to 32" when opened to 90 degrees Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
239	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974995 -99.732186]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	grab bars extend to 48.5" from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
240	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974808 -99.732184 6]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser 6.5" above rear grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
241	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974843 -99.732187 3]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser not located within compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	veu ep
242	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974808 -99.732207 4]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer protrudes 5" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	
243	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974831 -99.732188 7]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.7% slope at drain, 8.7% slope at shower	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	The state of the s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
244	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974808 -99.732207 4]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks mounted 62" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5	
245	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974761 -99.732191 3]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	lacks grab bars or compliant seat type	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6	STANDARD ROLL IN TYPE SHOWER COMPARTMENT C
246	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.597492, -99.732255 4], [29.5974722 -99.732397 5]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	(2) 1" gaps on walkway to parking	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	Mary difference representation to make a district of facel.  35 PRIACE  Mary Street Control of Facel.  Mary Street Control o

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
247	Rio Frio Camping Area: Rio Frio Restroom Bldg 14 - Women's	[29.5974784 -99.732188 7]	Element meets all standards and requirements	vending machine complies	None	2010 ADAS Section: N/A		
248	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952722 , -99.732875 3]	Element meets all standards and requirements	parking scoping complies- 1 of 5 stalls accessible	None	2010 ADAS Section: N/A		
249	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952792 -99.732878]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	access aisle width 56"	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces
250	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.595271, -99.732832 4]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks signage for van	Add van parking sign to1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
251	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952803 -99.732875 3]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	2.5% slope access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		
252	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.595271, -99.732879 3]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	loose gravel	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		½ max ½ ½ ½ ½ ½
253	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952628 , -99.732701]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	4.6% slope at men's restroom door	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
254	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952512 -99.732711 7]	The door operating hardware exceeds maximum height requirements. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, pinching or twisting of the wrist to operate.	door handle is installed 49.5" above finished floor	Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
255	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952593 -99.732703 6]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirrors 41" to bottom of reflecting surface	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		
256	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952558 -99.732706 3]	The rim of the urinal Is too high. Wall-hung urinals must be provided with an elongated rim projecting a minimum of 13 1/2 inches from the wall and a maximum of 17 inches above the floor.	both urinals 23"	Lower urinal so that rim height is max 17" aff	2015 ABAAS Section: 605.2 2012 TAS Section: 605.2 2010 ADAS Section: 605.2		13½ min 17 max
257	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952512 -99.732711 7]	The urinals flush handle is mounted too high. Flush controls shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist and shall be mounted no more than 48 inches above the floor. The force required to activate controls shall be no greater than 5 lb. Electronic automatic flushing controls are acceptable and preferable.	both flush handles 49.5"	Lower flush handle at urinal to max 48" aff	2015 ABAAS Section: 605.4 2012 TAS Section: 605.4 2010 ADAS Section: 605.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
258	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952628 -99.732701]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	elements installed above reach range - 50" sanitizer, 52.5" light switch, 57.5" hand dryer	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		JOPEN STORY OF THE
259	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952558 -99.732718 4]	There are not enough accessible toilet compartments. The room contains 1 toilet compartments. A minimum of 1 must be wheelchair accessible .	lacks accessible toilet compartment	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
Number 260	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952745 , -99.732698 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall width 30.5"	Widen stall doors to 32" when opened to 90 degrees	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2	
			be self-closing.			2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2	
						2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2	
261	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952698 -99.732706 3]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side grab bars installed 13" from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	2 10 11 3

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
262	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.595257, -99.732699 6]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks installed at 67" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
263	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952652 -99.732701]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	lacks accessible shower	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDARD ROLL IN TYPE SHOWER COMPARTMENT CHOSE THE STANDARD ROLL IN THE STANDARD
264	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Men's	[29.5952514 -99.732705 9]	The accessible path of travel contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	13.3% at shower, 2.8% at drain	Correct or repair cross slope of AR to max 2.08%	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3		**************************************

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
265	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5951544 , -99.732491 7]	Element meets all standards and requirements	parking scoping complies- 1 of 12 stalls accessible	None	2010 ADAS Section: N/A		
266	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5951416 -99.732491 7]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	access aisle width 55", does not meet minimum	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces  area to line
267	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5951521 -99.732538 7]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		See A seed of Process Seed of Process of Pro
268	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5951392 -99.732494 4]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	4.2% slope in access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
269	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5951509 , -99.732495 8]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	loose surface in stall and access aisle	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4	Wamax Wanay Walanta and Market an
270	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.595236, -99.732691 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%.	women' s- 6.3% slope in doorway, garbage can push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	
271	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952698 , -99.732692 9]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	reflective surface is 41.25" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3	
272	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952652 -99.732687 5]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink rim 34.5" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3	Toe clearance  Toe clearance  ** deep toe toacc

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
273	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952605 -99.732709]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY  To a ring or represent
274	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952512 -99.732706 3]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	hand dryer 57", outlets and soap dispenser installed high and over sink	Lower operating mechanisms to max 48" aff to highest operable part Lower to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2  2012 TAS Section: 308.2.1, 308.3.2  2010 ADAS Section: 308.2.1, 308.3.2		20 C S S S S S S S S S S S S S S S S S S

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
275	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952605 , -99.732695 6]	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of 1 must be wheelchair accessible.	ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		
276	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952419 -99.732706 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	30.5" wide, not self closing	Widen stall doors to 32" when opened to 90 degrees Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		
277	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952605 -99.732717 1]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side grab bars installed 13" from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	8 9 10 11 0 11 11 11 11 11 11 11 11 11 11 1	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
278	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952698 -99.732709]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser installed 8" above grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	
279	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952465 -99.732706 3]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	installed 5.5" in front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	View S
280	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952558 -99.732701]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 5" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
281	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952675 -99.732717 1]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	11.1% slope at shower	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
282	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952605 -99.732709]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks installed 69.5" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
283	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952582 , -99.732711 7]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	lacks accessible shower	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDARD ROLL IN TYPE SHOWER COMPARTMENT  Granding Train  Gran

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure	
284	Rio Frio Camping Area: Rio Frio Restroom Bldg 15 - Women's	[29.5952675 ,-99.73276 79], [29.5951777 -99.732653 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	(2) 1" gaps on route to women's, 1" gap along building, 1" gap near men's	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	demonst dischool of transf  war of forest proposals as it is  war of forest proposals as it is  section of the above of transf  ye max	
285	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5975613 , -99.730753 7]		parking scoping complies- 1 of 5 stalls accessible	None	2010 ADAS Section: N/A		
286	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5975694 -99.730740 3]	The accessible parking stall is not wide enough. Each parking space must be at least 8' feet wide and shall be marked to define the width. The measurements of parking spaces and access aisles shall be made from the centerline of the markings. Where the parking space is not adjacent to another parking space or access aisle, the measurement shall be permitted to include the full width of the line defining the parking space.	stall is 77" wide and a portion of the stall is overgrown with grass	Repaint stalls to be 8' wide each	2015 ABAAS Section: 502.2  2012 TAS Section: 502.2  2010 ADAS Section: 502.2	Feet for Van.	If Car in Carbon to p parking

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
287	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5975601 -99.730756 4]	The access aisle is not a minimum 5 feet wide. A car accessible parking stall's access aisle must be a minimum of 5 feet wide measured from centerline to centerline. Where the access aisle is not adjacent to another parking space or access aisle, measurements shall be permitted to include the full width of the line defining the access aisle.	access aisle is 55" wide	Repaint access aisles to be 5' each	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		access aisle serving car parking spaces
288	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5975613 -99.730714 8]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 5 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		Metabolic Planty Bases  Planty Bases  Bases
289	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5975823 -99.730767 1]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	3.1% slope stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		4-4-4-88

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
290	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974283 -99.730584 7]	The rim of the urinal Is too high. Wall-hung urinals must be provided with an elongated rim projecting a minimum of 13 1/2 inches from the wall and a maximum of 17 inches above the floor.	both urinals installed at 25" above finished floor	Lower urinal so that rim height is max 17" aff	2015 ABAAS Section: 605.2 2012 TAS Section: 605.2 2010 ADAS Section: 605.2		13½ min 17 max
291	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974202 -99.730603 5]	The urinals flush handle is mounted too high. Flush controls shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist and shall be mounted no more than 48 inches above the floor. The force required to activate controls shall be no greater than 5 lb. Electronic automatic flushing controls are acceptable and preferable.	both urinal flush handles at 52" above finished floor	Lower flush handle at urinal to max 48" aff	2015 ABAAS Section: 605.4 2012 TAS Section: 605.4 2010 ADAS Section: 605.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
292	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974213 -99.730590 1]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	elements installed above reach range - light switch 54", hand dryer 59"	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		3) PM. 32 S PM. 31 S
293	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974237 -99.730586]	There are not enough accessible toilet compartments. The room contains 1 toilet compartments. A minimum of 1 must be wheelchair accessible .	lacks accessible toilet compartment	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
294	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974132 , -99.730602 1]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	grab bars do not meet length standards	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
295	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974167 -99.730588 7]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks installed 69" above finished floor	Remount at least one hook to max 48" aff and shelves to 40" - 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
296	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Men's	[29.5974202 , -99.730603 5]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	lacks accessible shower	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDARD ROLL-IN TYPE SHOWER COMPARTMENT COMPARTMENT STANDARD ROLL-IN TYPE SHOWER COMPARTMENT TO STANDARD ROLL-IN TYPE SHOWER STANDARD ROLL-IN TYPE SHOWER STANDARD ROLL-IN TYPE SHOWER TO STA

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
297	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974243 -99.730597 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	women's- garbage can used to prop door open, reduces width	Provide required maneuvering clearance around pull side of door Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	2015 ABAAS Section: 404.2.4.1, 404.2.4.4 2012 TAS Section: 404.2.4.4, 404.2.4.1	The state of the s
						2010 ADAS Section: 404.2.4.4, 404.2.4.1	
298	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974202 , -99.730582]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirror reflective surface mounted 41.5" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3	
299	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974155 -99.730587 4]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	rim of sink 34.5" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3  2012 TAS Section: 606.3  2010 ADAS Section: 606.3	Tore clearance    Compared to the Space   Compared to

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
300	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974202 , -99.730590 1]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY
301	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974178 -99.730610 2]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	elements mounted above reach range - hand dryer 58", hook 70", outlets and soap dispenser high and over sink	Lower operating mechanisms in to max 48" aff to highest operable part Lower to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2  2012 TAS Section: 308.2.1, 308.3.2  2010 ADAS Section: 308.2.1, 308.3.2		23 - 75 - 75 - 75 - 75 - 75 - 75 - 75 - 7

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
302	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974202 , -99.730592 7]	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of 1 must be wheelchair accessible.	ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS	8	
						Section: 213.3.1		
303	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974155 , -99.730598 1]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The	grab bars extend to 46" from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1		
		,,	end furthest from the rear wall must be mounted minimum 54" from the rear wall.			2012 TAS Section: 604.5.1		
						2010 ADAS Section: 604.5.1		
304	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974295 -99.730600 8]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser mounted 9" above grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	S. Thorong	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
305	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974038 , -99.730600 8]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser installed too close to front of toilet	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	view sp.
306	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974108 -99.730600 8]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer protrudes 5" into the circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	
307	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974202 -99.730588 7]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	9.6% slope at shower	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
308	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974248 -99.730595 4]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	hooks mounted 68.25" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
309	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974073 , -99.730595 4]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	40" wide, 41" deep	Correct transfer shower to compliant 36" by 36" clear inside dimension	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		Seed to back wall well will be control of a
310	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974178 -99.730608 8]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	chair in CFS	Provide appropriate CFS on the exterior of the transfer shower	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1		Seed Control Will Control Will W

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
311	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974132 -99.730587 4]	A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610.A folding or non-folding seat shall be provided in transfer type shower compartments. A folding seat shall be provided in roll-in type showers required in transient lodging guest rooms with mobility features complying with 806.2. Seats shall comply with 610. EXCEPTION: In residential dwelling units, seats shall not be required in transfer type shower compartments provided that reinforcement has been installed in walls so as to permit the installation of seats complying with 608.4.	lacks seat	Provide the required folding or non-folding seat in the transfer shower.	2015 ABAAS Section: 608.4, 608.4 EXCEPTION 2012 TAS Section: 608.4, 608.4 Exception 2010 ADAS Section: 608.4, 608.4 Exception	
312	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974108 , -99.730586]	There is no hand held sprayer unit. The sprayer unit must have a 59 inches hose and be mounted 48 inches maximum to the top of mounting bracket off the floor. The shower spray unit shall have an on/off control with a non-positive shutoff. If an adjustable-height shower head on a vertical bar is used, the bar shall be installed so as not to obstruct the use of grab bars.	lacks hand held spray unit	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held	2015 ABAAS Section: 608.6 2012 TAS Section: 608.6 2010 ADAS Section: 608.6	SHOWER SPRAY UNIT  Space Long Flexible Water Temperature: 120° F Max.  Top of mounting bracket: 48" Max. above the shower floor.  ©Builder's Book, Inc.
313	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	[29.5974169 -99.730660 6]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	gaps where deteriorated, 1" gap by women's	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	demonst distinct of total  Integ there are preparable in the advance frager  St. max.

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
314	Rio Frio Camping Area: Rio Frio Restroom Bldg 16 - Women's	-99.730728	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1" change in elevation at parking	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½ ½

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figur	re
315	River Crossing Camping Area: Sample Campsites	[29.5889818 -99.739336 7]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 10 electric campsites in this area are accessible; total of 215 electric campsites in the park	Create the required number of accessible electric camp sites per table F244.2 as a smart practice; cost included in Live Oak finding.	2015 ABAAS Section: F244.2		
316	River Crossing Camping Area: River Crossing Parking	[29.5898495 , -99.740586 7]	Element meets all standards and requirements	parking scoping complies- 1 of 7 stalls accessible	None	2010 ADAS Section: N/A		
317	River Crossing Camping Area: River Crossing Parking	[29.5898786 -99.740546 4]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	2.8% slope in stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		4
318	River Crossing Camping Area: River Crossing Parking	[29.5898833 , -99.740596]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	sign mounted 56.75" above ground surface	Raise existing accessible parking signs so lowest end of bottom sign is min 60" aff	2015 ABAAS Section: 502.6  2012 TAS Section: 502.6  2010 ADAS Section: 502.6	SSIBL Accessible	60 Inches min.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
319	River Crossing Camping Area: River Crossing Men's Restroom	[29.5898681 -99.740698]	The compartment door is not self closing. The water closet compartment shall be equipped with a door that has an automatic- closing device.	stall door is not self closing	Replace or adjust stall door of accessible stall with one that is self-closing	2015 ABAAS Section: 604.8.1.2 2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2		COMPARTMENT DOORS  Fig.  Construction  Fig.  Construction  Fig.  F
320	River Crossing Camping Area: River Crossing Men's Restroom	[29.5898658 -99.740689 9]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.3% slope at sinks	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
321	River Crossing Camping Area: River Crossing Men's Restroom	[29.5898938 , -99.740693 9]	The water flow from the spout is too low. The spout shall provide a flow of water 4 inches high minimum.	Drinking fountains off, unable to test	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	2015 ABAAS Section: 602.6  2012 TAS Section: 602.6  2010 ADAS Section: 602.6		4 inches min 0 0

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
322	River Crossing Camping Area: River Crossing Women's Restroom	[29.58986, -99.74066]	Thresholds, if provided at doorways, shall be 1/2 inch (13 mm) high maximum. Raised thresholds and changes in level at doorways shall comply with 302 and 303. Changes in level of ¼ inch (6.4 mm) high maximum shall be permitted to be vertical Changes in level between ¼ inch (6.4 mm) high minimum and ½ inch (13 mm) high maximum shall be beveled with a slope not steeper than 1:2. Changes in level greater than ½ inch (13 mm) high shall be ramped, and shall comply with 405 or 406.	women's- 1" change in elevation	Repair, bevel or ramp CIL at doorway	2015 ABAAS Section: 303.3, 404.2.5, 303.2, 303.4 2012 TAS Section: 303.3, 404.2.5, 303.2, 303.4 2010 ADAS Section: 303.3, 404.2.5, 303.2, 303.4	2 3 4 5	1/2 Max 64
323	River Crossing Camping Area: River Crossing Women's Restroom	[29.5898751 -99.740696 6]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.		Lower soap dispenser to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		22 PFM 100 100 100 100 100 100 100 100 100 100

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
324	River Crossing Camping Area: River Crossing Women's Restroom	[29.5898705 , -99.740696 6]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	garbage can in clearance	Relocate garbage can to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
325	River Crossing Camping Area: River Crossing Women's Restroom	[29.5898751 , -99.74071]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser mounted 11" above side bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	William St. St. William St.	
326	River Crossing Camping Area: River Crossing Women's Restroom	[29.5898751 -99.740703 3]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door is not self- closing	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
327	River Crossing Camping Area: River Crossing Women's Restroom	[29.589874, -99.740693 9]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser is not installed with the compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	3	Nam 8b
328	River Crossing Camping Area: River Crossing Women's Restroom	[29.5898681 -99.740688 6]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	tiles buckled	Repair, bevel or ramp CIL along AR to max .25"	2015 ABAAS Section: 303.3 2012 TAS Section: 303.3 2010 ADAS Section: 303.3		Уд 1 <sup>2</sup> Уд
329	River Crossing Camping Area: River Crossing RV Dump Station	[29.5896664 ,-99.741435 6]	There is no accessible route to the pump station. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route or clear floor space to hookups. Surface is deteriorated asphalt and grass	Create an accessible route with crushed stone or other outdoor material from parking or walkway to pump station	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Property of the Control of th

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
330	River Crossing Camping Area: River Crossing Showers	[29.5898635 -99.740702]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	1 of 4 showers designated accessible, lacks accessible features	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6		STANDARD ROLLIN TYPE SHOWER COMPACT NEW TEXT THE
331	River Crossing Camping Area: River Crossing Showers	[29.5899018 , -99.7407]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	access shower- 2.6% slope	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
332	River Crossing Camping Area: River Crossing Showers	[29.5898831 -99.740700 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm).	3 standard showers- 2.2%, 29" wide	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	ANTON	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
333	River Crossing Camping Area: River Crossing Showers	[29.589887, -99.740755 4]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.4% behind building	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3		
						2010 ADAS Section: 403.3		
334	River Crossing Camping Area: Frio Canyon Trailhead	[29.5903509 , -99.737907 1]	The surface of outdoor recreation access routes, passing spaces, and resting intervals shall be firm and stable	No accessible route to trail head	Repair surface or ORAR to be firm and stable as a smart practice.	2015 ABAAS Section: 1016. 2		
335	River Crossing Camping Area: Frio Canyon Trailhead	[29.5903603 -99.738073 4]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of 6 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	No accessible stalls in trail head parking - approximately 6 standard, 0 accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		Variation of Franch States (Section 1) and the Common States of Franch States (Section 1) and the Common Sta

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
336	Shady Meadows Camping Area: Sample Campsites	[29.5888535 -99.742461 5]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	No campsites have accessible features; 26 electric campsites provided in this area, 215 total in park; 12 full hook-up campsites provided in this area and in the park	Create the required number of accessible camp sites of each type provided per table F244.2 as a smart practice; cost for electric sites included in Live Oak finding	2015 ABAAS Section: F244.2		
	ı							
337	Shady Meadows Camping Area: Shady Meadows RV Dump Station	[29.5896734 , -99.741436 9]	There is no accessible route to the hookups. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to hookups. Surface is deteriorated asphalt and grass	Create an accessible route with crushed stone or other outdoor material from parking or walkway to hookups	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Printing  Control of the Cont
338	Shady Meadows Camping Area: Cowboy Theater	[29.5884477 , -99.742874 6]	The running slope of walking surfaces shall not be steeper than 1:20.	11.6% running slope to covered area	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
339	Shady Meadows Camping Area: Cowboy Theater	[29.5883124 -99.742747 2]	There is no accessible route between the performance area and the assembly seating area. Where a circulation path directly connects a performance area to an assembly seating area, an accessible route shall directly connect the assembly seating area with the performance area.	lacks a route between performance area and seating area	Create an accessible route connecting assembly seating to performance area	2015 ABAAS Section: F206.2.6 2012 TAS Section: 206.2.6 2010 ADAS Section: 206.2.6	
340	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891953 , -99.741712 2]	There is no accessible route to the site elements. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	lacks AR to 4 benches, 1 garbage, 1 picnic table	Create an accessible route with crushed stone or other outdoor material from parking or walkway to site elements	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2	ACCESSIBLE ENTRANCES  PIPPY  P
341	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891661 -99.741817 8]	There is no accessible route to the play area. Accessible routes serving play areas shall comply with Chapter 4 and 1008.2 and shall be permitted to use the exceptions in 1008.2.1 through 1008.2.3. Where accessible routes serve ground level play components, the vertical clearance shall be 80 inches high (2030 mm) minimum.	lacks AR to play area	Create an AR to the play area within the site	2015 ABAAS Section: F206.2.2  2012 TAS Section: 1008.2  2010 ADAS Section: 206.2.2	ACCESSRILE ELIMENTS  Transmitted  Transmitte

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
342	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891684 , -99.741824 5]	Play area lacks designated entry. As a smart practice, play area should have a minimum 60" wide entry, free of changes in level, gaps, and slope.	lacks designated entry, border creates CIL around playground	Create designated entry by removing 60" portion of play area boundary as a smart practice	2015 ABAAS Section: F206.1  2012 TAS Section: 206.1  2010 ADAS Section: 206.1		
343	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891603 -99.741825 8]	Compliance with ASTM F 1951 for accessibility for ground surfaces on accessible routes, clear floor or ground spaces, and turning spaces has not been determined. Ground surfaces shall comply with ASTM F 1951. Ground surfaces shall be inspected and maintained regularly and frequently to ensure continued compliance with ASTM F 1951.	assumed EWF surface, uncertain	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces Establish protocols for regular and frequent inspection and maintenance of accessible playground surface Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	2012 TAS Section: 1008.2.6.1 2010 ADAS Section: 1008.2.6.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
344	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891626 -99.741829 9]	Element meets all standards and requirements	5 of 9 EPCs comply- on AR ring climber, suspended bridge, captain wheel, mirror, dual slide; lacks AR due to large ClLs- corkscrew slide, bar climber, tall slide, viewing bubble	None	2010 ADAS Section: N/A		
ı								

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
345	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891603 -99.741824 5]	Element meets all standards and requirements	meets one of each type of GLPC compliant (3 manipulables - steering wheel, letter spinner, abacus)	None	2010 ADAS Section: N/A		
346	Shady Meadows Camping Area: Shady Meadows Playground	[29.5891591 , -99.741825 8]	There are not enough accessible ground level play components based on the number of elevated play components. There should be a minimum of 3 accessible ground level play components of 3 types	only one type provided (3 manipulables)	Add 2 more GLPCs of 2 types to meet incentive scoping	2012 TAS Section: 240.2.1.2 2010 ADAS Section: 240.2.1.2		This peak of Section of Section 1 and Sectio

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
347	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886529 ,-99.74379 49], [29.5886716 ,-99.743735 9]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1.75" CIL between bridge and building, multiple .5" CILs on bridge, 1" on restroom side of bridge, CIL where shifted at tree	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½
348	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886838 ,-99.74368 07], [29.5886418 ,-99.743825 5]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	4.8% between bridge and building, 3% on bridge, 9.1% where shifted at tree	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3	ANT COUNTY OF THE PROPERTY OF	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
349	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.588694, -99.743655 4], [29.588631, -99.743875 3]		gaps up to 3" near entry, 1" crack at tree, 2" at edge of sidewalk	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	Nor de manuel de la constant de la c	described distribute of Stand
350	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5885713 , -99.744164 7]	requirements	dining hall- parking scoping complies, 19 standard 1 accessible	None	2010 ADAS Section: N/A		
351	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886005 -99.744180 8]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 21 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	dining hall- lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2.4		We consider the constraint of

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
352	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.588569, -99.744156 7]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	dining hall- parking stall 3.5% slope, access aisle 5.4% slope	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		4 4 4
353	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5885713 , -99.744167 4]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	dining hall- loose surface in parking stall	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		½ max ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½
354	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886694 ,-99.744192 2]	There is no accessible route to the site elements. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	lacks accessible route to picnic table and grill	Create an accessible route with crushed stone or other outdoor material from parking or walkway to picnic table and grill.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACESSIBLE ENTRANCES  POPUT PRINCE  Application of the control of t

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
355	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886418 , -99.74397 82], [29.588615, -99.744117 7]	The accessible path of travel between the building entrance and the accessible parking contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	cross slopes on accessible route to parking 2.9%, 4.7%, 2.3%	Correct or repair sidewalk cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
356	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886375 -99.74406], [29.5886153 -99.744117 7]	not be steeper than 1:20.	Running slopes of 10.7%, 8%	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
357	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5885587 -99.743894 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	restroom side entry- 11#, closes fast, 28.5" wide, 3.9% slope	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	MANATORIS DE LA CONTRACTORIS DE	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
358	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886501 -99.743931 7]	Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor. EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11.	parking entry- 16#, closes fast, window 51.5", 28.5" wide	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
359	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886183 -99.743916 1]	Element meets all standards and requirements	dining hall main space complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
360	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886168 -99.743920 6]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink rim installed 37.5" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3	Tee cl	1)* min 8' min 10 min 1
						2010 ADAS Section: 606.3		
361	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886215 , -99.743924 7]	Controls for faucets shall comply with 309. Hand-operated metering faucets shall remain open for 10 seconds minimum. Operable parts shall be operable with one hand and shall not require tight grasping,	knob controls require grasp/twist	Replace sink/shower hardware with one operable without a tight pinch or grasp.	2015 ABAAS Section: 309.4, 606.4 2012 TAS		
			pinching, or twisting of the wrist. The force required to activate operable parts shall be 5 pounds (22.2 N) maximum.			Section: 309.4, 606.4 2010 ADAS		
						Section: 309.4, 606.4		
362	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.588625, -99.743912 6]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5		ACCESSIBLE LAVATORY
						2010 ADAS Section: 606.5		
363	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886366 , -99.743923 3]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe	knee clearance 24.25" above finished floor	Remove base cabinet and lower sink height to max 34" aff	2015 ABAAS Section: 606.2, 804.4		9 mm \$ 5
		,	clearance.			2012 TAS Section: 606.2, 804.4		pan pan
						2010 ADAS Section: 606.2, 804.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos F	igure
364	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886098 -99.743909 9]	The fire extinguisher projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	fire extinguisher protrudes 7" if garbage can moved	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		
365	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5885923 -99.743912 6]	The controls are positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	hood controls high	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1	10 me	48 max 48 max
366	Shady Meadows Camping Area: Shady Meadows Dining Hall	[29.5886086 -99.743920 6]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	serving counter 39.5" above finished floor	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1	*36°m	36"max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
367	Shady Meadows Camping Area: Shady Meadows Shower 1	[29.5887896 -99.743321 7]	Element meets all standards and requirements	outdoor sink at bathhouse complies	None	2010 ADAS Section: N/A		
368	Shady Meadows Camping Area: Shady Meadows Shower 1	[29.5887906 -99.743306 4]	The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground.	bench seat 21" above finished floor	Remount bench with a seat height of 17" to 19" aff	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min
369	Shady Meadows Camping Area: Shady Meadows Shower 1	[29.5887789 -99.743314 5]	The operable parts of controls are not located correctly. In standard roll-in type shower compartments, the controls, faucets, and shower spray unit shall be located above the grab bar, but no higher than 48 inches (1220 mm) above the shower floor. Where a seat is provided, the controls, faucets, and shower spray unit shall be installed on the back wall adjacent to the seat wall and shall be located 27 inches (685 mm) maximum from the seat wall. Advisory 608.5.2 Standard Roll-In Type Shower Compartments. In standard roll-in type showers without seats, the shower head and operable parts can be located on any of the three walls of the shower without adversely affecting accessibility.	shower diverter installed below bar	Remount shower controls to the correct location in the roll in shower	2015 ABAAS Section: 608.5.2 2012 TAS Section: 608.5.2 2010 ADAS Section: 608.5.2		our to code on any out of above.  Officers of the code

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
370	Shady Meadows Camping Area: Shady Meadows Shower 1	[29.5887812 -99.743322 5]	There is no hand held sprayer unit. The sprayer unit must have a 59 inches hose and be mounted 48 inches maximum to the top of mounting bracket off the floor. The shower spray unit shall have an on/off control with a non-positive shutoff. If an adjustable-height shower head on a vertical bar is used, the bar shall be installed so as not to obstruct the use of grab bars.	no shower head provided on hose	Replace shower control with a compliant lever control with a shower head on a 59" hose and usable as hand held	2015 ABAAS Section: 608.6  2012 TAS Section: 608.6  2010 ADAS Section: 608.6		SHOWER SPRAY UNIT  59° Long Flexible Hose Temperature: 120° F Max.  Top of mounting bracket: 48" Max. above the shower floor.
371	Shady Meadows Camping Area: Shady Meadows Shower 1	[29.588792, -99.743316 8]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	shower 1 door - 11lb force to open	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
372	Shady Meadows Camping Area: Shady Meadows Shower 2	[29.5887843 -99.743323 6]	Shower room must comply with requirements for doors, benches, and shower compartments	shower 2 (adjacent to men's) is out of order, assume similar to other 3	Ensure shower room is compliant, see other shower rooms for possible corrections.	Capture Section: 1		
373	Shady Meadows Camping Area: Shady Meadows Shower 3	[29.5887753 -99.743312 9]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	shower 3- 12lb of force to open, closes fast	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
374	Shady Meadows Camping Area: Shady Meadows Shower 3	[29.5887836 -99.743311 8]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground.	bench seat 21" above finished floor	Lower bench to provide seat height 17" to 19" aff	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench 48" min
375	Shady Meadows Camping Area: Shady Meadows Shower 3	[29.5887766 -99.743322 5]	The operable parts of controls are not located correctly. In standard roll-in type shower compartments, the controls, faucets, and shower spray unit shall be located above the grab bar, but no higher than 48 inches (1220 mm) above the shower floor. Where a seat is provided, the controls, faucets, and shower spray unit shall be installed on the back wall adjacent to the seat wall and shall be located 27 inches (685 mm) maximum from the seat wall. Advisory 608.5.2 Standard Roll-In Type Shower Compartments. In standard roll-in type showers without seats, the shower head and operable parts can be located on any of the three walls of the shower without adversely affecting accessibility.	shower diverter installed below grab bar	Remount shower controls to the correct location in the roll in shower	2015 ABAAS Section: 608.5.2 2012 TAS Section: 608.5.2 2010 ADAS Section: 608.5.2		CONDENSIONS  SECURITION  SECUR

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
376	Shady Meadows Camping Area: Shady Meadows Shower 4	[29.5887719 -99.743319 8]	The bench is not deep enough or long enough or is missing. Benches shall be provided having seats that are 42 inches long minimum and 20 inches deep minimum and 24 inches deep maximum. The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be 2½ inches (64 mm) maximum from the rear edge of the seat measured horizontally. The top of the bench seat surface shall be 17 inches (430 mm) minimum and 19 inches (485 mm) maximum above the finish floor or ground.		Lower bench to provide seat height 17" to 19" aff	2012 TAS Section: 903.4, 903.2, 903.3, 903.5 2010 ADAS Section: 903.4, 903.2, 903.3, 903.5		Bench  48" min
377	Shady Meadows Camping Area: Shady Meadows Shower 4	[29.5887789 -99.743327 9]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	10lb of force to open	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
378	Shady Meadows Camping Area: Shady Meadows Men's Restroom	[29.5887789 -99.743309 1]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	11 lb of force to open door	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
379	Shady Meadows Camping Area: Shady Meadows Men's Restroom	[29.5887812 -99.743317 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	grab bar installed 36.5" above finished floor	Remount grab bars in accessible stall to 33" to 36" aff	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
380	Shady Meadows Camping Area: Shady Meadows Men's Restroom	[29.5887859 -99.743314 5]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.6% cross slope near drain	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
381	Shady Meadows Camping Area: Shady Meadows Men's Restroom	[29.5887714 -99.743312 4]	The bench seat is not within compliant height range. The top of the bench seat must be 17 inches minimum to 19 inches maximum above the finish floor.	left bench 21", right bench 21.25"	Lower bench to provide seat height 17" to 19" aff	2015 ABAAS Section: 903.5 2012 TAS Section: 903.5 2010 ADAS Section: 903.5		17"-19"
382	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887783 , -99.743326 3]	Exterior doors exceed 8.5 lbs of force to open; fire doors shall have a minimum opening force allowable by the appropriate administrative authority	women's- 10 lb force to open	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	2010 ADAS Section: 404.2.9		
383	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887859 -99.743327 9]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink rim installed 34.5" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		None cleanance    Tot. cleanance   Tot.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
384	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887859 -99.743327 9]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	soap dispensers mounted 46.5" and over sink	Lower soap dispenser to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
385	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887789 -99.743311 8]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	rear grab bar mounted 11" to wall side	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2		Top of bar 333-36°

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
386	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887859 -99.743325 2]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	side grab bars are mounted 36.75" above finished floor	Remount grab bars in accessible stall to 33" to 36" aff	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4	
387	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887859 -99.743317 1]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door not self- losing	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.3, 404.2.7, 604.8.2.2	
388	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.5887894 -99.743319 8]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	3% slope at drain	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
389	Shady Meadows Camping Area: Shady Meadows Women's	[29.5887863 , -99.743318 3]	The bench seat is not within compliant height range. The top of the bench seat must be 17 inches minimum to 19 inches maximum above the finish floor.	bench seat installed 21.75" above finished floor	Lower bench to provide seat height 17" to 19" aff	2015 ABAAS Section: 903.5		
	Restroom	0]	The American above the linest hoof.			2012 TAS Section: 903.5		17" - 19"
						2010 ADAS Section: 903.5		
390	Shady Meadows Camping Area: Shady Meadows Women's Restroom	[29.58875, -99.74331]	Element meets all standards and requirements	drinking fountain at restrooms complies	None	2010 ADAS Section: N/A		
391	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915101 -99.741618]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks accessible signage	Acquire and mount signage, including Braille, raised lettering and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character.	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
392	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915148 -99.741623 3]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	44" to bottom of reflective surface	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		
393	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915171 , -99.741613 9]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink rim 36.75" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		Toe clearance    Toe clearance
394	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915241 -99.741611 3]	The faucet controls require twisting of the wrist. Faucet controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 lb. Lever-operated, push-type and electronically controlled mechanisms are examples of acceptable designs. Self-closing valves are allowed if the faucet remains open for at least 10 seconds.	requires tight grasp	Replace faucet controls with lever controls	2015 ABAAS Section: 606.4 2012 TAS Section: 606.4 2010 ADAS Section: 606.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
395	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915195 -99.741613 9]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	elements mounted out of reach range - hand dryer 58", hook 62"	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
396	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915171 -99.741622]	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of 1 must be wheelchair accessible .	ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
397	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915171 , -99.741613 9]	The door to the ambulatory compartment swings into the minimum required compartment area. Toilet compartment doors shall not swing into the minimum required compartment area.	lacks stall door	Replace stall door of ambulatory stall with one that swings out and is self-closing	2015 ABAAS Section: 604.8.2.2 2012 TAS Section: 604.8.2.2 2010 ADAS Section: 604.8.2.2		
398	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915043 -99.741618]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	side grab bars 32"	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" aff	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4  2012 TAS Section: 609.4, 609.3, 604.8.2.3  2010 ADAS Section: 609.3, 609.4, 604.8.2.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
399	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915113 -99.741619 3]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	mounted 17" from back wall, 49" total	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	
400	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915171 -99.741613 9]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	reduces to 28" due to garbage can	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	24 max 48 min 48
401	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.5915125 -99.741619 3]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.3% cross slope at stall	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
402	Shady Meadows Camping Area: Shady Meadows North Area Men's Restroom	[29.591513, -99.741614 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.	men's- 9.9% slope, garbage can push side, 10#, closes fast	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
403	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.591524, -99.741620 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%.	women's- 7.5% slope	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	MARY III.	
404	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915125 -99.741613 9]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks Braille and raised characters, lacks sign at door	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
405	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915113 -99.741620 6]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	reflective surface is mounted 41.5" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3	
			assets the inner need of ground.			2010 ADAS Section: 603.3	
406	Shady Meadows Camping Area: Shady Meadows North Area	[29.5915148 , -99.741627 4]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim	sink rim 36.75" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3	Frein Seaconse Toe clearance Toe clearance
	Women's Restroom	,,	or counter edge no higher than 34 inches above the finished floor.			2012 TAS Section: 606.3	6° deep top space
						2010 ADAS Section: 606.3	
407	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915171 -99.741618]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5	ACCESSIBLE LAVATORY  Plas may or reports
						2010 ADAS Section: 606.5	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
408	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915113 -99.741616 6]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	hand dryer mounted 57" above finished floor	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		32 mm and a second a second and
409	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.591516, -99.741618]	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of 1 must be wheelchair accessible .	ambulatory stall only	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	2015 ABAAS Section: F213.3.1 2012 TAS Section: 213.3.1 2010 ADAS Section: 213.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
410	Shady Meadows Camping Area: Shady Meadows North Area	[29.5915125 , -99.741620 6]	The ambulatory stall is not between 35" to 37" wide and 60" deep.	stall is 58.25" deep	Correct ambulatory stall to be 35" to 37" wide and minimum 60" deep	2015 ABAAS Section: 604.8.2.1	\$ 1 0 C	00 min 1623
	Women's Restroom	oj				2012 TAS Section: 604.8.2.1		35.37 30.0000 \$\frac{1}{2} \text{ \$\frac{1}{2} \text{ \$\frac{1}{
						2010 ADAS Section: 604.8.2.1		
411	Shady Meadows Camping Area: Shady Meadows North Area Women's	[29.5915241 , -99.741616 6]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door 30" wide, not self-closing	Widen stall doors to 32" when opened to 90 degrees Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2		
	Restroom					2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2		
						2010 ADAS Section: 404.2.3, 404.2.7,		
						604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
412	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915148 -99.741619 3]	Grab bars shall comply with 609. A side-wall grab bar complying with 604.5.1 shall be provided on both sides of the compartment. The space between the wall and the grab bar shall be 1½ inches (38 mm). The space between the grab bar and projecting objects below and at the ends shall be 1½ inches (38 mm) minimum. The space between the grab bar and projecting objects above shall be 12 inches (305 mm) minimum. Grab bars shall be installed in a horizontal position, 33 inches (840 mm) minimum and 36 inches (915 mm) maximum above the finish floor measured to the top of the gripping surface, except that at water closets for children's use complying with 604.9, grab bars shall be installed in a horizontal position 18 inches (455 mm) minimum and 27 inches (685 mm) max	30" grab bars	Replace or add side grab bars with a 42" long grab bar, mounted max 12" from the rear wall at the close end and min 54" on the far end and 33" to 36" aff	2015 ABAAS Section: 604.8.2.3, 609.3, 609.4 2012 TAS Section: 609.4, 609.3, 604.8.2.3 2010 ADAS Section: 609.3, 609.4, 604.8.2.3	
413	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915206 -99.741615 3]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	bars too far from back wall	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1	
414	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915148 -99.741619 3]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	no dispenser, toilet paper stored left on grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	To and the second secon

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
415	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.5915171 ,-99.741622]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	60" clear turning space blocked with garbage can	Relocate obstacles to create turning space in restroom	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2		60 min
416	Shady Meadows Camping Area: Shady Meadows North Area Women's Restroom	[29.591526, -99.741791 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	multiple 1" gaps on path to men's, gap where damaged along edge on women's side	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3	OS D C Z GI	dependent described of transit.  Integral dependency perpendicular for manufacturar described of transit.  35 max.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
417	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.5899407 -99.743467 1]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	Frio Canyon trail rough gravel at trailhead by garden, sandy surface	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2	
418	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.5908957 -99.743972 2]	,	no accessible route to building, mulch, some loose crushed stone	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance	2015 ABAAS Section: F206.2.1  2012 TAS Section: 206.2.1  2010 ADAS Section: 206.2.1	
419	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.59091, -99.74396]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The threshold has a vertical change greater than 1/4 inch high.	entry- bench push side, change in elevation	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
420	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.5908944 -99.743968 9]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	28.5" to pass bench, less on side with whiteboard	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	THE REPORT OF THE PARTY OF THE	24 max
421	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.590897, -99.743964 9]	Each distinct viewing location shall provide a viewing space adjacent to the clear ground space required by 1015.2 through which the point of interest is viewable. The viewing space shall be 32 inches (815 mm) maximum and 51 inches (1295 mm) minimum high above the ground and shall extend the full width of the clear ground space.	rail at 39" in view interior, bottom of lowest exterior at 45"	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51"	2015 ABAAS Section: 1015.3		
422	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.5908948 -99.743969 7]	A turning space complying with 304.3 (60" by 60" or T shaped) shall be provided within viewing areas. The surface of clear ground spaces and turning spaces shall be firm and stable. The slope of the surface of clear ground spaces and turning spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	dirt surface at exterior viewing	Repair surface of viewing are clear ground space to be firm, stable and having max 2.08% slope or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1015.4, 1015.5, 1015.6, 1015.6 EXCEPTION		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
423	Shady Meadows Camping Area: Shady Meadows Viewing Area	[29.5908871 -99.743969]	The donation box is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	donation box 49", lacks clear floor space	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		15 min 15
424	Shady Meadows Camping Area: Shady Meadows Showers Parking	[29.5888279 , -99.743199 1]	Element meets all standards and requirements	parking scoping complies, 1 of 3 stalls accessible	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
425	Employee Spaces: Maintenance	[29.5917317 -99.738891 5]	Employee Work Areas. Common use circulation paths within employee work areas shall comply with 402. EXCEPTIONS:  1. Common use circulation paths located within employee work areas that are less than 1000 square feet (93 m2) and defined by permanently installed partitions, counters, casework, or furnishings shall not be required to comply with 402. 2. Common use circulation paths located within employee work areas that are an integral component of work area equipment shall not be required to comply with 402. 3. Common use circulation paths located within exterior employee work areas that are fully exposed to the weather shall not be required to comply with 402.	sign shop- 17" width due to work table	Make corrections for compliant circulation path.	2015 ABAAS Section: F206.2.8, F206.2.8.1, F206.2.8.2  2012 TAS Section: 206.2.8, 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 3, 206.2.8 Advisory 1, 206.2.8 Advisory 2  2010 ADAS Section: 206.2.8, 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 3,		
426	Employee Spaces: Maintenance	[29.591741, -99.738931 7]	Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater	sign shop- 1.5" change in elevation at doorway, 77.5" high, 29" wide, knob at 51.5", bottom 10" not smooth	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp mounted between 34" and 48" aff. For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" AFF.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number			than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.					

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
427	Employee Spaces: Maintenance	[29.5917457 -99.738937 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	maintenance restroom- lacks maneuvering clearance on push side	Provide required maneuvering clearance around pull side of door	2015 ABAAS Section: 404.2.4.1, 404.2.4.4 2012 TAS Section: 404.2.4.4, 404.2.4.1 2010 ADAS Section: 404.2.4.4, 404.2.4.1		Description of the second of t
428	Employee Spaces: Maintenance	[29.591748, -99.738913]	The door opening does not provide at least 32 inches between the face of the door and the opposite stop. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	maintenance restroom- door width 22"	Replace door with one having 32" clear width	2015 ABAAS Section: 404.2.3 2012 TAS Section: 404.2.3 2010 ADAS Section: 404.2.3		32 min By By B
429	Employee Spaces: Maintenance	[29.5917504 , -99.738883 5]	The operating hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist to operate. Handactivated hardware, handles, pulls, latches, locks, and other operating devices on accessible elements shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate.	maintenance restroom- lacks door hardware	For all doors along the public circulation route, replace hardware with lever hardware where indicated	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4		Lever Panic Bar Loop Handle Operating hardware must be centered between 34" and 44" above the floor or ground

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
430	Employee Spaces: Maintenance	[29.5917574 -99.738907 6]	The door must have a smooth surface within 10 inches of the floor on the push side. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. All gates, including ticket gates, shall meet all applicable specifications for doors.	maintenance restroom- lacks smooth surface on push side	Provide kick plate on push side of door from floor to 10" aff	2015 ABAAS Section: 404.2.10 2012 TAS Section: 404.2.10 2010 ADAS Section: 404.2.10		
431	Employee Spaces: Maintenance	[29.591741, -99.738872 7]	The restroom is not compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lavatory. The entry door does not contain the required minimum maneuvering spaces on the pull/push sides. The entry door encroach into the required clear floor space for fixtures. Grab bars are missing and/or incorrectly installed. Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both.	restroom is not compliant	Create a compliant wheelchair accessible restroom and correct all features to be accessible if feasible.	2015 ABAAS Section: 603.1  2012 TAS Section: 603.1  2010 ADAS Section: 603.1		SO' MIN. CLEAR SO' MIN.
432	Employee Spaces: Maintenance	[29.591755, -99.738867 4]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	small T shaped restroom, not accessible	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8  2012 TAS Section: 216.8  2010 ADAS Section: 216.8		RESTROOM

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
433	Employee Spaces: Maintenance	[29.591748, -99.738864 7]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks signage	Acquire and mount signage, including Braille and raised characters mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC Name
434	Employee Spaces: Maintenance	[29.591741, -99.738888 8]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	break room- accessible route width reduced to 32" at coffee bar	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max. 40 min. 24 max. 25 max. 26 max. 27 max. 28 max. 29 max. 29 max. 20 max. 20 max. 20 max. 20 max. 20 max. 21 max. 22 max. 23 max. 24 max. 25 max. 26 max. 27 max. 28 max. 29 max. 20 max. 20 max. 20 max. 20 max. 20 max. 21 max. 22 max. 23 max. 24 max. 25 max. 26 max. 27 max. 28 max. 29 max. 20 max. 21 max. 22 max. 23 max. 24 max. 25 max. 26 max. 27 max. 28 max. 29 max. 20 max. 21 max. 22 max. 23 max. 24 max. 25 max. 26 max. 27 max. 28 max. 28 max. 28 max. 29 max. 20 max. 21 max. 22 max. 23 max. 24 max. 25 max. 26 max. 27 max. 28 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
435	Employee Spaces: Maintenance	[29.5917457 -99.738872 7]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	break room- relocate furniture/storage to provide turning space	Relocate obstacles to create turning space in break area.	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2		60 min 60
436	Employee Spaces: Maintenance	[29.5917434 -99.738862]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	break room- fire extinguisher lacks clear floor space due to furniture, width 26"	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min
437	Employee Spaces: Maintenance	[29.5917457 ,-99.738862]	The controls are positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	break room- controls for oven hood controls 65"	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1		48 max 48 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
438	Employee Spaces: Maintenance	[29.5917504 , -99.738867 4]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	break room- sink rim installed 36.25" above finished floor, lacks knee clearance with oven provided	Remove base cabinet and lower sink height to max 34" aff	2015 ABAAS Section: 606.3  2012 TAS Section: 606.3  2010 ADAS Section: 606.3		Fore clearance  Tor clearance  6° deep tor space
439	Employee Spaces: Maintenance	[29.5917166 -99.738719 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%. The threshold has a vertical change greater than 1/4 inch high. Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	yellow storage building- 2.25" CIL at door, lacks compliant landing area, knob	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
440	Employee Spaces: Maintenance	[29.5917189 -99.738765 4]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	middle section- change in level, lacks accessible route, fire extinguisher on door	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Repair, bevel, or ramp CILs at door entries to max .25". Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
441	Employee Spaces: Maintenance	[29.591888, -99.738811]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	wood shop large doors- lacks AR, cabinet pull side; wood shop side door- step push side, 29" wide, 3.1%, large threshold	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Correct slope in door clearance to max 2.08%. Replace doors with doors having 80" overhead clearance and 32" clear width. Repair, bevel, or ramp CILs at door entries to max .25".	2015 ABAAS Section: F203.9  2012 TAS Section: 203.9  2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
442	Employee Spaces: Maintenance	[29.591881, -99.738805 7]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	right side storage room- lacks AR, slope, CIL, equipment and shelf back push side	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Correct slope in door clearance to max 2.08%. Repair, bevel, or ramp CILs at door entries to max .25". Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	
443	Employee Spaces: Maintenance	[29.5860371 -99.736136 9]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	park host laundry- clear width reduces to 27"	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	24 max
444	Employee Spaces: Maintenance	[29.5861292 -99.736163 7]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	park host laundry- lacks turning space due to equipment and storage	Relocate obstacles to create turning space in utility room.	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2	60 min  12 min  12 min  12 min  12 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
445	Employee Spaces: Maintenance	[29.5861661 -99.736129 3]	The threshold has a vertical change greater than 1/4 inch high.	Park host laundry- lacks AR, CIL	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" Create AR to laundry room entry	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		
446	Employee Spaces: Maintenance	[29.5915974 -99.738865 2]	There is no accessible route between the buildings. At least one accessible route shall connect accessible buildings, facilities, elements and spaces that are on the same site.	lacks AR to outbuildings, dirt parking, dirt surface at bays	Create AR with crushed and compacted stone or similar outdoor material from building to building within the site	2015 ABAAS Section: F206.2.2  2012 TAS Section: 206.2.2  2010 ADAS Section: 206.2.2		ACCESSIBLE DATRANCES  Printing of the printing

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
447	Employee Spaces: Maintenance	[29.5916483 -99.739144 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor.  EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11.	break room building- entries have stairs, railing pull side both, window high both, one door has knob	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		
448	Employee Spaces: Maintenance	[29.5916431 -99.739135 6]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	break room trailer- restroom lacks accessible features, lacks directional signage	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8  2012 TAS Section: 216.8  2010 ADAS Section: 216.8		RESTROOM

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
449	Employee Spaces: Maintenance	[29.5916431 -99.739142 3]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	break room trailer- lacks signage	Acquire and mount signage, including Braille and raised characters mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.
450	Employee Spaces: Maintenance	[29.5916395 -99.739138 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	break room trailer restroom- sliding door lacks hardware outside, garbage can in maneuvering clearance	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
451	Employee Spaces: Maintenance	[29.59166, -99.73915]	The controls are located such that operation require reaching across burners. Where knee and toe space is provided, the underside of the range or cooktop shall be insulated or otherwise configured to prevent burns, abrasions, or electrical shock. The location of controls shall not require reaching across burners	break room trailer- oven controls at back of unit	Replace oven with one having controls on the front panel	2015 ABAAS Section: 804.6.4 2012 TAS Section: 804.6.4 2010 ADAS Section: 804.6.4		20.25 max 20.25 max 20.25 max (a)

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Fi	gure
452	Employee Spaces: Maintenance	[29.5916722 , -99.738591 1]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	front storage- change in level at entry, knob hardware, window high, doorway 30" wide	Replace doors with doors having 80" overhead clearance and 32" clear width. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Replace doors with ones having sidelight viewing windows max 43" AFF.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
453	Employee Spaces: Maintenance	[29.5917037 -99.738626]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	rear storage buildings- stairs and knob at raised building, ramp and grass at other structure, knob	Provide required maneuvering clearance on push and pull side of doors. Repair, bevel, or ramp CILs at door entries to max .25". Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		
454	Employee Spaces: Maintenance	[29.5914863 -99.738865 8]	There is no accessible route to the maintenance bays. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	maintenance bays located off driveway, some gravel surface	Create an accessible route with crushed stone or other outdoor material from parking or walkway to maintenance bays	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2	ACCESSIBILITY OF THE PROPERTY	LE ENTRANCES  POPUT gent of the property of th

	1	T	T					
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
455	Employee Spaces: Maintenance	[29.5916378 -99.739133 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	shop restroom new area- 5.6% slope, wall pull side, 28" wide, knob, 2" change in level	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
456	Employee Spaces: Maintenance	[29.5918763 -99.738829 8]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	shop restroom new area- restroom lacks accessible features, lacks directional signage	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8 2012 TAS Section: 216.8 2010 ADAS Section: 216.8		TAL RESTROOM
457	Employee Spaces: Maintenance	[29.591888, -99.738811]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	shop restroom new area- restroom lacks signage	Acquire and mount signage, including Braille and raised characters mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC

458	Employee Spaces: On Moadrone	[29.5862529	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is	Approach to	Repair, bevel or ramp change in level along	2012 TAS	1/2 max
	Walkway	-99.736556 6] Wheel: N/A Dir: SW	the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	residence door has changes in elevation and the walkway is uneven flagstone	accessible route. Repair or reset pavers to eliminate change in level.	Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	74 2 12 12 12 12 12 12 12 12 12 12 12 12 1
				T			
459	Employee Spaces: Residence 2	[29.5887253 , -99.746334 6] Wheel: N/A Dir: SW	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	Approach to residence door has a change in level but is otherwise firm and stable	Repair, bevel or ramp change in level along accessible route.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	½ max ½ 2 ½ ½ 1 2 ½
460	Employee Spaces: Residence 3	[29.5950156 , -99.728374 6] Wheel: N/A Dir: SW	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	Approach to residence door has changes and level along the walkway	Repair, bevel or ramp change in level along accessible route.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	½ max ½ ½ ½ ½ ½

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
461	Employee Spaces: Residence 4	[29.6020659 , -99.730930 7] Wheel: N/A Dir: SW	The building entrance is not located on an accessible route. When a building, or portion of a building, is required to be accessible, an accessible route of travel shall be provided to all portions of the building, to accessible building entrances and between the building and the public way. All walks, halls, corridors, aisles, skywalks, tunnels, and other spaces that are part of an accessible route must comply. An accessible route of travel must not pass through kitchens, storage rooms, restrooms, closets or other spaces used for similar purposes. At least one accessible route within the boundary of the site must be provided from public transportation stops, accessible parking and accessible passenger loading zones and public streets or sidewalks to the accessible building entrance they serve. The accessible route shall, to the maximum extent feasible, coincide with the route for the general public. At least one accessible route shall connect accessible buildings, facilities, elements and spaces that are on the same site. At least one accessible spaces and elements.	Approach to residence door has changes and level and the walkway is uneven flagstone	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance	2015 ABAAS Section: F206.2.1 2012 TAS Section: 206.2.1 2010 ADAS Section: 206.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
462	Oakmont Camping Area: Oakmont Mini Golf	[29.58447, -99.73384]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	entry- surface surrounding door loose, knob hardware, 8% slope	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
463	Oakmont Camping Area: Oakmont Mini Golf	[29.5844801 -99.733857]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	service counter fails	Lower 36" wide segment of service counter to max 36" aff and keep clear of storage	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1	36° min 36° max
464	Oakmont Camping Area: Oakmont Mini Golf	[29.5844551 -99.733833 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The threshold has a vertical change greater than 1/4 inch high	rear door- lacks accessible route, change in level at door	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors and extend an accessible route to the door For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
465	Oakmont Camping Area: Oakmont Mini Golf	[29.5844566 , -99.733856 3]	There is no accessible route to the mini golf holes. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	surface provided is in extreme disrepair	Create an accessible route with crushed stone or other outdoor material from parking or walkway to at least 50% of mini golf holes that are consecutive	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  PROPERTY AND ADMINISTRATION OF THE PROPERTY AND ADMINISTRATION O
466	Oakmont Camping Area: Oakmont Mini Golf	[29.5844341 -99.733829 5]	Benches shall have a 36" by 48" clear ground space (CGS) positioned near the bench with one side of the space adjoining an outdoor recreation access route (ORAR) or trail, as applicable The CGS shall not overlap with the ORAR or trail or another CGS	5 benches lack CFS at mini golf	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice.	2015 ABAAS Section: 1011.2.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
467	Oakmont Camping Area: Oakmont Pavilion Parking	[29.5846566 -99.733893 6]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of accessible stalls based on the total: 1-25: 1 accessible/1 van 26-35: 2 accessible/1 van 36-50: 3 accessible/1 van 51-100: 4 accessible/1 van 101-300: 8 accessible/2 van 301-500: 12 accessible/2 van 501-800: 16 accessible/3 van 801-1000: 20 accessible/4 van 1001-over: 20 accessible plus 1 for every 100 spaces/1 of every 6 should be a van stall	130 stalls, 1 accessible stall	Create seven or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls.	2015 ABAAS Section: F208.2 2010 ADAS Section: 208.2		
468	Oakmont Camping Area: Oakmont Pavilion Parking	[29.5846631 -99.733895 3]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 130 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 8 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		Section of Principles (Section 2014) Section

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
469	Oakmont Camping Area: Oakmont Pavilion	[29.5847717 -99.733725 6]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	change in elevation 1"+, multiple areas from accessible stalls to main entrance	Repair, bevel or ramp CIL along AR Repair or reset pavers to eliminate CIL	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		W max  W  N  1  N  1  N  N  N  N  N  N  N  N  N

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
470	Oakmont Camping Area: Oakmont Pavilion	[29.5847962 -99.733842 2]	inch. Openings in floor or ground surfaces shall not allow passage of a sphere more	multiple 1.25"+ gaps and gap issues to main entrance of pavilion from main lot	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3		deminant distribution of training and traini

Finding Number Area Description Lat/Long Finding As Built Recommendation Citation	Photos Figure
Aft Dakmont Camping Area: Oakmont Pavilion  AR to max 2.08%  AR to max 2.08%  AR to max 2.08%  Oakmont Pavilion  Oakmont Pavili	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
472	Oakmont Camping Area: Oakmont Pavilion	[29.5847414 -99.733853]	The running slope of walking surfaces shall not be steeper than 1:20.	running slope 6.9% on accessible route	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	
473	Oakmont Camping Area: Oakmont Pavilion	[29.5848754 , -99.733847]	Element meets all standards and requirements	gift shop room complies	None	2010 ADAS Section: N/A	
474	Oakmont Camping Area: Oakmont Pavilion	[29.5849432 -99.733941 6]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	gift shop transaction counter 42" above finished floor	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1	36 min
475	Oakmont Camping Area: Oakmont Pavilion	[29.584999, -99.734041 5]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	ice cream counter 36.25" above finished floor	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1	36 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
476	Oakmont Camping Area: Oakmont Pavilion	[29.5849589 -99.733945 6]	Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise.	gift shop entry - door 25.5" wide, change in level, large threshold	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" For all doors along the public circulation route, repair, provide beveled threshold	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
477	Oakmont Camping Area: Oakmont Pavilion	[29.5849408 -99.733991 5]	Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise.	ice cream entry- similar to gift shop, door 25.5" wide, change in level, large threshold	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" For all doors along the public circulation route, repair, provide beveled threshold	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
478	Oakmont Camping Area: Oakmont Pavilion	[29.5849047 , -99.733891 9]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	clear width reduced to 30.5" near counter	Leave as is column as technically infeasible to correct and provide minimum 36" width to access counter	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	AL TE 100 AS SE SE SE SE	24 max 449 min 24 max 45 min 34 min 3
479	Oakmont Camping Area: Oakmont Pavilion	[29.584921, -99.733926 7]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	gift shop back room- wall reduces maneuvering clearance to 13.5" pull side, lacks hardware, juke box to ice cream- 21" wide	Provide required maneuvering clearance on push and pull side of doors. Replace doors with doors having 80" overhead clearance and 32" clear width.	2015 ABAAS Section: F203.9  2012 TAS Section: 203.9  2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
480	Oakmont Camping Area: Oakmont Pavilion	[29.584935, -99.733948 2]	Employee Work Areas. Common use circulation paths within employee work areas shall comply with 402. EXCEPTIONS:  1. Common use circulation paths located within employee work areas that are less than 1000 square feet (93 m2) and defined by permanently installed partitions, counters, casework, or furnishings shall not be required to comply with 402. 2. Common use circulation paths located within employee work areas that are an integral component of work area equipment shall not be required to comply with 402. 3. Common use circulation paths located within exterior employee work areas that are fully exposed to the weather shall not be required to comply with 402.	circulation path width reduces throughout space connecting to ice cream shop	Make corrections for compliant circulation path.	2015 ABAAS Section: F206.2.8, F206.2.8.1, F206.2.8.2  2012 TAS Section: 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 3, 206.2.8 Advisory 1, 206.2.8 Advisory 2  2010 ADAS Section: 206.2.8, 206.2.8 Exception 1, 206.2.8 Exception 2, 206.2.8 Exception 3		
481	Oakmont Camping Area: Oakmont Pavilion	[29.5849723 -99.734047 4]	The displays projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	jukebox room- animal trophies mounted below 80"	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
482	Oakmont Camping Area: Oakmont Pavilion	[29.58497, -99.734052 8]	Openings in floor or ground surfaces shall not allow passage of a sphere more than ½ inch (13 mm) diameter except as allowed in 407.4.3, 409.4.3, 410.4, 810.5.3 and 810.10. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	jukebox room- some larger indentations in floor	Fill and maintain gaps to max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		PRO APPROVED AND AND AND AND AND AND AND AND AND AN
483	Oakmont Camping Area: Oakmont Pavilion	[29.5849744 -99.734053 4]	Site element lacks accessible features.	photo booth provided in jukebox room, narrow entry with CIL, narrow space	Provide accessible photo booth or equivalent experience that is accessible.	Capture Section: 1		

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	Area Description	Lat/Long	Finding	AS BUILT	Recommendation	Citation	Photos	rigure
484	Oakmont Camping Area: Oakmont Pavilion	[29.5849732 -99.734051 6]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold has a gap greater than 1/2 inch wide. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	roadside entry door- 5" change in level, each door leaf narrow width, but doors kept open, thumb press hardware, 7.7% slope, gaps	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	700. 2000		,	7.0 24		0	1	
485	Oakmont Camping Area: Oakmont Pavilion	[29.5849774 -99.734054 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold has a gap greater than 1/2 inch wide. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	jukebox back patio entry- 1.5" CIL, 5.6% slope an threshold, 4% slope, gaps, 26.5" wide, thumb press	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, provide beveled threshold. For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
486	Oakmont Camping Area: Oakmont Pavilion	[29.5849665 -99.734044 7]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	rear door- change in level, wall pull side, door too narrow; jukebox- each leaf narrow	Provide required maneuvering clearance on push and pull side of doors. Replace doors with doors having 80" overhead clearance and 32" clear width. Repair, bevel, or ramp CILs at door entries to max .25".	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9	
487	Oakmont Camping Area: Oakmont Pavilion	[29.5846367 -99.734058 7]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	Garner Grill food trailer service counter 47" above ground	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1  2012 TAS Section: 904.4.1, 904.4.2  2010 ADAS Section: 904.4.2, 904.4.1	SEDE 36 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
488	Oakmont Camping Area: Oakmont Pavilion	[29.58522, -99.73417]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap at patio, multiple 1" gaps at expansion joints	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3	descript district of trails  Into district an appropriate for trail  Ye max
489	Oakmont Camping Area: Oakmont Pavilion	[29.5852892 -99.733902 9]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	stairs only to lower path along river	Repair, bevel or ramp change in level along accessible route.	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	½ max  ½ ½ ½
490	Oakmont Camping Area: Oakmont Pavilion	[29.585162, -99.733768 4]	Benches shall have a 36" by 48" clear ground space (CGS) positioned near the bench with one side of the space adjoining an outdoor recreation access route (ORAR) or trail, as applicable The CGS shall not overlap with the ORAR or trail or another CGS As a smart practice, add at least one armrest and achieve height of bench seat of 17" to 19"	bench at lowered area lacks clear floor space due to uneven surface	Repair and reset pavers to eliminate CIL and gaps in CFS at bench	2015 ABAAS Section: 1011.2.1	

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								
491	Oakmont Camping Area: Oakmont Pavilion	[29.5850441 -99.733849 4]	The running slope of walking surfaces shall not be steeper than 1:20.	8.5% at asphalt trail, 7.2% at turn by building, 7.3% on back patio, 6.5% to lowered section, 5.2% near wall	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	MANAGE 2000 B.S.	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
492	Oakmont Camping Area: Oakmont Pavilion	[29.5851187 -99.733461 5]	Visual characters shall be 40 inches (1015 mm) minimum above the finish floor or ground. EXCEPTION: Visual characters indicating elevator car controls shall not be required to comply with 703.5.6.	interpretive signage text starts low, sign clear floor space fails due to slopes	Remount signage to min 40" aff. Correct slope of CFS to max 2.08%.	2015 ABAAS Section: 703.5.6, 703.5.6 EXCEPTION  2012 TAS Section: 703.5.6, 703.5.6 Exception  2010 ADAS Section: 703.5.6, 703.5.6 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
493	Oakmont Camping Area: Oakmont Pavilion	[29.58533, -99.73436]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	4.6% cross near asphalt trail, 2.5% to lower section, 2.2% near wall, 2.2% near table, 4.6%	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3	MARKET COLUMN AND AND AND AND AND AND AND AND AND AN	
494	Oakmont Camping Area: Oakmont Pavilion	[29.58508, -99.73348]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	bike rack lacks accessible route	Relocate bike rack to be along accessible route.	2010 ADAS Section: 206.2.2, 206.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
495	Oakmont Camping Area: Oakmont Pavilion	[29.58508, -99.73357]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	0 of 1 picnic table complies	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2	
496	Oakmont Camping Area: Oakmont Pavilion	[29.5850761 -99.733433 2]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	1" CIL, 1" near trail, 1" CIL connecting to lower area, 1" where damaged at bike rack	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3	Mmax My My Max Max My My Max My

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure	
497	Oakmont Camping Area: Oakmont Pavilion	[29.5849008 -99.733810 5]	The building entrance is not located on an accessible route. When a building, or portion of a building, is required to be accessible, an accessible route of travel shall be provided to all portions of the building, to accessible building entrances and between the building and the public way. All walks, halls, corridors, aisles, skywalks, tunnels, and other spaces that are part of an accessible route must comply. An accessible route of travel must not pass through kitchens, storage rooms, restrooms, closets or other spaces used for similar purposes. At least one accessible route within the boundary of the site must be provided from public transportation stops, accessible parking and accessible passenger loading zones and public streets or sidewalks to the accessible building entrance they serve. The accessible route shall, to the maximum extent feasible, coincide with the route for the general public. At least one accessible route shall connect accessible buildings, facilities, elements and spaces that are on the same site. At least one accessible spaces and elements.	historical building, no ramp system to reach Pavilion or shops	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance	2015 ABAAS Section: F206.2.1 2012 TAS Section: 206.2.1 2010 ADAS Section: 206.2.1		Committee of the commit
498	Oakmont Camping Area: Oakmont Pavilion	[29.5846761 ,-99.734058 2]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	0 of 10 picnic tables provide wheelchair space	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
499	Oakmont Camping Area: Oakmont Pavilion	[29.5846947 , -99.734072 9]	Picnic facilities shall provide outdoor recreation access routes complying with 1016 in accordance with F245.4 and 245.4 of IAC	loose surface with low fill areas	Create ORAR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter or picnic area	2015 ABAAS Section: F245.4		
500	Oakmont Camping Area: Oakmont Pavilion	[29.5846213 -99.734032 7]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	multiple changes in elevation exceed standard	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
501	Oakmont Camping Area: Oakmont Pavilion	[29.5847134 -99.733894 5]	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	tree projects onto AR 9", reduces walkway to 31"	Widen AR to min 36" clear width; AR can reduce to 32" for max length of 24"	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max
502	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5820193 , -99.730532 4]		parking scoping complies- 1 of 4 stalls accessible	None	2010 ADAS Section: N/A		
503	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5820018 -99.730539 1]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	6.1% slope in parking stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
504	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5820146 , -99.730541 8]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	large loose rock	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		½ max ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½
505	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5820251 -99.730564 6]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	sign installed 54.5" above ground	Raise existing accessible parking signs so lowest end of bottom sign is min 60" aff	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6 2010 ADAS Section: 502.6	VA V CCES IBLE	Accessible 60 nches min.
506	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5819975 -99.730588 9]	The accessible route contains loose gravel and/or surfaces that do not provide for a stable, firm slip resistant surface.	accessible route entry at parking deteriorated	Resurface AR where deterioration occurs	2015 ABAAS Section: 302.1  2012 TAS Section: 302.1  2010 ADAS Section: 302.1		Dispos in their interest of the control of the cont

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
507	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.581953, -99.730636 1], [29.5820428 -99.730723 3]	The running slope of walking surfaces shall not be steeper than 1:20.	slope measurements - 5.3% at parking, 6% around curve approaching water spout, 5.7% approaching building	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	Section 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
508	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821273 , -99.730651 6]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	2.5% slope to women's restroom	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
509	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5820916 ,-99.730626 3]	The handrails as well as the handrail extensions are not at the correct height. The tops of handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground.	33.5", 32.5"	Replace or remount handrails to 34" to 38" aff	2015 ABAAS Section: 505.4 2012 TAS Section: 505.4 2010 ADAS Section: 505.4		(a) stairs

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
510	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821068 , -99.730665 2]	The water flow from the spout is too low. The spout shall provide a flow of water 4 inches high minimum.	fountain is not operational	Ensure spout flow height to min 4".	2015 ABAAS Section: 602.6 2012 TAS Section: 602.6 2010 ADAS Section: 602.6		4 inches min d d
511	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821149 -99.730666 5]	The required clear floor space is not deep enough. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	43" depth from fountain	Enlarge CFS to min 48" depth	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3	43 43 45 45 46 46	48 min
512	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821196 -99.730709 4]	The door is equipped with a door closer and returns to a closed position too quickly. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum.	men's- door is fast closing	Inspect, adjust, and maintain closing speed on door closers	2015 ABAAS Section: 404.2.8.1 2012 TAS Section: 404.2.8.1 2010 ADAS Section: 404.2.8.1		90° S seconds min.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
513	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821231 -99.730708 1]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	compliant signage is on parking lot side of building, none at door	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	TE MEN	FUC.
						2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		
514	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821243 , -99.7307]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAWTORY
515	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821266 -99.730708 1]	The urinal is located in an area that does not provide the required clear floor space for a front approach. The surrounding elements of a urinal must provide a minimum of 30 by 48 inches of clear floor space for a front approach.	left side 27" width	Relocate privacy wall at urinal to provide 30" CFS	2015 ABAAS Section: 605.2  2012 TAS Section: 605.2  2010 ADAS Section: 605.2	33 <b>1</b>	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
516	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821243 , -99.730698 7]	The toilet seat is not located within the range allowed off the floor. The height of accessible water closets shall be a minimum of 17 inches and a maximum of 19 inches measured to the top of a maximum 2-inch high toilet seat.	toilet seat installed at 19.5" above finished floor	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	2015 ABAAS Section: 604.4 2012 TAS Section: 604.4 2010 ADAS Section: 604.4		17" to 19"
517	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821208 , -99.730704 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	side grab bar mounted 36.5" above finished floor	Remount grab bars in accessible stall to 33" to 36" aff	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
518	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821243 -99.730710 8]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.3% slope in accessible stall	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
519	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821278 -99.730697 4]	The room does not contain compliant turning space. Dressing Rooms must contain a 60 inch circular turning space or a T-shaped turning space. Doors shall not swing into the room unless a clear floor or ground space is provided beyond the arc of the door swing.	dressing stall doesn't meet space requirements	Enlarge dressing stalls to 60" by 60" clear inside dimension	2015 ABAAS Section: 803.2  2012 TAS Section: 803.2  2010 ADAS Section: 803.2		60 in 60 in 12 in 36 in
520	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Men's	[29.5821289 -99.730704 1]	Clear floor space adjacent to the bench has not been provided. Clear floor or ground space shall be provided and be positioned at the end of the bench seat parallel to the short axis of the bench. The space must be 30 inches minimum by 48 inches minimum.	bench is not compliant, lacks clear floor space.	Provide required CFS of 30" by 48" on the short end of the bench	2015 ABAAS Section: 903.2 2012 TAS Section: 903.2 2010 ADAS Section: 903.2		
								·
521	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821104 -99.730691 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.	women's- garbage can pull side	Relocate storage, furniture and other obstacles to create 60" maneuvering clearance around door	2015 ABAAS Section: 404.2.4.1, 404.2.4.4  2012 TAS Section: 404.2.4.4, 404.2.4.1  2010 ADAS Section: 404.2.4.4, 404.2.4.1		The state of the s

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	Area Description	Lavicong	T maing	AS Built	necommendation	Citation	Filotos	rigure
522	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821196 , -99.7307]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY
523	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821254 -99.730705 4]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	hook installed 52.75" above finished floor	Lower operating mechanisms to max 48" aff to highest operable part	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
524	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821266 , -99.7307]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	garbage can in clearance floor clearance	Relocate garbage can to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		
525	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821208 -99.730706 7]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	side grab bar mounted 36.25", toilet paper dispenser mounted 10" above side grab bar, 1" gap at board	Remount grab bars in accessible stall to 33" to 36" aff Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
526	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821254 -99.730697 4]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door is not self- closing	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
527	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821184 -99.730697 4]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser is not installed within compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	vem ep
528	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821103 -99.730708 1]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 7"	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
529	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821254 , -99.7307]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.7% cross slope at stall	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
530	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821243 -99.730698 7]	There are no accessible fitting and/or dressing rooms. Where fitting or dressing rooms are provided for male or female customers, patients, employees or the general public, 5 percent, but never less than one, of dressings rooms for each type of use in each cluster of dressing rooms shall be accessible and located on an accessible route.	reduces to access changing areas, 1 of 6 larger and have bench	Renovate locker rooms/dressing rooms to provide accessible changing areas, showers and lockers	2015 ABAAS Section: F222.1  2012 TAS Section: 222.1  2010 ADAS Section: 222.1		
531	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821266 -99.730702 7]	The room does not contain compliant turning space. Dressing Rooms must contain a 60 inch circular turning space or a T-shaped turning space. Doors shall not swing into the room unless a clear floor or ground space is provided beyond the arc of the door swing.	37" to curtain, lacks turning space	Enlarge dressing stalls to 60" by 60" clear inside dimension	2015 ABAAS Section: 803.2  2012 TAS Section: 803.2  2010 ADAS Section: 803.2		60 in 60 in 12 in 36 in
532	Oakmont Camping Area: Oakmont Restroom Bldg 10 - Women's	[29.5821103 -99.730705 4]	Clear floor space adjacent to the bench has not been provided. Clear floor or ground space shall be provided and be positioned at the end of the bench seat parallel to the short axis of the bench. The space must be 30 inches minimum by 48 inches minimum.	bench is not compliant and lacks clear floor space	Provide required CFS of 30" by 48" on the short end of the bench	2015 ABAAS Section: 903.2 2012 TAS Section: 903.2 2010 ADAS Section: 903.2		
533	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5834853 , -99.731562 4]	Element meets all standards and requirements	parking scoping complies, 1 of 5 stalls accessible	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
534	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5834912 -99.731539 6]	The accessible parking is not located on the shortest accessible route to the building. Accessible parking spaces serving a particular building or facility entrance shall be located on the shortest accessible route of travel from the parking to an accessible entrance.	accessible parking is not on the shortest route	Relocate stalls to be on the shortest AR to the building entry or park features	2015 ABAAS Section: F208.3.1 2012 TAS Section: 208.3.1 2010 ADAS Section: 208.3.1		
535	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5834947 -99.731506]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 5 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van signage	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4  2012 TAS Section: 208.2, 208.2.4  2010 ADAS Section: 208.2, 208.2.4		Section of Annichment (Annichment (Annichm

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
536	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5834772 -99.731543 6]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	2.4% access aisle, 3.1% parking stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		4-4-88
537	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836124 -99.731518 1]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirror mounted 43" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3  2012 TAS Section: 603.3  2010 ADAS Section: 603.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
538	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836206 -99.731519 4]	The accessible path of travel contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp.	slopes - 3%, 3.4%, 2.7%	Correct or repair cross slope of AR to max 2.08%	2015 ABAAS Section: F206.2.4, 403.3 2012 TAS Section: 206.2.4, 403.3 2010 ADAS Section: 206.2.4, 403.3		
539	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836241 , -99.731520 8]	Shower controls are in the incorrect location In transfer type shower compartments, the controls, faucets, and shower spray unit shall be installed on the side wall opposite the seat 38 inches (965 mm) minimum and 48 inches (1220 mm) maximum above the shower floor and shall be located on the control wall 15 inches (380 mm) maximum from the centerline of the seat toward the shower opening.	shower head closer to back wall from seat centerline	Remount shower controls to the correct location in the transfer shower	2015 ABAAS Section: 608.5.1 2012 TAS Section: 608.5.1 2010 ADAS Section: 608.5.1		side wall  15 max  360  Wall Brown Age of the state of th

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
540	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836358 -99.731520 8]	Coat hooks provided within the room shall be located within one of the reach ranges specified in 308. Shelves shall be 40 inches (1015 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground. Where coat hooks or shelves are provided in dressing, fitting or locker rooms without individual compartments, at least one of each type shall comply with 803.5. Where coat hooks or shelves are provided in individual compartments at least one of each type complying with 803.5 shall be provided in individual compartments in dressing, fitting, or locker rooms required to comply with 222.1.	3 hooks exceed 50" above finished floor	Remount at least one hook to max 48" aff	2015 ABAAS Section: 308.2.1, 308.1, F222.2, 803.5 2012 TAS Section: 308.2.1, 308.1, 222.2, 803.5 2010 ADAS Section: 308.2.1, 308.1, 222.2, 803.5		
541	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836238 , -99.731520 8]	It is recommended that exterior doors be maintained so that the operating pressure does not exceed 8.5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 7 inches from the latch, measured to the leading edge of the door.	men's- 10 lb of force to open door, closes fast	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2012 TAS Section: 404.2.9, 404.2.9 Advisory, 404.2.8.1 2010 ADAS Section: 404.2.9, 404.2.8.1		
542	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Men's	[29.5836031 -99.731515 4]	Element meets all standards and requirements	drinking fountain complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
543	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.58362, -99.731518]	Element meets all standards and requirements	Women's restroom door complies	None	2010 ADAS Section: N/A	
544	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836276 -99.731516 8]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	mirror mounted 40.5" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3	
545	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836218 -99.731523 5]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	sink installed 34.5" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3	Toe clearance  Toe clearance  6° deep toe stance
546	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836241 -99.731502]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5	ACCESSIBLE LAVATORY  The stage of minorated

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
547	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836229 ,-99.731520 8]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	soap dispenser 49" above finished floor with reach over sink	Lower to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		DO FINAL STATE OF THE STATE OF
548	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836148 ; -99.731515 4]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	garbage can in clearance	Relocate garbage can to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
549	Oakmont Camping Area: Oakmont Restroom Bldg 11	[29.5836241 , -99.731520 8]	The toilet is not located within the range allowed from the side wall or partition. The centerline of the toilet must be 16 to 18 inches from the side wall.	18.5" from wall to centerline of toilet	Remount toilets to 16" to 18" from the side wall to centerline	2015 ABAAS Section: 604.2		Ę.
	- Women's	3,				2012 TAS Section: 604.2		
						2010 ADAS Section: 604.2		16"-18"
550	Oakmont Camping Area: Oakmont Restroom Bldg 11	[29.5836148 , -99.731522 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between	toilet paper dispenser mounted 6.5" above grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4		
	- Women's	,	the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.			2012 TAS Section: 609.4, 609.3		
			dispension of other obstitutions.			2010 ADAS Section: 609.3, 609.4		
551	Oakmont Camping Area: Oakmont Restroom Bldg 11	[29.5836078 , -99.731526 2]	The flush handle is located on the wrong side of the toilet. Controls shall be operable with one hand and shall not require tight grasping, pinching or twisting. Controls for	near centered, towards wall side	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit	2015 ABAAS Section: 604.6		
	- Women's	,	the flush valves shall be mounted on the wide side of toilet areas, no more than 44 inches above the floor.			2012 TAS Section: 604.6		Transfer side
						2010 ADAS Section: 604.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
552	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5835985 -99.731512 7]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door is not self- closing	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2	
553	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836218 , -99.731520 8]	The compartment door is located too far from the partition or wall. The door shall be located in front of the clear space and diagonal to the water closet. Where located in the front partition, the door opening shall be 4 inches maximum from the side wall or partition farthest from the water closet. Where located in the side wall or partition, the door opening shall be 4 inches maximum from the front partition. Toilet compartment doors shall not swing into the minimum required compartment area.	compartment door is 6" from wall	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	2015 ABAAS Section: 604.8.1.2 2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2	Alternate door location
554	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836171 -99.731520 8]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper is not installed in the compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	45 min Ad mark

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
555	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836206 -99.731518 1]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 9"	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	5 0 7 8 9 10 11 % % %	
556	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836218 -99.731515 4]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.3% cross slope	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	NAME OF THE PARTY	
557	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836264 -99.731510 1]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	36.25" wide	Correct transfer shower to compliant 36" by 36" clear inside dimension	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1	DP OP. SE ME AS MY SE WE FE SE  APPLICATION OF THE SE	Seed control was control was a few control parties parties grant or managers of the control parties grant grant grant or managers of the control parties grant gra

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
558	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836241 -99.731520 8]	Transfer type shower compartments shall be 36 inches (915 mm) by 36 inches (915 mm) clear inside dimensions measured at the center points of opposing sides and shall have a 36 inch (915 mm) wide minimum entry on the face of the shower compartment. Clearance of 36 inches (915 mm) wide minimum by 48 inches (1220 mm) long minimum measured from the control wall shall be provided.	drainage channel in clear floor space, 5.2% slope	Provide appropriate clear floor space on the exterior of the transfer shower	2015 ABAAS Section: 608.2.1 2012 TAS Section: 608.2.1 2010 ADAS Section: 608.2.1	ART FILLS	Seed control was seed we desire parts of appears seed
559	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5835985 ,-99.731510 1]	In transfer type compartments, grab bars shall be provided across the control wall and back wall to a point 18 inches (455 mm) from the control wall.	grab bars missing	Remount grab bars to the correct location in the transfer shower.	2015 ABAAS Section: 608.3.1 2012 TAS Section: 608.3.1 2010 ADAS Section: 608.3.1		back 18 wall 455 control wall
560	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836171 -99.731526 2]	Shower controls are in the incorrect location In transfer type shower compartments, the controls, faucets, and shower spray unit shall be installed on the side wall opposite the seat 38 inches (965 mm) minimum and 48 inches (1220 mm) maximum above the shower floor and shall be located on the control wall 15 inches (380 mm) maximum from the centerline of the seat toward the shower opening.	shower head installed 15" from back wall	Remount shower controls to the correct location in the transfer shower	2015 ABAAS Section: 608.5.1 2012 TAS Section: 608.5.1 2010 ADAS Section: 608.5.1		side wall  15 max  360  View 860  Vi

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
561	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5836288 -99.731510 1]	The 30 inches minimum by 48 inches minimum clear floor space required at the operable part is not flat (2% or 1:48 maximum slope) in all directions. Changes in level are not permitted at required clear floor or ground space except that slopes not steeper than 1:48 shall be permitted.	6.3% slope at park map	Correct or repair slope in CFS to max 2.08%	2015 ABAAS Section: 305.2 2012 TAS Section: 305.2 2010 ADAS Section: 305.2		48 min
562	Oakmont Camping Area: Oakmont Restroom Bldg 11 - Women's	[29.5835441 , -99.73150 39], [29.5836316 , -99.731603 2]	The running slope of walking surfaces shall not be steeper than 1:20.	5.4% to women's restroom, 7.4% to vending, 7.6% towards men's, 6.4% to men's	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3  2012 TAS Section: 403.3  2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
563	Oakmont Camping Area: Oakmont Picnic Areas	[29.58462, -99.73398]	There is no accessible route to the bench. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	lacks accessible route to bench in picnic area	Create an accessible route with crushed stone or other outdoor material from parking or walkway to bench	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  POPULATION OF THE POPULATI
564	Oakmont Camping Area: Oakmont Picnic Areas	[29.58463, -99.73409]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3.4% adjacent to picnic area, 6.8% next to tree by Garner Grill food truck	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
565	Oakmont Camping Area: Oakmont Picnic Areas	[29.584619, -99.734052 2]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	no ramp to vendor change in elevation 4"	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½ ½

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
566	Oakmont Camping Area: Oakmont Picnic Areas	[29.584542, -99.731257 9]	There is no accessible route to the picnic tables and grill. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to picnic tables. 9 tables with grills, 0 accessible	Create an accessible route with crushed stone or other outdoor material from parking or walkway to two picnic tables and grills.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Print's design of the state of the
567	Oakmont Camping Area: Oakmont Picnic Areas	[29.5840929 -99.730370 1]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of (XX) parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of (XX) accessible stalls with a minimum of (XX) being designed as van accessible.	Oakmont Picnic Area lacks accessible parking spaces - 82 standard spaces, 0 accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2  2012 TAS Section: 208.2  2010 ADAS Section: 208.2		Manual Principles   Manu
568	Oakmont Camping Area: Oakmont Picnic Areas	[29.5844382 -99.730812 7]	There is no accessible route to the picnic areas. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to picnic tables. 15 tables with grills, 0 accesible	Create an accessible route with crushed stone or other outdoor material from parking or walkway to picnic areas and amenities as a smart practice	2015 ABAAS Section: F206.2.2  2012 TAS Section: 206.2.2  2010 ADAS Section: 206.2.2		ACCESIBLE ENTRANCES  Printing  Access  Access

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
569	Oakmont Camping Area: Oakmont Sand Volleyball	[29.5800914 -99.731590 5]	There is no accessible route to the sand volleyball court. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	Lacks accessible route to sand volleyball court	Create an accessible route with crushed stone or other outdoor material from parking or walkway to sand volleyball court.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Printy  Access
570	Oakmont Camping Area: Oakmont Basketball	[29.5797963 -99.731603 9]	There is no accessible route to the basketball court. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	Lacks accessible route to basketball courts.	Create an accessible route with crushed stone or other outdoor material from parking or walkway to basketball court.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Priority  April  April  France
571	Oakmont Camping Area: Oakmont Basketball	[29.5797952 , -99.731534 2]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	4" hole in basketball court	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3		deemark decision of basel  Along direction perspective in the second of

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
572	Oakmont Camping Area: Oakmont Boat House	[29.5794721 , -99.731150 6]	There is no accessible route to the boat house. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	Lacks accessible route to boat house	Create an accessible route with crushed stone or other outdoor material from parking or walkway to boat house	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Printing and the p
573	Oakmont Camping Area: Oakmont Boat House	[29.5794499 , -99.73113 46], [29.5794488 -99.730988 4]	There is no accessible route to the paddle boats. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	Lacks accessible route to paddle boats. Exterior accessible route has 16.4% slope and steps.	Create an accessible route with crushed stone or other outdoor material from parking or walkway to paddle boats	2015 ABAAS Section: F206.2.2  2012 TAS Section: 206.2.2  2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Professor  Accessible Entrances  Accessible

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
574	Oakmont Camping Area: Oakmont Boat House	[29.5794768 -99.731239 2]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	Sales and Service counter 51" above ground and obstructed by bench/step.	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1		36'min 36'max
575	Oakmont Camping Area: Scenic Overlook	[29.5870998 , -99.737123 4]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of 4 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	Scenic Overlook parking - lacks accessible parking spaces - approximately 4 standard, 0 accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2  2012 TAS Section: 208.2  2010 ADAS Section: 208.2		Weather of Maniphysis (Maniphysis) (Maniphys
576	Oakmont Camping Area: Scenic Overlook	[29.5870844 -99.737114 5]	Element meets all standards and requirements	Garbage can complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
577	Oakmont Camping Area: Scenic Overlook	[29.5870745 , -99.737138 5]	A turning space complying with 304.3 (60" by 60" or T shaped) shall be provided within viewing areas. The surface of clear ground spaces and turning spaces shall be firm and stable. The slope of the surface of clear ground spaces and turning spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	5" CIL, gravel surface	Repair surface of viewing are clear ground space to be firm, stable and having max 2.08% slope or 5% for surfaces other than concrete, asphalt or boards as a smart practice. Repair, bevel, or ramp CIL to access viewing area as a smart practice	2015 ABAAS Section: 1015.4, 1015.5, 1015.6, 1015.6 EXCEPTION	
578	Oakmont Camping Area: Scenic Overlook	[29.5871005 , -99.737092 6]	Each distinct viewing location shall provide a viewing space adjacent to the clear ground space required by 1015.2 through which the point of interest is viewable. The viewing space shall be 32 inches (815 mm) maximum and 51 inches (1295 mm) minimum high above the ground and shall extend the full width of the clear ground space.	railings and cable within view height	Lower a 36" wide portion of railing to provide an unobstructed view between 32" and 51"	2015 ABAAS Section: 1015.3	
579	Oakmont Camping Area: Oakmont Pavilion Men's Restroom	[29.5851379 -99.734109 1]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	lacks accessible features, lacks directional signage	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8  2012 TAS Section: 216.8  2010 ADAS Section: 216.8	THE RESTROOM

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
580	Oakmont Camping Area: Oakmont Pavilion Men's Restroom	[29.5851356 -99.734114 5]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks Braille and raised characters	Acquire and mount signage, including Braille and raised characters mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		The state of the s
581	Oakmont Camping Area: Oakmont Pavilion Men's Restroom	[29.5851255 -99.734104 5]		men's- steps, large 6" change in elevation in doorway, thumb press	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, repair, provide beveled threshold For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
582	Oakmont Camping Area: Oakmont Pavilion Women's Restroom	[29.5851403 -99.734103 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
583	Oakmont Camping Area: Oakmont Pavilion Women's Restroom	[29.5851519 -99.734115 8]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	restroom lacks accessible features, lacks directional signage	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8  2012 TAS Section: 216.8  2010 ADAS Section: 216.8	TIPS RESTROOM

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
584	Oakmont Camping Area: Oakmont Pavilion Women's Restroom	[29.5851484 -99.734117 2]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	lacks Braille and raised characters	Acquire and mount signage, including Braille and raised characters mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6		FUC.
585	Oakmont Camping Area: Oakmont Dump Station	[29.584016, -99.730926 7]	30 inches (760 mm) by 60 inches (1525 mm) with the long side of the space adjoining or overlapping an accessible parking space or pull-up space for recreational vehicles Locate the space so that the hook-ups are at the rear center of the space. Bollards or other barriers shall not obstruct the clear ground space in front of the hook-ups	No accessible route to hookups. Surface is deteriorated asphalt and grass. 2.7% cross slope	Provide required 30" by 60" clear ground space with hook ups at the rear of the space as a smart practice	2015 ABAAS Section: 1011.2		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
586	Oakmont Camping Area: Sample Campsite	[29.582522, -99.730578]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 40 electric campsites in this area have accessible features; 215 total electric campsites in the park	Create the required number of accessible electric camp sites per table F244.2 as a smart practice; cost included in Live Oak finding	2015 ABAAS Section: F244.2		
587	Oakmont Camping Area: Sample Campsite	[29.5842889 -99.732875 3]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 5 shelter campsites in this area comply; 36 total shelter campsites in park	Create the required number of accessible shelter camp sites per table F244.2 as a smart practice; cost included in Shelter 9 finding	2015 ABAAS Section: F244.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
588	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5823774 , -99.733301 8]	Element meets all standards and requirements	parking scoping complies- 2 of 31 stalls accessible	None	2010 ADAS Section: N/A		
589	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5823949 -99.733321 9]	The access aisle is missing at the accessible parking stall. Access aisles serving parking spaces shall adjoin an accessible route. Two parking spaces shall be permitted to share a common access aisle.	one stall lacks access aisle	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	2015 ABAAS Section: 502.3.1 2012 TAS Section: 502.3.1 2010 ADAS Section: 502.3.1		Summarish and to as the summary of the street and stree
590	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824205 -99.733296 4]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 6 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van sign	Add van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		With Marker of Managellands (Section 1994)  Section 1994 (Section 1994)  S
591	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5823937 -99.733303 1]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	2.3% cross slope	Correct or repair slope to max 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
592	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824263 -99.733183 8]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Maneuvering clearances shall have a max slope of 2.08%.	laundry room- 9.9% slope at door landing	For all doors along the public circulation route, correct slope in door clearance to max 2.08%.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception	
593	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824454	The top of the washing machine and/or dryer is too high. Top loading machines shall have the door to the laundry compartment located 36 inches maximum above the finish floor. Front loading machines shall have the bottom of the opening to the laundry compartment located 15 inches minimum and 36 inches maximum above the finish floor.	laundry room- washing machine 37" above finished floor	Replace washing machines or remount machines to be max 36" to top	2015 ABAAS Section: 611.4  2012 TAS Section: 611.4	Tront loading front loading

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
594	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824333 -99.733181 1]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	camp store- multiple locations reduced to less than 36" due to storage	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		48 min 4 max. 48 min 4 max. 48 min 5 min 6 min 7

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
595	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824345 -99.733178 4]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	camp store- slopes: running - 5.6%, 5.5%, 8.3%, cross - 2.5%	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	MOUR!	AND

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
596	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824357 -99.733191 8]	The coffee machine is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	camp store- coffee machine 50"	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1	T HATER CALDERIN SPECIAL SPECI	10 max 48 max 48 max
597	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824438 -99.733183 8]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	camp store- coffee and microwave station high	Provide work surfaces at 28" to 34" aff	2015 ABAAS Section: 902.3  2012 TAS Section: 902.3  2010 ADAS Section: 902.3		Knee Space Space Set Men. to S
598	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824252 -99.733188 1]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	camp store- 36.25" service counter	Lower 36" wide segment of service counter to max 36" aff	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1		36°min 36°max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
599	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824003 -99.733245 9]	The curb ramp on the accessible route contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	bottom landing at parallel ramp 2.9%	Correct curb ramp cross slope to max 2.08%	2015 ABAAS Section: 405.3 2012 TAS Section: 405.3 2010 ADAS Section: 405.3	MANAGE STATE OF THE STATE OF TH	1000
600	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824652 , -99.733264 8]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3.3% cross slope on route to laundry	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		manus and a second
601	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824298 -99.733254 8]	The telephone is not accessible. Where coinoperated public pay telephones, coinless public pay telephones, public Closed-Circuit Telephones, public courtesy phones, or other types of public telephones are provided, public telephones shall be wheelchair accessible, have volume controls, TTY and meet the bank requirements if applicable for each type of public telephone provided. For purposes of this section, a bank of telephones shall be considered to be two or more adjacent telephones.	phone high and not of accessible design	Provide a TTY and wheelchair accessible phones within the same area as the public phone	2015 ABAAS Section: F217.1  2012 TAS Section: 217.1  2010 ADAS Section: 217.1		ACCESSIBLE TELEPHONES  All accuration improves and training of the state of a place from provided and the state of a place from provided and the state of the sta

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
602	Pecan Grove Camping Area: Pecan Grove Park Store	[29.582399, -99.733376 1]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	bike rack lacks accessible route	Relocate bike rack to be along AR	2010 ADAS Section: 206.2.2, 206.2		
603	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824378 -99.733377]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	picnic table lacks accessible route, lacks wheelchair space	Replace picnic table with one of an accessible design and locate along an AR as a smart practice	2015 ABAAS Section: 1011.4.2		
604	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824438 -99.733186 4]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	to freezer- knob hardware, door 28" wide; exit by freezer- knob hardware, storage push side in maneuvering clearance.	For employee spaces, relocate storage, furniture, and other obstacles at doorways to provide approach, enter and exit at the employee space. Replace doors with doors having 80" overhead clearance and 32" clear width. Replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2015 ABAAS Section: F203.9  2012 TAS Section: 203.9  2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
605	Pecan Grove Camping Area: Pecan Grove Park Store	[29.58244, -99.733188 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. All interior doors must be maintained so that the operating pressure does not exceed 5 lb. force to open. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door.	staff restroom- ATM pull side maneuvering clearance, 11 lbf to open, closes fast	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
606	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824345 -99.733175 7]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	staff restroom- restroom lacks signage	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	
607	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824298 -99.733185 1]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	staff restroom- reflective surface 49" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
608	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824415 ,-99.733181 1]	Knee clearance at 27 inches off the floor is not 8 inches minimum deep. The knee clearance, measured from the bottom of the apron or the outside bottom edge of the lavatory, must be 27 inches at a point located 8 inches back from the front edge and continuing to 11 inches minimum in depth at 9 inches above the floor. The top of the lavatory rim may be no higher than 34 inches.	staff restroom- storage in clear floor space	Relocate storage to provide CFS, knee clearance, and toe clearance at sink	2015 ABAAS Section: 306.3.1, 306.3.2, 306.3.4, 306.3.5  2012 TAS Section: 306.3.2, 306.3.4, 306.3.5, 306.3.1  2010 ADAS Section: 306.3.3, 306.3.4, 306.3.5, 306.3.1	Toe clearance of deep toe space
609	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824427 -99.733174 4]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	staff restroom- storage in clear floor space around toilet	Relocate storage to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3.  2012 TAS Section: 604.3.1  2010 ADAS Section: 604.3.1	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figu	ıre
610	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824392 -99.733189 1]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	staff restroom- lacks 12" to wall side	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2	Top of bar 333-36°	\$ ***
611	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824392 -99.733181 1]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	staff restroom- grab bar mounted at 36.75" above finished floor	Remount grab bars in accessible stall to 33" to 36" aff	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
612	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824392 -99.733183 8]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	staff restroom- no fixed dispenser, toilet paper on top of bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	7.9	46 max

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
613	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824415 -99.733183 8]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	staff restroom- space narrows due to storage	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 48 min 24
614	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824357 , -99.733179 7]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	staff restroom- lacks turning space due to storage	Relocate obstacles to create turning space in restroom	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2		60 min  60 min  60 min  60 min  12 min  12 min  12 min
615	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824322 -99.733189 1]	The paper towel dispenser will project more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	staff restroom- paper towel dispenser protrudes if storage moved	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
616	Pecan Grove Camping Area: Pecan Grove Park Store	[29.5824336 -99.733185 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater. The bottom 10 inches on the push side must be smooth and free of obstructions (hold open devices). Opening hardware must be mounted between 30 and 44 inches above the floor or ground.		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors.  For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice. For all doors along the public circulation route, provide kick plate on push side of door from floor to 10" AFF.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
617	Pecan Grove Camping Area: Pecan Grove Campsites	[29.5802442 -99.733417 1]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 48 water campsites in this area have accessible features; 123 total in park	Create the required number of accessible water camp sites per table F244.2 as a smart practice; cost included in Rio Frio finding	2015 ABAAS Section: F244.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
618	Pecan Grove Camping Area: Pecan Grove Men's Restroom	[29.5797054 -99.733006 7]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	left mirror 42", right mirror 40.75" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
619	Pecan Grove Camping Area: Pecan Grove Men's Restroom	[29.5797089 -99.733012 1]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	soap dispenser mounted 50.25" above finished floor	Lower to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2	DEPLEMENT STATES	20 CM
620	Pecan Grove Camping Area: Pecan Grove Men's Restroom	[29.5796972,-99.733]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	stall door is not self closing	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
621	Pecan Grove Camping Area: Pecan Grove Men's Restroom	[29.5796984 -99.732993 3]	The threshold is greater than 1/2 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise.	.75" change in elevation at door	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	2015 ABAAS Section: 404.2.5 2012 TAS Section: 404.2.5 2010 ADAS Section: 404.2.5		½ max ½ ½ ½ ½ ½
622	Pecan Grove Camping Area: Pecan Grove Men's Restroom	[29.5796984 -99.733002 7]	The water flow from the spout is too low. The spout shall provide a flow of water 4 inches high minimum.	Water off, unable to test	Water shut off - unable to test. Assure spout flow height is min. 4" when reopened.	2015 ABAAS Section: 602.6  2012 TAS Section: 602.6  2010 ADAS Section: 602.6		4 inches min 0 0
623	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.5797077 ,-99.733004]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAWATORY  The resign or impressed.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
624	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.5797077 -99.733001 4]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	soap dispenser mounted 50.5" with reach over sink	Lower soap to max 44" aff for a forward reach over counter	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		22 Press. 12 State 12
625	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.5797019 , -99.733006 7]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	garbage can in side clearance	Relocate garbage can to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
626	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.579717, -99.733022 8]	The stall door fails to comply with all of the door requirements. The stall door must be a minimum of 32" wide and have compliant hardware on both sides. The stall door must be self-closing.	self closes but then reopens a couple inches	Adjust stall door to be self-closing	2015 ABAAS Section: 404.2.3, 404.2.7, 604.8.2.2 2012 TAS Section: 404.2.3, 404.2.7, 604.8.2.2 2010 ADAS Section: 404.2.3, 404.2.7, 604.8.2.2	
627	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.5797007 -99.733006 7]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser not mounted within compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7	xeu 8b
628	Pecan Grove Camping Area: Pecan Grove Women's Restroom	[29.5796975 -99.732998 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise.	women's- 1" threshold, 3.6% slope	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, provide beveled threshold.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
629	Pecan Grove Camping Area: Parking	[29.5787291 , -99.732355]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of (XX) parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of (XX) accessible stalls with a minimum of (XX) being designed as van accessible.	south roadway parking- 40 parking spaces, 0 accessible	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		May the property of the proper
630	Pecan Grove Camping Area: Parking	[29.5796051 , -99.733146 2]	Element meets all standards and requirements	restroom- parking scoping complies, 1 of 13 stalls accessible	None	2010 ADAS Section: N/A		
631	Pecan Grove Camping Area: Parking	[29.5796097 -99.733130 1]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	restroom- 3.6% slope in accessible stall	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		8
632	Pecan Grove Camping Area: Parking	[29.579626, -99.733103 3]	The parking sign is mounted too low. Parking space identification signs shall include the International Symbol of Accessibility complying with. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	restroom- van sign mounted 57.5" above ground	Raise existing accessible parking signs so lowest end of bottom sign is min 60" aff	2015 ABAAS Section: 502.6 2012 TAS Section: 502.6 2010 ADAS Section: 502.6	CCES	Von Accessible 60 nches min.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
633	Pecan Grove Camping Area: Pecan Grove Showers	[29.5797054 -99.733001 4]	There are no accessible bathing or shower facilities. Where facilities for bathing are provided for the public, clients or employees, including showers or bathtubs, at least one shower or bathtub and support facilities such as lockers, and not less than 1 percent of all facilities, shall be accessible.	1 shower designated accessible but lacks grab bars, other showers lack access features	Create an accessible shower in locker/bathing room	2015 ABAAS Section: F213.3.6 2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6	STANDAD ROLL-IN TYPE SHOWER COMPARTMENT  TOTAL COMP
634	Pecan Grove Camping Area: Pecan Grove Showers	[29.579702, -99.733000 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise.	access shower- 1" threshold, 2.4% slope, chair in maneuvering clearance push side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, provide beveled threshold.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	

Finalina.	Area Description	1.04/1.000	Findin	A - Duill	De common delien	Oitatia n	Photos	Finne
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
635	Pecan Grove Camping Area: Pecan Grove Showers	[29.579718, -99.733006 6]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. The sweep period for doors with closers shall be adjusted so that from an open position of 70 degrees, the door will take at least 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. Exterior doors are recommended to be maintained at 8.5 lbf as a smart practice. Force is to be measured at the operating hardware or 30 inches from the hinges, whichever is greater.		For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, provide beveled threshold. For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers. For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
636	Pecan Grove Camping Area: Pecan Grove Showers	[29.5796725 , -99.733043 9]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3.4% cross along front of building, 3.8% to drinking fountain	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3	MAAART COUL.	
637	Pecan Grove Camping Area: Pecan Grove Day Use Area	[29.5792971 , -99.731086 3]	Beach access routes shall connect an entry point to the beach to the: 1. High tide level at tidal beaches; 2. Mean high water level at river beaches; or 3. Normal recreation water level at lake, pond, and reservoir beaches	No accessible route to swimming area. Sand and gravel surface	Create a beach access route to mean high water level level of a firm and stable material as a smart practice	2015 ABAAS Section: 1018.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
638	Sample Cabins: Cabin 4	[29.5827867 -99.732912 9]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	3 cabins viewed in Oakmont area, none accessible; 0 of 17 cabin sites accessible in park	Create the required number of accessible camp sites per table F244.2 as a smart practice	2015 ABAAS Section: F244.2		
639	Sample Cabins: Cabin 4	[29.582824, -99.732895 4]	The door operating hardware is not accessible. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	exterior door in bedroom- knob hardware requires grasp/twist	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2015 ABAAS Section: 404.2.7 2012 TAS Section: 404.2.7 2010 ADAS Section: 404.2.7		Lever Panic Bar Loop Handle Operating hardware must be centered between 34" and 48" above the floor or ground
640	Sample Cabins: Cabin 4	[29.5828462 -99.732894 1]	Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.	exterior door in bedroom- lacks egress from bedroom	For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
641	Sample Cabins: Cabin 4	[29.5828497 ,-99.732899 4]	The window blinds are positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	living space- window controls and blinds too high	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max 48 max
642	Sample Cabins: Cabin 4	[29.582838, -99.732896 8]	The window controls are not accessible because it requires tight grasping, pinching or twisting of the wrist.	living space- window controls require tight grip	Replace window controls with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4 2012 TAS Section: 309.4 2010 ADAS Section: 309.4		
643	Sample Cabins: Cabin 4	[29.5828369 -99.732884 7]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	bedroom- less than 24" clear width adjacent to bed on right	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 48 min 24 max 24

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
644	Sample Cabins: Cabin 4	[29.5828322 , -99.732892 7]	The accessible route contains running slopes greater than 5 percent and cross slopes greater than 2 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails, wheel guides, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as ramp. Surface cross slopes must not exceed one unit vertical in 48 units. Horizontal (2-percent slope).	bedroom- 2.7% cross slope next to bed	Correct or repair slope to max 5% running and 2.08% cross	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
645	Sample Cabins: Cabin 4	[29.5828392 -99.732894 1]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	bedroom- clear floor space at window controls not adequate due to bed	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3  2012 TAS Section: 305.3  2010 ADAS Section: 305.3		48 min
646	Sample Cabins: Cabin 4	[29.5828404 -99.732892 7]	The window hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist.	bedroom- window hardware requires tight grip	Replace window hardware with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
647	Sample Cabins: Cabin 4	[29.5828468 -99.732889]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the table	lacks accessible seating, lacks accessible route to picnic table	Replace picnic table with one of an accessible design and locate along an AR as a smart practice	2015 ABAAS Section: 1011.4.2		
648	Sample Cabins: Cabin 4	[29.5828343 -99.732899 8]	Fire building surfaces shall be 9 inches (230 mm) minimum above the ground	lacks accessible route to grill/fire area, fire surface low	Correct fire building surface to be 9" min above the ground as a smart practice.  Extend AR to fire ring and provide 48" x 48"  CGS on all usable sides	2015 ABAAS Section: 1011.5.1		
649	Sample Cabins: Cabin 4	[29.5828404 -99.732895 4]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	table knee clearance 25.25" above floor or ground	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		Space

		T		A D '''		a:: ::		
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
650	Sample Cabins: Cabin 4	[29.5828441 -99.732897]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor.  EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11.	entry- 2.5" change in elevation, knob hardware, 59" window, fire place hearth pull side maneuvering clearance	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25" For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

	1	1	1	ı	T			1
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
651	Sample Cabins: Cabin 4	[29.5828466 -99.732887 1]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	bathroom - door 28" wide, sink pull side, knob hardware	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
652	Sample Cabins: Cabin 4	[29.582845, -99.732895 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	bedroom - back of bed pull side, knob hardware, 27" wide	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
653	Sample Cabins: Cabin 4	[29.5828415 -99.732898 1]	The U-shaped kitchen is not wide enough. In U-shaped kitchens enclosed on three contiguous sides, clearance between all opposing base cabinets, counter tops, appliances, or walls within kitchen work areas shall be 60 inches.	kitchen- 46" at fridge, 52" at counter	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and applicances	2015 ABAAS Section: 804.2.2 2012 TAS Section: 804.2.2 2010 ADAS Section: 804.2.2		60 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
654	Sample Cabins: Cabin 4	[29.5828427 , -99.732902 1]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches	kitchen- sink installed 36" above floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3		Simin  Si
			above the finished floor.			Section: 606.3 2010 ADAS	(a)	6" deep toe space
						Section: 606.3		
655	Sample Cabins: Cabin 4	[29.5828404 , -99.732891 4]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise	kitchen- pipes lack insulation	Insulate exposed pipes under sink	2015 ABAAS Section: 606.5		ACCESSIBLE LAVATORY
			configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.			2012 TAS Section: 606.5		
						2010 ADAS Section: 606.5		
656	Sample Cabins: Cabin 4	[29.5828462 , -99.732900 8]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe	kitchen- shelf below sink in knee and toe space	Remove base cabinet and lower sink height to max 34" aff	2015 ABAAS Section: 606.2, 804.4		2 mm. 23 mm. 23 mm. 20 mm. 24 mm. 25
		·	clearance.			2012 TAS Section: 606.2, 804.4		
						2010 ADAS Section: 606.2, 804.4		
657	Sample Cabins: Cabin 4	[29.5828415 , -99.732890 1]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less.	kitchen5" change in elevation to enter kitchen	Repair, bevel or ramp CIL along AR to max .25"	2015 ABAAS Section: 303.3		½ max ½ ½ ½ ½ ½ ½
		,,	Changes in level greater than 1/2 inch must be by way of a ramp.			2012 TAS Section: 303.3		
						2010 ADAS Section: 303.3		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
658	Sample Cabins: Cabin 4	[29.5828439 -99.732891 4]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	kitchen- hood controls, window hardware, light switch, window shade pulls all high	Lower operating mechanisms to max 48" above the finished floor (AFF) to highest operable part. Lower operable parts to max 44" above the finished floor (AFF) for a forward reach over counter.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		
659	Sample Cabins: Cabin 4	[29.5828404 -99.732898 1]	The window hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist.	kitchen- window hardware requires grasp/pinch, window shade pull strings	Replace window hardware with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4 2012 TAS Section: 309.4 2010 ADAS Section: 309.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
660	Sample Cabins: Cabin 4	[29.5828485 -99.732895 4]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	cabin restroom lacks accessible features, lacks directional information to accessible restrooms	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8 2012 TAS Section: 216.8 2010 ADAS Section: 216.8	TAL RESTROOM —
661	Sample Cabins: Cabin 4	[29.5828478 -99.732894 1]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	rough stone surface, multiple CILs and gaps, typical of all cabin sites	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3  2012 TAS Section: 302.3  2010 ADAS Section: 302.3	deminent distriction of the real  large demands perspecticular in the demand of the real  25 max
662	Sample Cabins: Cabin 13	[29.582396, -99.732025]	The U-shaped kitchen is not wide enough. In U-shaped kitchens enclosed on three contiguous sides, clearance between all opposing base cabinets, counter tops, appliances, or walls within kitchen work areas shall be 60 inches.	kitchen- width of kitchen 52"	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and applicances	2015 ABAAS Section: 804.2.2 2012 TAS Section: 804.2.2 2010 ADAS Section: 804.2.2	60 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
663	Sample Cabins: Cabin 13	[29.5823937 -99.732017]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	kitchen- sink installed 36.25" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		Toe clearance  8" min  10 of clearance  8" deep toe space
664	Sample Cabins: Cabin 13	[29.5823972 -99.732022 4]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	kitchen- sink pipes lack insulation	Insulate exposed pipes under sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACESSIBLE LAVATORY
665	Sample Cabins: Cabin 13	[29.5823949 -99.732015 7]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe clearance.	kitchen- 13" shelf in knee and toe clearance	Remove base cabinet and lower sink height to max 34" aff	2015 ABAAS Section: 606.2, 804.4 2012 TAS Section: 606.2, 804.4 2010 ADAS Section: 606.2, 804.4		1 mm (s)
666	Sample Cabins: Cabin 13	[29.5823937 -99.732015 7]	Combination refrigerators and freezers shall have at least 50 percent of the freezer space 54 inches (1370 mm) maximum above the finish floor or ground. The clear floor or ground space shall be positioned for a parallel approach to the space dedicated to a refrigerator/freezer with the centerline of the clear floor or ground space offset 24 inches (610 mm) maximum from the centerline of the dedicated space.	kitchen- wall is 17" from centerline of fridge	Provide required CFS at refrigerator.	2015 ABAAS Section: 804.6.6 2012 TAS Section: 804.6.6 2010 ADAS Section: 804.6.6		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos F	igure
667	Sample Cabins: Cabin 13	[29.5823925 -99.732025]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	kitchen- 54.5" width, 54" depth, insufficient turning space	Relocate obstacles to create turning space in room or space	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2	24 min 24 min 12	60 min
668	Sample Cabins: Cabin 13	[29.5823972 -99.732017]		kitchen75" change in elevation at surface change	Repair, bevel or ramp CIL along AR to max .25"	2015 ABAAS Section: 303.3  2012 TAS Section: 303.3  2010 ADAS Section: 303.3	Wamax Way Way Was a second sec	12 12

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
669	Sample Cabins: Cabin 13	[29.5824018 , -99.732022 4]	Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches (1220 mm) maximum where the reach depth is 20 inches (510 mm) maximum. Where the reach depth exceeds 20 inches (510 mm), the high forward reach shall be 44 inches (1120 mm) maximum and the reach depth shall be 25 inches (635 mm) maximum. Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches (865 mm) maximum and the depth of the obstruction shall be 24 inches (610 mm) maximum. The high side reach shall be 48 inches (1220 mm) maximum for a reach depth of 10 inches (255 mm) maximum. Where the reach depth exceeds 10 inches (255 mm), the high side reach shall be 46 inches (1170 mm) maximum for a reach depth of 24 inches (610 mm) maximum.	kitchen- light switch is not within reach range	Lower light switch to max 44" above the finished floor (AFF) for a forward reach over counter.	2015 ABAAS Section: 308.2.1, 308.3.2 2012 TAS Section: 308.2.1, 308.3.2 2010 ADAS Section: 308.2.1, 308.3.2		33 PM
670	Sample Cabins: Cabin 13	[29.5824018 -99.732018 3]	The window hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist.	kitchen- window hardware require grip and pinch	Replace window hardware with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4 2012 TAS Section: 309.4 2010 ADAS Section: 309.4		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
671	Sample Cabins: Cabin 13	[29.5823972 -99.732009]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	living space- lacks clear floor space at windows due to table	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min viu 08
672	Sample Cabins: Cabin 13	[29.5824042 -99.732025]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	living space- table knee clearance 25.25" above floor	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3  2012 TAS Section: 902.3  2010 ADAS Section: 902.3		Knee Space S
673	Sample Cabins: Cabin 13	[29.5823925 , -99.732025]	There are no accessible parking stalls. Each lot where parking is provided for the public as clients, guests or employees, shall provide accessible parking and shall be located on the shortest accessible route of travel from adjacent parking to an accessible entrance. There are a total of (XX) parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of (XX) accessible stalls with a minimum of (XX) being designed as van accessible.	paved surface can be loose, no stalls defined, typical of all campsites	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping based on the total number of stalls	2015 ABAAS Section: F208.2 2012 TAS Section: 208.2 2010 ADAS Section: 208.2		Vide Autor of Parago Name  William Control of Marco Name of Parago Name  Vide Name of
674	Sample Cabins: Cabin 13	[29.5823947 ,-99.732022 7]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between	entry - 30.5", knob hardware, window high, fireplace hearth in pull side clearance, change in elevation	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, 404.2.11 Exception		

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Finding Number	Area Description	Lat/Long	the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Doors, gates, and side lights adjacent to doors or gates, containing one or more glazing panels that permit viewing through the panels shall have the bottom of at least one glazed panel located 43 inches (1090 mm) maximum above the finish floor. EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11. Egress doors shall provide a continuous and	As Built	Recommendation  lever hardware or hardware operable without a tight pinch or grasp. For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" AFF.	Citation	Photos	Figure
			mm) maximum above the finish floor. EXCEPTION: Vision lights with the lowest part more than 66 inches (1675 mm) from the finish floor or ground shall not be required to comply with 404.2.11. Egress					

			T	I		T		
	ea Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	rea Description  cample Cabins: Cabin 13	[29.5823902 -99.732024 2]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	As Built  bathroom- 27.5", knob hardware, sink pull side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
676	Sample Cabins: Cabin 13	[29.5823883 -99.732018 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). Handactivated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	bedroom- 27.5", knob hardware, bed and dresser pull side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
677	Sample Cabins: Cabin 13	[29.5823879 -99.732022 4]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	bedroom exit- lacks maneuvering clearance push side, change in elevation, bed pull side, knob	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.11, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
678	Sample Cabins: Cabin 13	[29.5823867 -99.732018 3]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	restroom lacks accessible features, no information on accessible restroom	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8  2012 TAS Section: 216.8  2010 ADAS Section: 216.8		RESTROOM -
679	Sample Cabins: Cabin 13	[29.5823925 ,-99.732025]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	bedroom- narrows throughout area with furniture placement	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 48 min 48 min 48 min 48 min 48 min 58

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
680	Sample Cabins: Cabin 13	[29.5824018 -99.732019 7]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	bedroom- bed in clear floor space at thermostat and windows; has the required clear floor space between beds	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min
681	Sample Cabins: Cabin 13	[29.5823855 , -99.732013]	The window hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist.	bedroom- window hardware requires pinch/grasp	Replace window hardware with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4		
682	Sample Cabins: Cabin 17	[29.581561, -99.732070 6]	The fire extinguisher projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	living space- fire extinguisher projects 5" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
683	Sample Cabins: Cabin 17	[29.5815656 , -99.732073 3]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	living space- work surface 25.25" above finished floor	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3	25 25 25 25 25 25 25 25 25 25 25 25 25 2	Knee Space S
684	Sample Cabins: Cabin 17	[29.5815598 -99.732061 3]	The U-shaped kitchen is not wide enough. In U-shaped kitchens enclosed on three contiguous sides, clearance between all opposing base cabinets, counter tops, appliances, or walls within kitchen work areas shall be 60 inches.	kitchen- width 58", lacks turning space	Renovate U shaped kitchen to provide required 60" clearance between cabinets, counter tops and applicances	2015 ABAAS Section: 804.2.2 2012 TAS Section: 804.2.2 2010 ADAS Section: 804.2.2	53. 537 53 550 60 61	60 min
685	Sample Cabins: Cabin 17	[29.5815679 , -99.732061 3]	The top rim of the sink is too high. All lavatories/sinks that are designated to be accessible shall be a minimum 17 inches in horizontal depth and mounted with the rim or counter edge no higher than 34 inches above the finished floor.	kitchen-sink installed 36" above finished floor	Lower sinks to max 34" aff to front of rim	2015 ABAAS Section: 606.3 2012 TAS Section: 606.3 2010 ADAS Section: 606.3		Toe clearance  So deep toe space
686	Sample Cabins: Cabin 17	[29.5815738 -99.732068]	Knee and toe space has not been provided at the sink. Kitchen sinks must be provided with a clear floor space positioned for a forward approach including knee and toe clearance.	kitchen-12" shelf	Remove base cabinet and lower sink height to max 34" aff	2015 ABAAS Section: 606.2, 804.4 2012 TAS Section: 606.2, 804.4 2010 ADAS Section: 606.2, 804.4		25 mm. Signature of the state o

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
687	Sample Cabins: Cabin 17	[29.5815621 -99.732057 2]	Combination refrigerators and freezers shall have at least 50 percent of the freezer space 54 inches (1370 mm) maximum above the finish floor or ground. The clear floor or ground space shall be positioned for a parallel approach to the space dedicated to a refrigerator/freezer with the centerline of the clear floor or ground space offset 24 inches (610 mm) maximum from the centerline of the dedicated space.	kitchen- wall interrupts CFS at fridge	Provide required CFS at refrigerator	2015 ABAAS Section: 804.6.6 2012 TAS Section: 804.6.6 2010 ADAS Section: 804.6.6	
688	Sample Cabins: Cabin 17	[29.5815621 -99.732059 9]	There is a change in level greater than 1/4 inch. I/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	kitchen5" change in elevation	Repair, bevel or ramp CIL along AR to max .25"	2015 ABAAS Section: 303.3  2012 TAS Section: 303.3  2010 ADAS Section: 303.3	½ max ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½ ½

	I	T	1	T				
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
689	Sample Cabins: Cabin 17	[29.5815527 -99.732068 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.	entry- multiple change in elevations leading up to cabin, 2" high threshold, 29" wide, lacks accessible route	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, provide beveled threshold. For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
690	Sample Cabins: Cabin 17	[29.5815619 -99.732069 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.	bedroom exit- bed and dresser pull side, multiple CILs leading up to cabin, high threshold, 29" wide, lacks AR	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, provide beveled threshold. For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
691	Sample Cabins: Cabin 17	[29.5815466 -99.732060 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees.  Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground.  Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm).	bedroom- 29" wide, bed and dresser pull side	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
692	Sample Cabins: Cabin 17	[29.5815559 -99.732056 5]	The door opening does not provide at least 32 inches between the face of the door and the opposite stop. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	bathroom- 29" wide	Replace door with one having 32" clear width	2015 ABAAS Section: 404.2.3 2012 TAS Section: 404.2.3 2010 ADAS Section: 404.2.3		32 min  Hinged Door or Gate

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
693	Sample Cabins: Cabin 17	[29.5815656 -99.732061 3]	This restroom is not accessible. Where existing toilet rooms or bathing rooms do not comply, directional signs indicating the location of the nearest accessible toilet room or bathing room within the facility shall be provided. Signs shall include the International Symbol of Accessibility. Where existing toilet rooms or bathing rooms do comply), the accessible toilet rooms or bathing rooms shall be identified by the International Symbol of Where clustered single user toilet rooms or bathing facilities are permitted, accessible toilet rooms or bathing facilities shall be identified by the International Symbol of Accessibility unless all toilet rooms and bathing facilities are accessible.	lacks accessible features, no information on accessible restroom	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom	2015 ABAAS Section: F216.8 2012 TAS Section: 216.8 2010 ADAS Section: 216.8	RE	STROOM
694	Sample Cabins: Cabin 17	[29.5815458 , -99.732068]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	bedroom- clear width of travel reduces to access beds	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	Paris Service Control of the Control	49.min 24.max 49.min 51.50 51.
695	Sample Cabins: Cabin 17	[29.5815878 -99.732046 5]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	bedroom- lacks 60" turning space with furniture	Relocate obstacles to create turning space in bedroom	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2	24 min	60 min 60 min Circle 30 min 12 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
696	Sample Cabins: Cabin 17	[29.5815423 -99.732072]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	bedroom- lacks clear floor space at thermostat, windows, lacks between beds	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3	48 min
697	Sample Cabins: Cabin 17	[29.581585, -99.732040 2]	The closet space is not accessible because the closet pole is not within reach range. Accessible storage spaces, including closets with a clothes rod or shelf shall be within 48 inches of the floor.	bedroom- closet bar above reach range	Remount closet bar to be max 48"	2015 ABAAS Section: 811.3 2012 TAS Section: 811.3 2010 ADAS Section: 811.3	19 mas 2 19
698	Sample Cabins: Cabin 17	[29.5815598 -99.732035 8]	The window hardware is not accessible because it requires tight grasping, pinching or twisting of the wrist.	bedroom- window hardware requires pinch/grasp	Replace window hardware with an operable part usable without a tight pinch or grasp	2015 ABAAS Section: 309.4  2012 TAS Section: 309.4  2010 ADAS Section: 309.4	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
699	Sample Shelter Campsites: Shelter 9	[29.5802465 -99.733670 6]	Camping facilities shall provide camping units with mobility features complying with F244.2 in accordance with Table F244.2. Where a camping facility provides different types of camping units, Table F244.2 shall apply to each type of camping unit provided. Total Number of Camping Units Provided in Camping Facility Minimum Number of Camping Units with Mobility Features Required 1 1 2 to 25 2 26 to 50 3 51 to 75 4 76 to 100 5 101 to 150 7 151 to 200 8 201 and over 8, plus 2 percent of the number over 200	0 of 36 total shelter campsites are accessible (15 in Pecan Grove, 16 in River Crossing, 5 in Oakmont)	Create the required number of accessible camp sites per table F244.2 as a smart practice	2015 ABAAS Section: F244.2	
700	Sample Shelter Campsites: Shelter 9	[29.5807375 -99.733677 3]	The shelf projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	shelf with clothes bar protrudes 12"	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	
701	Sample Shelter Campsites: Shelter 9	[29.5807574 -99.733665 2]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	table lacks wheelchair space	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3  2012 TAS Section: 902.3  2010 ADAS Section: 902.3	Strate St

<b>-</b>	l	1	I			<b>0</b> '' ''		
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
702	Sample Shelter Campsites: Shelter 9	[29.5807612 -99.733680 5]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, remount hardware to 34" to 48" aff. For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
703	Sample Shelter Campsites: Shelter 9	[29.5807597 -99.733674 6]	for either a side or front approach. Where a clear floor or ground space allows a parallel	clothes bar and hooks high, light switch 56", outdoor outlets 57", breaker switches high	Remount operable parts to be in reach range of 15" min to 48" max	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1		10 max
704	Sample Shelter Campsites: Shelter 9	[29.580768, -99.733674 3]	Fire building surfaces shall be 9 inches (230 mm) minimum above the ground	lacks accessible route to element, element is on ground	Correct fire building surface to be 9" min above the ground as a smart practice.	2015 ABAAS Section: 1011.5.1		

Finding	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number	r ii ou zoonipiion			7.0 2				940
705	Sample Shelter Campsites: Shelter 9	[29.5807548 ,-99.733666 2]	Water spouts at water hydrants and water utility hook-ups shall be 28 inches (710 mm) minimum and 36 inches (915 mm) maximum above the ground	handle 28", requires tight grip, lacks AR	Remount water spouts to 28" min or 36" max above the ground as a smart practice Extend AR to water spout	2015 ABAAS Section: 1011.6		
706	Sample Shelter Campsites: Shelter 22	[29.5822825 -99.731087 3]	Element meets all standards and requirements	entry door complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
707	Sample Shelter Campsites: Shelter 22	[29.5822814 -99.731085 1]	The building entrance is not located on an accessible route. When a building, or portion of a building, is required to be accessible, an accessible route of travel shall be provided to all portions of the building, to accessible building entrances and between the building and the public way. All walks, halls, corridors, aisles, skywalks, tunnels, and other spaces that are part of an accessible route must comply. An accessible route of travel must not pass through kitchens, storage rooms, restrooms, closets or other spaces used for similar purposes. At least one accessible route within the boundary of the site must be provided from public transportation stops, accessible parking and accessible passenger loading zones and public streets or sidewalks to the accessible building entrance they serve. The accessible route shall, to the maximum extent feasible, coincide with the route for the general public. At least one accessible route shall connect accessible buildings, facilities, elements and spaces that are on the same site. At least one accessible spaces and elements.	loose crushed stone path leading to entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to building entrance	2015 ABAAS Section: F206.2.1 2012 TAS Section: 206.2.1 2010 ADAS Section: 206.2.1	
708	Sample Shelter Campsites: Shelter 22	[29.5822822 , -99.731081 2]	Fire building surfaces shall be 9 inches (230 mm) minimum above the ground	fire surface at ground	Correct fire building surface to be 9" min above the ground as a smart practice.	2015 ABAAS Section: 1011.5.1	
709	Sample Shelter Campsites: Shelter 22	[29.582282, -99.731089 7]	Water spouts at water hydrants and water utility hook-ups shall be 28 inches (710 mm) minimum and 36 inches (915 mm) maximum above the ground	spout at 18" above ground	Remount water spouts to 28" min or 36" max above the ground as a smart practice	2015 ABAAS Section: 1011.6	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
710	Sample Shelter Campsites: Shelter 22	[29.5822806 , -99.731086 3]	The shelf and hanging rod projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	shelf with hanging rod protrudes	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		
711	Sample Shelter Campsites: Shelter 22	[29.5822899 -99.731099 7]	The controls is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	light switch/fuse box controls 73" above ground, shelf 69", hanging rod 67" above ground	Remount operable parts to be in reach range of 15" min to 48" max Remount hanging rod and shelf to height between 40" and 48" aff	2015 ABAAS Section: 308.1  2012 TAS Section: 308.1  2010 ADAS Section: 308.1	R. S.	48 max
712	Sample Shelter Campsites: Shelter 22	[29.5822852 , -99.731086 3]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	lacks toe clearance	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3	10 H W	Knee Space S

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
713	Sample Shelter Campsites: Shelter 26	[29.5898105 -99.739813 9]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The threshold has a vertical change greater than 1/4 inch high. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.	entry- 3%, lacks accessible route, change in elevation	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
714	Sample Shelter Campsites: Shelter 26	[29.5898157 -99.739820 9]	The surface of parking spaces and pull-up spaces shall be firm and stable. The slope of the surface of parking spaces and pull-up spaces shall not be steeper than 1:48 in any direction. EXCEPTION: Where the surface is other than asphalt, concrete, or boards, slopes not steeper than 1:20 shall be permitted when necessary for drainage.	(typical) paved parking at each shelter, surface becomes loose, stalls not marked	Correct surface of parking spaces to be firm and stable with slopes max of 2.08% or 5% for surfaces other than concrete, asphalt or boards as a smart practice.	2015 ABAAS Section: 1012.4, 1012.5, 1012.5 EXCEPTION	
715	Sample Shelter Campsites: Shelter 26	[29.589811, -99.739820 9]	The shelf and hanging rod projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	shelf with hanging rod protrudes	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
716	Sample Shelter Campsites: Shelter 26	[29.5898075 -99.739819 5]	The operable parts are positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	coat hooks range 71" -76 ", fuse box 73.5" installed above ground, shelf 70", hanging rod 68"	Remount operable parts to be in reach range of 15" min to 48" max Remount shelf and hanging rod to height between 40" and 48" aff	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		15 min 15
717	Sample Shelter Campsites: Shelter 26	[29.5898075 -99.739823 6]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	11" knee/toe clearance	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3  2012 TAS Section: 902.3  2010 ADAS Section: 902.3	Z7 Mm.	Knee Space Community of Man to Man Max Man Max Dising or Work Surface

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
718	Sample Shelter Campsites: Shelter 36	[29.5899071 -99.738092 3]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold has a vertical change greater than 1/4 inch high. The threshold has a gap greater than 1/2 inch wide. Egress doors shall provide a continuous and unobstructed way of egress travel from any point in a building or facility that provides an accessible route to an area of refuge, a horizontal exit, or a public way.	entry- 27.5" wide, 5" gap, 12" maneuvering clearance pull side, lacks accessible route, change in elevation	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25". For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, enlarge cement pad at exit to allow 18" clearance on the latch side, and extend a pathway away from the building for emergency egress.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		
719	Sample Shelter Campsites: Shelter 36	[29.5899113 -99.738093 5]	The shelf and hanging rod projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	shelf and hanging rod protrude	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
720	Sample Shelter Campsites: Shelter 36	[29.5899078 -99.738098 9]	The fuse box is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	fuse box 73", shelf 73", hanging rod 67" above ground	Remount operable parts to be in reach range of 15" min to 48" max Remount shelf and hanging rod to height between 40" and 48" aff	2015 ABAAS Section: 308.1 2012 TAS Section: 308.1 2010 ADAS Section: 308.1		10 max / 48 max
721	Sample Shelter Campsites: Shelter 36	[29.5899136 -99.738096 2]	The top of the work surface is not within a compliant height range. The tops of tables and counters shall be 28 inches to 34 inches from the floor or ground.	13" depth, does not provide knee clearance	Provide tables and work surfaces at 28" to 34" aff with required knee and toe clearances	2015 ABAAS Section: 902.3 2012 TAS Section: 902.3 2010 ADAS Section: 902.3		Square Square Square Max. Squa

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
722	Visitors Center: Visitor Center Parking East Lot	[29.5895626 , -99.742056 5]	Element meets all standards and requirements	parking scoping complies- 1 of 14 stalls accessible	None	2010 ADAS Section: N/A		
723	Visitors Center: Visitor Center Parking East Lot	[29.5895766 -99.742014 9]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 14 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van stall	Add van parking sign to 1 accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		The principle of the pr
724	Visitors Center: Visitor Center Parking East Lot	[29.5895731 , -99.742072 6]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	2.3% slope in access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		
725	Visitors Center: Visitor Center Parking East Lot	[29.5895649 -99.742056 5]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	stall surface is loose and unstable	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4 2012 TAS Section: 502.4 2010 ADAS Section: 502.4		½ max ½ ½ ½ ½ ½ ½

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
726	Visitors Center: Visitor Center West Lot	[29.5897597 -99.742377]	There are no van accessible parking stalls.  1 in every 6, minimum of one, required accessible stalls must be a van accessible stall. There are a total of 7 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	lacks van stall	Add van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8' per the table	2015 ABAAS Section: F208.2, F208.2.4 2012 TAS Section: 208.2, 208.2.4 2010 ADAS Section: 208.2, 208.2,		March of designation (Control to the Control to the
727	Visitors Center: Visitor Center West Lot	[29.5897853 ,-99.742359 6]	The cross slopes (narrow dimension) and/or running slopes (long dimension) of the access aisle exceeds 2%. The running slope and the cross slope in an accessible parking stall and the access aisle must not exceed 2%.	2.4% slope in access aisle	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		4-4-
728	Visitors Center: Visitor Center West Lot	[29.5897783 , -99.742365]	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical. Parking spaces and access aisles serving them shall be stable, firm, and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	loose surface, overgrown grass/weeds in accessible route	Resurface accessible stalls and access aisles with a firm, stable, and slip resistant material	2015 ABAAS Section: 502.4  2012 TAS Section: 502.4  2010 ADAS Section: 502.4		Уд та 1 2 Уд 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1
729	Visitors Center: Visitor Center West Lot	[29.5897772 , -99.742365]		parking scoping complies- 1 of 9 stalls accessible	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
730	Visitors Center: Exterior Accessible Route	[29.58961, -99.74234]	At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site. For areas of sport activity, an accessible route is required to connect to the boundary of each area of sport activity. The size of an area of sport activity includes only the space needed to play. Where multiple sports fields or courts are provided, an accessible route is required to each field or area of sport activity.	route off AR into garden area not accessible. loose unstable dirt/gravel path	Provide an accessible route to each element within the site.	2010 ADAS Section: 206.2.2, 206.2		
731	Visitors Center: Exterior Accessible Route	[29.5897178 , -99.74232]	The route of travel at this location does not provide the required minimum width. The minimum clear width for sidewalks and walks is 36 inches.	pathway is overgrown, reduced to less than 12"	Widen EAR to min 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 mas.  48 mis.  24 mas.  25 mas.  26 mas.
732	Visitors Center: Exterior Accessible Route	[29.5895947 ,-99.74208]	Element meets all standards and requirements	educational signage	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
733	Visitors Center: Exterior Accessible Route	[29.589741, -99.742327 4]	The ramps slope exceeds the maximum running slope (direction of travel) allowable of 8.33%. Ramps should have the least possible slope but in no case more than 8.3% (1:12).	10.4% slope on ramp	Correct slope of ramp to max 8.33%	2015 ABAAS Section: 405.2  2012 TAS Section: 405.2  2010 ADAS Section: 405.2		HAM'S
734	Visitors Center: Exterior Accessible Route	[29.589748, -99.742335 5]	The curb ramp on the accessible route contains cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3% cross slope on ramp	Correct curb ramp cross slope to max 2.08%	2015 ABAAS Section: 405.3  2012 TAS Section: 405.3  2010 ADAS Section: 405.3		Along James
735	Visitors Center: Exterior Accessible Route	[29.5897457 -99.742336 8]	Detectable warning surfaces complying with R305 shall be provided at the following locations on pedestrian access routes and at transit stops: Curb ramps and blended transitions at pedestrian street crossings; Pedestrian refuge islands; Pedestrian atgrade rail crossings not located within a street or highway; Boarding platforms at transit stops for buses and rail vehicles where the edges of the boarding platform are not protected by screens or guards; and Boarding and alighting areas at sidewalk or street level transit stops for rail vehicles where the side of the boarding and alighting areas facing the rail vehicles is not protected by screens or guards. Detectable warning surfaces are not required at pedestrian refuge islands that are cutthrough at street level and are less than 1.8 meters (6.0 ft) in length in the direction of pedestrian travel.	lacks detectable warning surface	Install required detectable warnings at curb ramps along the public right of way or at curb ramps within a site as a smart practice.	2012 TAS Section: 705.1 2010 ADAS Section: 705		Heres delay and the state of th

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
736	Visitors Center: Exterior Accessible Route	[29.5897347 ; -99.742146 1]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	shifting pavement caused CILs	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½
737	Visitors Center: Exterior Accessible Route	[29.5896913 ,-99.74213 47], [29.5897392 , -99.742153 4]	The accessible route of travel on the accessible route contains cross slopes greater than 2%. Cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope).	3% at corner, 3.4% along east parking	Correct or repair cross slope along AR to max 2.08%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
738	Visitors Center: Exterior Accessible Route	[29.5895932 , -99.742052 7]	The walkway contains abrupt vertical edges and/or variations over a 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	.75" by east parking	Repair, bevel or ramp CIL along AR	2012 TAS Section: 303.2, 303.3 2010 ADAS Section: 303.2, 303.3		½ max ½ ½ ½ ½ ½
739	Visitors Center: Exterior Accessible Route	[29.5896487 -99.742286 9]	There is a gap spaced greater than a 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	1" gap	Correct or fill gaps to be max .5"	2015 ABAAS Section: 302.3 2012 TAS Section: 302.3 2010 ADAS Section: 302.3		deemant decides of host of the

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
740	Visitors Center: Exterior Accessible Route	[29.5897385 -99.742155] [29.5897467 -99.742333 4]	The running slope of walking surfaces shall not be steeper than 1:20.	6.1% from west parking, 7.5% at turn, 9.3% to restrooms	Correct running slope along the AR to max 5%	2015 ABAAS Section: 403.3 2012 TAS Section: 403.3 2010 ADAS Section: 403.3		
741	Visitors Center: Exterior Accessible Route	[29.5896337 -99.742165 1]	Benches shall have a 36" by 48" clear ground space (CGS) positioned near the bench with one side of the space adjoining an outdoor recreation access route (ORAR) or trail, as applicable The CGS shall not overlap with the ORAR or trail or another CGS As a smart practice, add at least one armrest and achieve height of bench seat of 17" to 19"	bench lacks space due to table	Relocate table to provide CFS at bench	2015 ABAAS Section: 1011.2.1		
742	Visitors Center: Exterior Accessible Route	[29.5896348 , -99.742163 6]	Picnic tables shall provide at least one wheelchair space for each 24 linear feet (7320 mm) of usable table surface perimeter. Wheelchair spaces shall be 30 inches (760 mm) minimum by 48 inches (1220 mm) minimum. Wheelchair spaces shall be positioned for a forward approach to the table and provide knee and toe clearance complying with 306 under the	table lacks wheelchair space	Replace picnic table with one of an accessible design as a smart practice	2015 ABAAS Section: 1011.4.2		
743	Visitors Center: Exterior Accessible Route	[29.5896982 , -99.742140 7]	table Element meets all standards and requirements	vending machine complies	None	2010 ADAS Section: N/A		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
744	Visitors Center: Exterior Accessible Route	[29.5897553 , -99.742127 3]	Element meets all standards and requirements	garbage can complies	None	2010 ADAS Section: N/A		
745	Visitors Center: Exterior Accessible Route	[29.5897043 -99.742783 1]	There is no accessible route to the tables and bleachers. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	0 of 4 tables accessible, lacks AR to tables and bleachers	Create an accessible route with crushed stone or other outdoor material from parking or walkway to tables and bleachers Replace one picnic table with one of an accessible design as a smart practice and locate along an AR	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Priority  And Priority
746	Visitors Center: Visitor Center Gift Shop	[29.5897072 -99.742238 9]	Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area. Employee work areas, or portions of employee work areas, other than raised courtroom stations, that are less than 300 square feet (28 m2) and elevated 7 inches (180 mm) or more above the finish floor or ground where the elevation is essential to the function of the space shall not be required to comply with these requirements or to be on an accessible route.	interpreter - knob hardware, vent below 10" shop office - knob hardware, vent below 10", display in push side maneuvering clearance	Replace hardware with lever hardware or hardware operable without a tight pinch or grasp. Provide kick plate on push side of door from floor to 10" AFF.	2015 ABAAS Section: F203.9 2012 TAS Section: 203.9 2010 ADAS Section: 203.9		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
747	Visitors Center: Visitor Center Gift Shop	[29.58968, -99.74223]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.  Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.  Maneuvering clearances shall have a max slope of 2.08%. The threshold has a vertical change greater than 1/4 inch high.	entry- 5% slope, 1" change in elevation	For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25".	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception	
748	Visitors Center: Visitor Center Gift Shop	[29.5896901 , -99.742239 7]	The transaction counter is too high. A portion of the counter surface that is 36 inches long minimum and 36 inches high maximum above the finish floor shall be provided. Knee and toe space must be provided for a forward approach. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach.	counter 44", lowered portion 32" but only 24" wide and has computer on it	Relocate storage from lower counter	2015 ABAAS Section: 904.4.2, 904.4.1 2012 TAS Section: 904.4.1, 904.4.2 2010 ADAS Section: 904.4.2, 904.4.1	36 max
749	Visitors Center: Visitor Center Gift Shop	[29.5896815 -99.742206 7]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	reduces to 35" at counter, reduces at retail displays	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1	24 max 48 min 24

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
750	Visitors Center: Visitor Center Gift Shop	[29.58972, -99.74223]		rear door - table in maneuvering clearance on pull side, knob hardware, 3.1% slope, lacks 18" pull side maneuvering clearance, 2" gap	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors. For all doors along the public circulation route, correct slope in door clearance to max 2.08%. For all doors along the public circulation route, fill gaps at door entries to max .5". For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp.	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11, Exception		
751	Visitors Center: Visitor Center Men's Restroom	[29.5897025 , -99.742225 5]		lacks compliant signage, lacks symbol of accessibility	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	MEN	FUC.

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
752	Visitors Center: Visitor Center Men's Restroom	[29.5896955 , -99.742244 3]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	reflective surface 42.5" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3 2012 TAS Section: 603.3 2010 ADAS Section: 603.3		
753	Visitors Center: Visitor Center Men's Restroom	[29.5896932 , -99.742251]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	sink pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5 2012 TAS Section: 606.5 2010 ADAS Section: 606.5		ACCESSIBLE LAVATORY  The same to equivariant
754	Visitors Center: Visitor Center Men's Restroom	[29.5896944 -99.742244 3]	The operable part is not accessible because there is not adequate clear floor space for either a forward or side approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	lacks CFS at sink due to door, 36"	Provide required 30" by 48" CFS at operable parts	2015 ABAAS Section: 305.3 2012 TAS Section: 305.3 2010 ADAS Section: 305.3		48 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
755	Visitors Center: Visitor Center Men's Restroom	[29.5896979 ,-99.742251]	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.	side grab bar installed 13" from back, 50" total	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1		
756	Visitors Center: Visitor Center Men's Restroom	[29.589699, -99.742246 9]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	lacks rear bar	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2		Top of bar 33°-36°

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
757	Visitors Center: Visitor Center Men's Restroom	[29.5897049 , -99.742236 2]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser installed 6" above grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
758	Visitors Center: Visitor Center Men's Restroom	[29.5896909 -99.742225 5]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	insufficient turning space	Relocate obstacles to create turning space in toilet compartment.	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2		60 min 60
759	Visitors Center: Visitor Center Men's Restroom	[29.5897002 , -99.742217 4]	The hand dryer projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	hand dryer projects 8" into circulation path	Relocate protruding objects or place cane detectable warning or bollard at foot of item	2015 ABAAS Section: 307.2 2012 TAS Section: 307.2 2010 ADAS Section: 307.2		The state of the s

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
760	Visitors Center: Visitor Center Women's Restroom	[29.58972, -99.74223]	Minimum maneuvering clearances at doors and gates shall comply with 404.2.4. Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance. Door openings shall provide a clear width of 32 inches (815 mm) minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. Openings more than 24 inches (610 mm) deep shall provide a clear opening of 36 inches (915 mm) minimum. There shall be no projections into the required clear opening width lower than 34 inches (865 mm) above the finish floor or ground. Projections into the clear opening width between 34 inches (865 mm) and 80 inches (2030 mm) above the finish floor or ground shall not exceed 4 inches (100 mm). The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. I/4 inch is the maximum vertical rise. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate. Hardware shall be 34 inches minimum and 48 inches maximum above the finish floor or ground.	women's- 31.5" wide, knob hardware, sink in pull side maneuvering clearance, 1.25" change in elevation with threshold	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width For all doors along the public circulation route, repair, provide beveled threshold For all doors along the public circulation route, replace hardware with lever hardware or hardware operable without a tight pinch or grasp	2010 ADAS Section: 404.2.3, 404.2.7, 404.2.4, 404.2.11 Exception		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
761	Visitors Center: Visitor Center Women's Restroom	[29.5896955 ,-99.742236 2]	The restroom sign does not comply with one or more applicable requirements for the location, height, and properties of the sign.	sign door mounted, lacks symbol of accessibility	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	2015 ABAAS Section: F216.2, 703.1, 703.2, 703.5, 703.6 2012 TAS Section: 216.2, 703.1, 703.2, 703.5, 703.6 2010 ADAS Section: 216.2, 703.1, 703.2, 703.5, 703.6	WOMEN	The state of the s
762	Visitors Center: Visitor Center Women's Restroom	[29.5896815 , -99.742206 7]	The mirror is mounted too high. Mirrors must have the bottom edge of the reflecting surface a maximum of 40 inches above the floor if above a sink or counter. Mirrors not located above lavatories or countertops shall be installed with the bottom edge of the reflecting surface 35 inches maximum above the finish floor or ground.	reflective surface installed 49.5" above finished floor	Lower mirror so reflective surface is max 40" aff	2015 ABAAS Section: 603.3  2012 TAS Section: 603.3  2010 ADAS Section: 603.3		
763	Visitors Center: Visitor Center Women's Restroom	[29.5897002 -99.742246 9]	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	pipes lack insulation	Insulate exposed pipes under one sink	2015 ABAAS Section: 606.5  2012 TAS Section: 606.5  2010 ADAS Section: 606.5		ACCESSIBLE LAWATORY  For any or equivalent

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos Figure
764	Visitors Center: Visitor Center Women's Restroom	[29.5897119 , -99.742233 5]	The required 56 inches by 60 inches clear floor space for the water closet has been obstructed. The clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall.	sink meets safe harbor, garbage can in clearance	Relocate garbage can to provide required 60" clearance around toilet	2015 ABAAS Section: 604.3. 2012 TAS Section: 604.3.1	
						2010 ADAS Section: 604.3.1	
765	Visitors Center: Visitor Center Women's Restroom	[29.5896897 , -99.742233 5]	The toilet is not located within the range allowed from the side wall or partition. The centerline of the toilet must be 16 to 18 inches from the side wall.	toilet mounted 19.5" from side wall	Remount toilets to 16" to 18" from the side wall to centerline	2015 ABAAS Section: 604.2	Ę H
	nestroom	5]	inches from the side wall.			2012 TAS Section: 604.2	
						2010 ADAS Section: 604.2	16"-18"
766	Visitors Center: Visitor Center Women's Restroom	[29.5896979 , -99.742236 2]	The toilet seat is not located within the range allowed off the floor. The height of accessible water closets shall be a minimum of 17 inches and a maximum of 19	seat installed 16" above finished floor	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	2015 ABAAS Section: 604.4	
	nestroom	2]	inches measured to the top of a maximum 2-inch high toilet seat.			2012 TAS Section: 604.4	17" to 19"
						2010 ADAS Section: 604.4	
767	Visitors Center: Visitor Center Women's	[29.5896885 , -99.742238	The side grab bars are not in the correct location. Grab bars on the side wall must be installed so that the end closest to the rear	36" grab bar	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	2015 ABAAS Section: 604.5.1	
	Restroom	9]	wall is maximum 12" from the rear wall. The end furthest from the rear wall must be mounted minimum 54" from the rear wall.			2012 TAS Section: 604.5.1	
						2010 ADAS Section: 604.5.1	

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
768	Visitors Center: Visitor Center Women's Restroom	[29.5897072 ,-99.742236 2]	The rear grab bar is not 36" long or is not mounted in the correct location. The rear grab bar must be a minimum of 36" long and extend from the toilet centerline a minimum 12" towards the wall side and a minimum 24" towards the open side of the toilet. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	lacks rear bar	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	2015 ABAAS Section: 604.5.2 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2		Top of bar 33°-36°
769	Visitors Center: Visitor Center Women's Restroom	[29.5896932 -99.742234 9]	The grab bar height and/or spacing fails. Grab bars must be mounted between 33" and 36" to the top of the gripping surface. There must be 1.5" of clearance between the grab bar and the wall. There must be a minimum of 1.5" of clearance below and minimum 12" above the grab bar to any dispenser or other obstruction.	toilet paper dispenser installed 5" above side grab bar	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 609.3, 609.4 2012 TAS Section: 609.4, 609.3 2010 ADAS Section: 609.3, 609.4		
770	Visitors Center: Visitor Center Women's Restroom	[29.5897025 -99.742237 6]	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	toilet paper dispenser not mounted within compliant range	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	2015 ABAAS Section: 604.7 2012 TAS Section: 604.7 2010 ADAS Section: 604.7		to min to the min to t

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
771	Visitors Center: Visitor Center Women's Restroom	[29.5897049 , -99.742237 6]	The route of travel at this location does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	only 32" to get past door	Widen AR to compliant 36" clear width	2015 ABAAS Section: 403.5.1 2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1		24 max 48 min usus 52 max 5
772	Visitors Center: Visitor Center Women's Restroom	[29.5897025 -99.742248 3]	There is insufficient turning space within this room or space. The space required for a wheelchair to make a 180-degree turn is a clear space of 60 inches in diameter or a T-shaped space.	room too small	Relocate obstacles to create turning space in restroom	2015 ABAAS Section: 304.3.1, 304.3.2 2012 TAS Section: 304.3.1, 304.3.2 2010 ADAS Section: 304.3.1, 304.3.2		60 min  12 min  12 min  12 min

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
773	Trails: Madrone Walkway	[29.5845455	The surface of trails, passing spaces, and resting intervals shall be firm and stable	Deteriorated asphalt	Replace deteriorated surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
774	Trails: Madrone Walkway	[29.5838387 -99.734034]	Trails with a clear tread width less than 60 inches (1525 mm) shall provide passing spaces complying with 1017.4 at intervals of 1000 feet (300 m) maximum. Where the full length of a trail does not fully comply with 1017, a passing space shall be located at the end of the trail segment that fully complies with 1017. Passing spaces and resting intervals shall be permitted to overlap	None of trail is wider that 50" - 50", 46", 50"	Create 60" level turning space every 1000' along the trail	2015 ABAAS Section: 1017.4		
775	Trails: Madrone Walkway	[29.5838784 , -99.734117 2]	The cross slope shall not be steeper than 1:48. EXCEPTION: Where the surface is other than concrete, asphalt, or boards, cross slopes not steeper than 1:20 shall be permitted when necessary for drainage.	Many areas of trail had steep cross slopes. 6.7%, 4.4%, 5.2%, 6.2%	Correct or repair pathway cross slope to max 2.08% or 5% depending on surface as a smart practice.	2015 ABAAS Section: 1017.2		

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
Number								
777	Trails: Madrone Walkway	[29.5884454 -99.739486 9]	There is no accessible route to the trailhead. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to trailhead. Sand and gravel	Create an accessible route with crushed stone or other outdoor material from parking or walkway to trailhead	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  PROPERTY AND ADMINISTRATION OF THE PROPERTY A

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
778	Trails: Old Entry Road	[29.5877795 , -99.737834 7]	There is no accessible route to the trailhead. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to trailhead, gravel	Create an accessible route with crushed stone or other outdoor material from parking or walkway to trailhead.	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  POPUT  GENERAL  ACCESSIBLE ENTRANCES  ACCESSIBLE  ACCESSIB
779	Trails: Old Entry Road	[29.5877725 -99.737971 5]	The surface of trails, passing spaces, and resting intervals shall be firm and stable	Deteriorated asphalt	Replace surface of trail with one that is firm and stable as a smart practice.	2015 ABAAS Section: 1017.2		
780	Trails: Old Entry Road	[29.587776, -99.737861 5] Wheel: Trail is the remains of Dir: N/A	The cross slope shall not be steeper than 1:48. EXCEPTION: Where the surface is other than concrete, asphalt, or boards, cross slopes not steeper than 1:20 shall be permitted when necessary for drainage.	6.2% cross slope	Correct or repair pathway cross slope to max 2.08% or 5% depending on surface as a smart practice.	2015 ABAAS Section: 1017.2	The state of the s	

## Garner State Park - 234 RR 1050 Concan, TX 78838

Finding Number	Area Description	Lat/Long	Finding	As Built	Recommendation	Citation	Photos	Figure
781	Trails: Bridges Trail	[29.5855691 , -99.736036 2]	There is no accessible route to the trailhead. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to trailhead. Sand and gravel	Create an accessible route with crushed stone or other outdoor material from parking or walkway to trailhead	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSIBLE ENTRANCES  Organic State of Control of Contr
782	Trails: Crystal Cave Trail	[29.5858395 , -99.736662 8]	There is no accessible route to the trailhead. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	No accessible route to trailhead. Sand and gravel	Create an accessible route with crushed stone or other outdoor material from parking or walkway to trailhead	2015 ABAAS Section: F206.2.2 2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2		ACCESSBLE ENTRANCES  POTENTIAL PROPERTY OF THE