

# TFFC IF- ADA Evaluation



**IF-Athens TX, TFFC ADA Evaluation**

**5550 FM2495**

**Athens, TX 75752**

**Accessibility Evaluation**

**Inspection Date: 11/15/2022**

**Inspectors: Christopher Meza**

**Prepared By**



**(512) 424 - 2000**

**[tpwd.texas.gov](http://tpwd.texas.gov)**

**Report Date: 02/04/2024**

**Table of Contents**

---

**Findings** ..... 3

**Exterior of Property (Public) - Parking Lots/Walkways** ..... 3

**Structures on Property (Public) - Visitors Center** ..... 12

**Structures on Property (Public) - Conservatory Center** ..... 38

**Structures on Property (Public) - Anglers Pavilion** ..... 49

**Outdoor Features (Public)** ..... 57





**Structures on Property (STAFF) - Visitor Center Top Floor** ..... 92

**Structures on Property (STAFF) - Visitor Center Bottom Floor** ..... 95





**Structures on Property (STAFF) - Conservatory Center** ..... 99



**Structures on Property (STAFF) - Anglers Pavilion** ..... 103



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
1	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Curb Ramp (Main Route)	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.33% (1:12).	Curb ramp running Slope is 10% Located on accessible pathway to admission from parking lot.	<a href="https://www.access-board.gov/ada/#ada-406_1">https://www.access-board.gov/ada/#ada-406_1</a>	2012 TAS Section: 406.1 2010 ADAS Section: 406.1 2015 ABAAS Section: 406.1		
2	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Entrance Ramps (Non Curb Ramp)	The landing at the bottom of the ramp has a slope greater than 2%. Bottom landings shall have a dimension in the direction of ramp run of not less than 60 inches and have a slope of 2% maximum in any direction.	Non curb ramp landing (bottom) slope is 3% Non curb ramp landing dimensions are good but because it overlaps with curb ramp this entire area is treated as landing for both curb ramp and non curb ramp, cant be over 2% in any direction.	<a href="https://www.access-board.gov/ada/#ada-405_7_1">https://www.access-board.gov/ada/#ada-405_7_1</a>	2012 TAS Section: 405.7.1, 405.7.1 Exception 2010 ADAS Section: 405.7.1, 405.7.1 Exception 2015 ABAAS Section: 405.7.1, 405.7.1 EXCEPTION		



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
3	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Entrance Ramps (Non Curb Ramp)	The ramp does not have compliant handrails. Handrails are required on both sides of all surfaces that are sloped greater than 5 percent (1:20). Handrails must be between 34 inches and 38 inches above the ramp surface, must extend 12 inches beyond the top and bottom of the ramp and be parallel to the floor or ground surface. The diameter of the handrails must be between 1 1/4 inches and 2 inches in cross-sectional nominal dimension for circular handrails. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2 1/4 inches maximum. The space between handrails and walls must be 1 1/2 inches minimum.	Handrail needs to be added to opposing side.	<a href="https://www.access-board.gov/ada/#ada-505_1">https://www.access-board.gov/ada/#ada-505_1</a>	2012 TAS Section: 505.1  2010 ADAS Section: 505.1  2015 ABAAS Section: 505.1		
4	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Entrance Ramps (Non Curb Ramp)	The ramp run has not been provided with edge protection. The floor or ground surface of the ramp run or landing shall extend 12 inches minimum beyond the inside face of a handrail or a curb or barrier shall be provided that prevents the passage of a 4 inch diameter sphere, where any portion of the sphere is within 4 inches of the finish floor or ground surface.	Edge protection looks higher than 4" Both sides of ramp would need rails with correct edge protection. 2 ways to satisfy compliance 1- install bottom bar at 4" or less 2- add ground surface to extend 12" minimum from handrails	<a href="https://www.access-board.gov/ada/#ada-405_9_1">https://www.access-board.gov/ada/#ada-405_9_1</a> <a href="https://www.access-board.gov/ada/#ada-405_9_2">https://www.access-board.gov/ada/#ada-405_9_2</a>	2012 TAS Section: 405.9.1, 405.9.2  2010 ADAS Section: 405.9.1, 405.9.2  2015 ABAAS Section: 405.9.1, 405.9.2		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
5	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Entrance Ramps (Non Curb Ramp)	The handrail extension is not a minimum 12 inches. Handrails must be between 34 inches and 38 inches above the ramp surface and must extend beyond the top and bottom of the ramp run 12 inches horizontally. The 12 inches horizontal extensions must not include the radius at the top end of round handrails. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent ramp run.	Handrail extension looks less than 12" Both sets of handrails would need handrails with extensions at 12" minimum.	<a href="https://www.access-board.gov/ada/#ada-505_10_1">https://www.access-board.gov/ada/#ada-505_10_1</a>	2012 TAS Section: 505.10.1  2010 ADAS Section: 505.10.1  2015 ABAAS Section: 505.10.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
6	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Exterior Walkway	The accessible route between the building entrance and the accessible parking has running slopes greater than 5% and has not been constructed as a ramp (i.e. handrails, edge protection, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp. Surface cross slopes must not exceed one unit vertical in 48 units horizontal (2-percent slope).	Multiple locations exceed running slope of 5% Running slope as high as 12.4%, other locations at 9% See additional photos for location of slope non compliance in accessible pathway or sidewalk.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3  2010 ADAS Section: 403.3  2015 ABAAS Section: 403.3		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
7	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Admission - Exterior Walkway	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Drain slope is 3.7% Located on accessible route to admission from parking lot.	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception  2010 ADAS Section: 303.3, 304.2, 304.2 Exception  2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
8	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Gift Shop - Curb Ramp (Main Route)	The curb ramp on the accessible route has cross slopes greater than 2 percent and running slopes greater than 8.33 percent. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). Surface running slopes shall not exceed one unit vertical in 12 units horizontal (8.33-percent slope).	Curb ramp running slope is 11.3% and Cross Slope 4.2%	<a href="https://www.access-board.gov/ada/#ada-405_2">https://www.access-board.gov/ada/#ada-405_2</a> <a href="https://www.access-board.gov/ada/#ada-405_3">https://www.access-board.gov/ada/#ada-405_3</a> <a href="https://www.access-board.gov/ada/#ada-406_1">https://www.access-board.gov/ada/#ada-406_1</a>	2012 TAS Section: 405.3, 405.2, 406.1  2010 ADAS Section: 405.3, 405.2, 406.1  2015 ABAAS Section: 405.2, 405.3, 406.1		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
9	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to Visitors Center Gift Shop - Exterior Walkway	The accessible path of travel between building entrances has cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp.	Exterior route cross slope is 3.3% and 2.5% both locations on pathway near parking lot. There is enough accessible space to use alternate routes when traveling to gift shop.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3  2010 ADAS Section: 403.3  2015 ABAAS Section: 403.3		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
10	Exterior of Property (Public) - Parking Lots/Walkways : Parking Lot Conservation Center (1 Van, 5 Car) - Accessible Stall (Unlabeled)	The required parking signage is missing. Parking space identification signs shall include the International Symbol of Accessibility (ISA). Signs identifying van parking spaces shall contain the designation "van accessible." All signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.	There are 6 accessible spaces total, 1 Labeled van with 2 labeled car. Signs for other stall are missing. The dimensions provided of unlabeled stall meet van designation requirements, additional van spot can be added. Each accessible parking spot needs its own identification sign. Sign can be off centered or placed on wall.	Designate this parking space as van accessible and provide sign. <a href="https://www.access-board.gov/ada/#ada-502_6">https://www.access-board.gov/ada/#ada-502_6</a>	2012 TAS Section: 502.6  2010 ADAS Section: 502.6  2015 ABAAS Section: 502.6		
11	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to CC Building Entrance - Path of Travel (From (R) Side of Parking Lot)	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.33% (1:12).	Curb ramp running slope is 9.6% This ramp does not connect to main entrance but does connect to side entrance.	<a href="https://www.access-board.gov/ada/#ada-406_1">https://www.access-board.gov/ada/#ada-406_1</a>	2012 TAS Section: 406.1  2010 ADAS Section: 406.1  2015 ABAAS Section: 406.1		







**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
12	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to CC Building Entrance - Path of Travel (From (L) Side of Parking lot)	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33%. Curb ramps should have the least possible slope but in no case more than 8.33% (1:12).	Curb ramp running slope is 9% This curb ramp provides access to main entrance from van spot.	<a href="https://www.access-board.gov/ada/#ada-406_1">https://www.access-board.gov/ada/#ada-406_1</a>	2012 TAS Section: 406.1  2010 ADAS Section: 406.1  2015 ABAAS Section: 406.1		
13	Exterior of Property (Public) - Parking Lots/Walkways : Path of Travel Parking Lot to CC Building Entrance - Path of Travel (Main Route)	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Gap over 1" located before door entrance.	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3  2010 ADAS Section: 302.3  2015 ABAAS Section: 302.3		







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
14	Structures on Property (Public) - Visitors Center : Entrance into Visitors Center - Entrance Doors from Overlook Area to Visitors Center	The threshold has a vertical change greater than 1/4 inch. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. The maximum vertical rise shall be 1/4 inch.	N/A		<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5	
15	Structures on Property (Public) - Visitors Center : Entrance into Visitors Center - Entrance Doors from Overlook Area to Visitors Center	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional. This applies to all doors marked with visual exit signs.		<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1	

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
16	Structures on Property (Public) - Visitors Center : Entrance into Visitors Center - Exit Doors (Visitors Center)	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		
17	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		







**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
18	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The force required to operate the element exceeds the maximum allowable force. The force required to activate operable parts is 5 pounds maximum.	6 pounds force		<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4  2010 ADAS Section: 309.4  2015 ABAAS Section: 309.4	  
19	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The light switch is positioned too high for either a side or front approach. Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	Light switch height over 48"		<a href="https://www.access-board.gov/ada/#ada-308_1">https://www.access-board.gov/ada/#ada-308_1</a>	2012 TAS Section: 308.1  2010 ADAS Section: 308.1  2015 ABAAS Section: 308.1	  
20	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The threshold has a vertical change greater than 1/4 inch. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. The maximum vertical rise shall be 1/4 inch.	N/A		<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5	  

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
21	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The door exceeds the maximum allowable opening force. Interior doors shall have a maximum opening force of 5 pounds. These forces do not apply to the force required to retract latch bolts or disengage other devices that hold the door or gate in a closed position.	Door requires 9lbs of force to operate.	<a href="https://www.access-board.gov/ada/#ada-404_2_9">https://www.access-board.gov/ada/#ada-404_2_9</a>	2012 TAS Section: 404.2.9  2010 ADAS Section: 404.2.9  2015 ABAAS Section: 404.2.9		
22	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Men's) Admission	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		
23	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**








Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
24	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The grab bar is obstructed. Adjacent elements shall be positioned to provide unobstructed use of grab bars. The space between the grab bar and projecting objects below and at the ends shall be 1-1/2 inches minimum. The space between the grab bar and projecting objects above shall be 12 inches minimum.	This only applies when lid to receptacle is open as it causes obstruction to access side grab bar, bottom portion. Consider relocating.	N/A - Refer to Finding	2012 TAS Section: 609.3 2010 ADAS Section: 609.3 2015 ABAAS Section: 609.3		
25	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The toilet paper is not installed within the compliant range in front of the toilet. Toilet paper dispensers shall be 7 inches minimum and 9 inches maximum in front of the water closet measured to the centerline of the dispenser. The outlet of the dispenser shall be 15 inches minimum and 48 inches maximum above the finish floor and shall not be located behind grab bars. Dispensers shall not be of a type that controls delivery or that does not allow continuous paper flow. There shall be a clearance of 1 1/2 inches minimum below the grab bar.	TP dispenser is less than 7" from front of toilet.	<a href="https://www.access-board.gov/ada/#ada-604_7">https://www.access-board.gov/ada/#ada-604_7</a>	2012 TAS Section: 604.7 2010 ADAS Section: 604.7 2015 ABAAS Section: 604.7		
26	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The force required to operate the element exceeds the maximum allowable force. The force required to activate operable parts is 5 pounds maximum.	6 pounds of force	<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4 2010 ADAS Section: 309.4 2015 ABAAS Section: 309.4		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure	
27	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	Coat hook height is over 57"		<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1  2010 ADAS Section: 308.2.1  2015 ABAAS Section: 308.2.1		
28	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The dispenser controls are not accessible because they require tight grasping, tight pinching or twisting of the wrist to operate. Controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 pounds of force.	There is no requirement for providing these sanitary products at this time. If provided, they need to be accessible by allowing clear floor space and compliant hardware used to operate them. TPWD personnel is aware and provides this product in Visitors Gift Shop. They are looking to remove these from restroom and exclusively provide them at Gift Shop.		<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4  2010 ADAS Section: 309.4  2015 ABAAS Section: 309.4		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
29	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Admission) - Restroom (Women's) Admission	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	N/A		<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10	  
30	Structures on Property (Public) - Visitors Center : Interior Hallways of Visitors Center - Indoor Exhibits	The element projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend into the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	There are a few exhibits in this area which create protruding object barrier. Consider alternative options regarding display cases or placing buffers in front of exhibits that can be detected by cane users. There is enough clear accessible space to maneuver around these exhibits. See additional photos for locations of obstructions, most near the entrance to visitors center from overlook area.		<a href="https://www.access-board.gov/ada/#ada-307_2">https://www.access-board.gov/ada/#ada-307_2</a>	2012 TAS Section: 307.2  2010 ADAS Section: 307.2  2015 ABAAS Section: 307.2	    

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
31	Structures on Property (Public) - Visitors Center : Interior Hallways of Visitors Center - Interior Ramps (3 Total)	The ramp does not have compliant handrails. Handrails are required on both sides of all surfaces that are sloped greater than 5 percent (1:20). Handrails must be between 34 inches and 38 inches above the ramp surface, must extend 12 inches beyond the top and bottom of the ramp and be parallel to the floor or ground surface. The diameter of the handrails must be between 1 1/4 inches and 2 inches in cross-sectional nominal dimension for circular handrails. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2 1/4 inches maximum. The space between handrails and walls must be 1 1/2 inches minimum.	There are no handrails installed on all 3 interior ramps. Ramps pictured are connected and continuous. These ramps would need continuous handrails on both sides, with accompanying handrail extensions at ends of ramp. The handrails don't have to be installed on the wall. They just have to have the minimum required clearance. Ramp extensions in alterations can be minimized if they would become a hazard. * See uploaded photo for example of compliant ramp style.	Review handrail componets to make accessible <a href="https://www.access-board.gov/aba/#aba-505_1">https://www.access-board.gov/aba/#aba-505_1</a>	2012 TAS Section: 505.1  2010 ADAS Section: 505.1  2015 ABAAS Section: 505.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
32	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Large Reservation Ramp	The handrail is not continuous the entire length of the ramp. The handrail must be continuous. Handrails shall be placed on each side of each ramp, and shall be continuous the full length of the ramp. The inside handrail on switchback or dogleg ramps shall always be continuous.	Handrail does not extend the length of the ramp. Handrails need to be installed on both sides with compliant handrail extensions for all sets.	<a href="https://www.access-board.gov/ada/#ada-505_3">https://www.access-board.gov/ada/#ada-505_3</a>	2012 TAS Section: 505.3 2010 ADAS Section: 505.3 2015 ABAAS Section: 505.3		
33	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Large Reservation Ramp	The handrail exceeds maximum height requirements. Handrails are measured to the top of the gripping surface and must be between 34 inches and 38 inches above the ramp surface. Handrails must extend horizontally 12 inches beyond the top and bottom of the ramp.	Handrail height is over 41"	<a href="https://www.access-board.gov/ada/#ada-505_4">https://www.access-board.gov/ada/#ada-505_4</a>	2012 TAS Section: 505.4 2010 ADAS Section: 505.4 2015 ABAAS Section: 505.4		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
34	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Large Reservation Ramp	The handrail is not continuous the entire length of the ramp. The handrail must be continuous. Handrails shall be placed on each side of each ramp, and shall be continuous the full length of the ramp. The inside handrail on switchback or dogleg ramps shall always be continuous.	Handrail and extension do not extend length of ramp.	<a href="https://www.access-board.gov/ada/#ada-505_3">https://www.access-board.gov/ada/#ada-505_3</a>	2012 TAS Section: 505.3  2010 ADAS Section: 505.3  2015 ABAAS Section: 505.3		
35	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Large Reservation Ramp	The handrail exceeds maximum height requirements. Handrails are measured to the top of the gripping surface and must be between 34 inches and 38 inches above the ramp surface. Handrails must extend horizontally 12 inches beyond the top and bottom of the ramp.	Handrail height is 40"	<a href="https://www.access-board.gov/ada/#ada-505_4">https://www.access-board.gov/ada/#ada-505_4</a>	2012 TAS Section: 505.4  2010 ADAS Section: 505.4  2015 ABAAS Section: 505.4		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
36	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Stream Pond Ramp	The ramp does not have compliant handrails. Handrails are required on both sides of all surfaces that are sloped greater than 5 percent (1:20). Handrails must be between 34 inches and 38 inches above the ramp surface, must extend 12 inches beyond the top and bottom of the ramp and be parallel to the floor or ground surface. The diameter of the handrails must be between 1 1/4 inches and 2 inches in cross-sectional nominal dimension for circular handrails. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum, and a cross-section dimension of 2 1/4 inches maximum. The space between handrails and walls must be 1 1/2 inches minimum.	There are no compliant handrails for this side of ramp. Handrails need to be continuous and unobstructed.	<a href="https://www.access-board.gov/ada/#ada-505_1">https://www.access-board.gov/ada/#ada-505_1</a>	2012 TAS Section: 505.1  2010 ADAS Section: 505.1  2015 ABAAS Section: 505.1		
37	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Stream Pond Ramp	The handrail exceeds maximum height requirements. Handrails are measured to the top of the gripping surface and must be between 34 inches and 38 inches above the ramp surface. Handrails must extend horizontally 12 inches beyond the top and bottom of the ramp.	Handrail height is over 41" (L) side of ramp	<a href="https://www.access-board.gov/ada/#ada-505_4">https://www.access-board.gov/ada/#ada-505_4</a>	2012 TAS Section: 505.4  2010 ADAS Section: 505.4  2015 ABAAS Section: 505.4		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
38	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Stream Pond Ramp	The handrail does not extend past the ramp. Handrails must be between 34 inches and 38 inches above the ramp surface and must extend beyond the top and bottom of the ramp run 12 inches horizontally. The 12 inches horizontal extensions must not include the radius at the top end of round handrails. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent ramp run.	There are no handrail extensions on either side of the ramp. Ensure ramp run has compliant edge protection. Bottom of ramp is no higher than 4" or ramp extends 12' beyond the rail.	<a href="https://www.access-board.gov/ada/#ada-505_10_1">https://www.access-board.gov/ada/#ada-505_10_1</a>	2012 TAS Section: 505.10.1  2010 ADAS Section: 505.10.1  2015 ABAAS Section: 505.10.1		
39	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Farm Pond Ramp	The handrail is not continuous the entire length of the ramp. The handrail must be continuous. Handrails shall be placed on each side of each ramp, and shall be continuous the full length of the ramp. The inside handrail on switchback or dogleg ramps shall always be continuous.	Handrail does not extend the length of the ramp. Handrails need to extend full length of ramp, with no obstructions and with compliant handrail extensions for all sets.	<a href="https://www.access-board.gov/ada/#ada-505_3">https://www.access-board.gov/ada/#ada-505_3</a>	2012 TAS Section: 505.3  2010 ADAS Section: 505.3  2015 ABAAS Section: 505.3		







**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
40	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Farm Pond Ramp	The handrail exceeds maximum height requirements. Handrails are measured to the top of the gripping surface and must be between 34 inches and 38 inches above the ramp surface. Handrails must extend horizontally 12 inches beyond the top and bottom of the ramp.	Guardrails height is 44"	<a href="https://www.access-board.gov/ada/#ada-505_4">https://www.access-board.gov/ada/#ada-505_4</a>	2012 TAS Section: 505.4  2010 ADAS Section: 505.4  2015 ABAAS Section: 505.4		
41	Structures on Property (Public) - Visitors Center : Outdoor Exhibits - Farm Pond Ramp	The handrail does not extend past the ramp. Handrails must be between 34 inches and 38 inches above the ramp surface and must extend beyond the top and bottom of the ramp run 12 inches horizontally. The 12 inches horizontal extensions must not include the radius at the top end of round handrails. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent ramp run.	Extensions need to be added to both sets of ramps on each end.	<a href="https://www.access-board.gov/ada/#ada-505_10_1">https://www.access-board.gov/ada/#ada-505_10_1</a>	2012 TAS Section: 505.10.1  2010 ADAS Section: 505.10.1  2015 ABAAS Section: 505.10.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
42	Structures on Property (Public) - Visitors Center : - Visitor Center - Gift Shop - - Entrance Doors - From Parking to - Gift Shop	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
43	Structures on Property (Public) - Visitors Center : Visitor Center Gift Shop - Service/Sales Counter Gift Shop	Clear floor space has not be provided. A portion of the counter surface that is 36 inches long minimum for a parallel approach or 30 inches long minimum for a forward approach and 36 inches high maximum above the finish floor shall be provided. A 30 inch by 48 inch clear floor space on an accessible route must be provided for either a forward or parallel approach. Additionally, if a forward approach is desired, knee and toe space must be provided.	Accessible portion of counter cannot be accessed via front or parallel approach. Remove barrier to create enough width under counter to meet compliance for parallel approach.	<a href="https://www.access-board.gov/ada/#ada-904_4_1">https://www.access-board.gov/ada/#ada-904_4_1</a> <a href="https://www.access-board.gov/ada/#ada-904_4_2">https://www.access-board.gov/ada/#ada-904_4_2</a>	2012 TAS Section: 904.4.1, 904.4.2  2010 ADAS Section: 904.4.2, 904.4.1  2015 ABAAS Section: 904.4.2, 904.4.1		
44	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Men's) Gift Shop	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
45	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Men's) Gift Shop	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	Coat height hook is 59"	<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1  2010 ADAS Section: 308.2.1  2015 ABAAS Section: 308.2.1		
46	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Men's) Gift Shop	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Floor drain slope is 4.8%	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception  2010 ADAS Section: 303.3, 304.2, 304.2 Exception  2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
47	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Men's) Gift Shop	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		
48	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		
49	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	Coat hook height is 59"	<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1  2010 ADAS Section: 308.2.1  2015 ABAAS Section: 308.2.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
50	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Floor drain slope is 3.9%	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception  2010 ADAS Section: 303.3, 304.2, 304.2 Exception  2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		
51	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The sanitary napkins controls are not accessible because they requires tight grasping, tight pinching or twisting of the wrist to operate. Controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 pounds of force.	There is no requirement for providing these sanitary products at this time. If provided, they need to be accessible by allowing clear floor space and compliant hardware used to operate them. TPWD personnel is aware and provides this product in Visitors Gift Shop. They are looking to remove these from restroom and exclusively provide them at Gift Shop.	<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4  2010 ADAS Section: 309.4  2015 ABAAS Section: 309.4		






Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure	
52	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The door exceeds the maximum allowable opening force. Interior doors shall have a maximum opening force of 5 pounds. These forces do not apply to the force required to retract latch bolts or disengage other devices that hold the door or gate in a closed position.	8lbs of force required		<a href="https://www.access-board.gov/ada/#ada-404_2_9">https://www.access-board.gov/ada/#ada-404_2_9</a>	2012 TAS Section: 404.2.9  2010 ADAS Section: 404.2.9  2015 ABAAS Section: 404.2.9		
53	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Restroom (Women's) Gift Shop	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop		<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
54	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Gift Shop) - Water Fountain Gift Shop	There is not enough knee clearance under the drinking fountain. The drinking fountain must have a clear knee space between the bottom of the drinking fountain and the floor not less than 27 inches in height, 30 inches in width, and 8 inches in depth.	Seated water fountain height is less than 26"	<a href="https://www.access-board.gov/ada/#ada-602_2">https://www.access-board.gov/ada/#ada-602_2</a>	2012 TAS Section: 602.2 2010 ADAS Section: 602.2 2015 ABAAS Section: 602.2		
55	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2 2015 ABAAS Section: 604.8.1.2		







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
56	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	Coat hook height is over 59"	<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1  2010 ADAS Section: 308.2.1  2015 ABAAS Section: 308.2.1		 Considered Unobstructed
57	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Floor drain slope is 3.1%	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception  2010 ADAS Section: 303.3, 304.2, 304.2 Exception  2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		




**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
58	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop		<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10	
59	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The wall sign is incorrectly located. Where permanent identification signs are provided for rooms and spaces, signs shall be installed on the wall adjacent to the latch side of the door. Where there is no wall space on the latch side, including at double leaf doors, signs shall be placed on the nearest adjacent wall, preferably on the right. Mounting location shall be located so that a person may approach within 3 inches of the sign and that a clear floor space of 18 inches minimum by 18 inches minimum, centered on the tactile characters, is provided beyond the arc of any door swing between the closed position and 45 degree open position.	There is a display preventing sign location compliance.	<a href="https://www.access-board.gov/ada/#ada-703_4">https://www.access-board.gov/ada/#ada-703_4</a> Sign Height <a href="https://www.access-board.gov/ada/#ada-703_4_1">https://www.access-board.gov/ada/#ada-703_4_1</a> Sign Location <a href="https://www.access-board.gov/ada/#ada-703_4_2">https://www.access-board.gov/ada/#ada-703_4_2</a>	2012 TAS Section: 703.4.1  2010 ADAS Section: 703.4.1  2015 ABAAS Section: 703.4.1		
60	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Men's) Overlook	The room identification sign is noncompliant. Wall signs identifying permanent rooms and spaces of a building shall be in a horizontal format and the characters raised 1/32 inch minimum and shall be sans serif uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Characters and their background shall have a non-glare finish. Characters shall contrast with their background with either light characters on a dark background or dark characters on a light background. Signs with raised characters or Braille shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	Temporary paper sign needs to be replaced with correct sign type and mounted in correct location.	Wall sign designation <a href="https://www.access-board.gov/ada/#ada-216_2">https://www.access-board.gov/ada/#ada-216_2</a> Wall signs general <a href="https://www.access-board.gov/ada/#ada-703_1">https://www.access-board.gov/ada/#ada-703_1</a>	2012 TAS Section: 216.2, 703.1  2010 ADAS Section: 216.2, 703.1  2015 ABAAS Section: F216.2, 703.1		




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
61	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Women's) Overlook	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		
62	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Women's) Overlook	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	Coat hook height is 60"	<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1  2010 ADAS Section: 308.2.1  2015 ABAAS Section: 308.2.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
63	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Women's) Overlook	The sanitary products controls are not accessible because they requires tight grasping, tight pinching or twisting of the wrist to operate. Controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 pounds of force.	There is no requirement for providing these sanitary products at this time. If provided, they need to be accessible by allowing clear floor space and compliant hardware used to operate them. TPWD personnel is aware and provides this product in Visitors Gift Shop. They are looking to remove these from restroom and exclusively provide them at Gift Shop.	<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4  2010 ADAS Section: 309.4  2015 ABAAS Section: 309.4		
64	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Restroom (Women's) Overlook	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		








**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
65	Structures on Property (Public) - Visitors Center : Restrooms/Water Fountains (Overlook) - Water Fountain Overlook	There is not enough knee clearance under the drinking fountain. The drinking fountain must have a clear knee space between the bottom of the drinking fountain and the floor not less than 27 inches in height, 30 inches in width, and 8 inches in depth.	Seated water fountain height is 25"	<a href="https://www.access-board.gov/ada/#ada-602_2">https://www.access-board.gov/ada/#ada-602_2</a>	2012 TAS Section: 602.2 2010 ADAS Section: 602.2 2015 ABAAS Section: 602.2		
66	Structures on Property (Public) - Visitors Center : Raceways (Private Tours) - Pathways Around Raceway/Production Areas	The path of contains multiple issues and is not accessible. The path of travel exceeds the maximum allowable cross and running slope requirements. It also contains changes in level and/or gaps that exceed the allowable maximum requirements. The path of travel does not meet the minimum width requirements for clearances, turning spaces, and/or passing spaces. The floor or ground surface is not firm, stable, and slip resistant.	Route has narrow areas with storage items needed for infrastructure preventing access. Majority of pathways are accessible. This area is closed to regular public and only viewed via private tours. These areas cannot be made accessible due to the equipment and purpose of their function.	Route around raceways does not need to be accessible but tour program does need to meet Title II requirements for accessible programs/services. Finding route which bypasses tight walkways is an example of program modification.	2012 TAS Section: 403.1 2010 ADAS Section: 403.1 2015 ABAAS Section: 403.1		







**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
67	Structures on Property (Public) - Conservatory Center: Entrance into Conservation Center Building - Front Entrance Doors CC Building	The threshold is greater than 1/2 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. 1/4 inch is the maximum vertical rise.	Entrance doors into main hallway of CC building		<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5	
68	Structures on Property (Public) - Conservatory Center: Entrance into Conservation Center Building - Back Doors CC Building	The door does not open at least 90 degrees. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	Both sets of rear entry doors do not open to 90 degrees.		<a href="https://www.access-board.gov/ada/#ada-404_2_3">https://www.access-board.gov/ada/#ada-404_2_3</a>	2012 TAS Section: 404.2.3  2010 ADAS Section: 404.2.3  2015 ABAAS Section: 404.2.3	
69	Structures on Property (Public) - Conservatory Center: Entrance into Conservation Center Building - Side Exit Door CC Building	The door does not open at least 90 degrees. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	Both sets of side exit doors.		<a href="https://www.access-board.gov/ada/#ada-404_2_3">https://www.access-board.gov/ada/#ada-404_2_3</a>	2012 TAS Section: 404.2.3  2010 ADAS Section: 404.2.3  2015 ABAAS Section: 404.2.3	





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
70	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Men's)	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		
71	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Men's)	The compartment door is not self closing. The water closet compartment shall be equipped with a door that has an automatic-closing device.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		
72	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Men's)	An accessible urinal is not provided. Where more than one urinal is provided, at least one shall be accessible.	If there is more than one urinal in a bathroom, at least one must follow accessibility guidelines. Pending verification	Min number required <a href="https://www.access-board.gov/ada/#ada-213_3_3">https://www.access-board.gov/ada/#ada-213_3_3</a> Review urinal elements <a href="https://www.access-board.gov/ada/#ada-605">https://www.access-board.gov/ada/#ada-605</a>	2010 ADAS Section: 213.3.3		
73	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Men's)	The threshold has a vertical change greater than 1/4 inch. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. The maximum vertical rise shall be 1/4 inch.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
74	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Women's)	The water closet compartment is missing a loop handle on both sides of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door immediately below the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		
75	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Women's)	The element is not accessible because it requires tight grasping, pinching or twisting of the wrist. Controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 pounds of force.	Paper towels are not accessible, require pinching and gripping.	<a href="https://www.access-board.gov/ada/#ada-309_4">https://www.access-board.gov/ada/#ada-309_4</a>	2012 TAS Section: 309.4  2010 ADAS Section: 309.4  2015 ABAAS Section: 309.4		
76	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Restroom (Women's)	The threshold has a vertical change greater than 1/4 inch. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. The maximum vertical rise shall be 1/4 inch.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5		







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
77	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Water Fountain Exterior	Toe clearance under the drinking fountain does not meet minimum height requirements. Space under an element between the finish floor or ground and 9 inches above the finish floor or ground shall be considered toe clearance. Space extending greater than 6 inches beyond the available knee clearance at 9 inches above the finish floor or ground shall not be considered toe clearance.	Water fountain mounted too low and does not allow toe height space. Space provided is less than 9"	<a href="https://www.access-board.gov/ada/#ada-306_2_1">https://www.access-board.gov/ada/#ada-306_2_1</a> <a href="https://www.access-board.gov/ada/#ada-602_2">https://www.access-board.gov/ada/#ada-602_2</a>	2012 TAS Section: 606.2, 306.2.1  2010 ADAS Section: 602.2, 306.2.1  2015 ABAAS Section: 602.2, 306.2.1		
78	Structures on Property (Public) - Conservatory Center: Restrooms/Water Fountains (Conservation Center) - Water Fountain Exterior	There is not enough knee clearance under the drinking fountain. The drinking fountain must have a clear knee space between the bottom of the drinking fountain and the floor not less than 27 inches in height, 30 inches in width, and 8 inches in depth.	Seated water fountain height is 22"	<a href="https://www.access-board.gov/ada/#ada-602_2">https://www.access-board.gov/ada/#ada-602_2</a>	2012 TAS Section: 602.2  2010 ADAS Section: 602.2  2015 ABAAS Section: 602.2		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
79	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room (A) CC Building	Compliant room identification signs are missing. Sign shall be located alongside the door at the latch side. Where a tactile sign is provided at double doors with one active leaf, the sign shall be located on the inactive leaf. Where a tactile sign is provided at double doors with two active leaves, the sign shall be located to the right of the right hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall. Signs containing tactile characters shall be located so that a clear floor space of 18 inches minimum by 18 inches minimum, centered on the tactile characters, is provided beyond the arc of any door swing between the closed position and 45 degree open position. Wall signs identifying permanent rooms and spaces of a building shall be in a horizontal format and the characters raised 1/32 inch minimum and shall be sans serif uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Contracted Grade 2 Braille shall be in a horizontal format and shall be placed a minimum of 3/8 inch and a maximum of 1/2 inch directly below the tactile characters; flush left or centered. Dots shall be 1/10 inch on center in each cell with 2/10-inch space between cells, measured from the second column of dots in the first cell to the first column of dots in the second cell. Dots shall be raised a minimum of 1/40 inch above the background. Braille dots shall be domed or rounded. Signs with raised characters or Braille shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	Signs that identify a room, space or area are required to have raised characters and Braille. This requirement includes both public access areas as well as all employee areas.	Wall sign designation <a href="https://www.access-board.gov/ada/#ada-216_2">https://www.access-board.gov/ada/#ada-216_2</a> Wall signs general <a href="https://www.access-board.gov/ada/#ada-703_1">https://www.access-board.gov/ada/#ada-703_1</a> Height Above Finish Floor or Ground <a href="https://www.access-board.gov/ada/#ada-703_4_1">https://www.access-board.gov/ada/#ada-703_4_1</a> Location <a href="https://www.access-board.gov/ada/#ada-703_4_2">https://www.access-board.gov/ada/#ada-703_4_2</a>	2012 TAS Section: 216.2, 703.4.2  2010 ADAS Section: 216.2, 703.4.2  2015 ABAAS Section: F216.2, 703.4.2		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
80	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room (A) CC Building	The door is equipped with a door closer and returns to a closed position too quickly. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum.	Closing speed 4 seconds.	<a href="https://www.access-board.gov/ada/#ada-404_2_8_1">https://www.access-board.gov/ada/#ada-404_2_8_1</a>	2012 TAS Section: 404.2.8.1  2010 ADAS Section: 404.2.8.1  2015 ABAAS Section: 404.2.8.1		
81	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Exit Door Conference Room (A)	The door does not open at least 90 degrees. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	None of the exit doors open 90 degrees.	<a href="https://www.access-board.gov/ada/#ada-404_2_3">https://www.access-board.gov/ada/#ada-404_2_3</a>	2012 TAS Section: 404.2.3  2010 ADAS Section: 404.2.3  2015 ABAAS Section: 404.2.3		






Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
82	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Exit Door Conference Room (A)	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional. This applies to all doors marked with visual exit signs.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
83	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room (B) CC Building	Compliant room identification signs are missing. Sign shall be located alongside the door at the latch side. Where a tactile sign is provided at double doors with one active leaf, the sign shall be located on the inactive leaf. Where a tactile sign is provided at double doors with two active leaves, the sign shall be located to the right of the right hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall. Signs containing tactile characters shall be located so that a clear floor space of 18 inches minimum by 18 inches minimum, centered on the tactile characters, is provided beyond the arc of any door swing between the closed position and 45 degree open position. Wall signs identifying permanent rooms and spaces of a building shall be in a horizontal format and the characters raised 1/32 inch minimum and shall be sans serif uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Contracted Grade 2 Braille shall be in a horizontal format and shall be placed a minimum of 3/8 inch and a maximum of 1/2 inch directly below the tactile characters; flush left or centered. Dots shall be 1/10 inch on center in each cell with 2/10-inch space between cells, measured from the second column of dots in the first cell to the first column of dots in the second cell. Dots shall be raised a minimum of 1/40 inch above the background. Braille dots shall be domed or rounded. Signs with raised characters or Braille shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	Signs that identify a room, space or area are required to have raised characters and Braille. This requirement includes both public access areas as well as all employee areas.	Wall sign designation <a href="https://www.access-board.gov/ada/#ada-216_2">https://www.access-board.gov/ada/#ada-216_2</a> Wall signs general <a href="https://www.access-board.gov/ada/#ada-703_1">https://www.access-board.gov/ada/#ada-703_1</a> Height Above Finish Floor or Ground <a href="https://www.access-board.gov/ada/#ada-703_4_1">https://www.access-board.gov/ada/#ada-703_4_1</a> Location <a href="https://www.access-board.gov/ada/#ada-703_4_2">https://www.access-board.gov/ada/#ada-703_4_2</a>	2012 TAS Section: 216.2, 703.4.2  2010 ADAS Section: 216.2, 703.4.2  2015 ABAAS Section: F216.2, 703.4.2		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure	
84	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room (B) CC Building	The door exceeds the maximum allowable opening force. Interior doors shall have a maximum opening force of 5 pounds. These forces do not apply to the force required to retract latch bolts or disengage other devices that hold the door or gate in a closed position.	B conference room (R) side door.		<a href="https://www.access-board.gov/ada/#ada-404_2_9">https://www.access-board.gov/ada/#ada-404_2_9</a>	2012 TAS Section: 404.2.9  2010 ADAS Section: 404.2.9  2015 ABAAS Section: 404.2.9		
85	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Exit Door Conference Room (B)	The door does not open at least 90 degrees. Door openings shall provide a clear width of 32 inches minimum. Clear openings of doorways with swinging doors shall be measured between the face of the door and the stop, with the door open 90 degrees. There shall be no projections into the required clear opening width lower than 34 inches above the finish floor or ground. Projections into the clear opening width between 34 inches and 80 inches above the finish floor or ground shall not exceed 4 inches.	None of the exit doors opens to 90 degrees		<a href="https://www.access-board.gov/ada/#ada-404_2_3">https://www.access-board.gov/ada/#ada-404_2_3</a>	2012 TAS Section: 404.2.3  2010 ADAS Section: 404.2.3  2015 ABAAS Section: 404.2.3		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
86	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Exit Door Conference Room (B)	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional. This applies to all doors marked with visual exit signs.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		
87	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room Kitchen Area (Rentable/Public) CC Building	Knee and toe clearance has not been provided at the sink. The knee clearance shall be 11 inches deep minimum at 9 inches above the finish floor or ground, and 8 inches deep minimum at 27 inches above the finish floor or ground. The toe clearance is the space under the sink between the finish floor or ground and 9 inches above the finish floor 30 inches wide minimum. The toe clearance shall extend a minimum of 17 inches and a maximum of 25 inches underneath the sink.	There is no forward approach. Forward approach sinks are required in kitchen spaces with stove tops.	<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a>	2012 TAS Section: 606.2  2010 ADAS Section: 606.2  2015 ABAAS Section: 606.2		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**








Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
88	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room Kitchen Area (Rentable/Public) CC Building	The required number of accessible sinks is not provided. Where sinks are provided, at least 5 percent, but no fewer than one, of each type provided in each accessible room or space shall be accessible. The toe clearance is the space under the sink between the finish floor or ground and 9 inches above the finish floor 30 inches wide minimum. The toe clearance shall extend a minimum of 17 inches and a maximum of 25 inches underneath the sink.	N/A	<a href="https://www.access-board.gov/ada/#ada-212_3">https://www.access-board.gov/ada/#ada-212_3</a>	2012 TAS Section: 212.3  2010 ADAS Section: 212.3  2015 ABAAS Section: F212.3		
89	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room Kitchen Area (Rentable/Public) CC Building	The controls are located such that operation require reaching across burners. Where knee and toe space is provided, the underside of the range or cooktop shall be insulated or otherwise configured to prevent burns, abrasions, or electrical shock. The location of controls shall not require reaching across burners	Non compliant stove type.	<a href="https://www.access-board.gov/ada/#ada-804_6_4">https://www.access-board.gov/ada/#ada-804_6_4</a>	2012 TAS Section: 804.6.4  2010 ADAS Section: 804.6.4  2015 ABAAS Section: 804.6.4		
90	Structures on Property (Public) - Conservatory Center: Interior Space of Conservation Center - Conference Room Kitchen Area (Rentable/Public) CC Building	The required storage space is not within an acceptable reach range. At least 50% of the storage space must be a minimum of 15 inches and a maximum of 48 inches off the floor with an unobstructed approach. For side approach, the maximum reach range is 46 inches high over an obstruction that is a maximum of 34 inches tall and 24 inches deep.	No accessible storage space provided.	<a href="https://www.access-board.gov/ada/#ada-804_5">https://www.access-board.gov/ada/#ada-804_5</a>	2012 TAS Section: 804.5  2010 ADAS Section: 804.5  2015 ABAAS Section: 804.5		








Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
91	Structures on Property (Pubic) - Anglers Pavilion: Entrance into Anglers Pavilion - Front Door Entrance	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
92	Structures on Property (Pubic) - Anglers Pavilion: Entrance into Anglers Pavilion - Rear Door Entrance	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		
93	Structures on Property (Pubic) - Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The side grab bar is not long enough. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar length is 36"	<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a>	2012 TAS Section: 604.5.1  2010 ADAS Section: 604.5.1  2015 ABAAS Section: 604.5.1		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
94	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The locking/latching hardware is not accessible. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2 2015 ABAAS Section: 604.8.1.2		 
95	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The water closet compartment is missing a loop handle on the one side of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door near the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2 2015 ABAAS Section: 604.8.1.2		
96	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Floor drain slope is 3.4%	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception 2010 ADAS Section: 303.3, 304.2, 304.2 Exception 2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
97	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Lavatory pipes are not insulated.	<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a>	2012 TAS Section: 606.5 2010 ADAS Section: 606.5 2015 ABAAS Section: 606.5		
98	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The urinal is located in an area that does not provide the required clear floor space for a front approach. The surrounding elements of a urinal must provide a minimum of 30 by 48 inches of clear floor space for a front approach.	If partition extends greater than 24" then 36" clear floor space must be provided. If partition extends less than 24" then 30" clear floor space is provided which would make finding compliant. Pending verification.	Measure depth of partition <a href="https://www.access-board.gov/ada/#ada-605_3">https://www.access-board.gov/ada/#ada-605_3</a>	2012 TAS Section: 605.3 2010 ADAS Section: 605.3 2015 ABAAS Section: 605.2, 605.3		
99	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	An accessible urinal is not provided. Where more than one urinal is provided, at least one shall be accessible.	If there is more than one urinal in a bathroom, at least one must follow accessibility guidelines. Pending verification	Min number required <a href="https://www.access-board.gov/ada/#ada-213_3_3">https://www.access-board.gov/ada/#ada-213_3_3</a> Review urinal elements <a href="https://www.access-board.gov/ada/#ada-605">https://www.access-board.gov/ada/#ada-605</a>	2010 ADAS Section: 213.3.3		



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
100	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Men's)	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		
101	Structures on Property (Pubic) - Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The side grab bar is not long enough. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar length is 36"	<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a>	2012 TAS Section: 604.5.1  2010 ADAS Section: 604.5.1  2015 ABAAS Section: 604.5.1		
102	Structures on Property (Pubic) - Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The locking/latching hardware is not accessible. Hand-activated door opening hardware, handles, pulls, latches, locks, and other operating devices on accessible doors shall have a shape that is easy to grasp with one hand and does not require tight grasping, tight pinching or twisting of the wrist to operate.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2  2010 ADAS Section: 604.8.1.2  2015 ABAAS Section: 604.8.1.2		



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
103	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The water closet compartment is missing a loop handle on the one side of the door. Water closet compartments must be equipped with a door that has a loop or U-shaped handle on both sides of the door near the latch. The latch must be flip-over style, sliding or other hardware not requiring the user to grasp or twist.	N/A	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: 604.8.1.2 2010 ADAS Section: 604.8.1.2 2015 ABAAS Section: 604.8.1.2		
104	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The coat hook is installed greater than 48 inches above the finished floor. Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum above the finished floor.	The coat hook height is 67"	<a href="https://www.access-board.gov/ada/#ada-308_2_1">https://www.access-board.gov/ada/#ada-308_2_1</a>	2012 TAS Section: 308.2.1 2010 ADAS Section: 308.2.1 2015 ABAAS Section: 308.2.1		
105	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The floor drain is set too low in the floor which causes a slope over 2 percent. Changes in level are not permitted in clear floor or ground spaces or surfaces of a turning spaces and shall not slope greater than 1:48.	Floor drain slope is 4.7%	<a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a> <a href="https://www.access-board.gov/ada/#ada-304_2">https://www.access-board.gov/ada/#ada-304_2</a>	2012 TAS Section: 303.3, 304.2, 304.2 Exception 2010 ADAS Section: 303.3, 304.2, 304.2 Exception 2015 ABAAS Section: 303.3, 304.2, 304.2 EXCEPTION, 305.2 EXCEPTION		


Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
106	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Lavatory pipes are not insulated.	<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a>	2012 TAS Section: 606.5 2010 ADAS Section: 606.5 2015 ABAAS Section: 606.5		
107	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Restroom (Women's)	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10 2010 ADAS Section: 404.2.10 2015 ABAAS Section: 404.2.10		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
108	Structures on Property (Pubic) - Anglers Pavilion: Restrooms/Water Fountains (Angler Pavilion) - Water Fountain	There is no drinking fountain for standing persons. No fewer than two drinking fountains shall be provided. One drinking fountain shall meet requirements for wheelchair accessibility and one drinking fountain shall meet requirements for standing persons. Where a single drinking fountain complies with both wheelchair accessibility and requirements for standing persons, it shall be permitted to be substituted for two separate drinking fountains. Spout outlets of drinking fountains for standing persons shall be 38 inches minimum and 43 inches maximum above the finish floor or ground.	The Building Code may only require one drinking fountain be provided, but the Accessibility Standards require at least two. One at a lower height and the other at standing height. Standing water fountain is not provided. Its required that if one is provided then the other option is as well. Water refill station cannot take the place of either water fountain unless only water refill station is provided and no water fountains. This version of water fountain does not comply with scoping requirements	Review drinking fountain requirements Clear floor space <a href="https://www.access-board.gov/ada/#ada-403_5_1">https://www.access-board.gov/ada/#ada-403_5_1</a> Drinking fountain requirements, general <a href="https://www.access-board.gov/ada/#ada-602_1">https://www.access-board.gov/ada/#ada-602_1</a> Minimum number <a href="https://www.access-board.gov/ada/#ada-211_2">https://www.access-board.gov/ada/#ada-211_2</a> Standing person requirements <a href="https://www.access-board.gov/ada/#ada-602_7">https://www.access-board.gov/ada/#ada-602_7</a>	2012 TAS Section: 602.7, 211.2  2010 ADAS Section: 602.7, 211.2  2015 ABAAS Section: 602.7, F211.2		






Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
109	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Mr. Bill's Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Transition from sidewalk to fishing pier has large gaps, preventing access.	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		
110	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Mr. Bill's Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Exterior pathway leading to Mr. Bills pier has gap greater than 1/2"	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
111	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Mr. Bill's Fishing Pier & Walkways	The required edge protection is not provided. Where compliant railings, guards, or handrails are provided, edge protection shall also be provided. Curbs or barriers shall extend 2 inches minimum above the surface of the fishing pier or platform or The ground or deck surface shall extend 12 inches minimum beyond the inside face of the railing. Toe clearance shall be provided and shall be 30 inches wide minimum and 9 inches minimum above the ground or deck surface beyond the railing.	There is no edge protection or extended deck surface provided. Where railings, guards, or handrails are provided, edge protection must be provided and extend a minimum of 2 inches above the ground or deck surface. Edge protection is not required where a railing, guardrail, or handrail is provided, if the deck surface extends a minimum of 12 inches beyond the inside face of the railing. Fishing pier edge compliance can be satisfied 1 of 2 ways. 1- install curb barrier at 2" minimum vertical to end of deck surface. 2- extend deck surface 12" minimum beyond inside facing guard rail.	Fishing pier edge protection <a href="https://www.access-board.gov/ada/#ada-1005_3">https://www.access-board.gov/ada/#ada-1005_3</a> Curb or barrier <a href="https://www.access-board.gov/ada/#ada-1005_3_1">https://www.access-board.gov/ada/#ada-1005_3_1</a> Extended ground or floor surface <a href="https://www.access-board.gov/ada/#ada-1005_3_2">https://www.access-board.gov/ada/#ada-1005_3_2</a>	2010 ADAS Section: 1005.3.1, 1005.3.2  2015 ABAAS Section: 1005.3.1, 1005.3.2		
112	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Mr. Bill's Fishing Pier & Walkways	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	Transition from fishing pier to pathway has vertical change over 1/4"	<a href="https://www.access-board.gov/ada/#ada-303_2">https://www.access-board.gov/ada/#ada-303_2</a> <a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a>	2012 TAS Section: 303.3, 303.2  2010 ADAS Section: 303.3, 303.2  2015 ABAAS Section: 303.2, 303.3		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
113	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The required edge protection is not provided. Where compliant railings, guards, or handrails are provided, edge protection shall also be provided. Curbs or barriers shall extend 2 inches minimum above the surface of the fishing pier or platform or The ground or deck surface shall extend 12 inches minimum beyond the inside face of the railing. Toe clearance shall be provided and shall be 30 inches wide minimum and 9 inches minimum above the ground or deck surface beyond the railing.	There is no edge protection or extended deck surface provided. Where railings, guards, or handrails are provided, edge protection must be provided and extend a minimum of 2 inches above the ground or deck surface. Edge protection is not required where a railing, guardrail, or handrail is provided, if the deck surface extends a minimum of 12 inches beyond the inside face of the railing. Fishing pier edge compliance can be satisfied 1 of 2 ways. 1- install curb barrier at 2" minimum vertical to end of deck surface. 2- extend deck surface 12" minimum beyond inside facing guard rail.	Fishing pier edge protection <a href="https://www.access-board.gov/ada/#ada-1005_3">https://www.access-board.gov/ada/#ada-1005_3</a> Curb or barrier <a href="https://www.access-board.gov/ada/#ada-1005_3_1">https://www.access-board.gov/ada/#ada-1005_3_1</a> Extended ground or floor surface <a href="https://www.access-board.gov/ada/#ada-1005_3_2">https://www.access-board.gov/ada/#ada-1005_3_2</a>	2010 ADAS Section: 1005.3.1, 1005.3.2  2015 ABAAS Section: 1005.3.1, 1005.3.2		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
114	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	Exterior pathway used to gain access to CC fishing pier has transition over 1/4" in 2 locations. Same locations also have gap greater than 1/2" See additional photos for locations.	<a href="https://www.access-board.gov/ada/#ada-303_2">https://www.access-board.gov/ada/#ada-303_2</a> <a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a>	2012 TAS Section: 303.3, 303.2  2010 ADAS Section: 303.3, 303.2  2015 ABAAS Section: 303.2, 303.3		


**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
115	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	See previous finding for details on location.	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		
116	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Exterior pathway used to gain access from (L) side of CC pier has gap greater than 1/2" This gap also creates change in elevation over 1/4"	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		
117	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	See previous finding for location details.	<a href="https://www.access-board.gov/ada/#ada-303_2">https://www.access-board.gov/ada/#ada-303_2</a> <a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a>	2012 TAS Section: 303.3, 303.2 2010 ADAS Section: 303.3, 303.2 2015 ABAAS Section: 303.2, 303.3		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
118	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Exterior pathway to (L) side of CC fishing pier has gap greater than 1/2" and vertical change greater than 1/4"	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		
119	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Conservation Center Fishing Pier & Walkways	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	See previous finding for location details.	<a href="https://www.access-board.gov/ada/#ada-303_2">https://www.access-board.gov/ada/#ada-303_2</a> <a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a>	2012 TAS Section: 303.3, 303.2 2010 ADAS Section: 303.3, 303.2 2015 ABAAS Section: 303.2, 303.3		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
120	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Anglers Pavilion Fishing Pier & Walkways	There is no accessible route to the accessible element. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	This fishing pier is not accessible via (R) or (L) side approach. Both pathways are non compliant in running slopes and gaps in side walk. See additional photos for location details.	https://www.access-board.gov/ada/#ada-206_2_2 Review accessible pathway componets to make accessible https://www.access-board.gov/ada/#ada-402 https://www.access-board.gov/ada/#ada-403_1	2012 TAS Section: 206.2.2  2010 ADAS Section: 206.2.2  2015 ABAAS Section: F206.2.2		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
121	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Anglers Pavilion Fishing Pier & Walkways	The required edge protection is not provided. Where compliant railings, guards, or handrails are provided, edge protection shall also be provided. Curbs or barriers shall extend 2 inches minimum above the surface of the fishing pier or platform or The ground or deck surface shall extend 12 inches minimum beyond the inside face of the railing. Toe clearance shall be provided and shall be 30 inches wide minimum and 9 inches minimum above the ground or deck surface beyond the railing.	There is no edge protection or extended deck surface provided. Where railings, guards, or handrails are provided, edge protection must be provided and extend a minimum of 2 inches above the ground or deck surface. Edge protection is not required where a railing, guardrail, or handrail is provided, if the deck surface extends a minimum of 12 inches beyond the inside face of the railing. Fishing pier edge compliance can be satisfied 1 Of 2 ways. 1- install curb barrier at 2" minimum vertical to end of deck surface. 2- extend deck surface 12" minimum beyond inside facing guard rail.	Fishing pier edge protection <a href="https://www.access-board.gov/ada/#ada-1005_3">https://www.access-board.gov/ada/#ada-1005_3</a> Curb or barrier <a href="https://www.access-board.gov/ada/#ada-1005_3_1">https://www.access-board.gov/ada/#ada-1005_3_1</a> Extended ground or floor surface <a href="https://www.access-board.gov/ada/#ada-1005_3_2">https://www.access-board.gov/ada/#ada-1005_3_2</a>	2010 ADAS Section: 1005.3.1, 1005.3.2  2015 ABAAS Section: 1005.3.1, 1005.3.2		






**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
122	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Anglers Pavilion Fishing Pier & Walkways	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails, edge protection, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp. Surface cross slopes must not exceed one unit vertical in 48 units horizontal (2-percent slope).	Running slope, (R) side of fishing pier is over 5% See additional photos for location of slope non compliance in accessible pathway or sidewalk.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3 2010 ADAS Section: 403.3 2015 ABAAS Section: 403.3		
123	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Anglers Pavilion Fishing Pier & Walkways	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Exterior pathways leading to Angler Pavilion fishing pier have multiple locations where gap exceed 1/2"	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
124	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails, edge protection, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp. Surface cross slopes must not exceed one unit vertical in 48 units horizontal (2-percent slope).	There are several locations where exterior pathway exceeds running slope of 5%. This section of pathway accesses Mr. Bills fishing pier, maneuvers around pier heading towards outdoor picnic area. See additional photos for location of running slope non compliance on accessible pathway to feature.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3 2010 ADAS Section: 403.3 2015 ABAAS Section: 403.3		


Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
125	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The accessible path of travel has cross slopes greater than 2%. Surface cross slopes shall not exceed one unit vertical in 48 units horizontal (2-percent slope). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp.	There are several locations where exterior pathway cross slope exceeds 2%. This section of pathway leads from Mr. Bills fishing pier around (R) side pathway towards Anglers Pavilion fishing pier. See additional photos for location of cross slope non compliance on accessible pathway to feature.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3 2010 ADAS Section: 403.3 2015 ABAAS Section: 403.3		



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
126	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The accessible route contains loose gravel and/or surface materials that do not provide for a stable, firm slip resistant surface. Floor and ground surfaces shall be stable, firm, and slip resistant.	Exterior route in various stages of deterioration and would need repair in order to gain compliance. This location is closest to Angler Pavilion. Exterior route should be free from debris or anything else which could compromise secure footing.	<a href="https://www.access-board.gov/ada/#ada-302_1">https://www.access-board.gov/ada/#ada-302_1</a>	2012 TAS Section: 302.1  2010 ADAS Section: 302.1  2015 ABAAS Section: 302.1		
127	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The path of contains multiple issues and is not accessible. The path of travel exceeds the maximum allowable cross and running slope requirements. It also contains changes in level and/or gaps that exceed the allowable maximum requirements. The path of travel does not meet the minimum width requirements for clearances, turning spaces, and/or passing spaces. The floor or ground surface is not firm, stable, and slip resistant.	The exterior pathway is not accessible due to running and cross slope compliance, loose debris on path, and large gaps in pathway. This section of pathway leads from Anglers Pavilion to Anglers fishing pier.	Review accessible pathway components to make accessible <a href="https://www.access-board.gov/ada/#ada-402">https://www.access-board.gov/ada/#ada-402</a> <a href="https://www.access-board.gov/ada/#ada-403_1">https://www.access-board.gov/ada/#ada-403_1</a>	2010 ADAS Section: 403.1  2015 ABAAS Section: 403.1		




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
128	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The walking surface is obstructed. A 36 inch wide minimum walking surface is required.	Exterior pathway deterioration limits accessible space to less than 36" This section of pathway, (L) side approach, leads from Anglers Pavilion to CC fishing pier.	<a href="https://www.access-board.gov/ada/#ada-403_5_1">https://www.access-board.gov/ada/#ada-403_5_1</a>	2012 TAS Section: 403.5.1 2010 ADAS Section: 403.5.1 2015 ABAAS Section: 403.5.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
129	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 1/4 inch is the maximum vertical rise. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. Changes in level greater than 1/2 inch must be by way of a ramp.	There are several locations where change in elevation exceed 1/4" allowance. Locations are dispersed along pathways that serve both ponds and each fishing pier. Mainly located along pathways that lead to wetland trails, angler pavilion, visitors center to piers, and picnic areas to (R) of angler pavilion. See additional photos for location of vertical rise non compliance on accessible pathway to feature.	<a href="https://www.access-board.gov/ada/#ada-303_2">https://www.access-board.gov/ada/#ada-303_2</a> <a href="https://www.access-board.gov/ada/#ada-303_3">https://www.access-board.gov/ada/#ada-303_3</a>	2012 TAS Section: 303.3, 303.2  2010 ADAS Section: 303.3, 303.2  2015 ABAAS Section: 303.2, 303.3		




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
130	Outdoor Features (Public) : Fishing Piers Near Visitors Center (3 total) - Path Of Travel Around Piers	The route contains openings greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	There are many locations where large gaps in pathway exceed 1/2" allowance. Locations are dispersed along pathways that serve both ponds and each fishing pier. Mainly located along pathways that lead to wetland trails, angler pavilion, visitors center to piers, and picnic areas to (R) of angler pavilion. See additional photos for location of gap non compliance on accessible pathway to feature.	<a href="https://www.access-board.gov/ada/#ada-302_3">https://www.access-board.gov/ada/#ada-302_3</a>	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		






Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
131	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (Beginning)	An accessible access route is not provided between elements, spaces and the facilities provided within the accessible camping unit. At least one outdoor recreation access route shall connect accessible elements, spaces and facilities provided within camping units with mobility features.	There is no access routes to benches along path. Accessible bench placement should be equally dispersed in given area with accessible route. Not ever bench needs to be made accessible but scoping requires even dispersion and equal access to same feature or element. Each feature or element seating should be treated separately from other features or elements.	N/A - Refer to Finding	2015 ABAAS Section: F244.5.1		
132	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (Beginning)	There are not enough outdoor constructed features with mobility features located in the common uses and public use areas. Where provided in common use and public use areas that serve picnic units with mobility features, at least 20 percent, but not less than one, of each type of outdoor constructed feature must be provided at each location.	Benches are not best practice for accessible option. See guidelines for outdoor spaces regarding bench accessibility.	N/A - Refer to Finding	2015 ABAAS Section: F245.3		









Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
133	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (Beginning)	The element is not accessible because there is not adequate clear floor space for an approach. The clear floor or ground space shall be 30 inches minimum by 48 inches minimum.	There is no clear floor space provided around benches to be designated as accessible. Trail bench requirements- A minimum of 36 by 48 inches of clear ground space must be provided near a bench, with one side of the clear space adjoining an ORAR or trail as applicable. This clear ground space must not overlap the ORAR, trail tread, or another clear ground space. Although there are no technical requirements for the bench itself, providing a bench with at least one armrest and back support that runs the full length of the bench is helpful.	<a href="https://www.access-board.gov/ada/#ada-305_3">https://www.access-board.gov/ada/#ada-305_3</a>	2012 TAS Section: 305.3 2010 ADAS Section: 305.3 2015 ABAAS Section: 305.3		
134	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (Middle)	Detailed evaluation of Wetland trail is needed. Trail is mostly accessible and made of concrete material with accessible width for length of trail. Trail does not have passing spaces, access to bench seating is fair but could be improved, needs improved access to kiosk or trail view features, trail maintenance or repair is needed for sloping, cracks, and deterioration.	N/A	N/A - Refer to Finding	2012 TAS Section: Recommended 2010 ADAS Section: Recommended 2015 ABAAS Section: Recommended		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
135	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (End)	The running slope of the surface of the trail is too steep. Not more than 30 percent of the total length of a trail shall have a running slope steeper than 1:12 (8.33%).	Exterior route running slope is 8.8% This section of pathway is located near of Wetland trail and next to tram pick up/drop off	N/A - Refer to Finding	2015 ABAAS Section: 1017.7.1		
136	Outdoor Features (Public) : Wetlands Trail - Wetlands Trail (End)	There are openings in the surface of the trails, passing spaces, and resting intervals that allow the passage of a sphere more than 1/2 inch in diameter. Openings in the surface of trails, passing spaces, and resting intervals shall not allow the passage of a sphere more than 1/2 inch (13 mm) in diameter.	There is a large gap near end of Wetland trail, same area as previous finding.	N/A - Refer to Finding	2015 ABAAS Section: 1017.6		
137	Outdoor Features (Public) : Fly Fishing Area - Picnic Pavilion	There are not enough picnic units with mobility features. Where picnic facilities contain more than two picnic units, at least 20 percent, but not less than two, of the picnic units shall provide mobility features.	There are no accessible picnic tables provided	Provide complaint picnic table Knee space for wheelchair seating must be at least 30 inches (760 millimeters) wide, 19 inches (485 millimeters) deep, and 27 inches (685 millimeters) high, as measured from the ground or floor to the bottom of the tabletop. Toe clearance of at least 9 inches (230 millimeters) above the ground or floor must extend at least an additional 5 inches (25 millimeters) beyond the knee clearance	2015 ABAAS Section: F245.2.2		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
138	Outdoor Features (Public) : Fly Fishing Area - Fly Fish Pier (4 Total)	There is no accessible route to the accessible element. At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements, and accessible spaces that are on the same site.	There is no accessible route to any of the 4 floating platforms which serve this pond. Would need at least 1 to meet compliance.	https://www.access-board.gov/ada/#ada-206_2_2 Review accessible pathway components to make accessible https://www.access-board.gov/ada/#ada-402 https://www.access-board.gov/ada/#ada-403_1	2012 TAS Section: 206.2.2 2010 ADAS Section: 206.2.2 2015 ABAAS Section: F206.2.2		
139	Outdoor Features (Public) : Fly Fishing Area - Fly Fish Pier (4 Total)	The curb or barrier does not extend 2 inches minimum above the surface. Where compliant railings, guards, or handrails are provided, edge protection shall also be provided. Curbs or barriers shall extend 2 inches minimum above the surface of the fishing pier or platform or The ground or deck surface shall extend 12 inches minimum beyond the inside face of the railing. Toe clearance shall be provided and shall be 30 inches wide minimum and 9 inches minimum above the ground or deck surface beyond the railing.	This is not required since there is no guardrail but if edge protection is provided, it needs to extend 2" min above platform surface. Needs photo verification	https://www.access-board.gov/ada/#ada-1005_3_1	2010 ADAS Section: 1005.3.1 2015 ABAAS Section: 1005.3.1		
140	Outdoor Features (Public) : Fly Fishing Area - Access Route To Fly Fishing Area Restrooms	The grate openings are greater than 1/2 inch and are parallel to the direction of travel. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	Exterior route leading to restrooms, grate preventing access	https://www.access-board.gov/ada/#ada-302_3	2012 TAS Section: 302.3 2010 ADAS Section: 302.3 2015 ABAAS Section: 302.3		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
141	Outdoor Features (Public) : Fly Fishing Area - Access Route To Fly Fishing Area Restrooms	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails, edge protection, etc.). When the slope in the direction of travel of any walk exceeds 1 unit vertical in 20 units horizontal (5-percent slope), it must be constructed as a ramp. Surface cross slopes must not exceed one unit vertical in 48 units horizontal (2-percent slope).	Check exterior pathway leading to restrooms for running and cross slope compliance. This needs to be verified.	<a href="https://www.access-board.gov/ada/#ada-403_3">https://www.access-board.gov/ada/#ada-403_3</a>	2012 TAS Section: 403.3  2010 ADAS Section: 403.3  2015 ABAAS Section: 403.3		
142	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The restroom is not nearly compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lavatory. The entry door does not contain the required minimum maneuvering spaces on the pull/push sides. The entry door encroaches into the required clear floor space for fixtures. Grab bars are missing and/or incorrectly installed. Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both. The restroom contains floor level changes greater than a 1/2 inch of the floor drains and is slope (XX) - (XX), the shower is too small and missing numerous accessible elements.	This restroom requires a number of components to gain compliance.	<a href="https://www.access-board.gov/ada/#ada-213_2">https://www.access-board.gov/ada/#ada-213_2</a> Review restrooms components to make accessible. <a href="https://www.access-board.gov/ada/#ada-603">https://www.access-board.gov/ada/#ada-603</a>	2012 TAS Section: 213.2  2010 ADAS Section: 213.2  2015 ABAAS Section: F213.2	  	

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
143	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The side grab bar is not long enough. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar is 36" long		<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a> 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1 2015 ABAAS Section: 604.5.1		
144	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The side grab bar does not extend far enough from the rear wall. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar extends 46" from rear wall		<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a> 2012 TAS Section: 604.5.1 2010 ADAS Section: 604.5.1 2015 ABAAS Section: 604.5.1		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
145	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The rear grab bar is not a minimum 36 inches in length. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank (any obstruction) shall be 1-1/2 inches minimum.	Rear grab bar less than 25" long		<a href="https://www.access-board.gov/ada/#ada-604_5_2">https://www.access-board.gov/ada/#ada-604_5_2</a>	2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2 2015 ABAAS Section: 604.5.2	
146	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side. The rear grab bar must be a minimum of 36 inches long and extend from the centerline of the toilet 12 inches minimum on one side and 24 inches minimum on the other side. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	Rear grab bar not long enough and mounted in wrong location. Rear grab bar does not extend 12" to wall side from midline or 24" to open side from midline.		<a href="https://www.access-board.gov/ada/#ada-604_5_2">https://www.access-board.gov/ada/#ada-604_5_2</a>	2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2 2015 ABAAS Section: 604.5.2	

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
147	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The grab bar is obstructed. Adjacent elements shall be positioned to provide unobstructed use of grab bars. The space between the grab bar and projecting objects below and at the ends shall be 1-1/2 inches minimum. The space between the grab bar and projecting objects above shall be 12 inches minimum.	Soap dispenser location would impede rear grab bar access. Once correct rear grab bar installed then soap dispenser placement would not be compliant, it preventing access above rear grab bar.	<a href="https://www.access-board.gov/ada/#ada-609_3">https://www.access-board.gov/ada/#ada-609_3</a>	2012 TAS Section: 609.3 2010 ADAS Section: 609.3 2015 ABAAS Section: 609.3		
148	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The lavatory's clear floor space is obstructed by the paper towel dispenser and trashcan placement. The wall mounted soap dispenser projects (XX) from the wall and encroaches into the required 30 inches by 48 inches clear floor space. The maximum projection that a dispenser may project at this location is (XX) inches.	Paper towel dispenser location and trash can prevent access to lavatory.	<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a>	2012 TAS Section: 606.2 2010 ADAS Section: 606.2 2015 ABAAS Section: 606.2		
149	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The lavatory is too close to the side wall. There must be a minimum of 15 inches from the centerline of the lavatory to the nearest side wall or side partition to allow for an unobstructed 30 inches by 48 inches clear floor space.	Looks less than 15" Needs verification	<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a>	2012 TAS Section: 606.2 2010 ADAS Section: 606.2 2015 ABAAS Section: 606.2		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
150	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The clearance for the lavatory encroaches into the clearance required for the toilet. No fixtures are allowed in the clear floor space required for the toilet. Where a wall mounted water closet is installed within an accessible water closet compartment, clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall closest to the water closet and 56 inches minimum measured perpendicular from the rear wall. Where a floor mounted water closet is installed within an accessible water closet compartment, clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 59 inches minimum measured perpendicular from the rear wall.	N/A		<a href="https://www.access-board.gov/ada/#ada-604_3_2">https://www.access-board.gov/ada/#ada-604_3_2</a> 2012 TAS Section: 604.3.2 2010 ADAS Section: 604.3.2 2015 ABAAS Section: 604.3.2		
151	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Lavatory pipes not sufficiently covered.		<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a> 2012 TAS Section: 606.5 2010 ADAS Section: 606.5 2015 ABAAS Section: 606.5		










Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
152	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	There is not enough clear floor space at the water closet. Clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall. No other fixture is allowed in this space.	Compartment is not correct dimensions. Accessible length space impeded by door encroachment and width of compartment is 57" There is also an obstruction at bottom of floor which limits in usable space. See additional photos for details.	<a href="https://www.access-board.gov/ada/#ada-604_3">https://www.access-board.gov/ada/#ada-604_3</a>	2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1 2015 ABAAS Section: 604.3.		







**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
153	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The door swing encroaches more than 12 inches into the restroom turning space. Doors shall not swing into the clear floor space or clearance required for any fixture. Doors to accessible water closet compartments shall be permitted to encroach into the turning space without limitation. Other than doors to accessible water closet compartments, a door, in any position, shall be permitted to encroach into the turning space by 12 inches maximum. A clear space measured from the floor to a height of 27 inches above the floor, within the restroom, of sufficient size to inscribe a circle with a diameter not less than 60 inches in size or a "T" turning space must be provided. Changes of level are not permitted.	N/A		<a href="https://www.access-board.gov/ada/#ada-603_2_3">https://www.access-board.gov/ada/#ada-603_2_3</a>  2012 TAS Section: 603.2.3  2010 ADAS Section: 603.2.3  2015 ABAAS Section: 603.2.3		
154	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The threshold is greater than 1/2 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. 1/4 inch is the maximum vertical rise.	Entry into restroom may comply with beveled requirements, verify. Exiting restroom is not compliant, threshold exceeds 1/2"		<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>  2012 TAS Section: 404.2.5  2010 ADAS Section: 404.2.5  2015 ABAAS Section: 404.2.5		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
155	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The door is equipped with a door closer and returns to a closed position too quickly. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_8_1">https://www.access-board.gov/ada/#ada-404_2_8_1</a>	2012 TAS Section: 404.2.8.1 2010 ADAS Section: 404.2.8.1 2015 ABAAS Section: 404.2.8.1		
156	Outdoor Features (Public) : Fly Fishing Area - Restroom (Men's)	The wall sign is incorrectly located. Where permanent identification signs are provided for rooms and spaces, signs shall be installed on the wall adjacent to the latch side of the door. Where there is no wall space on the latch side, including at double leaf doors, signs shall be placed on the nearest adjacent wall, preferably on the right. Mounting location shall be located so that a person may approach within 3 inches of the sign and that a clear floor space of 18 inches minimum by 18 inches minimum, centered on the tactile Characters, is provided beyond the arc of any door swing between the closed position and 45 degree open position.	Sign placement incorrect.	Height Above Finish Floor or Ground <a href="https://www.access-board.gov/ada/#ada-703_4_1">https://www.access-board.gov/ada/#ada-703_4_1</a> Location <a href="https://www.access-board.gov/ada/#ada-703_4_2">https://www.access-board.gov/ada/#ada-703_4_2</a>	2012 TAS Section: 703.4.1 2010 ADAS Section: 703.4.1 2015 ABAAS Section: 703.4.1		
157	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The restroom is not nearly compliant. The restroom does not have the required minimum clear floor space or maneuvering clearances for the toilet. The restroom does not have the required minimum clear floor space or maneuvering clearances for the lavatory. The entry door does not contain the required minimum maneuvering spaces on the pull/push sides. The entry door encroach into the required clear floor space for fixtures. Grab bars are missing and/or incorrectly installed. Accessories, such as toilet seat covers, paper towel holders, garbage cans, hand dryers, and mirrors are either too high or without clear floor space or both. The restroom contain floor level changes greater than a 1/2 inch of the floor drains and is slope (XX) - (XX), the shower is too small and missing numerous accessible elements.	This restroom requires a number of componets to gain compliance.	<a href="https://www.access-board.gov/ada/#ada-213_2">https://www.access-board.gov/ada/#ada-213_2</a> Review restrooms componets to make accessible. <a href="https://www.access-board.gov/ada/#ada-603">https://www.access-board.gov/ada/#ada-603</a>	2012 TAS Section: 213.2 2010 ADAS Section: 213.2 2015 ABAAS Section: F213.2	 	

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
158	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The side grab bar is not long enough. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar is 36" long		<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a> 2012 TAS Section: 604.5.1  2010 ADAS Section: 604.5.1  2015 ABAAS Section: 604.5.1		
159	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The side grab bar does not extend far enough from the rear wall. The side grab bar must extend at least 54 inches minimum beyond the rear wall and start a maximum of 12 inches from the rear wall. A 42 inch grab bar installed the maximum distance from the rear wall (12 inches) will leave the leading end 54 inches from the rear wall. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface.	Side grab bar extends 46" from rear wall		<a href="https://www.access-board.gov/ada/#ada-604_5_1">https://www.access-board.gov/ada/#ada-604_5_1</a> 2012 TAS Section: 604.5.1  2010 ADAS Section: 604.5.1  2015 ABAAS Section: 604.5.1		
160	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The rear grab bar is not a minimum 36 inches in length. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank (any obstruction) shall be 1-1/2 inches minimum.	Rear grab bar less than 25" long		<a href="https://www.access-board.gov/ada/#ada-604_5_2">https://www.access-board.gov/ada/#ada-604_5_2</a> 2012 TAS Section: 604.5.2  2010 ADAS Section: 604.5.2  2015 ABAAS Section: 604.5.2		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
161	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The rear grab bar does not extend adequately past the centerline of the toilet on the wall side. The rear grab bar must be a minimum of 36 inches long and extend from the centerline of the toilet 12 inches minimum on one side and 24 inches minimum on the other side. Grab bars shall be installed in a horizontal position, 33 inches minimum and 36 inches maximum above the finish floor measured to the top of the gripping surface and the space between the grab bar and the top of the tank shall be 1-1/2 inches minimum.	Rear grab bar not long enough and mounted in wrong location. Rear grab bar does not extend 12" to wall side from midline or 24" to open side from midline.		<a href="https://www.access-board.gov/ada/#ada-604_5_2">https://www.access-board.gov/ada/#ada-604_5_2</a> 2012 TAS Section: 604.5.2 2010 ADAS Section: 604.5.2 2015 ABAAS Section: 604.5.2		
162	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The lavatory's clear floor space is obstructed by the paper towel dispenser. The wall mounted soap dispenser projects (XX) from the wall and encroaches into the required 30 inches by 48 inches clear floor space. The maximum projection that a dispenser may project at this location is (XX) inches.	Paper towel dispenser location, soap dispenser, and trash can prevent access to lavatory.		<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a> 2012 TAS Section: 606.2 2010 ADAS Section: 606.2 2015 ABAAS Section: 606.2		
163	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The lavatory is too close to the side wall. There must be a minimum of 15 inches from the centerline of the lavatory to the nearest side wall or side partition to allow for an unobstructed 30 inches by 48 inches clear floor space.	Midline of lavatory is 12" from side wall.		<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a> 2012 TAS Section: 606.2 2010 ADAS Section: 606.2 2015 ABAAS Section: 606.2		




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
164	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The clearance for the lavatory encroaches into the clearance required for the toilet. No fixtures are allowed in the clear floor space required for the toilet. Where a wall mounted water closet is installed within an accessible water closet compartment, clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall closest to the water closet and 56 inches minimum measured perpendicular from the rear wall. Where a floor mounted water closet is installed within an accessible water closet compartment, clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 59 inches minimum measured perpendicular from the rear wall.	N/A		<a href="https://www.access-board.gov/ada/#ada-604_3_2">https://www.access-board.gov/ada/#ada-604_3_2</a>  2012 TAS Section: 604.3.2  2010 ADAS Section: 604.3.2  2015 ABAAS Section: 604.3.2		
165	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	Lavatory pipes not sufficiently covered.		<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a>  2012 TAS Section: 606.5  2010 ADAS Section: 606.5  2015 ABAAS Section: 606.5		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
166	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	There is not enough clear floor space at the water closet. Clear floor space around the water closet shall be 60 inches minimum measured perpendicular from the side wall and 56 inches minimum measured perpendicular from the rear wall. No other fixture is allowed in this space.	Compartment is not correct dimensions. Accessible length space impeded by door encroachment and width of compartment is 58"	<a href="https://www.access-board.gov/ada/#ada-604_3_1">https://www.access-board.gov/ada/#ada-604_3_1</a>	2012 TAS Section: 604.3.1 2010 ADAS Section: 604.3.1 2015 ABAAS Section: 604.3.		
167	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The door swing encroaches more than 12 inches into the restroom turning space. Doors shall not swing into the clear floor space or clearance required for any fixture. Doors to accessible water closet compartments shall be permitted to encroach into the turning space without limitation. Other than doors to accessible water closet compartments, a door, in any position, shall be permitted to encroach into the turning space by 12 inches maximum. A clear space measured from the floor to a height of 27 inches above the floor, within the restroom, of sufficient size to inscribe a circle with a diameter not less than 60 inches in size or a "T" turning space must be provided. Changes of level are not permitted.	N/A	<a href="https://www.access-board.gov/ada/#ada-603_2_3">https://www.access-board.gov/ada/#ada-603_2_3</a>	2012 TAS Section: 603.2.3 2010 ADAS Section: 603.2.3 2015 ABAAS Section: 603.2.3		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
168	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The threshold is greater than 1/2 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. 1/4 inch is the maximum vertical rise.	Entry into restroom may comply with beveled requirements, verify. Exiting restroom is not compliant, threshold exceeds 1/2"	<a href="https://www.access-board.gov/ada/#ada-404_2_5">https://www.access-board.gov/ada/#ada-404_2_5</a>	2012 TAS Section: 404.2.5 2010 ADAS Section: 404.2.5 2015 ABAAS Section: 404.2.5		
169	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The door is equipped with a door closer and returns to a closed position too quickly. Door closers and gate closers shall be adjusted so that from an open position of 90 degrees, the time required to move the door to a position of 12 degrees from the latch is 5 seconds minimum.	N/A	<a href="https://www.access-board.gov/ada/#ada-404_2_8_1">https://www.access-board.gov/ada/#ada-404_2_8_1</a>	2012 TAS Section: 404.2.8.1 2010 ADAS Section: 404.2.8.1 2015 ABAAS Section: 404.2.8.1		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
170	Outdoor Features (Public) : Fly Fishing Area - Restroom (Women's)	The wall sign is incorrectly located. Where permanent identification signs are provided for rooms and spaces, signs shall be installed on the wall adjacent to the latch side of the door. Where there is no wall space on the latch side, including at double leaf doors, signs shall be placed on the nearest adjacent wall, preferably on the right. Mounting location shall be located so that a person may approach within 3 inches of the sign and that a clear floor space of 18 inches minimum by 18 inches minimum, centered on the tactile Characters, is provided beyond the arc of any door swing between the closed position and 45 degree open position.	Sign placement incorrect.	Height Above Finish Floor or Ground <a href="https://www.access-board.gov/ada/#ada-703_4_1">https://www.access-board.gov/ada/#ada-703_4_1</a> Location <a href="https://www.access-board.gov/ada/#ada-703_4_2">https://www.access-board.gov/ada/#ada-703_4_2</a>	2012 TAS Section: 703.4.1  2010 ADAS Section: 703.4.1  2015 ABAAS Section: 703.4.1		
171	Outdoor Features (Public) : Picnic Spaces Near Visitors Center - Angler Pavilion Picnic Area	There is no outdoor recreation access route that connects accessible elements, spaces, and facilities within the picnic unit. At least one outdoor recreation access route shall connect accessible elements, spaces, and facilities provided within picnic units with mobility features.	Ground/surface material not compliant around picnic tables. Exterior pathway leading to tables non compliant.	N/A - Refer to Finding	2015 ABAAS Section: F245.4.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
172	Outdoor Features (Public) : Picnic Spaces Near Visitors Center - Angler Pavilion Picnic Area	The picnic unites are not adequately dispersed. Picnic units required to provide mobility features shall provide choices of picnic units comparable to, and integrated with, those available to others.	There are no compliant picnic tables at this location. Need 1 to gain compliance.	Provide compliant picnic table Knee space for wheelchair seating must be at least 30 inches wide, 19 inches deep, and 27 inches high, as measured from the ground or floor to the bottom of the tabletop. Toe clearance of at least 9 inches above the ground or floor must extend at least an additional 5 inches beyond the knee clearance.	2015 ABAAS Section: F245.2.4		
173	Outdoor Features (Public) : Picnic Spaces Near Visitors Center - School Group Area	There is no outdoor recreation access route that connects accessible elements, spaces, and facilities within the picnic unit. At least one outdoor recreation access route shall connect accessible elements, spaces, and facilities provided within picnic units with mobility features.	Ground/surface material around picnic tables is mostly compliant. Exterior pathway leading to tables non compliant.	N/A - Refer to Finding	2015 ABAAS Section: F245.4.1		





**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
174	Outdoor Features (Public) : Picnic Spaces Near Visitors Center - School Group Area	The picnic unites are not adequately dispersed. Picnic units required to provide mobility features shall provide choices of picnic units comparable to, and integrated with, those available to others. Provide compliant picnic table Knee space for wheelchair seating must be at least 30 inches wide, 19 inches deep, and 27 inches high, as measured from the ground or floor to the bottom of the tabletop. Toe clearance of at least 9 inches above the ground or floor must extend at least an additional 5 inches beyond the knee clearance.	Looks to be 2 accessible picnic tables with a somewhat accessible pathway and landing pad around tables. These need to be evenly dispersed around area with improved pathways.	N/A - Refer to Finding	2015 ABAAS Section: F245.2.4		
175	Outdoor Features (Public) : Picnic Spaces Near Visitors Center - Overlook Area	There is no outdoor recreation access route that connects accessible elements, spaces, and facilities within the picnic unit. At least one outdoor recreation access route shall connect accessible elements, spaces, and facilities provided within picnic units with mobility features.	Ground/surface material not compliant around picnic tables. Exterior pathway leading to tables non compliant.	N/A - Refer to Finding	2015 ABAAS Section: F245.4.1		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
176	Structures on Property (STAFF) - Visitor Center Top Floor: Entrance into Staff Work Area - Entrance Doors	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		
177	Structures on Property (STAFF) - Visitor Center Top Floor: Entrance into Staff Work Area - Entrance Doors	The floor mat at the door is not secured in place. If carpet or carpet tile is used on a ground or floor surface, then it shall be securely attached; have a firm cushion, pad or backing or no cushion or pad; and have a level loop, textured loop, level-cut pile or level-cut/uncut pile texture. The maximum pile height shall be 1/2 inch. Exposed edges of carpet shall be fastened to floor surfaces and have trim along the entire length of the exposed edge. Recessed doormats shall be adequately anchored to prevent interference with wheelchair traffic.	Floor Mat is not in good working condition or secured to floor. Carpet fraying and deteriorating to right of floor mat, not located on main path of travel.	<a href="https://www.access-board.gov/ada/#ada-302_2">https://www.access-board.gov/ada/#ada-302_2</a>	2012 TAS Section: 302.2  2010 ADAS Section: 302.2  2015 ABAAS Section: 302.2		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
178	Structures on Property (STAFF) - Visitor Center Top Floor: Elevator	The existing passenger elevators contain several non compliant features in accordance with ASME A17.1, (Safety Code for Elevators and Escalators). The elevator car size (XX) (length & width) (XX) is are too small, door operation, door size, door protective and reopening devices are noncompliant, hall & car calls are incorrect and/or missing, the hall lantern and door jamb markings are missing and/or incorrect. An audible signal shall sound once for the "up" direction and twice for the "down" direction or shall have verbal annunciators that say "up" or "down." Contact the elevator contractor and/or vendor to ensure compliance with ASME A17.1.	This elevator is for staff only and requires a key to use. This elevator can be used as a accommodations with TPWD personnel chaperoning participant. There are a few elements needed to gain full compliance. Emergency button location, and audio elements are non compliant.	<a href="https://www.access-board.gov/ada/#ada-407_1">https://www.access-board.gov/ada/#ada-407_1</a>	2012 TAS Section: 407.1  2010 ADAS Section: 407.1  2015 ABAAS Section: 407.1		
179	Structures on Property (STAFF) - Visitor Center Top Floor: Interior Hallways	The element projects more than 4 inches into the circulation path. Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall, a manner of cane detection must be provided.	This protruding object is found in staff only hallway. There are no official ADA fire extinguisher height or fire alarm ADA requirements. However, there are rules that govern the placement of all protruding objects, no matter their function, to accommodate blind and other visually impaired people Other elements of walkway are within compliance.	<a href="https://www.access-board.gov/ada/#ada-307_2">https://www.access-board.gov/ada/#ada-307_2</a>	2012 TAS Section: 307.2  2010 ADAS Section: 307.2  2015 ABAAS Section: 307.2		 <p>4" max 4" is the max. an object may project if the bottom is greater than 27" off the floor X &gt; 27"</p>

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**




Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
180	Structures on Property (STAFF) - Visitor Center Bottom Floor: Conference Room/Kitchenette	The sink drain pipes are exposed. Hot water and drain pipes exposed under sinks shall be insulated or otherwise configured so as to protect against contact. There shall be no sharp or abrasive surfaces under sinks.	Pipes need to be insulated or guard provided for knee and toe clearance. Other sink elements are compliant and can be accessed via parallel approach or frontal approach.	<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a>	2012 TAS Section: 606.5 2010 ADAS Section: 606.5 2015 ABAAS Section: 606.5	 	
181	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Men's)	The accessible stall has been found to be in substantial compliance with accessibility codes, standards, and regulations.	Accessible stall needs a few elements for full compliance including door handles and accessible locking mechanisms.	<a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a>	2012 TAS Section: Advisory 2010 ADAS Section: Advisory 2015 ABAAS Section: Advisory		



**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
182	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Men's)	There are not enough accessible lavatories. Where lavatories are provided, at least one shall be accessible and shall not be located in a toilet compartment.	Lavatory hardware, Lavatory approach space, and accessories are not compliant.	Review lavatory components to make accessible. <a href="https://www.access-board.gov/ada/#ada-213_3_4">https://www.access-board.gov/ada/#ada-213_3_4</a> <a href="https://www.access-board.gov/ada/#ada-606">https://www.access-board.gov/ada/#ada-606</a>	2012 TAS Section: 213.3.4  2010 ADAS Section: 213.3.4  2015 ABAAS Section: F213.3.4		
183	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Men's)	There are no accessible bathing and shower facilities. Where bathtubs or showers are provided, at least one accessible bathtub or at least one accessible shower shall be provided.	This type of shower needs to be evaluated for accessibility. Pending review	<a href="https://www.access-board.gov/ada/#ada-213_3_6">https://www.access-board.gov/ada/#ada-213_3_6</a> <a href="https://www.access-board.gov/ada/#ada-608_3_1">https://www.access-board.gov/ada/#ada-608_3_1</a>	2012 TAS Section: 213.3.6  2010 ADAS Section: 213.3.6  2015 ABAAS Section: F213.3.6		
184	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Women's)	The accessible stall has been found to be in substantial compliance with accessibility codes, standards, and regulations.	Accessible stall needs a few elements for full compliance including free flowing TP dispenser, coat hook height, door handles and accessible locking mechanisms.	<a href="https://www.access-board.gov/ada/#ada-604_7">https://www.access-board.gov/ada/#ada-604_7</a> <a href="https://www.access-board.gov/ada/#ada-604_8_1_2">https://www.access-board.gov/ada/#ada-604_8_1_2</a> <a href="https://www.access-board.gov/ada/#ada-604_8_3">https://www.access-board.gov/ada/#ada-604_8_3</a>	2012 TAS Section: Advisory  2010 ADAS Section: Advisory  2015 ABAAS Section: Advisory		







Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
185	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Women's)	The water and drain pipes under the lavatory are not adequately insulated. Water supply and drain pipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or abrasive surfaces under lavatories and sinks.	N/A		<a href="https://www.access-board.gov/ada/#ada-606_5">https://www.access-board.gov/ada/#ada-606_5</a>	2012 TAS Section: 606.5 2010 ADAS Section: 606.5 2015 ABAAS Section: 606.5	
186	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Women's)	The faucet controls require twisting of the wrist. Faucet controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 lb. Lever-operated, push-type and electronically controlled mechanisms are examples of acceptable designs. Self-closing valves are allowed if the faucet remains open for at least 10 seconds.	N/A		<a href="https://www.access-board.gov/ada/#ada-606_4">https://www.access-board.gov/ada/#ada-606_4</a>	2012 TAS Section: 606.4 2010 ADAS Section: 606.4 2015 ABAAS Section: 606.4	
187	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Restroom (Women's)	There are no accessible bathing and shower facilities. Where bathtubs or showers are provided, at least one accessible bathtub or at least one accessible shower shall be provided.	This type of shower needs to be evaluated for accessibility. Pending review		<a href="https://www.access-board.gov/ada/#ada-213_3_6">https://www.access-board.gov/ada/#ada-213_3_6</a> <a href="https://www.access-board.gov/ada/#ada-608_3_1">https://www.access-board.gov/ada/#ada-608_3_1</a>	2012 TAS Section: 213.3.6 2010 ADAS Section: 213.3.6 2015 ABAAS Section: F213.3.6	





Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
188	Structures on Property (STAFF) - Visitor Center Bottom Floor: Restrooms/Water Fountains - Water Fountain	The drinking fountain has multiple violations. Drinking fountains must be on an accessible route that provides a 30 inch by 48 inch clear floor space centered on the low unit, allowing a forward approach. Spout outlets shall be 36 inches maximum above the finish floor or ground. Spout outlets of drinking fountains for standing persons shall be 38 inches minimum and 43 inches maximum above the finish floor or ground. The spout shall be located 15 inches minimum from the vertical support and 5 inches maximum from the front edge of the unit, including bumpers. The spout shall provide a flow of water 4 inches high minimum and shall be located 5 inches maximum from the front of the unit. The angle of the water stream shall be measured horizontally relative to the front face of the unit. Where spouts are located less than 3 inches of the front of the unit, the angle of the water stream shall be 30 degrees maximum. Where spouts are located between 3 inches and 5 inches maximum from the front of the unit, the angle of the water stream shall be 15 degrees maximum. Operable parts shall comply with applicable standards.	Standing water fountain is not provided. Its required that if one is provided then the other option is as well. Water refill station cannot take the place of either water fountain unless only water refill station is provided and no water fountains. The Building Code may only require one drinking fountain be provided, but the Accessibility Standards require at least two. One at a lower height and the other at standing height.	Review drinking fountain requirements Clear floor space <a href="https://www.access-board.gov/ada/#ada-403_5_1">https://www.access-board.gov/ada/#ada-403_5_1</a> Drinking fountain requirements, general <a href="https://www.access-board.gov/ada/#ada-602_1">https://www.access-board.gov/ada/#ada-602_1</a>	2012 TAS Section: 403.5.1, 602.1  2010 ADAS Section: 403.5.1, 602.1  2015 ABAAS Section: 403.5.1, 602.1		



Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
189	Structures on Property (STAFF) - Conservatory Center : Entrance/Exit Doors - Exit Doors into Main Hallway	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional. Exit door leading towards hallway.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		





IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
190	Structures on Property (STAFF) - Conservatory Center : Entrance/Exit Doors - Exit Doors into Parking Lot	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional. Exit door leading outside to parking lot	https://www.access-board.gov/ada/#ada-216_4_1	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		
191	Structures on Property (STAFF) - Conservatory Center : Interior Hallways of Building - Conference Room/Kitchenette	The room identification sign is noncompliant. Wall signs identifying permanent rooms and spaces of a building shall be in a horizontal format and the characters raised 1/32 inch minimum and shall be sans serif uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Characters and their background shall have a non-glare finish. Characters shall contrast with their background with either light characters on a dark background or dark characters on a light background. Signs with raised characters or Braille shall be located 48 inches minimum above the finish floor or ground surface, measured from the baseline of the lowest tactile character and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile character.	Incorrect sign type. Signs that identify a room, space or area are required to have raised characters and Braille. This requirements includes both public access areas as well as all employee areas.	Wall sign designation https://www.access-board.gov/ada/#ada-216_2 Wall signs general https://www.access-board.gov/ada/#ada-703_1	2012 TAS Section: 216.2, 703.1  2010 ADAS Section: 216.2, 703.1  2015 ABAAS Section: F216.2, 703.1		

**IF-Athens TX, TFFC ADA Evaluation - 5550 FM2495 Athens, TX 75752**

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
192	Structures on Property (STAFF) - Conservatory Center : Interior Hallways of Building - Conference Room/Kitchenette	Knee and toe clearance has not been provided at the sink. The knee clearance shall be 11 inches deep minimum at 9 inches above the finish floor or ground, and 8 inches deep minimum at 27 inches above the finish floor or ground. The toe clearance is the space under the sink between the finish floor or ground and 9 inches above the finish floor 30 inches wide minimum. The toe clearance shall extend a minimum of 17 inches and a maximum of 25 inches underneath the sink.	Forward approach has obstruction in clear toe space provided. Sink is accessible once obstruction is cleared.	<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a>	2012 TAS Section: 606.2  2010 ADAS Section: 606.2  2015 ABAAS Section: 606.2		
193	Structures on Property (STAFF) - Conservatory Center : Interior Hallways of Building - Classroom	There are not enough accessible lavatories. Where lavatories are provided, at least one shall be accessible and shall not be located in a toilet compartment.	Sink not required to have front approach due to function of this area. parallel approach height needs to be verified.	<a href="https://www.access-board.gov/ada/#ada-213_3_4">https://www.access-board.gov/ada/#ada-213_3_4</a>	2012 TAS Section: 213.3.4  2010 ADAS Section: 213.3.4  2015 ABAAS Section: F213.3.4		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
194	Structures on Property (STAFF) - Conservatory Center : Interior Hallways of Building - Classroom	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
195	Structures on Property (STAFF) - Anglers Pavilion: Entrance/Exit Doors - Exit Door to Staff Parking Lot	The tactile EXIT sign is missing at the door. Wall signs identifying exits shall have characters raised 1/32 inch minimum and shall be uppercase characters a minimum of 5/8 inch and a maximum of 2 inches high. Braille shall be placed directly below the tactile characters; flush left or centered. Signs shall be located a minimum of 48 inches above the floor, measured from the baseline of the lowest tactile characters and 60 inches maximum above the finish floor or ground surface, measured from the baseline of the highest tactile characters. Where a tactile sign is provided at a door, the sign shall be located on the latch side. Where a tactile sign is provided at double doors the sign shall be located to the right of the right-hand door. Where there is no wall space at the latch side of a single door or at the right side of double doors, signs shall be located on the nearest adjacent wall.	Where visual EXIT is provided, accompanying tactile EXIT sign must also be provided for same doorway. Doorway exit signs and emergency exits with emergency exit signs that are overhead or visual only, or pictograms only, must have an accompanying ADA Braille sign. Exit passages, including doors, stairs and routes, must be identified with tactile ADA signage. Signs must include braille and raised characters. Pictograms are optional.	<a href="https://www.access-board.gov/ada/#ada-216_4_1">https://www.access-board.gov/ada/#ada-216_4_1</a>	2012 TAS Section: 216.4.1  2010 ADAS Section: 216.4.1  2015 ABAAS Section: F216.4.1		
196	Structures on Property (STAFF) - Anglers Pavilion: Interior Hallways of Building	The door has a door stop which prevents it from having a smooth surface at the bottom. Swinging door surfaces within 10 inches of the finish floor or ground measured vertically must have a smooth surface on the push side extending the full width of the door. Parts creating horizontal or vertical joints in these surfaces shall be within 1/16 inch of the same plane as the other. Cavities created by added kick plates shall be capped. This is required to allow those that use wheelchairs to use their footrests to push the door open without getting trapped or injured by the gate material. All gates, including ticket gates, shall meet all applicable specifications for doors.	Door stop leading to staff area.	<a href="https://www.access-board.gov/ada/#ada-404_2_10">https://www.access-board.gov/ada/#ada-404_2_10</a>	2012 TAS Section: 404.2.10  2010 ADAS Section: 404.2.10  2015 ABAAS Section: 404.2.10		

Finding Number	Area Description	Finding	As Built	Recommendation	Citation	Photos	Figure
197	Structures on Property (STAFF) - Anglers Pavilion: Interior Hallways of Building - Kitchenette	Knee and toe clearance has not been provided at the sink. The knee clearance shall be 11 inches deep minimum at 9 inches above the finish floor or ground, and 8 inches deep minimum at 27 inches above the finish floor or ground. The toe clearance is the space under the sink between the finish floor or ground and 9 inches above the finish floor 30 inches wide minimum. The toe clearance shall extend a minimum of 17 inches and a maximum of 25 inches underneath the sink.	There is no accessible sink provided at this time. Sink required to have a front approach due to function of this area.	<a href="https://www.access-board.gov/ada/#ada-606_2">https://www.access-board.gov/ada/#ada-606_2</a>	2012 TAS Section: 606.2  2010 ADAS Section: 606.2  2015 ABAAS Section: 606.2	