

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
455319	SHARP'S MOTORSPORTS INC	\$ 1,476.43		TO MAINTAIN STATE OWNED ATVS IN SAFE OPERATING CONDITION			E	R28	Internal Repairs
455352	COSELMON MECHANICAL LLC	\$ 2,500.00		-INTERNAL REPAIR ESTIMATE-- Remove and Replace A/C Condenser			E	R28	Internal Repairs
455365	VONDERAU FORD LP	\$ 770.88		Internal repair to State Vehicle property number-189144. TPWD contact is eric.young@tpwd.state.tx.us or 361-972- 5483.			E	R28	Internal Repairs
455369	WAGGONER AND SON ELECTRIC INC	\$ -		INTERNAL REPAIR--ESTIMATE to repair main water supply line for Copper Breaks State Park			E	R28	Internal Repairs
455383	JACK L WELLMAN	\$ 583.44		INTERNAL REPAIR--ESTIMATE for repairs to 2000 Ford (Prop#169179), heater core repair			E	R28	Internal Repairs
455385	HACKNEY AUTO TRUCK AND FLEET SERVICE INC	\$ -		Internal Repair - ESTIMATE - Parts and labor ro repair A/C system on #186229, 2010 Ford.			E	R28	Internal Repairs
455449	JENNINGS ANDERSON FORD	\$ 1,615.61		Internal Repairs PO for Truck # 183809 @ GRSP			E	R28	Internal Repairs
455467	RLJ ADVANCED AIR SYSTEMS INC	\$ 3,600.00		INTERNAL REPAIR TO RESIDENCE AT FT. BOGGY SP CENTRAL HEAT AND AIR UNIT.			E	R28	Internal Repairs
455484	NATIONAL COTTON/DBA PIER 77 MARINE SERVICE	\$ 2,687.26		Internal repair on property # 201672 not to exceed \$2184.17 without written permission from an authorized TPWD staff member.			E	R28	Internal Repairs
455493	TAG AUTO INC	\$ 454.57		Internal Repairs: Engine whining on 2009 Ford F150; License #1070865; Property #183845; Mileage = 73050; Custodian: Annaliese Scoggin.			E	R28	Internal Repairs
455514	IMMEL MOTORS	\$ 3,000.00		Internal Repairs to 2003 Ford F250 PID#172-380			E	R28	Internal Repairs
455539	DAVIS HEAVY EQUIPMENT SERVICE	\$ 1,400.00		Repair Service for lift cylinders on Case 850-D Dozer; Property #141758 assigned to Robert Adams			E	R28	Internal Repairs
455606	LAND AND SEA SERVICES 1 INC	\$ 4,500.00		Redo of PO#453608, Internal repair on property #188627 for the Port O Connor FS not to exceed \$4500.00 without permission from an authorized TPWD staff member. experiencing faulty sensor and problems with the rear throttle.			E	R28	Internal Repairs
455607	E-Z AIR CONDITIONING	\$ 500.00		Internal Repair for Lodge Air Conditioner			E	R28	Internal Repairs
455652	POWERS AUTOMOTIVE	\$ 1,000.00		Internal Repairs: Problems with the transfer case on 2004 Ford F250; License #867070; Property #174414; Mileage = 147,782;Custodian: Mark Garrett			E	R28	Internal Repairs
455656	MCMAMARA CUSTOM SERVICES INC	\$ -		INTERNAL REPAIR--ESTIMATE to evaluate HVAC unit at Residence (Prop#996380)			E	R28	Internal Repairs
455679	C OWENS INC	\$ 2,700.00		Internal Repairs to 3 ton AC Unit located in Lake House on Mason Mtn WMA			E	R28	Internal Repairs
455696	WESTERN EQUIPMENT LLC	\$ 1,156.09		INTERNAL REPAIRS TO SKID STEER #175433, TDCJ BUDGET			E	R28	Internal Repairs
455753	WEST TEXAS GOLF CARS INC	\$ -		INTERNAL REPAIR--ESTIMATE to evaluate/possibly repair Workhorse (Prop#171445)			E	R28	Internal Repairs
455755	WYLIE AND SON INC	\$ -		INTERNAL REPAIR--ESTIMATE to evaluate/possibly repair Gator HPX (Prop#187967)			E	R28	Internal Repairs
455785	QUALITY IMPLEMENT CO	\$ -		INTERNAL REPAIR--ESTIMATE to evaluate/possibly repair Gator HPX (Prop#187967)			E	R28	Internal Repairs

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
455825	TYLER FORD	\$ 2,767.43		*Internal Repairs-2007 Ford Freestar SE - prop# 177406-est of parts and labor-not to exceed \$150.00- repair/labor services unless prior authorization is provided by Craig Bonds-start date 9/18/14-completion 9/24/14-estimate			E	R28	Internal Repairs
455828	HACKNEY AUTO TRUCK AND FLEET SERVICE INC	\$ -		Internal Repair-ESTIMATE-parts and labor to troubleshoot check engine light on 2008 Toyota Prius #183812			E	R28	Internal Repairs
455841	FOX SERVICE COMPANY II LLC	\$ 327.50		Internal Repair: NTE \$2000.00 - Repair of Ice Maker at TPWD HQ.			E	R28	Internal Repairs
455845	RPR CONSTRUCTION COMPANY INC	\$ 395.00		*internal repairs-Dist.3C a/c unit-making a noise-diagnostic check to determine problem -start date 9/18/14 with est. completion date 9/29/14-not to exceed \$85.00 with out prior approval from Rick Ott			E	R28	Internal Repairs
455873	CONDITIONED AIR INC	\$ 346.28		INTERNAL REPAIR-Estimate to repair AC unit at Sheldon Lake State Park - Park Managers P/N: 596232			E	R28	Internal Repairs
455917	FULTON YACHT YARD	\$ 11,144.51		INTERNAL REPAIR - Property # 125596 Capt. Williams Throttle Control Repairs			Q	R28	Internal Repairs
455941	ROBERT W HODDE	\$ 2,318.56		Service/Repair of two (2) 2005 Polaris Magnum 4x4 ATVs (PN 176208 & 176207) used at Bastrop State Park per Repair Order Quote 4430 & 4429			E	R28	Internal Repairs
455948	R & R TRACTOR & EQUIPMENT LTD	\$ 2,363.04		INTERNAL REPAIRS: Estimate to repair the drive system on a John Deere 5300 tractor, property #159099.			E	R28	Internal Repairs
455983	RPR CONSTRUCTION COMPANY INC	\$ 900.00		%intn'l repair-Reg 3 IF- AC unit-still not working properly-diagnostic check to track down problem- why unit will work sometimes & then shut down-start 9/22/14 not to exceed \$85. w/out prior approval completion 10/3/14 est. service involved			E	R28	Internal Repairs
456039	ON SITE GAS SYSTEMS	\$ 10,680.00		*Internal repair* to oxygen generator at AE Wood FH.			Q	R28	Internal Repairs
456130	SPRING BRANCH WATER WELL SERVICE INC	\$ 6,929.54		Internal Repair - water well repair, Guadalupe River SP			Q	R28	Internal Repairs
456171	EQUIPMENT DEPOT LTD	\$ 470.00		INTERNAL REPAIRS-Estimate for labor only to repair New holland tractor, Property#171677, Mother Neff SP			E	R28	Internal Repairs
456251	DON DAVIS DEALERSHIPS INC	\$ 2,752.10		ESTIMATE FOR MAINTENANCE AND REPAIR ON 2008 DODGE STATE VEHICLE. PEROPERTY # 181088			E	R28	Internal Repairs
456310	POWERS AUTOMOTIVE	\$ 872.24		COM: Outreach-Internal Repair Property 172379			E	R28	Internal Repairs
456365	WEST TEXAS GOLF CARS INC	\$ 428.70		INTERNAL REPAIR-ESTIMATE to evaluate/possibly repair Workhorse (Prop#171445) - PREVIOUS PO#455753			E	R28	Internal Repairs
456370	QUALITY IMPLEMENT CO	\$ 613.54		INTERNAL REPAIR-ESTIMATE to evaluate/possibly repair Gator HPX (Prop#187967) - PREVIOUS PO#455785			E	R28	Internal Repairs
456373	CHARLES CLARK CHEVROLET CO	\$ 11,081.83		ESTIMATED INTERNAL REPAIRS ON LE VEHICLE (PROP# 205151) FOR WARDEN JENKINS			Q	R28	Internal Repairs
456389	EWALD KUBOTA INC	\$ 296.23		Internal Repair - ESTIMATE - Parts and labor to repair front axle to Kubota Tractor #162299.			E	R28	Internal Repairs
456412	EQUIPMENT DEPOT LTD	\$ 2,737.32		Internal repair skid steer (prop # 203527) and tree shear attachment			E	R28	Internal Repairs
456423	FOX SERVICE COMPANY II LLC	\$ -		INTERNAL REPAIR NTE \$3000.00 - repair ice machines in canteen			E	R28	Internal Repairs

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
456437	RPR CONSTRUCTION COMPANY INC	\$ 85.00		Internal repair of a/c unit at Reg 3 Fisheries office building - unit not cooling properly			E	R28	Internal Repairs
456516	HACKNEY AUTO TRUCK AND FLEET SERVICE INC	\$ 685.42		Internal Repair-ESTIMATE-parts and labor to the engine on Ford F350 #183805.			E	R28	Internal Repairs
456548	CANADIAN WATER WELL INC	\$ 206.00		INTERNAL REPAIR - TO MAINTAIN WATER SUPPLY FOR WILDLIFE AND LIVESTOCK, ROB			E	R28	Internal Repairs
456576	CARLTON AUTOMOTIVE	\$ 728.21		INTERNAL REPAIR--Estimate to repair two park pickup trucks, property #182444 and #182430			E	R28	Internal Repairs
456581	COMFORT AIR ENGINEERING INC	\$ 8,555.68		INTERNAL REPAIR NTE \$5000 for repair services unless prior authorization is provided by the agency. HVAC controller system crashed, located in Bldg B3.			Q	R28	Internal Repairs
456690	BURTON BOAT WORKS LLC	\$ 1,358.59		Internal repair on Mercury 150HP outboard engine, property #184865, serial #1B751166 not to exceed \$1358.59 without written permission from an authorized TPWD staff member.			E	R28	Internal Repairs
456771	DIETZ TRACTOR COMPANY	\$ 1,638.73		Internal repair - Repair and rebuild clutch in Case 385 tractor, property# 146356.			E	R28	Internal Repairs
456826	GRG SANDERS AND CO	\$ 200.00		-INTERNAL REPAIR- BREAKROOM SINK			E	R28	Internal Repairs
456852	7M FABRICATION HEATING AND AIR CONDITIONING LLC	\$ 4,999.87		WALK IN FREEZER REPAIRS			N/A	R28	Internal Repairs
456950	STROEHER & OLFERS INC	\$ 336.66		Internal repair - Repair of Kawasaki Mule, property # 176445			E	R28	Internal Repairs
456958	FOUR SEASONS IRRIGATION LP	\$ 1,275.00		INTERNAL REPAIR--ESTIMATE for repairs to pump for bison water well			E	R28	Internal Repairs
456968	SHANNON WELL SERVICE	\$ 4,500.00		INTERNAL REPAIR - TO PROVIDE WATER SUPPLY FOR WILDLIFE & LIVESTOCK. MATADOR WMA #3 SOLAR WELL.			E	R28	Internal Repairs
456980	BIOSONICS INC	\$ 1,500.00		Internal repair on property with serial number 184872 DT-X Echosounder used on the RV Karankawa not to exceed \$1500.00 without Written permission from an authorized TPWD staff member.			E	R28	Internal Repairs
457024	EWALD KUBOTA INC	\$ 858.48		Kubota UTV repair, property # 188255			E	R28	Internal Repairs
457068	4C LONESTAR RANCH AND OUTDOORS INC DBA LONESTAR RANCH AND OUTDOORS	\$ -		Internal Repair--Estimate to repair transmission on Grasshopper, Prop#171028			E	R28	Internal Repairs
457089	JAAR WATER WELL SERVICE	\$ 6,436.00		**Estimate*** INTERNAL REPAIR- Carrizo well that supplies potable water has ceased to function- breackdown , diagnose & repair well.			Q	R28	Internal Repairs
457113	STROEHER & OLFERS INC	\$ 470.20		Internal Repair to Kawasaki mule, property # 1766455			E	R28	Internal Repairs
457267	STONE CAMPER SALES INC	\$ 703.70		COM: OUTREACH: TRAILER REPAIRS			E	R28	Internal Repairs
457270	STEVE HADLEY	\$ 5,450.00		Internal repair not to exceed \$5450.00. for the Port Oconnor R/V San Antonio #188627 .			N/A	R28	Internal Repairs
457481	MARK W RIBBLE	\$ 225.00		*Internal Repair* Evaluate and repair refrigerator at AE Wood FH.			E	R28	Internal Repairs
457514	STROEHER & OLFERS INC	\$ 181.55		Internal Repair - parts & labor to repair the Kawasaki Mule # 176445.			E	R28	Internal Repairs
457554	KNOWLTON AUTOMOTIVE	\$ 507.00		Internal Repair of Vehicle Property # 171577 - Biq Spring SP			E	R28	Internal Repairs
457587	TEXAS OUTDOOR POWER SALES INC	\$ 2,695.00		Internal Repair-Estimate to repair Brake Disc Actuator on 2008 John Deere Tractor-Property#181802			E	R28	Internal Repairs
457629	LIMONS ROAD SERVICE LTD	\$ 2,895.03		body and frame repair to fleet truck property #174488 2007 Ford F350			E	R28	Internal Repairs
457647	EWALD KUBOTA INC	\$ 3,987.22		Internal Repair of Ford 4830 Tractor with Loader, Prop #152967			E	R28	Internal Repairs
457678	GREEN COUNTRY EQUIPMENT LLC	\$ 716.01		INTERNAL REPAIR TO MAINTAIN STATE OWNED EQUIPMENT			E	R28	Internal Repairs

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
457819	CONDITIONED AIR INC	\$ 2,348.26		INTERNAL REPAIR / REGION 4 AIR CONDITIONING UNIT MAINTENANCE AND REPAIR			E	R28	Internal Repairs
457922	STEVE FENTER	\$ 800.00		INTERNAL REPAIR-ESTIMATE for repairs to Prop#169184 (power steering/fuel pump)			E	R28	Internal Repairs
457933	AFFORDABLE AIR AND HEAT	\$ 485.00		Internal Repair-Park Mgr house-Property#960087-heater repair			E	R28	Internal Repairs
457955	ANDY PRUDE WELL SERVICE	\$ 395.80		INTERNAL REPAIRS: Windmill supplying water to Black Gap WMA Shurley House residence stopped pumping water.			E	R28	Internal Repairs
457957	WILLIAM L REASONER	\$ 3,421.00		Internal Repair: prop. # 174458, oil and EGR cooler problems			E	R28	Internal Repairs
457970	CHRIS'S MARINE	\$ 2,200.00		Internal Repair: outboard motor repair, prop. # 166848			E	R28	Internal Repairs
457985	COVINGTON ENTERPRISES	\$ 7,050.00		Internal Repairs: Heating Unit at State-Owned Residence at Elephant Mountain Not Heating; Needs Repair			E	R28	Internal Repairs
458207	PRICE INTERNATIONAL INC	\$ 5,197.09		INTERNAL REPAIR: TRANSMISSION REPAIR TO BUCKET TRUCK, TPWD PROPERTY #181877			Q	R28	Internal Repairs
458314	PUMP MECHANICAL TECHNICAL SERVICE	\$ 3,435.00		Internal Repair to irrigation system computer controller			E	R28	Internal Repairs
458315	WESTMORELAND PLUMBING	\$ 3,000.00		Internal Repair for broken water pipe at maintenance shop behind Bldg. D at TPWD HQ. NTE \$3000.00 for repair services unless prior authorization is provided by the agency.			E	R28	Internal Repairs
458340	MCNAMARA CUSTOM SERVICES INC	\$ -		INTERNAL REPAIR - SEWER CAMERA SERVICES			E	R28	Internal Repairs
458529	A C COLLINS FORD INC	\$ 237.80		INTERNAL REPAIRS PO TO REPLACE THE DISABLE AIRBAG LAMP ASSEMBLY PN # 181040-2008 FORD			E	R28	Internal Repairs
458632	BLAKE UTTER AUTOMOBILE COMPANY INC	\$ 1,271.62		INTERNAL REPAIR 2008 FORD PU: CAMSHAFT/ROCKER ARMS/LASH ADJUSTERS			E	R28	Internal Repairs
458664	O J'S MARINE INC	\$ 3,473.16		Internal repair to property # 166710 for haul out, bottom job and install zincs. not to exceed \$3473.16 without written permission from an authorized TPWD staff member.			N/A	R28	Internal Repairs
458675	BLACKSTONE RIDGE	\$ 900.00		Internal Repair to prop# 184149(ProDrive Boat motor) - Dist. 3A Marshall- repair oil leak and starter start 12/2/14 expected completion 12/31/14			E	R28	Internal Repairs
458702	DENTEX TRACTOR REPAIR SERVICE	\$ 2,958.38		INTERNAL REPAIR - PROP 157307 - BACKHOE - ESTIMATED REPAIR OF stinger cylinder and stinger bucket arms (bent). TOTAL COSTS OF REPAIR NOT TO EXCEED \$3,200.00			E	R28	Internal Repairs
458706	DENTEX TRACTOR REPAIR SERVICE	\$ 1,600.25		INTERNAL REPAIR - ESTIMATE ON REPAIR OF TRACTOR PROP 160265 - CLUTCH REPAIR			E	R28	Internal Repairs
458777	RAY'S AUTO BODY AND PAINT SHOP	\$ 1,092.25		Internal Repair Cost not to exceed without prior written notice from owner TPWD- Ford Dually #174415 of front fender for the use of park operations at Devils River			E	R28	Internal Repairs
458819	H AND W RECREATIONAL VEHICLES LLC	\$ 500.00		Internal Repair - prop# 175365 (serial # 1B029244) 150 HP motor - repair due to poor motor performanc and high fuel consumption - Dist. 3C-contact:Richard Ott or Bill Hughes 903/566-2161- service involved-repairs unknown			E	R28	Internal Repairs
458879	AG POWER INC	\$ 9,100.17		Internal Repair: Property # 175416, 2004 John Deer Tractor model # 6603, for use on the MTREP			Q	R28	Internal Repairs

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
458892	RENO'S RENTALS INC	\$ -		Quote# q4017 Estimate for Internal repair of Grasshopper Lawnmower Prop.#170104			E	R28	Internal Repairs
458955	FURRY INDUSTRIES INC DBA COMMERCIAL ELECTRIC CO	\$ 821.50		Internal Repair for Nails Creek Lift Station			E	R28	Internal Repairs
458962	DICK POE MOTORS L P	\$ 5,415.46		Internal Repair of Vehicle Property # 189809 2012 Jeep Wrangler - Big Bend Ranch SP			Q	R28	Internal Repairs
458996	CRAIGS TIRE SERVICE INC	\$ 1,500.00		SERVICES-Internal repairs to the suspension of the Ford F-250 Ppty #174460.			E	R28	Internal Repairs
459029	ROBERT'S GARAGE	\$ 438.60		INTERNAL REPAIR, PRICE IS AN ESTIMATE TO REPAIR SHIFT INDICATOR AND TUNE UP TOSTATE TRUCK# 182484			E	R28	Internal Repairs
459035	A C COLLINS FORD INC	\$ 724.52		INTERNAL REPAIRS PO TO REPLACE EGR VALVE & REPAIR LOOSE POWER WIRE IN DRIVER DOOR PN # 182447-2008 FORD			E	R28	Internal Repairs
459128	EAST TEXAS REFRIGERATION COMPANY INC	\$ 643.97		Internal repair to ice maker (Scotsman model CME506) - repair undetermined until repairman evaluates the problems-no property number on ice maker-start 12/11/14 completion 12/18/14			E	R28	Internal Repairs
459177	TEAM FORD MERCURY	\$ 1,199.86		INTERNAL REPAIRS, Estimate to repair Ford Ranger #181019 at WOB.			E	R28	Internal Repairs
459252	ASG FAMILY INVESTMENTS LLC DBA MR APPLIANCE OF EAST TEXAS	\$ 89.95		Internal repair to ice maker at Tyler Reg Fisheriers office-repairman will have to evaluate problem to determine the repair & cost -start 12-16-14 with completion date 12/29/14 if parts need to be ordered-no prop# Kenmore-ser#BA43727495			E	R28	Internal Repairs
459338	STEVE FENTER	\$ 325.00		INTERNAL REPAIR--ESTIMATE, R/R starter, 98 GMC, Prop #164628			E	R28	Internal Repairs
459402	ANDY PRUDE WELL SERVICE	\$ 1,400.00		INTERNAL REPAIRS: Well services, water well at Elephant Mountain WMA that is the primary water source for eight water troughs at Windmill Canyon.			E	R28	Internal Repairs
459471	TYLER FORD	\$ 714.25		Internal Repair to state vehicle (2007 Ford prop#177406)- unknown issues-electrical/computer malfunction - start 12/18/14 with est. completion 1/15/15-no idea of cost-est. of \$300 with approval if over by Craig			E	R28	Internal Repairs
459802	CLEBURNE FORD INC	\$ 500.00		INTERNAL REPAIR--ESTIMATE to repair water pump, Prop#169754, truck			E	R28	Internal Repairs
459809	CLEBURNE FORD INC	\$ 1,250.00		INTERNAL REPAIR--Estimate to repair A/C, Prop#182471			E	R28	Internal Repairs
460081	HILL COUNTRY PUMP	\$ 4,950.00		"Internal Repair" Repair & Maintenance of Windmills at Kerr WMA			E	R28	Internal Repairs
460083	VLASEK PUMP CO	\$ 4,995.00		Repair & Maintenance of Solar & Standard Wells at Kerr WMA			E	R28	Internal Repairs
460088	ELITE DIESEL SERVICE LLC	\$ 20,214.87		Internal Repair on TPWD property # 138310 RV Trinity Bay not to exceed 20214.87 without written permission from authorized TPWD staff.			Q	R28	Internal Repairs
460094	EP HVAC US INC	\$ 2,350.86		Services- New electrical circuit for A/C & correction of old electrical circuit			E	R28	Internal Repairs
460098	WICHITA FALLS FORD LINCOLN MERCURY	\$ 3,600.00		INTERNAL REPAIR: prop. # 177476, no turbo pressure, won't know the full cost of repair until engine is opened			E	R28	Internal Repairs
460188	MCNAMARA CUSTOM SERVICES INC	\$ 1,600.00		INTERNAL REPAIR--ESTIMATE to repair leak/change trim, Bthrm at park residence, Prop#195492			E	R28	Internal Repairs
460200	FULTON YACHT YARD	\$ 11,617.67		INTERNAL REPAIR - Property # 125596 Capt. Williams Turbo Charger Engine Repairs			Q	R28	Internal Repairs

PO	VENDOR_NAME	PO_AMOUNT	BLANKET_TOTAL	COMMENTS	START_DATE	END_DATE	PCC	REASON_CODE	DESCRIPTION
460224	LANSDOWNE-MOODY CO INC	\$ 5,199.79		INTERNAL REPAIRS, ESTIMATE TO REPAIR TRACTOR, PROPERTY# 188259, AT GALVESTON ISLAND STATE PARK.			N/A	R28	Internal Repairs
460290	HULL SUPPLY COMPANY INC	\$ 1,000.00		Internal Repair NTE \$1000.00 for repair services of the handicap door in Bldg D at TPWD HQ unless prior authorization is provided by the agency.			E	R28	Internal Repairs
460382	THOMAS AUTOMOTIVE INC	\$ 1,000.00		INTERNAL REPAIR FOR SAFE OPERATIONS OF STATE TRUCK - WL DISTRICT 2			E	R28	Internal Repairs
460400	TEXAS FIFTH WALL ROOFING SYSTEMS INC	\$ 1,000.00		Internal Repair NTE \$1000.00 unless prior authorization is provided by agency for service call for leak investigation and repairs (non-warranty) for roof at TPWD HQ.			E	R28	Internal Repairs
460482	ELWIN E TRUAX	\$ 600.00		Service-Intall Air Conditioner			E	R28	Internal Repairs
460493	SHANNON WELL SERVICE	\$ 250.00		TO MAINTAIN WATER SUPPLY FOR WILDLIFE AND LIVESTOCK, ROB			E	R28	Internal Repairs
460528	CONYERS SERVICES	\$ 75.00		TO MAINTAIN WATER SUPPLY FOR WILDLIFE AT THE DIMMITT WMA			E	R28	Internal Repairs
460738	3 C ELECTRIC LLC	\$ 550.00		INTERNAL REPAIR- Estimate: Assessment/examination of picnic area park host RV site @ WOB, possible rewire/upgrade.			E	R28	Internal Repairs
460759	MCCROMETER INC	\$ 770.24		Internal repair - estimate - repairs to flow meter at irrigation field			E	R28	Internal Repairs
460826	STEWART & STEVENSON POWER PRODUCTS LLC	\$ 4,688.00		Internal repair of backup generator.			E	R28	Internal Repairs
460837	TRANSPORT BOATS INC	\$ 4,090.00		Intermdal Repair on TPWD Property # 178104 for Palacios Field Station Internal repair not to exceed \$4090.00			E	R28	Internal Repairs
460852	COASTAL MACHINE AND MECHANICAL LLC	\$ 1,680.00		internal repair to two Fybroc pumps located at the Perry R. Bass MFRS. TPWD contact is paul.cason@tpwd.texas.gov or 361-972-5483			E	R28	Internal Repairs
460938	KEL ABBY COLLISION CENTER LLC	\$ 3,500.00		INTERNAL REPAIR-ESTIMATE to make repairs, '08 Ford Ranger Pickup, Prop#182746			E	R28	Internal Repairs
460989	RPR CONSTRUCTION COMPANY INC	\$ 565.00		AC/Heat unit needing repair- replacing functional TXU valve- service involved-start 1/30/15 with completion 2/3/15 not to exceed \$565 with out prior approval from regional office (Craig or Jimmie)			E	R28	Internal Repairs